

ASS. REC. BY:

REF

CS/FCT18019338 / Ng d3d

Special Instruction:

Surveyor
CWS

ASSIGNMENT (Officer)

From (Person):

May chua

of

FCT

Date/Time:

24/10/18 @ 2:08pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 2496P

Insured:

8HC8150L

at Workshop m/s

Yew Tee Automobile

Tel:

67653373

of

Blk 6, woodlands Rd 399F, Yew Tee Ind-Est

Policy No:

Claim No:

D18007695MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/10/2018

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement:

Date/Time:

2:51pm @ 24/10/18

Person Contacted:

Vinnie

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SMD 2496P-X
	8HC8150L-CS/FCT11005461/Kvr
30/10 @ 9:57am	revised preli advise via email

D.O.A: 18/03/2011

100-100

Signature: NAZ

REF:

FCI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 23K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMD 2496P Yr Regn: 15 MAY 2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 5SP C.C. 1999

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 101,042 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6CR 10F 170104857

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 21/10/18 D.O.I. 26/10/18

Survey held at YEN TEE AUTOMOBILE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COE Renewal 5 years

COE rebate \$18,260

RECEIVED 10 JAN 2019

8/1/19 Repair range \$3K - \$3.5K
FINALIZED LUMP SUM REPAIR \$1,200.00 / 3 days

CRD \$6852.10, 85%

NV = \$7316.44; GIA = \$18260; NV = \$4740

Date/Time, File Pass to?

☐ : Preli. Report

1) 10/1/19 10/1/19

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee: 160

Transportation: 50

S + RS. SI 50

Photos 28

Others _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format: TP

Lump Sum / I.B.I. (\$) 1200

TOTAL

288

MOTOR SURVEY ASSIGNMENT

Date	23-10-2018	Our Ref No. D18007695MFSH
Accident Date	21-10-2018	Claim Type. Third Party
Insured Vehicle	SHC8150L	Third Party Vehicle. SMD2496P
Survey Location	BLK 6 WOODLANDS ROAD 399F YEW TEE INDUSTRIAL ESTATE	
Contact Person.	VINNIE LIM	
Contact No.	67653373/ 67622081	Fax No. 67604895
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YEW TEE AUTOMOBILE TECH PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 30 October 2018 9:57 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'May Chua Hui Chin'; SUR
Subject: RE: SURVEY ASSESSMENT - D18007695MFSH/1
Attachments: PRELI ADVISED SMD 2496P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SMD 2496P**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 24 October 2018 2:54 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua Hui Chin' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007695MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 24 October 2018 2:08 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua Hui Chin <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007695MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007695MFSH

Date: 30/10/2018

Our Ref: CS/FCI18019338/Nqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMD 2496P

Please be informed that we had conducted the inspection of the abovementioned vehicle 26/10/2018 at the premises of M/s Yew Tee have the following to report: -

Workshop Estimate Amount	: S\$ 8,052.10
Revised Estimate Amount	: S\$ 1,855.00
"Check" Items Amount	: S\$ 675.40
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Naz

Automotive Assessor

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SMD2496P
Vehicle Type :	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	MAZDA
Vehicle Model :	MAZDA5 SP
Chassis No. :	JM6CR10F170104857
Propellant :	Petrol
Engine No. :	LF10253859
Engine Capacity :	1999 cc
Maximum Power Output :	101.0 kW (135 bhp)
Maximum Laden Weight :	2105 kg
Unladen Weight :	1495 kg
Year Of Manufacture :	2007
Original Registration Date :	15 May 2007
Lifespan Expiry Date :	-
COE Category :	B - Car (1601cc & above)
PQP Paid :	\$26,004.00
COE Expiry Date :	30 Apr 2022
Road Tax Expiry Date :	14 May 2019
Inspection Due Date :	14 May 2019
Intended Transfer Date :	26 Oct 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3843B
Vehicle Details	
Vehicle No.:	SMD2496P
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 SP
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	LF10253859
Chassis No.:	JM6CR10F170104857
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$18,249.00
Original Registration Date:	15 May 2007
First Registration Date:	15 May 2007
Transfer Count:	2
Actual ARF Paid:	\$20,074.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$26,004.00
COE Rebate Amount:	\$18,260.00
Total Rebate Amount:	\$18,260.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Oct 2018

OK

Make & Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status


**Mazda 5 2.0A Sunroof
(COE till 03/2022)**
\$20,800

\$6,190 /yr

07-Mar-
2007

1,999 cc

150,000
km

MPV

Available

Cheapest In Market, High Paper Value At \$17k, can Loan Up To \$18k, New Road Tax, Well Maintained, Loan/Trade-In Available, Call To Scrutinize.

Posted: 24-Oct-2018

Tags: 2007 Mazda 5, 2007 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda


**Mazda 5 2.0A Sunroof
(COE till 03/2022)**

-

N.A

04-Jun-2007

1,999 cc

-

MPV

SOLD

Cheapest In Town. Car Is Restore To Full Working Condition Before Owner Renew The COE, Buy With Confidence. Most Wear And Tear Replaced. Car Is Now Beautiful Inside Out. View To Believe. A Must View U...

Posted: 06-Oct-2018

Tags: 2007 Mazda 5, 2007 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda


**Mazda 5 2.0A Sunroof
(COE till 05/2022)**

-

N.A

11-May-
2007

1,999 cc

-

MPV

SOLD

Evaluated By Vicom, Free 6 Months Maintenance And 1 Grooming.

Yong Lee Seng Motor

Posted: 27-Sep-2018

Tags: 2007 Mazda 5, 2007 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda


**Mazda 5 2.0A Sunroof
(COE till 04/2022)**

-

N.A

15-May-
2007

1,999 cc

-

MPV

SOLD

Well Maintained Unit With Perfect Condition. Well Known Reliability With Perfect Car. Spacious And Powerful Drive The Best Value For Money Drive For The Whole Family. Warranty Can Be Arranged, STA Gra...

PREMIUM KD

Posted: 12-Aug-2018

Tags: 2007 Mazda 5, 2007 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/10/2018 15:07
Date Of Accident	21/10/2018 22:55
Exact Location Of Accident	AIRPORT BOULEVARD TO PIE(BEFORE PIE TUAS EXIT)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMD2496P
Insured/Policyholder	
Name Of Registered Owner	EC CARZ RENTAL
Co Reg No	53353843B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90670493
Vehicle Particulars	
Manufacturer	MAZDA
Model	5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5103485806
Cover Note Number	
Driver	
Name of Driver	SUHARTO BIN ISMAIL
NRIC No	S1803984B
Date Of Birth	11/02/1967
Occupation	OUTDOOR
Date Of Driving Pass	09/11/1994
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90670493
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 630 YISHUN STREET 61 #04-43
Postcode	760630
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHANGKAT NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 109 TAMPINES STREET 11 #01-261 , POSTCODE: 521109 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7819999 - FAX NO: 67832722
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8150L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SUHARTO BIN ISMAIL

Approximate Age 51

Injuries Sustain SLIGHT

Injured person in which vehicle? SMD2496P

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/ten be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



 A - SMP 2796P

 B - s/c 8150L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer


 To

 Police

 Report


DECLARATION

I/We declare the foregoing particulars are true in every respect.



 Policyholder's Signature

 Date & Time:



 Driver's Signature

 (If driver is not the policyholder)

 Date & Time:



 Reporting Officer/Personnel's Signature

 Name:

 NRIC/ID No.:

Sketch Plan #3



**SINGAPORE
POLICE FORCE**



T/20181022/2050

1 of 3

Report No. T/20181022/2050

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/10/2018 12:21		Vide Report No.:		Station Diary No.: 9	
Informant's Particulars					
Name of Informant: SUHARTO BIN ISMAIL			Address: APT BLK 630 YISHUN STREET 61 #04-43 SINGAPORE 760630		
ID Type / ID No.: NRIC NO / S1803984B			Contact No.: Home/Office: Mobile: 90670493		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 51	Date of Birth: 11/02/1967	Type of Informant: Driver		
Race: Javanese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 21/10/2018 22:55	Type of Location: Roundabout
Location: Along Road 1 Traveling Toward Road 2 AIRPORT BOULEVARD PAN ISLAND EXPRESSWAY Just before PIE (Tuas) exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC8150L	Car					0
SMD2496P	Car				Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Sketch Plan #4



**SINGAPORE
POLICE FORCE**



T/20181022/2050

2 of 3

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

Report No. T/20181022/2050

CONTINUATION OF REPORT

Driver			
Name	SUHARTO BIN. ISMAIL	ID No.	S1803984B
Related Vehicle	SMD2496P (Car)	Contact No.	90670493
Hospital/Clinic	SUNSHINE CLINIC FAMILY PRACTICE & SURGERY	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	22/10/2018	Date Discharge	22/10/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On the 21/10/2018 at about 2255hrs, I was driving along Airport Boulevard. I just picked up a passenger from Airport Terminal 3 and was heading towards Bukit Batok Ave 5. I was driving along the fourth lane from the right and was going towards PIE (Tuas). Just as I was under the bridge, the vehicle in front of mine applied his brakes. I also applied my brakes and came to a complete stop.

Suddenly, I heard a sound and felt an impact at the back of my vehicle. I then asked my passenger if he was okay and he was fine. I came out of my vehicle and talked to the vehicle behind mine (SHC8150L). I then assessed the damages on my vehicles and asked the driver for his particulars. However, the driver of SHC8150L did not want to give me his particulars and just told me to claim insurance. As I did not want to argue with him, I just took picture of his plate number and my vehicle, and continued on my journey.

My vehicle suffered dents on the left side of my rear bumper. I am unsure how much the damages cost. The next day, I went to see a doctor and was given a 5 day MC. I am suffering from neck and back pain.

Sketch Plan #5



SINGAPORE
POLICE FORCE



T/20181022/2050

3 of 3

Report No. T/20181022/2050

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 TEO YEE WAN, RENNY

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

22/10/2018 12:21

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE.

Contact No.: 65476414

Classification Of Case:

Authentication Stamp

NP168



Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : FIRST CAPITAL INSURANCE LTD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTHQ/TP/1810/016
Policy No:	5103485806	Date of Loss:	21/10/2018
Vehicle Reg. No.:	SMD2496P	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SHC8150L
Any Injuries?	no	Contact No:	
Insured/Claimant:	EC CAR RENTAL	Driver:	SUHARTO BIN ISMAIL

Make/Model:	Mazda, 5 SP - JM6CR10F	Vehicle Reg. Date:	15/05/2007
Vehicle Colour:	BLACK	Engine Number:	LF10253859
Chassis No:	JM6CR10F170104857	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS		Amount
Parts		5,597.10
Miscellaneous Items		405.00
Labour		1,190.00
Paintwork Labour		860.00
Towing		0.00
Gross Total(S\$):		8,052.10
GST 7.00%(S\$):		563.65
Nett Amount(S\$):		8,615.75

This claim is handled by: Sky Toh T C

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER	900.00	900.00	-20.00	720.00 /ce
2	1	REAR BUMPER SIDE RETAINER LH	33.00	33.00	-10.00	29.70 ?XS
3	1	REAR BUMPER SIDE RETAINER RH	33.00	33.00	-10.00	29.70 XSV
4	1	REAR BUMPER BRACKET LH	18.00	18.00	-10.00	16.20 ?XS
5	1	REAR BUMPER BRACKET RH	18.00	18.00	-10.00	16.20 ?XS
6	1	REAR BUMPER REFLECTOR LH	52.00	52.00	-10.00	46.80 XSV
7	1	REAR BUMPER REFLECTOR RH	52.00	52.00	-10.00	46.80 XSV
8	1	REAR BUMPER REINFORCEMENT	148.00	148.00	-20.00	118.40 ?XS
9	1	REAR FENDER INNER TRIM BOARD LH	609.00	609.00	-10.00	548.10 XSV
10	1	REAR FENDER INNER TRIM BOARD RH	609.00	609.00	-10.00	548.10 XSV
11	1	REAR TAILGATE	3,045.00	3,045.00	-20.00	2,436.00 XSV
12	1	REAR TAILGATE LOGO	69.00	69.00	-10.00	62.10 XSV
13	1	REAR TAILGATE MAZDA 5 EMBLEM	61.00	61.00	-10.00	54.90 XSV
14	1	REAR TAILGATE LOCK	340.00	340.00	-10.00	306.00 XSV
15	1	REAR TAILGATE INNER BOARD	154.00	154.00	-20.00	123.20 XSV
16	1	REAR END PANEL	487.00	487.00	-20.00	389.60 ?XS
17	1	REAR END PANEL INNER GARNISH	117.00	117.00	-10.00	105.30 ?XS

Total Parts (\$\$) 5,597.10

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	45.00	45.00	0.00	45.00 XSV
2	1	REAR BUMPER SENSORS (SET)	260.00	260.00	0.00	260.00 XSV
3	1	REAR TAILGATE INNER BOARD CLIPS	40.00	40.00	0.00	40.00 XSV
4	1	REAR WINDSCREEN SEALANT	60.00	60.00	0.00	60.00 XSV

Sub Total (\$\$) 405.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 XSV
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 30
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	80.00 XSV
4	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00 XSV
5	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	900.00	900.00	0.00	900.00 200

Gross Labour Cost (\$\$) 1,190.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00 30
2	1	To Spray painting on the Replaced and Repair	800.00	800.00	0.00	800.00 300

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.				330
Gross Labour Cost (S\$)						860.00

< END OF ESTIMATES >

NA2 LKIC

26/10/18 1100

LIS

3 DAYS

- CHECK ITEMS PHOTOS

- AFTER REPAIR PHOTOS


29/10/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : FIRST CAPITAL INSURANCE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1810/016
Policy No:	5103485806	Date of Loss:	21/10/2018
Vehicle Reg. No.:	SMD2496P	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SHC8150L
Any Injuries?	no	Contact No:	
Insured/Claimant:	EC CAR RENTAL	Driver:	SUHARTO BIN ISMAIL

Make/Model:	Mazda, 5 SP - JM6CR10F	Vehicle Reg. Date:	15/05/2007
Vehicle Colour:	BLACK	Engine Number:	LF10253859
Chassis No:	JM6CR10F170104857	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	5,597.10
Miscellaneous Items	405.00
Labour	1,190.00
Paintwork Labour	860.00
Towing	0.00
Gross Total(\$\$):	8,052.10
GST 7.00%(\$\$):	563.65
Nett Amount(\$\$):	8,615.75

This claim is handled by: Sky Toh T C

Parts \$720

S/N \$305

L \$230

S/P \$330

Total \$1585

-20%

\$1268

≈ \$1200 (LIS 6 kpr days)

3 DAYS

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER	900.00	900.00	-20.00	720.00 <i>CRK</i>
2	1	REAR BUMPER SIDE RETAINER LH	33.00	33.00	-10.00	29.70 <i>SVC</i>
3	1	REAR BUMPER SIDE RETAINER RH	33.00	33.00	-10.00	29.70 <i>SVC</i>
4	1	REAR BUMPER BRACKET LH	18.00	18.00	-10.00	16.20 <i>SVC</i>
5	1	REAR BUMPER BRACKET RH	18.00	18.00	-10.00	16.20 <i>SVC</i>
6	1	REAR BUMPER REFLECTOR LH	52.00	52.00	-10.00	46.80 <i>SVC</i>
7	1	REAR BUMPER REFLECTOR RH	52.00	52.00	-10.00	46.80 <i>SVC</i>
8	1	REAR BUMPER REINFORCEMENT	148.00	148.00	-20.00	118.40 <i>SVC</i>
9	1	REAR FENDER INNER TRIM BOARD LH	609.00	609.00	-10.00	548.10 <i>SVC</i>
10	1	REAR FENDER INNER TRIM BOARD RH	609.00	609.00	-10.00	548.10 <i>SVC</i>
11	1	REAR TAILGATE	3,045.00	3,045.00	-20.00	2,436.00 <i>SVC</i>
12	1	REAR TAILGATE LOGO	69.00	69.00	-10.00	62.10 <i>NFA</i>
13	1	REAR TAILGATE MAZDA 6 EMBLEM	61.00	61.00	-10.00	54.90 <i>NFA</i>
14	1	REAR TAILGATE LOCK	340.00	340.00	-10.00	306.00 <i>SVC</i>
15	1	REAR TAILGATE INNER BOARD	154.00	154.00	-20.00	123.20 <i>SVC</i>
16	1	REAR END PANEL	487.00	487.00	-20.00	389.60 <i>SVC</i>
17	1	REAR END PANEL INNER GARNISH	117.00	117.00	-10.00	105.30 <i>SVC</i>

Total Parts (\$\$) \$720 5,597.10

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	45.00	45.00	0.00	45.00 <i>NFA</i>
2	1	REAR BUMPER SENSORS (SET)	260.00	260.00	0.00	260.00 <i>SVC</i>
3	1	REAR TAILGATE INNER BOARD CLIPS	40.00	40.00	0.00	40.00 <i>NFA</i>
4	1	REAR WINDSCREEN SEALANT	60.00	60.00	0.00	60.00 <i>NFA</i>

Sub Total (\$\$) \$305 405.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 <i>NFA</i>
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 <i>SVC</i>
3	1	To Transfer Rear Tailgate.	80.00	80.00	0.00	80.00 <i>NFA</i>
4	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	100.00	0.00	100.00 <i>NFA</i>
5	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	900.00	900.00	0.00	900.00 <i>SVC</i>

Gross Labour Cost (\$\$) \$230 1,190.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00 <i>SVC</i>
2	1	To Spray painting on the Replaced and Repair	800.00	800.00	0.00	800.00 <i>SVC</i>

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.				330
Gross Labour Cost (S\$)				830		860.00

< END OF ESTIMATES >

NA2 LKIC

26/10/18 1100

LIS

3 DAYS

- CHECK ITEMS PHOTOS
- AFTER REPAIR PHOTOS




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18019338/Nqd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8150L	Veh. Inspected	SMD 2496P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007695MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	24/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA5 SP	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JM6CR10F170104857	Colour	BLACK	
Odometer	101042	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	5 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	5 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	5 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/10/2018	Inspection Date	26/10/2018	
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 2496P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CRACKED	900.00	900.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	148.00	-
1	REAR TAILGATE	SERVICEABLE	3,045.00	-
1	REAR TAILGATE INNER BOARD	SERVICEABLE	154.00	-
1	REAR END PANEL	SERVICEABLE	487.00	-
	LESS 20% DISCOUNT		-946.80	-180.00
			3,787.20	720.00
<u>NETT ITEMS</u>				
1	REAR BUMPER SIDE RETAINER LH (N)	SERVICEABLE	33.00	-
1	REAR BUMPER SIDE RETAINER RH (N)	SERVICEABLE	33.00	-
1	REAR BUMPER BRACKET LH (N)	SERVICEABLE	18.00	-
1	REAR BUMPER BRACKET RH (N)	SERVICEABLE	18.00	-
1	REAR BUMPER REFLECTOR LH (N)	SERVICEABLE	52.00	-
1	REAR BUMPER REFLECTOR RH (N)	SERVICEABLE	52.00	-
1	REAR FENDER INNER TRIM BOARD LH (N)	SERVICEABLE	609.00	-
1	REAR FENDER INNER TRIM BOARD RH (N)	SERVICEABLE	609.00	-
1	REAR TAILGATE LOGO (N)	NOT NECESSARY	69.00	-
1	REAR TAILGATE MAZDA 5 EMBLEM (N)	NOT NECESSARY	61.00	-
1	REAR TAILGATE LOCK (N)	SERVICEABLE	340.00	-
1	REAR END PANEL INNER GARNISH (N)	SERVICEABLE	117.00	-
	LESS 10% DISCOUNT		-201.10	-
			1,809.90	-
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	45.00	45.00
1	SET REAR BUMPER SENSORS (SN)	SCRATCHED	260.00	260.00
1	REAR TAILGATE INNER BOARD CLIPS (SN)	NOT NECESSARY	40.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			405.00	305.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.	NOT NECESSARY	30.00	-
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		80.00	30.00
	TO TRANSFER REAR TAILGATE.	NOT NECESSARY	80.00	-
	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	100.00	-
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.		900.00	200.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		60.00	30.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		800.00	300.00
			2,050.00	560.00
GRAND TOTAL			8,052.10	1,585.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/FCI18019338/Nqd3e2

MARKET VALUE: \$23,000.00(EST)-LTA REIMBURSEMENT VALUE: \$18,260.00=NETT VALUE: \$4,740.00

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.