

1/15/2018

INS. CASE OWNER

CC6 /AIG1801

LJK
IDAC

Surveyor:

MARLING

DOI:

ASSIGNMENT

Date / Time:

26/10/18

Registered in Merimen:

26/10/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFV 1V70D

Name of Insured:

AIRLINE RENT A CAR PTE

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

26/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MOND WAPPE BIR KAYAT

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

62068493254

Policy No.:

A00000542

Make / Model:

MAZDA

Place of Accident:

PE TMS BYE

OI GIA REPORT: YES NO : TP GIA REPORT: YES NO

Insured Liability:

% Final ? Yes / No

SFS 5114D



INSRS:

WSP:

Tel:

Liability:

RMKS:

Tan
Lim

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20/10/18
204

1/65140-X

SFV1V70D-X

CHAIN COLLISION

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

18-12-18 J64

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

X

After call 1st to OI:

X

Authorisation To Act:

X

Release Voucher:

X

Final Repair Bill:

X

Car Rental Invoice:

X

Towing Invoice:

X

LTA / GIA:

X

Medical Bill:

X

PIR:

X

Mandate/Reject Instruction:

X

LOD

X

Payment Breakdown Form:

X

Post-Repair Photos:

X

Others:

X

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No. : 28

If NO or B 28. Ass. Lia.:

Repair Cost:

\$5

(days) Reduction:

Loss of Rental (LOR):

\$5

(days) Reduction:

Loss of Use (LOU):

\$5

(days) Reduction:

Loss of Income (LOI):

\$5

(days) Reduction:

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/TA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

X

Payee 3: (Strike if N.A.)

\$5

Name 3:

X



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18019358/Ujb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 24-10-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKW 1270D	Veh. Inspected	SJS 5114D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/10/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/10/2018	Inspection Date	24/10/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3336C
Vehicle Details	
Vehicle No.:	SJS5114D
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	L13A4220884
Chassis No.:	GE61201514
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$13,856.00
Original Registration Date:	20 Aug 2009
First Registration Date:	20 Aug 2009
Transfer Count:	2
Actual ARF Paid:	\$12,495.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Aug 2019
PARF Rebate Amount:	\$6,247.00
Intended COE Rebate Details	
COE Expiry Date:	19 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$4,694.00
COE Rebate Amount:	\$1,227.00
Total Rebate Amount:	\$7,474.00

The information contained herein is correct as at 24 Oct 2018

OK

Not Authorized
 1/5 @ 7000/2
 24/10/18
 Take photo After repair
 1 Hdy



陳林璋摩打私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
 Tel : 68585151 (24 Hours) Fax : 68580877
 GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKW1270D
 Date of Accident : 24 October 2018

Miss Nur Zarifah Binte Mustapha

Date : 24 October 2018

Estimate To Repair SJS5114D - Honda FIT 1.3G A
 Chassis No : GE61201514

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	tailgate lid / <i>Body 703-10</i>	\$ 814.00
02	1 pc	tailgate lid Fit badge / <i>NEC REC</i>	\$ 25.00
03	1 pc	tailgate lid lock <i>DD/ym</i>	\$ 175.00
04	1 pc	tailgate lid lock striker <i>11</i>	\$ 27.50
05	1 pc	tailgate lid weatherstrip <i>2W1/TOA</i>	\$ 98.30
06	1 pc	tailgate lid inner trimboard <i>DE/CRA</i>	\$ 98.00
07	2 ps	tailgate lid hinges @ \$58.00 <i>11</i>	\$ 116.00
08	1 pc	tailgate lid damper stay <i>11</i>	\$ 75.00
09	2 ps	tailgate lid rubber stopper @ \$12.50 <i>11</i>	\$ 25.00
10	1 pc	tailgate lid rubber grommet <i>11</i>	\$ 66.00
11	1 pc	tailgate lid outer garnish <i>11</i>	\$ 166.00
12	1 pc	tailgate lid outer garnish H badge <i>11</i>	\$ 35.00
13	1 pc	rear wiper motor <i>11</i>	\$ 228.00
14	1 pc	rear windscreen glass weatherstrip bottom <i>REC 41-20</i>	\$ 95.80
15	1 pc	rear windscreen glass weatherstrip top <i>REC 41-20</i>	\$ 95.80
16	2 ps	rear licence plate lamps @ \$95.00 <i>11</i>	\$ 190.00
17	1 pc	rear luggage floor panel - <i>cramped/suc</i>	\$ 645.90
18	1 pc	rear luggage floor panel insulation padding <i>11</i>	\$ 350.00
19	1 pc	rear end panel / <i>DD Body 269.60</i>	\$ 390.00
20	1 pc	rear end panel inner trim / <i>DD 11</i>	\$ 68.50
21	4 ps	rear end panel inner trim clips @ \$4.50 <i>11</i>	\$ 18.00
22	1 pc	rear bumper / <i>DD 456.30</i>	\$ 710.30
23	2 ps	rear bumper brackets @ \$45.00 <i>11</i>	\$ 90.00
24	2 ps	rear bumper side retainers @ \$18.40 / <i>CRA</i>	\$ 36.80
25	2 ps	rear bumper side holders @ \$25.50 / <i>CRA</i>	\$ 51.00
26	1 pc	rear luggage floor trimboard - <i>worped/DE</i>	\$ 225.00
27	10 ps	rear bumper clips @ \$4.50 / <i>NEC 11 30</i>	\$ 45.00
28	2 ps	rear bumper end splashield cover @ \$19.90 <i>11</i>	\$ 39.80
29	2 ps	rear lamps @ \$212.50 / <i>CRA/BAW</i>	\$ 425.00
30	2 ps	rear lamp panels @ \$75.30 <i>11/50 015R</i>	\$ 150.60
31	4 ps	rear lamp clip holders @ \$4.50 <i>11</i>	\$ 18.00
32	2 ps	rear fender @ \$559.30 / <i>11/50 Body 015R</i>	\$ 1,118.60
33	2 ps	rear fender inner trim @ \$88.50 <i>11/50</i>	\$ 177.00
34	8 ps	rear fender inner trim clips @ \$4.50 <i>11</i>	\$ 36.00
35	2 ps	rear fender air vent @ \$26.00 <i>11</i>	\$ 52.00
36	1 pc	left rear chassis frame <i>R</i>	\$ 157.00
37	1 pc	left rear door inner lock <i>11</i>	\$ 172.30
38	1 pc	left rear door inner lock striker <i>11</i>	\$ 27.50
39	1 pc	spare tyre - mechanic jack <i>11</i>	\$ 250.00



陳林摩打私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SKW1270D

Date of Accident : 24 October 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Nur Zarifah Binte Mustapha

Date : 24 October 2018

Estimate To Repair SJS5114D - Honda FIT 1.3G A

Chassis No : GE61201514

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
40	1 pc	spare tyre fastener clamp 11	\$ 215.00
41	2 ps	rear exhaust box mount @ \$16.50 11	\$ 33.00
42	1 pc	bonnet lock / buff/cw 105.00	\$ 189.80
43	1 pc	bonnet lock cable 11 X	\$ 48.60
44	2 ps	bonnet hinges @ \$35.00 38	\$ 70.00
45	1 pc	front support panel / buff/cw 382.90	\$ 985.00
46	1 pc	front bumper / DM 7.5	\$ 458.50
47	1 pc	front bumper reinforcement / DD 173.30	\$ 203.30
48	1 pc	front bumper tow cover / MIS 25	\$ 35.00
49	1 pc	front bumper lower centre air grille / SCR/cw	\$ 185.00
50	2 ps	front bumper side retainer @ \$15.40 / 38	\$ 30.80
51	10 ps	front bumper clips @ \$4.50 / NEC 30	\$ 45.00
52	1 pc	front bumper lower splashshield cover 11	\$ 180.60
53	2 ps	headlamps @ \$649.50 / 82 MSB 01511	\$ 1,299.00
54	2 ps	headlamp lower brackets @ \$21.90 MSB	\$ 43.80
55	1 pc	front fender left / DD/bw	\$ 559.30
56	1 pc	front fender left inner liner / 10.1	\$ 165.60
57	1 pc	front fender bridge chassis frame R	\$ 157.00
58	1 pc	front fender bridge chassis panel R	\$ 357.00
59	1 pc	battery tray 11	\$ 88.90
60	1 pc	battery support bracket 11	\$ 45.80
61	1 pc	battery fastener clamp 11	\$ 12.00
62	1 pc	battery cover 11	\$ 22.30
63	1 pc	air-cleaner tank assy / CW	\$ 150.60
64	1 pc	air-cleaner tank - intake duct 11	\$ 75.00
65	2 ps	engine mounts @ \$152.80 11	\$ 305.60
66	1 pc	gearbox mount 11	\$ 194.60
67	1 pc	radiator assy 11	\$ 1,982.00
68	2 ps	radiator top mount @ \$28.50 11	\$ 57.00
69	1 pc	radiator top mount bracket left 11	\$ 22.50
70	1 pc	radiator top mount bracket right 11	\$ 22.50
71	1 pc	radiator grille / CW	\$ 170.50
72	1 pc	radiator grille emblem badge 11	\$ 23.40
73	1 pc	radiator fan blade 11	\$ 54.80
74	1 pc	radiator fan motor 11	\$ 309.80
75	1 pc	radiator fan shroud 11	\$ 89.30
76	1 pc	radiator top hose 11	\$ 25.00
77	1 pc	radiator bottom hose 11	\$ 25.00
78	1 pc	radiator expansion tank 11	\$ 55.60



陳林峰略私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKW1270D
Date of Accident : 24 October 2018

Miss Nur Zarifah Binte Mustapha

Date : 24 October 2018

Estimate To Repair SJS5114D - Honda FIT 1.3G A
Chassis No : GE61201514

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
79	1 pc	radiator expansion tank bracket <i>11</i>	\$ 34.50
80	1 pc	aircon condenser <i>11</i>	\$ 762.80
81	1 pc	aircon condenser top mount bracket right <i>11</i>	\$ 16.50
82	2 ps	aircon condenser bottom mounts @ \$12.50 <i>11</i>	\$ 25.00
83	1 pc	aircon condenser discharge hose <i>11</i>	\$ 166.90
84	1 pc	aircon condenser suction hose <i>11</i>	\$ 155.00
85	1 pc	aircon condenser liquid pipe <i>11</i>	\$ 91.60
86	1 pc	wiper garnish / grille <i>CU</i>	\$ 145.00
87	1 pc	engine ECU <i>11</i>	\$ 2,250.00
88	2 ps	horn @ \$58.60 <i>11</i>	\$ 117.20
89	2 ps	horn bracket @ \$25.00 <i>11</i>	\$ 50.00
			\$ 20,392.70
Less 20 %			\$ 4,078.54
			\$ 16,314.16
<u>SPECIAL NETT ITEMS</u>			
90	1 pc	rear licence plate <i>11</i>	\$ 80.00
91	1 pc	backoff camera <i>11</i>	\$ 450.00
92	1 set	rear bumper parking sensor / <i>shorted</i>	\$ 450.00
93	2 set	rear fender 1/4 glass sealant @ \$80.00 <i>rec 1/5</i>	\$ 160.00
94	1 pc	rear exhaust box - HKS <i>11</i>	\$ 2,200.00
95	1 pc	rear exhaust box - heat shield <i>11</i>	\$ 30.00
96	1 pc	bonnet - carbon accessory / <i>DM Buc/CME</i>	\$ 1,500.00
97	1 pc	bonnet insulation foam pad <i>11</i>	\$ 480.00
98	1 pc	front licence plate / <i>CEA CM</i>	\$ 60.00
99	1 pc	battery <i>DD</i>	\$ 280.00
100	1 pc	voltage stabilizer (accessory) <i>11</i>	\$ 280.00
101	1 pc	voltage regulator (accessory) <i>11</i>	\$ 300.00
102	1 tin	radiator coolant <i>11</i>	\$ 30.00
			\$ 6,300.00
<u>LABOUR & MISC. CHARGES</u>			
01		Towing charges.	\$ 120.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 280.00
03		To reinstall of rear bumper parking sensor.	\$ 150.00
04		To upholstery and make good repair to cushion sesat and seat frame and reclining mechanism.	\$ 450.00
05		To rust-proofing of the affected areas.	\$ 380.00

\$1150

60

80

50

50

120



陳林源峰私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKW1270D
Date of Accident : 24 October 2018

Miss Nur Zarifah Binte Mustapha

Date : 24 October 2018

Estimate To Repair SJS5114D - Honda FIT 1.3G A
Chassis No : GE61201514


S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
06		To remove and refit rear windscreen glass.	\$ 180.00
07		To check electrical lighting concerned.	\$ 60.00
08		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00
09		To drop rear exhaust box and renew the same.	\$ 160.00
10		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 250.00
11		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 800.00
12		Reinstall rear back off camera and settings	\$ 11 120.00
13		To remove and renew engine and gearbox mountings.	\$ 11 550.00
14		To reinstall accessory LED light	\$ 11 100.00
15		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 3,300.00
16		Putty and spray painting of the affected portion.	\$ 2,600.00
			\$ 9,650.00
		Total	\$ 32,264.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

120
30
60
60
100
250
X
X
X
2400
1800
\$5140



honda fit Price Range Depreciation 2009 Vehicle Type

Advanced Search

Home » Used Cars » SG Car Consign Pte Ltd » Honda Fit 1.3A G

Resources


- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Tyres



215 million
Royalty-free Images

shutterstock



Honda Fit 1.3A G

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$15,900	
Depreciation	\$6,790 /yr	?
	View models with similar depreciation	
Reg Date	22-Oct-2009	
	(11mths 27days COE left)	
Manufactured	2009	?
Mileage	141,020 km (15.6k /yr)	
Transmission	Auto	
Engine Cap	1,339 cc	
Road Tax	\$590 /yr	?
Power	73.0 kW (97 bhp)	
	View specs of the Honda Fit (2008-2013)	
Curb Weight	1,010 kg	?
Features	Red Color.	
Accessories	As Per Factory Fittings.	
Description	Flaming Red Unit, Well Maintained By Owner. Selling Due To Relocating. Small Yet Spacious. Why Not? Highly Recommended For Family User Or Daily Usage. No Obligation. Don't Miss. Please Call To Arrange For Viewing.	
COE	\$18,899	?
OMV	\$14,364	?
ARF	\$14,364	?
Dereg Value	\$9,056 as of today (change)	?
No. of Owners	2	?
Type of Veh	Hatchback	
Category	PARF Car	
Availability	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 22-Oct-2018 | Last Updated on: 22-Oct-2018

Tags: Honda Fit, honda fit, 2009 Honda Fit, 2009 honda fit, Honda, fit, fit, Used Honda

Upfront Payment

www.sgcardeal.info

Transfer Fee	\$25	?
Down Payment	\$4,770 (change)	Maximum 70% Loan ?
1st Instalment	\$1,039	?
Total Upfront Payment	\$5,834 (excluding insurance)	?

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.



Seller Information

Company	SG Car Consign Pte Ltd	
	• dealer's pricelist	
	• 60 vehs sold 104 vehs available	
Address	170 Upper Bukit Timah Road #01-28	
	Search cars nearby this location	
Location	Bukit Timah Shopping Centre	
Office No	61000200	
Contact Person(s)	Bryan Tan	91795745
	Joey Kwan	87158050

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



honda fit

Price Range

Depreciation

2009

Vehicle Type

Advanced Search

Home » Used Cars » Direct Owners » Honda Fit 1.3A G

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Tyres



FORTYTWO

UP TO
70% off CHAIRS

100 DAY FR

SHOP

Honda Fit 1.3A G

Overview

Financial

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$13,200**Depreciation** \$9,030 /yr

View models with similar depreciation

Reg Date 21-Jul-2009

(8mths 26days COE left)

Manufactured 2008**Mileage** 115,000 km (12.4k /yr)**Transmission** Auto**Engine Cap** 1,339 cc**Road Tax** \$590 /yr**Power** 73.0 kW (97 bhp)

View specs of the Honda Fit (2008-2013)

Curb Weight 1,010 kg**Features** Responsive 1.3 I-VTEC Engine, Smooth 5 Speed CVT Auto Gearbox Transmissions.**Accessories** Black Leather Seat, Sun Visor Solar Film, High End Amplifier, DVD Player, Reverse Sensors, 16" Sports Rim, Front Fog Lamps, Expensive Shock Absorbers.**Description** Full Body Start Bars And Stabilizer. Excellent Condition, View To Believe, Well Maintained, No Repairs Needed.**COE** \$7,032**OMV** \$14,454**ARF** \$13,086**Dereg Value** \$7,061 as of today (change)**No. of Owners** 2**Type of Veh** Hatchback**Category** PARF Car, Direct Owner Sale**Availability** Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 08-Oct-2018 | Last Updated on: 23-Oct-2018

Tags: Honda Fit, honda fit, 2009 Honda Fit, 2008 honda fit, Honda, Fit, fit, Used Honda

100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

Preferred Viewing Area

Price Analysis

Seller Information

Contact Person(s) Andy Lim**Contact No.** 91860160**Enquiry** Contact Seller

USEFUL FORMS

» Indemnity form

» Sales agreement

» Receipt

» Hand-over form

» M01

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare:

Joy Irene (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Thursday, 31 January 2019 11:26 AM
To: Foo, Chityan
Cc: Admin A; Joy Irene (LKKAuto)
Subject: FW: OUR REF: 6246894932SG; ACCIDENT INVOLVING SKW1270D & SJS5114D ON 24.10.18 ALONG KPE TWDS AYE

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC6/AIG18019358/UJB3Q2	Joy

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Foo, Chityan <Chityan.Foo@aig.com>

Sent: Thursday, 31 January 2019 10:54 AM

To: Admin A <admin-a@lkkauto.com>

Subject: OUR REF: 6246894932SG; ACCIDENT INVOLVING SKW1270D & SJS5114D ON 24.10.18 ALONG KPE TWDS AYE

Dear Sir/Mdm,

We refer to the above matter.

We seek your clarification on the replacement of the following parts:

- Air-cleaner Tank Assy (upload photographs)

Please furnish us on the market value, PARF and repair limit of SJS5114D – Honda Fit.

Kindly let us hear from you soon before approval of mandate.

Jimmy Foo

AIG

Complex Claims Examiner



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref TP032102018
Your Ref SKW12700

Date 06/12/18

WITHOUT PREJUDICE

Claims Department - Executive in charge
AGG Asia Pacific Insurance Pte Ltd

Dear Sir/Madam,

ACCIDENT INVOLVING SJS5114D / SKW12700 on 24.10.18

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- ☐ Original survey report / _____ copies of photographs _____
- ☒ Original Tax-invoice number TP118/013 ☒ Original rental invoice number INV-18190177
- ☐ SAS / AS & IS / police report ☐ police result
- ☐ Certificate Of Insurance _____ ☒ Vehicle search result
- ☒ Authorization to act ☐ _____

*Survey under insurance instruction / Independent surveyor / No survey.

a)	Cost of repair (inclusive GST)	\$ <u>7,490.00</u>
b)	Survey fees / Photographs as per request	\$ <u>-</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>7.49</u>
d)	Loss of hire / use / rental / earnings / rental fees	\$ <u>2,118.60</u>
e)	Scene photographs	\$ <u>-</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>-</u>
g)	_____	\$ <u>-</u>
	Total	\$ <u>9,616.09</u>

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Patricia Tan / Sam Low / Johnson Chua

Email: pt@tlimotor.com.sg / sam@tlimotor.com.sg / johnson.chua@tlimotor.com.sg

Print Received Message

This mail is associated with :

***SJS5114D (6246894932SG)**
[SKW1270D]

TP

NUR ZARIFAH BINTE MUSTAPHA

Oct 24 2018 12:00AM

[BIZLINK RENT-A-CAR PTE LTD]

Tan Lim Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 12/03/2019 17:58 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9297.49) - SJS5114D - Claim Handler: Foo, Chit Yan

Approved:9297.49:Please proceed to settle up to \$9,297.49.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18019358/Ujb3

18 December 2018

Bizlink Rent-A-Car Pte Ltd

18 Ubi Rd 4
#01-11 Ubi Car Mall
Singapore 408616

Dear Sir/Madam,

ACCIDENT INVOLVING SKW 1270D / SJS 5114D / OTHERS ON 24/10/18

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Joy Irene
Case Handler
DID: 6841 2409
FAX: 6741 4108
Email: joyirene@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Nur Zarifah Binte Mustapha ("the third party claimant")
of Block 676D Punggol Drive #17-740 S824676 (address),
owner of SJS 5114D (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SJS 5114D that was
damaged pursuant to the accident which occurred on 24/10/18 (date) along
KPE towards PIE after Airport Road exit (location)
involving vehicle no/s 4W 12700 ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 24 day of Oct (month) 20 18 (year)

"The contents of this document apply to vehicle
damages only. All personal injuries and
damages arising therefrom are excluded from
the ambit and application of this document."

Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$7,490.00 (Repair Cost), S\$1,800.00 (Loss of Use/Rental), S\$7.49 (Disbursement) for vehicle no. SJS 5114D that was damaged pursuant to the accident which occurred on 24/10/2018 (date) along KPE TOWARDS PIE/AYE (TUNNEL) (location) involving vehicle no/s SKW 1270D. This is pursuant to the inspection conducted on 24/10/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NUR ZARIFAH BINTE MUSTAPHA ("the third party claimant") of vehicle no. SJS 5114D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJS 5114D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 9th (day) of APRIL (month) 2019 (year)

cks

Signed by appointed surveyor


Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP1118/013

(Please quote our reference number TP032102018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Nur Zarifah Binte Mustapha

Date: 14/11/2018

Vehicle No: SJ55114D
Model: HONDA FIT 1.3G A

Description	Amount
To lump sum repair as recommended by surveyor.	\$7,000.00
Reimbursement of LTA search fees.	\$7.00

Sub Total	\$7,007.00
Add 7% GST	\$490.49
Total	\$7,497.49

Tan Lim Motor Pte Ltd

**GLOBAL ADVANCE LEASING**

51 Defu Lane 10, Singapore 539216

T: +65 6100 0425 | enquiry@gal.com.sg | GST Reg No.: 200409785W

Bill To

Nur Zarifah Binte Mustapha
C/O: Tan Lim Motor Pte Ltd
Apt Blk 676D Punggol Drive #17-740
Singapore 824676

TAX INVOICE

Invoice No INV-18190177
Invoice Date 13 Nov 2018
Reference SJX1842K

Description	Qty	Unit Price	GST	Amount
SJX1842K, REF: TP032102018-SJS5114D (ST7149)				
Rental from 24/10/2018 to 13/11/2018	1.00	1,980.00	7%	1,980.00
03 weeks @ \$660.00 per week				
Subtotal				1,980.00
Total GST				138.60
Amount Due				2,118.60

PAID
33 NOV 2018
BY: 006183889

No Official Receipts will be issued. This is a computer generated document. No signature required.

PAYMENT METHOD**VISA**[View and pay online now](#)**CREDIT CARD:**

Credit Card Convenience Fees applicable

CHEQUE: All cheques should be crossed and made payable to : **GLOBAL ADVANCE LEASING**. Please indicate invoice number and payer's name on reverse of cheque**BANK TRANSFER:** UOB Bank Account Number 208-315-273-9

Payment is due on or before the first day of rental. Kindly make payment promptly to avoid incurring admin charges and late payment interest.

E. & O. E.



GLOBAL ADVANCE LEASING

Bus Reg: B52935825E
GST Reg No: 200409785W
C/o S1 Defu Lane 10 S1539216)
Tel: 61000GAL

Agreement: 7149

Vehicle No	SIX 1842K	Make & Model	Mercedes	Date	24.10.2018
Hirer Name	Nur Zairifah Binte Mustapha			Check Out / Check In	24.10.2018
Hirer Address	676D Runggal Drive #17-740 JSS (824676			Date Out	24.10.2018
Contact Person	Tel 98204604			Time Out	1040 hrs
1st Driver Name	Muhammad Harwan Bin Mohamed			KM Out	129183
1st Driver Address	- As above -			PETROL	E 1/4 1/2 3/4 F
(HP) 86913290	(H)			Date In	13.11.2018
Passport/NRIC No	886150221	Nationality		Time In	1715 hrs
Driving Licence No		Driving Exp	YTS	KM In	131013
Country of Issue	Singapore	Expiry Date		PETROL	E 1/4 1/2 3/4 F
Additional Driver Name				Mode of Payment	
Additional Driver Address				Cash / Cheque / Company Billing / Credit Card / Others	
(HP) (O) (H)				Cheque / Card Details:	
Passport/NRIC No				Expiry Date:	
Driving Licence No				Rental Charges	
Country of Issue				Day/s	
				Week/s	
				Month/s	
				SUBTOTAL	
				CDW	
				PAI	
				Petrol Top Up	
				Delivery / Collection fee	
				Misc	
				Misc	
				Less	
				Pre-Payment / Deposit	
				Misc	
				Total Due	
				Charges Subject to Final Audit	
				Refundable Deposit	
				Deposit	
				Date of Refund	
				Refund Acknowledgement	
				For Official Use	
				Invoice No	
				Receipt No	

Important Notes

- Rental Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the owner.
- Only persons authorized by Global Advance Leasing may drive the vehicle.
- All parking and traffic violations are the responsibility of the Hirer. An Administrative charge will be levied on any traffic violations redirected.
- The Hirer shall be liable for excess charges for any late return at the rate shown per hour or per day.
- In the event of accident, the Hirer shall report to the rental office immediately.

I/We have read and agreed to the terms and conditions as set out on both sides of the agreement and certify that the information given is true and correct. If I/we opt to pay by credit / charge card, I agree that all amounts payable under this agreement may be billed to the same account and my signature here will be deemed to have been made on the applicable credit card charge slip.

X
(Hirer's signature)

X
(Additional Driver's signature)

X
(Global Advance Leasing)

Enquire Vehicle & Owner Information (Vehicle No. SKW1270D As At 24 Oct 2018 / 07:48:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: SRSTPSJ55114D:TLM

Current Owner Details

Owner ID Type: Company

Owner ID: 200402911Z

Owner Name: BIZLINK RENT-A-CAR PTE. LTD.

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 18

Registered Street Name: UBI ROAD 4

Registered Unit No.: # 01 - 11

Registered Building Name: -

Registered Postal Code: 408616

Current Vehicle Details

Vehicle No.: SKW1270D

Make Description/Model: MAZDA / MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2018 Edit Reg		24 Oct 2018 00:00 Edit Adj Rpt	\$57,000.00 Edit Estimates	\$57,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: BIZLINK RENT-A-CAR PTE LTD , Co. Reg. No.: 200482911Z									
Main Claimant: NUR ZARIFAH BINTE MUSTAPHA , ID: S8623336C									
Vehicle Reg. No.: SJS5114D		Date of Loss: 24/10/2018 00:00 - :59 [110 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6246894932SG		Policy/Cover Note No.: 0999994542 (Comprehensive)							
Vehicle Reg. No. (Insured): SKW1270D		Policy No. (Claimant): 5081665200-02							
		Excess:							
Repairer: Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6, 539365 Defu Lane - Tel: 6858 5151									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LXX Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 02/11/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (12/03/2019): Alert - Adj Mandate Approved (\$9297.49) - SJS5114D - Claim Handler: Foo, Chit Y... - AIG_SG (25/10/2018): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS5114D (6246894932SG)
[SKW1270D]
TP
NUR ZARIFAH BINTE MUSTAPHA
Oct 24 2018 12:00AM
[BIZLINK RENT-A-CAR PTE LTD]
Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Letters/Correspondences														1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown											1	Edit		
Photos/Images														3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print		
1	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
2	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
3	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
4	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
5	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
6	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
7	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
8	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
9	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
10	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
11	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
12	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
13	12/11/18 19:58	Reinspection Photo											1	Load JPG	☒	
14	12/01/19 16:35	General View											1	Load JPG	☒	
15	12/01/19 16:35	General View											1	Load JPG	☒	
16	12/01/19 16:35	General View											1	Load JPG	☒	
17	12/01/19 16:35	General View											1	Load JPG	☒	
18	12/01/19 16:35	General View											1	Load JPG	☒	
19	12/01/19 16:35	General View											1	Load JPG	☒	
20	12/01/19 16:35	General View											1	Load JPG	☒	
21	12/01/19 16:35	General View											1	Load JPG	☒	
22	12/01/19 16:35	General View											1	Load JPG	☒	
23	12/01/19 16:35	General View											1	Load JPG	☒	
24	12/01/19 16:35	General View											1	Load JPG	☒	
25	12/01/19 16:35	General View											1	Load JPG	☒	
26	12/01/19 16:35	General View											1	Load JPG	☒	
27	12/01/19 16:35	General View											1	Load JPG	☒	
28	12/01/19 16:35	General View											1	Load JPG	☒	
29	12/01/19 16:35	General View											1	Load JPG	☒	
30	12/01/19 16:35	General View											1	Load JPG	☒	
31	12/01/19 16:35	General View											1	Load JPG	☒	
32	12/01/19 16:35	General View											1	Load JPG	☒	
33	12/01/19 16:35	General View											1	Load JPG	☒	
34	12/01/19 16:35	General View											1	Load JPG	☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	12/01/19 16:35	General View	 Load JPG	☒
36	12/01/19 16:35	General View	 Load JPG	☒
37	12/01/19 16:35	General View	 Load JPG	☒
38	12/01/19 16:35	General View	 Load JPG	☒
39	12/01/19 16:35	General View	 Load JPG	☒
40	12/01/19 16:35	General View	 Load JPG	☒
41	12/01/19 16:35	General View	 Load JPG	☒
42	12/01/19 16:35	General View	 Load JPG	☒
43	12/01/19 16:35	General View	 Load JPG	☒
44	12/01/19 16:35	General View	 Load JPG	☒
45	12/01/19 16:35	General View	 Load JPG	☒
46	12/01/19 16:35	General View	 Load JPG	☒
47	12/01/19 16:35	General View	 Load JPG	☒
48	12/01/19 16:35	General View	 Load JPG	☒
49	12/01/19 16:35	General View	 Load JPG	☒
50	12/01/19 16:35	General View	 Load JPG	☒
51	12/01/19 16:35	General View	 Load JPG	☒
52	12/01/19 16:35	General View	 Load JPG	☒
53	12/01/19 16:35	General View	 Load JPG	☒
54	12/01/19 16:35	General View	 Load JPG	☒
55	12/01/19 16:35	General View	 Load JPG	☒
56	12/01/19 16:35	General View	 Load JPG	☒
57	12/01/19 16:35	General View	 Load JPG	☒
58	12/01/19 16:35	General View	 Load JPG	☒
59	12/01/19 16:35	General View	 Load JPG	☒
60	12/01/19 16:35	General View	 Load JPG	☒
61	12/01/19 16:35	General View	 Load JPG	☒
62	12/01/19 16:35	General View	 Load JPG	☒
63	12/01/19 16:35	General View	 Load JPG	☒
64	12/01/19 16:35	General View	 Load JPG	☒
65	12/01/19 16:35	General View	 Load JPG	☒
66	12/01/19 16:35	General View	 Load JPG	☒
67	12/01/19 16:35	General View	 Load JPG	☒
68	12/01/19 16:35	General View	 Load JPG	☒
69	12/01/19 16:35	General View	 Load JPG	☒
70	12/01/19 16:35	General View	 Load JPG	☒
71	12/01/19 16:35	General View	 Load JPG	☒
72	12/01/19 16:35	General View	 Load JPG	☒
73	12/01/19 16:35	General View	 Load JPG	☒
74	12/01/19 16:35	General View	 Load JPG	☒
75	12/01/19 16:35	General View	 Load JPG	☒
76	12/01/19 16:35	General View	 Load JPG	☒
77	12/01/19 16:35	General View	 Load JPG	☒
78	12/01/19 16:35	General View	 Load JPG	☒
79	12/01/19 16:35	General View	 Load JPG	☒
80	12/01/19 16:35	General View	 Load JPG	☒
81	12/01/19 16:35	General View	 Load JPG	☒
82	12/01/19 16:35	General View	 Load JPG	☒
83	12/01/19 16:35	General View	 Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	12/01/19 16:35	General View		☒
85	12/01/19 16:35	General View		☒
86	12/01/19 16:35	General View		☒
87	12/01/19 16:35	General View		☒
88	12/01/19 16:35	General View		☒
89	12/01/19 16:35	General View		☒
90	12/01/19 16:35	General View		☒
91	12/01/19 16:35	General View		☒
92	12/01/19 16:35	General View		☒
93	12/01/19 16:35	General View		☒
94	12/01/19 16:35	General View		☒
95	12/01/19 16:35	General View		☒
96	12/01/19 16:35	General View		☒
97	12/01/19 16:35	General View		☒
98	12/01/19 16:35	General View		☒
99	12/01/19 16:35	General View		☒
100	12/01/19 16:35	General View		☒
101	12/01/19 16:35	General View		☒
102	12/01/19 16:35	General View		☒
103	12/01/19 16:35	General View		☒
104	12/01/19 16:35	General View		☒
105	12/01/19 16:35	General View		☒
106	12/01/19 16:35	General View		☒
107	12/01/19 16:35	General View		☒
108	12/01/19 16:35	General View		☒
109	12/01/19 16:35	General View		☒
110	12/01/19 16:35	General View		☒
111	12/01/19 16:35	General View		☒
112	12/01/19 16:35	General View		☒
113	12/01/19 16:35	General View		☒
114	12/01/19 16:35	General View		☒
115	12/01/19 16:35	General View		☒
116	12/01/19 16:35	General View		☒
117	12/01/19 16:35	General View		☒
118	12/01/19 16:35	General View		☒
119	12/01/19 16:35	General View		☒
120	12/01/19 16:35	General View		☒
121	12/01/19 16:35	General View		☒
122	12/01/19 16:35	General View		☒
123	12/01/19 16:35	General View		☒
124	12/01/19 16:35	General View		☒
125	12/01/19 16:35	General View		☒
126	12/01/19 16:35	General View		☒
127	12/01/19 16:35	General View		☒
128	12/01/19 16:35	General View		☒
129	12/01/19 16:35	General View		☒
130	12/01/19 16:35	General View		☒
131	12/01/19 16:35	General View		☒
Documentation			1 per page	☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/10/18 11:30	TP ESTIMATE- MARKED		Load PDF	
2	26/10/18 11:30	TP GIA REPORT		Load PDF	
3	07/01/19 12:21	RENTAL RECEIPT		Load PDF	
4	07/01/19 12:21	LTA SEARCH		Load PDF	
5	15/04/19 14:57	WORKSHOP INVOICE		Load PDF	
6	15/04/19 14:57	AUTHORISATION TO ACT FORM		Load PDF	
7	15/04/19 14:57	Release Voucher		Load PDF	
8	15/04/19 14:57	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	25/10/18 13:37	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKW1270D (Insd veh)	Model:	HONDA FIT 1.3 (A)
	SJS5114D (TP veh)		
Date of Accident:	24/10/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	: \$	34,522.65	
Final Repair Cost	: \$	7,490.00	
Loss of Use	: \$	days at \$0.00 per day	
Rental (if any)	: \$	1,800.00	18 days
LTA / GIA Search Fee	: \$	7.49	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	9,297.49	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	: \$	9,297.49
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

15 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18019358/UJB3Q2

Date: 15/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994542
 Claimant Vehicle No: SJS5114D Insured Vehicle No: SKW1270D
 Date of Loss: 24/10/2018 Nature of Claim: TP Claim No: 6246894932SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS5114D
 Make & Model: HONDA FIT, 1.3 (A) Engine No: L13A4220884
 Reg. Date: 20/08/2009 (Man. Year: 2009) Chassis No: GE61201514
 Colour: Blue/Red Odometer: 159347 km
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,614.16	7,243.92	15,370.24	67.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,650.00	5,180.00	4,470.00	46.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,264.16	12,423.92	19,840.24	61.49
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	32,264.16	7,000.00	25,264.16	78.30
+ GST 7.00/7.00% (S\$)	2,258.49	490.00	1,768.49	78.30
Nett Amount (S\$)	34,522.65	7,490.00	27,032.65	78.30
+ Car Rental (18.0 x S\$100.00/day) (S\$)		1,800.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		9,297.49		

INSPECTION

Date of Assignment: 24/10/2018
 Date Inspected: 24/10/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216

Estimated Period of Repair: 14.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Badly Dented	814.00 FL	*703.10 FL
2	1		*TAILGATE LID FIT BADGE	Necessary	25.00 FL	*25.00 FL
3	1		*TAILGATE LID LOCK	Dented / Jammed	175.00 FL	*175.00 FL
4	1		*TAILGATE LID LOCK STRIKER	Not Necessary	27.50 FL	*- FL
5	1		*TAILGATE LID WEATHERSTRIP	Twisted / Torn	98.30 FL	*98.30 FL
6	1		*TAILGATE LID INNER TRIMBOARD	Deformed / Cracked	98.00 FL	*98.00 FL
7	2		*TAILGATE LID HINGES	Not Necessary	116.00 FL	*- FL
8	1		*TAILGATE LID DAMPER STAY	Not Necessary	75.00 FL	*- FL
9	2		*TAILGATE LID RUBBER STOPPER	Not Necessary	25.00 FL	*- FL
10	1		*TAILGATE LID RUBBER GROMMET	Not Necessary	66.00 FL	*- FL
11	1		*TAILGATE LID OUTER GARNISH	Not Necessary	166.00 FL	*- FL
12	1		*TAILGATE LID OUTER GARNISH H BADGE	Not Necessary	35.00 FL	*- FL
13	1		*REAR WIPER MOTOR	Not Necessary	228.00 FL	*- FL
14	1		*REAR WINDSCREEN GLASS WEATHERSTRIP BOTTOM	Necessary	95.80 FL	*41.20 FL
15	1		*REAR WINDSCREEN GLASS WEATHERSTRIP TOP	Necessary	95.80 FL	*41.20 FL
16	2		*REAR LICENCE PLATE LAMPS	Not Necessary	190.00 FL	*- FL
17	1		*REAR LUGGAGE FLOOR PANEL	Crumpled / Buckled	645.90 FL	*645.90 FL
18	1		*REAR LUGGAGE FLOOR PANEL INSULATION PADDING	Not Necessary	350.00 FL	*- FL
19	1		*REAR END PANEL	Dented	390.00 FL	*269.60 FL
20	1		*REAR END PANEL INNER TRIM	Distorted	68.50 FL	*68.50 FL
21	4		*REAR END PANEL INNER TRIM CLIPS	Not Necessary	18.00 FL	*- FL
22	1		*REAR BUMPER	Distorted	710.30 FL	*456.30 FL
23	2		*REAR BUMPER BRACKETS	Bent	90.00 FL	*90.00 FL
24	2		*REAR BUMPER SIDE RETAINERS	Cracked	36.80 FL	*36.80 FL
25	2		*REAR BUMPER SIDE HOLDERS	Cracked	51.00 FL	*51.00 FL
26	1		*REAR LUGGAGE FLOOR TRIMBOARD	Warped / Deformed	225.00 FL	*225.00 FL
27	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*30.00 FL
28	2		*REAR BUMPER END SPALASHIELD COVER	Not Necessary	39.80 FL	*- FL
29	2		*REAR LAMPS	Cracked / Broken	425.00 FL	*425.00 FL
30	1		*REAR LAMP PANELS	N/S Dented/ O/S Repair	150.60 FL	*75.30 FL
31	4		*REAR LAMP CLIP HOLDERS	Not Necessary	18.00 FL	*- FL
32	1		*REAR FENDER	N/S Badly Dented / O/S Repair	1,118.60 FL	*559.30 FL
33	2		*REAR FENDER INNER TRIM	Deformed / Distorted	177.00 FL	*177.00 FL
34	8		*REAR FENDER INNER TRIM CLIPS	Not Necessary	36.00 FL	*- FL
35	2		*REAR FENDER AIR VENT	Not Necessary	52.00 FL	*- FL
36	1		*LEFT REAR CHASSIS FRAME	Repair	157.00 FL	*- FL
37	1		*LEFT REAR DOOR INNER LOCK	Not Necessary	172.30 FL	*- FL
38	1		*LEFT REAR DOOR INNER LOCK STRIKER	Not Necessary	27.50 FL	*- FL
39	1		*SPARE TYRE -MECHANISM JACK	Not Necessary	250.00 FL	*- FL
40	1		*SPARE TYRE FASTENER CLAMP	Not Necessary	215.00 FL	*- FL
41	2		*REAR EXHAUST BOX MOUNT	Not Necessary	33.00 FL	*- FL
42	1		*BONNET LOCK	Bent / Twisted	189.80 FL	*105.00 FL
43	1		*BONNET LOCK CABLE	Not Necessary	48.60 FL	*- FL
44	2		*BONNET HINGES	Bent	70.00 FL	*70.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FRONT SUPPORT PANEL	Bent / Twisted	985.00 FL	*385.90 FL
46	1		*FRONT BUMPER	Distorted	458.50 FL	*458.50 FL
47	1		*FRONT BUMPER REINFORCEMENT	Dented	203.30 FL	*173.30 FL
48	1		*FRONT BUMPER TOW COVER	Missing	35.00 FL	*25.00 FL
49	1		*FRONT BUMPER LOWER CENTRE AIR GRILLE	Scratched / Cracked	185.00 FL	*185.00 FL
50	2		*FRONT BUMPER SIDE RETAINER	Bent	30.80 FL	*30.80 FL
51	10		*FRONT BUMPER CLIPS	Necessary	45.00 FL	*30.00 FL
52	1		*FRONT BUMPER LOWER SPLASHIELD COVER	Not Necessary	180.60 FL	*- FL
53	1		*HEADLAMPS	N/S Broken / O/S Not Necessary	1,299.00 FL	*649.50 FL
54	1		*HEADLAMP LOWER BRACKETS	N/S Bent	43.80 FL	*21.90 FL
55	1		*FRONT FENDER LEFT	Dented / Buckled	559.30 FL	*559.30 FL
56	1		*FRONT FENDER LEFT INNER LINER	Torn	165.60 FL	*165.60 FL
57	1		*FRONT FENDER BRIDGE CHASSIS FRAME	Repair	157.00 FL	*- FL
58	1		*FRONT FENDER BRIDGE CHASSIS PANEL	Repair	357.00 FL	*- FL
59	1		*BATTERY TRAY	Not Necessary	88.90 FL	*- FL
60	1		*BATTERY SUPPORT BRACKET	Not Necessary	45.80 FL	*- FL
61	1		*BATTERY FASTENER CLAMP	Not Necessary	12.00 FL	*- FL
62	1		*BATTERY COVER	Not Necessary	22.30 FL	*- FL
63	1		*AIR-CLEANER TANK ASSY	Cracked	150.60 FL	*150.60 FL
64	1		*AIR-CLEANER TANK -INTAKE DUCT	Not Necessary	75.00 FL	*- FL
65	2		*ENGINE MOUNTS	Not Necessary	305.60 FL	*- FL
66	1		*GEARBOX MOUNT	Not Necessary	194.60 FL	*- FL
67	1		*RADIATOR ASSY	Not Necessary	1,982.00 FL	*- FL
68	2		*RADIATOR TOP MOUNT	Not Necessary	57.00 FL	*- FL
69	1		*RADIATOR TOP MOUNT BRACKET LEFT	Not Necessary	22.50 FL	*- FL
70	1		*RADIATOR TOP MOUNT BRACKET RIGHT	Not Necessary	22.50 FL	*- FL
71	1		*RADIATOR GRILLE	Cut	170.50 FL	*170.50 FL
72	1		*RADIATOR GRILLE EMBLEM BADGE	Not Necessary	23.40 FL	*- FL
73	1		*RADIATOR FAN BLADE	Not Necessary	54.80 FL	*- FL
74	1		*RADIATOR FAN MOTOR	Not Necessary	309.80 FL	*- FL
75	1		*RADIATOR FAN SHROUD	Not Necessary	89.30 FL	*- FL
76	1		*RADIATOR TOP HOSE	Not Necessary	25.00 FL	*- FL
77	1		*RADIATOR BOTTOM HOSE	Not Necessary	25.00 FL	*- FL
78	1		*RADIATOR EXPANSION TANK	Not Necessary	55.60 FL	*- FL
79	1		*RADIATOR EXPANSION TANK BRACKET	Not Necessary	34.50 FL	*- FL
80	1		*AIRCON CONDENSER	Not Necessary	762.80 FL	*- FL
81	1		*AIRCON CONDENSER TOP MOUNT BRACKET RIGHT	Not Necessary	16.50 FL	*- FL
82	2		*AIRCON CONDENSER BOTTOM MOUNTS	Not Necessary	25.00 FL	*- FL
83	1		*AIRCON CONDENSER DISCHARGE HOSE	Not Necessary	166.90 FL	*- FL
84	1		*AIRCON CONDENSER SUCTION HOSE	Not Necessary	155.00 FL	*- FL
85	1		*AIRCON CONDENSER LIQUID PIPE	Not Necessary	91.60 FL	*- FL
86	1		*WIPER GARNISH /GRILLE	Cut	145.00 FL	*145.00 FL
87	1		*ENGINE ECU	Not Necessary	2,250.00 FL	*- FL
88	2		*HORN	Not Necessary	117.20 FL	*- FL
89	2		*HORN BRACKET	Not Necessary	50.00 FL	*- FL
90	1		*REAR LICENCE PLATE	Not Necessary	80.00 FS	*- FS
91	1		*BACKOFF CAMERA	Not Necessary	450.00 FS	*- FS
92	2		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
93	1		*SET REAR FENDER 1/4 GLASS SEALANT	N/S Necessary	160.00 FS	*30.00 FS
94	1		*REAR EXHAUST BOX -HKS	Not Necessary	2,200.00 FS	*- FS
95	1		*REAR EXHAUST BOX -HEAT SHIELD	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
96	1		*BONNET -CARBON ACCESSORY	Buckled / Cracked	1,500.00 FS	*800.00 FS
97	1		*BONNET INSULATION FOAM PAD	Not Necessary	480.00 FS	*- FS
98	1		*FRONT LICENCE PLATE	Cracked	60.00 FS	*40.00 FS
99	1		*BATTERY	Dented	280.00 FS	*80.00 FS
100	1		*VOLTAGE STABILIZER (ACCESSORY)	Not Necessary	280.00 FS	*- FS
101	1		*VOLTAGE REGULATOR (ACCESSORY)	Not Necessary	300.00 FS	*- FS
102	1		*TIN RADIATOR COOLANT	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **26,692.70** **8,767.40**
 - List Item Discount on L Items 20.00/20.00% (S\$) **4,078.54** **1,523.48**

Total Parts (S\$) **22,614.16** **7,243.92**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	120.00	60.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	280.00	80.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
4	TO UPHOLSTERY AND MAKE GOOD REPAIR TO CUSHION SESAT AND SEAT FRAME AND RECLINING MECHANISM	New	450.00	50.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	380.00	120.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
8	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	150.00	60.00
9	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	160.00	60.00
10	TO DISMANTLE AIR-CON ASSY ,REMOVE AND RENEWAL OF PARTS ,VACUUM AND CHARGE -IN GAS	New	250.00	100.00
11	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURE SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	800.00	250.00
12	REINSTALL REAR BACK OFF CAMERA AND SETTINGS	New	120.00	0.00
13	TO REMOVE AND RENEW ENGINE AND GEARBOX MOUNTINGS	New	550.00	0.00
14	TO REINSTALL ACCESSORY LED LIGHT	New	100.00	0.00
15	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,300.00	2,400.00
16	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,600.00	1,800.00
Gross Labour Cost (\$\$)			9,650.00	5,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >