

Not Authorized

1/5 @ 7000/2

24/10/18

Blue print Author

1 Hdy



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AlGAsia Insured's Veh No : SKW1270D

Date of Accident : 24 October 2018

Miss Nur Zarifah Binte Mustapha

Date : 24 October 2018

Estimate To Repair SJS5114D - Honda FIT 1.3G A

Chassis No : GE61201514

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	tailgate lid / Body 703-10	\$ 814.00
02	1 pc	tailgate lid Fit badge / NEC	\$ 25.00
03	1 pc	tailgate lid lock / DD/ym	\$ 175.00
04	1 pc	tailgate lid lock striker / 1	\$ 27.50
05	1 pc	tailgate lid weatherstrip / TWI/TOA	\$ 98.30
06	1 pc	tailgate lid inner trimboard / De/cra	\$ 98.00
07	2 ps	tailgate lid hinges @ \$58.00 / 1	\$ 116.00
08	1 pc	tailgate lid damper stay / 1	\$ 75.00
09	2 ps	tailgate lid rubber stopper @ \$12.50 / 1	\$ 25.00
10	1 pc	tailgate lid rubber grommet / 1	\$ 66.00
11	1 pc	tailgate lid outer garnish / 1	\$ 166.00
12	1 pc	tailgate lid outer garnish H badge / 1	\$ 35.00
13	1 pc	rear wiper motor / 1	\$ 228.00
14	1 pc	rear windscreen glass weatherstrip bottom / NEC 41-20	\$ 95.80
15	1 pc	rear windscreen glass weatherstrip top / NEC 41-20	\$ 95.80
16	2 ps	rear licence plate lamps @ \$95.00 / 1	\$ 190.00
17	1 pc	rear luggage floor panel / crumpled/suc	\$ 645.90
18	1 pc	rear luggage floor panel insulation padding / 1	\$ 350.00
19	1 pc	rear end panel / DD Body 269.60	\$ 390.00
20	1 pc	rear end panel inner trim / DD 1	\$ 68.50
21	4 ps	rear end panel inner trim clips @ \$4.50 / 1	\$ 18.00
22	1 pc	rear bumper / TN 1 456.30	\$ 710.30
23	2 ps	rear bumper brackets @ \$45.00 / 1	\$ 90.00
24	2 ps	rear bumper side retainers @ \$18.40 / CRA	\$ 36.80
25	2 ps	rear bumper side holders @ \$25.50 / CRA	\$ 51.00
26	1 pc	rear luggage floor trimboard / warped/de	\$ 225.00
27	10 ps	rear bumper clips @ \$4.50 / NEC 1 30	\$ 45.00
28	2 ps	rear bumper end splashshield cover @ \$19.90 / 1	\$ 39.80
29	2 ps	rear lamps @ \$212.50 / CRA/1	\$ 425.00
30	2 ps	rear lamp panels @ \$75.30 / 1 015R	\$ 150.60
31	4 ps	rear lamp clip holders @ \$4.50 / 1	\$ 18.00
32	2 ps	rear fender @ \$559.30 / 1 015R	\$ 1,118.60
33	2 ps	rear fender inner trim @ \$88.50 / 1	\$ 177.00
34	8 ps	rear fender inner trim clips @ \$4.50 / 1	\$ 36.00
35	2 ps	rear fender air vent @ \$26.00 / 1	\$ 52.00
36	1 pc	left rear chassis frame / R	\$ 157.00
37	1 pc	left rear door inner lock / 1	\$ 172.30
38	1 pc	left rear door inner lock striker / 1	\$ 27.50
39	1 pc	spare tyre - mechanic jack / 1	\$ 250.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKW1270D
Date of Accident : 24 October 2018

Miss Nur Zarifah Binte Mustapha

Date : 24 October 2018

Estimate To Repair SJS5114D - Honda FIT 1.3G A
Chassis No : GE61201514

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
40	1 pc	spare tyre fastener clamp 11	\$ 215.00
41	2 ps	rear exhaust box mount @ \$16.50 11	\$ 33.00
42	1 pc	bonnet lock / but/ewi 105.00	\$ 189.80
43	1 pc	bonnet lock cable 11 X	\$ 48.60
44	2 ps	bonnet hinges @ \$35.00 Berl	\$ 70.00
45	1 pc	front support panel / but/ewi 385.90	\$ 985.00
46	1 pc	front bumper / DM Dis	\$ 458.50
47	1 pc	front bumper reinforcement / DO 173.30	\$ 203.30
48	1 pc	front bumper tow cover / MIS 25	\$ 35.00
49	1 pc	front bumper lower centre air grille / SCR/one	\$ 185.00
50	2 ps	front bumper side retainer @ \$15.40 / Berl	\$ 30.80
51	10 ps	front bumper clips @ \$4.50 / NEC Nel 30	\$ 45.00
52	1 pc	front bumper lower splashshield cover 11	\$ 180.60
53	2 ps	headlamps @ \$649.50 / BR N/S 300 / S/N 1	\$ 1,299.00
54	2 ps	headlamp lower brackets @ \$21.90 N/S Berl	\$ 43.80
55	1 pc	front fender left / DO/Buc	\$ 559.30
56	1 pc	front fender left inner liner / 10.1	\$ 165.60
57	1 pc	front fender bridge chassis frame R	\$ 157.00
58	1 pc	front fender bridge chassis panel R	\$ 357.00
59	1 pc	battery tray 11	\$ 88.90
60	1 pc	battery support bracket 11	\$ 45.80
61	1 pc	battery fastener clamp 11	\$ 12.00
62	1 pc	battery cover 11	\$ 22.30
63	1 pc	air-cleaner tank assy / one	\$ 150.60
64	1 pc	air-cleaner tank - intake duct 11	\$ 75.00
65	2 ps	engine mounts @ \$152.80 11	\$ 305.60
66	1 pc	gearbox mount 11	\$ 194.60
67	1 pc	radiator assy 11	\$ 1,982.00
68	2 ps	radiator top mount @ \$28.50 11	\$ 57.00
69	1 pc	radiator top mount bracket left 11	\$ 22.50
70	1 pc	radiator top mount bracket right 11	\$ 22.50
71	1 pc	radiator grille / Cu 1	\$ 170.50
72	1 pc	radiator grille emblem badge 11	\$ 23.40
73	1 pc	radiator fan blade 11	\$ 54.80
74	1 pc	radiator fan motor 11	\$ 309.80
75	1 pc	radiator fan shroud 11	\$ 89.30
76	1 pc	radiator top hose 11	\$ 25.00
77	1 pc	radiator bottom hose 11	\$ 25.00
78	1 pc	radiator expansion tank 11	\$ 55.60



陳林摩呀私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKW1270D
Date of Accident : 24 October 2018

Miss Nur Zarifah Binte Mustapha

Date : 24 October 2018

Estimate To Repair SJS5114D - Honda FIT 1.3G A
Chassis No : GE61201514

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
79	1 pc	radiator expansion tank bracket 11	\$ 34.50
80	1 pc	aircon condenser 11	\$ 762.80
81	1 pc	aircon condenser top mount bracket right 11	\$ 16.50
82	2 ps	aircon condenser bottom mounts @ \$12.50 11	\$ 25.00
83	1 pc	aircon condenser discharge hose 11	\$ 166.90
84	1 pc	aircon condenser suction hose 11	\$ 155.00
85	1 pc	aircon condenser liquid pipe 11	\$ 91.60
86	1 pc	wiper garnish / grille 11	\$ 145.00
87	1 pc	engine ECU 11	\$ 2,250.00
88	2 ps	horn @ \$58.60 11	\$ 117.20
89	2 ps	horn bracket @ \$25.00 11	\$ 50.00
			\$ 20,392.70
Less 20 %			\$ 4,078.54
			\$ 16,314.16
<u>SPECIAL NETT ITEMS</u>			
90	1 pc	rear licence plate 11	\$ 80.00
91	1 pc	backoff camera 11	\$ 450.00
92	1 set	rear bumper parking sensor / shocked	\$ 450.00
93	2 set	rear fender 1/4 glass sealant @ \$80.00 rec 1/5	\$ 160.00
94	1 pc	rear exhaust box - HKS 11	\$ 2,200.00
95	1 pc	rear exhaust box - heat shield 11	\$ 30.00
96	1 pc	bonnet - carbon accessory / am buc/cru	\$ 1,500.00
97	1 pc	bonnet insulation foam pad 11	\$ 480.00
98	1 pc	front licence plate / GEA cru	\$ 60.00
99	1 pc	battery 11	\$ 280.00
100	1 pc	voltage stabilizer (accessory) 11	\$ 280.00
101	1 pc	voltage regulator (accessory) 11	\$ 300.00
102	1 tin	radiator coolant 11	\$ 30.00
			\$ 6,300.00
<u>LABOUR & MISC. CHARGES</u>			
01		Towing charges.	\$ 120.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 280.00
03		To reinstall of rear bumper parking sensor.	\$ 150.00
04		To upholstery and make good repair to cushion sesat and seat frame and reclining mechanism.	\$ 450.00
05		To rust-proofing of the affected areas.	\$ 380.00



陳林曉峰私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKW1270D
Date of Accident : 24 October 2018

Miss Nur Zarifah Binte Mustapha

Date : 24 October 2018

Estimate To Repair SJS5114D - Honda FIT 1.3G A
Chassis No : GE61201514

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
06		To remove and refit rear windscreen glass.	\$ 180.00
07		To check electrical lighting concerned.	\$ 60.00
08		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00
09		To drop rear exhaust box and renew the same.	\$ 160.00
10		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 250.00
11		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 800.00
12		Reinstall rear back off camera and settings	\$ 11 120.00
13		To remove and renew engine and gearbox mountings.	\$ 11 550.00
14		To reinstall accessory LED light	\$ 11 100.00
15		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 3,300.00
16		Putty and spray painting of the affected portion.	\$ 2,600.00
			\$ 9,650.00
		Total	\$ 32,264.16

120
30
60
60
100
250
X
X
X
2400
1800
\$5180

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: