ASS. REC. BY:			REF:	Cs / Eli	180193	361 (AV)	n2 Special	l Instruction	E
Surveyor :		15.0		1001120000	San Special Site	T (Office)		100	
From (Person):	Yec	ki Li		of	EGIL		Da	te/Time:	24.102018 354pm
Estimated Cost				2.5	В	till to:			1
OD / TP / Ws To Inspect Vel				3658 R	EV / CS		Insured:		TP 7908E
at Workshop n	/s		1st	Autuwirks			Tel:	6798	8933.
of				aki Bulat		#014-01			
Policy No:						Claim No: _	YP 791	18E/S	L/PI
Sum Insured:_						Excess:			
Make of Veh: (Client's Record							D.	O.A	19/10/18
CA / REV /	REP. /	REV 24	HRS W	121				H.O.D. End	lorsament:
Date/Time:	34-1070	18 H386	M_Per	rson Contac	eted:	Suhain	Veh	icle IN/	6119
Date/Time	Action/	Instruction	( <	) Estiv	nate				
	NAME OF THE PARTY	3658R -			10.112			1.1	
		7908E	-						
		1170			441				
3010 18	In for	ng l	» l»		المسا	shop est	h. a	maril	
14/1/19			•						10, 58%
11/19	Emo			evised			Check	7057.	10, 3017

Date/Time, File Pass to?	Date/Time, File Return to?
1) 14 1- typist	2)
3) 1 31	(4)
5)	(6)
Preli. Report.	
Final Report	4.1

Part Prices Check: N OUT Survey Fee: Sasic & Add.

390

10,200

\_\_S+RS, \_\_SI Photos Others

TOTAL



Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

YP 7908E/SL/pl

Our ref:

CS/EGI18019361/Avb

Date: 14/1/2019

The Motor Claims Department

M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam.

### PRELIMINARY ADVICE OF VEHICLE NO.SLS 3658R

We thank you for your instruction on 24/10/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29/10/2018 at the premises of M/s FIRST AUTOWORKS

Workshop Estimate Amount	: S\$12,038.20	
Revised Estimate Amount	: S\$5,001.10	
"Check" Items Amount	: S\$	
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	


Description of Damage:

The vehicle sustained damages at the

rear portion

nearside

rear



front

Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 14 January 2019 4:23 PM

To:

'Survey Report (ERGO Insurance Pte. Ltd.)'

Cc:

SUR

Subject:

RE: YP7908E / TP: SLS3658R/LKK / DOA: 27/07/2018

Attachments:

SLS 3658R PRELI REVISED.pdf

Dear Sir/Madam.

Enclosed preliminary revised of vehicle SLS 3658R

Date of survey: 29/10/2018 Number of days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Tuesday, 30 October 2018 8:42 AM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: RE: YP7908E / TP: SLS3658R/LKK / DOA: 27/07/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle on SLS 3658R on 29/10/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 24 October 2018 4:39 PM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <<u>Survey.Report@ergo.com.sg</u>>

Cc: SUR < sur@lkkauto.com >; assignments < assignments@lkkauto.com >

Subject: RE: YP7908E / TP: SLS3658R/LKK / DOA: 27/07/2018

Dear Pei Li.

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

#### LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Wednesday, 24 October, 2018 3:54 PM

To: admin-d@lkkauto.com Cc: survey@jpknights.com

Subject: OI: YP7908E / TP: SLS3658R/LKK / DOA: 27/07/2018

Dear Catherine.

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please conduct this survey request from 1ST AUTOWORKS PTE LTD.

**ADDRESS** 

23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING)

SINGAPORE 415933

PERSON TO CONTACT

SUHAIMI ONG / RONNIE TAN @ 6844 1985 / 8298 8933

**ERGO OFFICER-IN-CHARGE** 

STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer <u>in writing</u>, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via <a href="mailto:Survey.Report@ergo.com.sg">Survey.Report@ergo.com.sg</a>.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards, <u>Yee</u> Pei Li Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five

Singapore 038985 DID.: +65 6829 9194 Tel: +65 6829 9199 Fax: +65 6829 9247

### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 30 October 2018 8:42 AM

To:

'Survey Report (ERGO Insurance Pte. Ltd.)'

Cc:

SUR

Subject:

RE: YP7908E / TP : SLS3658R/LKK / DOA : 27/07/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle on SLS 3658R on 29/10/2018.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 24 October 2018 4:39 PM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: YP7908E / TP: SLS3658R/LKK / DOA: 27/07/2018

Dear Pei Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Wednesday, 24 October, 2018 3:54 PM

To: admin-d@lkkauto.com Cc: survey@jpknights.com

Subject: OI: YP7908E / TP: SLS3658R/LKK / DOA: 27/07/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please conduct this survey request from 1ST AUTOWORKS PTE LTD.

**ADDRESS** 

: 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933

PERSON TO CONTACT

: SUHAIMI ONG / RONNIE TAN @ 6844 1985 / 8298 8933

ERGO OFFICER-IN-CHARGE

: STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle.

Obtain estimate from workshop and inform the repairer <u>in writing</u>, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards, Yee Pei Li Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five Singapore 038985

DID.: +65 6829 9194 Tel: +65 6829 9199 Fax: +65 6829 9247

**ERGO** 

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

## Veron Chen (LKKAuto)

From:

ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>

Sent:

Thursday, 15 November 2018 2:49 PM

To:

ronnie.tan@firstautoworks.com.sg

Cc: Subject: Suhaimi; Admin-D (LKKAuto); SUR RE: Is the liabilty clear for SLS3658R ( Ergo) Steve Llm (CDMCG18000712)

### WITHOUT PREJUDICE

Dear Ronnie,

We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. Appointed assessor  $\underline{LKK}$  will finalize the reasonable cost of repairs and the number of days.

Aside to LKK, please assist to confirm direct settlement with the third party workshop.

Regards, <u>Yee</u> Pei Li Claims Assistant (Motor)

### ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five

Singapore 038985 DID: +65 6829 9194 Tel: +65 6829 9199 Fax: +65 6829 9247

**ERGO** 

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

From: Ronnie Tan [mailto:ronnie.tan@firstautoworks.com.sg]

Sent: Wednesday, November 14, 2018 2:13 PM To: ERGO Insurance Pte. Ltd. (Claims Department)

Cc: Suhaimi

Subject: fw: Is the liabilty clear for SLS3658R ( Ergo) Steve LIm

Hi Mr Steve Lim

Good day to you

Is the liabilty clear for SLS 3658R

Your client vehicle YP7908E .

Thank

Regard

Ronnie

Tel 6844 1985

From: "Ronnie Tan" < ronnie.tan@firstautoworks.com.sg >

Sent: Wednesday, 14 November, 2018 2:01 PM

To: chewht@lkkauto.com

Cc: "Suhaimi" <<u>suhaimi@firstautoworks.com.sg</u>>
Subject: Is the liabilty clear for SLS3658R ( Ergo)

Hi Ms Hsiao Tong

Good day to you

Is the liabilty clear for SLS 3658R

Your client vehicle YP7908E .

Thank

Regard

Ronnie Tel 6844 1985

### Catherine Chong (LKK Auto)

From:

Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent:

Wednesday, 24 October, 2018 3:54 PM

To:

admin-d@lkkauto.com

Cc:

survey@jpknights.com

Subject:

OI: YP7908E / TP: SLS3658R/LKK / DOA: 27/07/2018

Attachments:

YP7908E - SAS.pdf; SLS3658R - SAS.pdf; SLS3658R - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please conduct this survey request from 1ST AUTOWORKS PTE LTD.

**ADDRESS** 

: 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING)

SINGAPORE 415933

PERSON TO CONTACT

SUHAIMI ONG / RONNIE TAN @ 6844 1985 / 8298 8933

ERGO OFFICER-IN-CHARGE

: STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle.

Obtain estimate from workshop and inform the repairer <u>in writing</u>, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via <a href="mailto:Survey.Report@ergo.com.sg">Survey.Report@ergo.com.sg</a>.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards, <u>Yee</u> Pei Li Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five

Singapore 038985 DID: +65 6829 9194 Tel: +65 6829 9199 Fax: +65 6829 9247

**ERGO** 

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

# **ERGO**

urvey (PRS)			or Email	
1ST AUT	TOWORKS PTE LTD	-	V/C/V	
urvey (PRS)		-	Email	
urvey (PRS)		āc		ronnie.tan@firstautoworks.com.sg
ection:	) Acknowledgement			Totalie talle in 218010 Workston.
ection:	Acknowledgement			
	SLS 3658R	<del>-</del> 0		
le:	YP 7908E	-		
nt:	19.10.2018			
e receipt of	your request for PRS on:	23.10.2018	3	
with "State C	Courts Practice Directions Am	endment No.1	of 2016", do se	ect an assessor from
nd indicate y	your selection in the box mar	ked *.		* LKK Auto Consultants Pte Ltd
Automobile	e Inspection Services Pte Ltd	LBS	L.B.S Auto Co	nsultants Pte Ltd
FormTeam	Consultancy Pte Ltd	LKK		sultants Pte Ltd
		PS	_	es
JP Knights	Pte Lia	VAC	VICOM LIG	
uest for inspec	ction does not have your client's ction does not have your client's	GIA report, kindl	y forward a copy.	
uest for inspec owledge your red's driver ha		GIA report, kindl e will assess & re s todate.	y forward a copy.	
uest for inspec owledge your red's driver ha	ction does not have your client's Interest for direct settlement, w as not reported the accident to u	GIA report, kindl e will assess & re s todate.	y forward a copy. vert soon upon re	
uest for inspec owledge your red's driver ha	ction does not have your client's Interest for direct settlement, w as not reported the accident to u	GIA report, kindl e will assess & re is todate.	y forward a copy. vert soon upon re	ceipt of estimate.
	ge receipt of with "State C and indicate  Automobil FormTeam Infiniti App	ge receipt of your request for PRS on: with "State Courts Practice Directions Am	with "State Courts Practice Directions Amendment No.1 and indicate your selection in the box marked *.  Automobile Inspection Services Pte Ltd LBS FormTeam Consultancy Pte Ltd LKK Infiniti Appraisal Service PS	with "State Courts Practice Directions Amendment No.1 of 2016", do sell and indicate your selection in the box marked *.  Automobile Inspection Services Pte Ltd LBS L.B.S Auto ConformTeam Consultancy Pte Ltd LKK LKK Auto Conforming Infiniti Appraisal Service PS Priority Service



1.

### Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5094469516-01

Cover : drivo PREMIUM

1. Index mark and Registration Number of Vehicle

SLS3658R

Chassis Number

2. Name of Policyholder

: WOLBE6EA2HG173874

2. Nome of Folicyfloider

: CHOONG MING LING SUSAN

3. Effective Date of Insurance

: 21 Sep 2018

4. Expiry Date of Insurance

: 20 Sep 2019

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

#### This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use for the carriage of goods (other than samples) in connection with any trade or business.

(d) Use for any purpose in connection with the Motor Trade.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation)
Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

 EXCESS (SECTION 1)
 : \$\$600

 EXCESS (SECTION 2)
 : N/A

 WINDSCREEN EXCESS
 : \$\$100

 ADDITIONAL EXCESS
 : N/A

UNNAMED DRIVER EXCESS

: PLEASE REFER OVERLEAF

REPAIR AT OWNER'S PREFERRED WORKSHOP : YES
INSURE WITH COE : YES
NCD PROTECTION : YES
TRANSPORT ALLOWANCE : NO

EXCESS WAIVER : NO

PRIMARY DRIVER : CHOONG MING LING SUSAN

NAMED DRIVER (1) : N/A

NAMED DRIVER (2) : N/A

HIRE PURCHASE COMPANY : MAYBAN

SUM INSURED : MARKET

UM INSURED : MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency

: ALPINE CREDIT PTE LTD (00000615217)

Date of Issue Reprint : 07 Sep 2018 18:55 hrs : 07 Sep 2018 18:56 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

# REPUBLIC OF SINGAPORE DENTITY CARD NO. \$1517024G





Name

CHOONG MING LING SUSAN

錘 Rece

琳

CHINESE Date of birth

Sex

S1517024G

Date of 1

09-05-1962 Country/Place of birth SINGAPORE

REPUBLIC OF SINGAPORE DRIVING-LICENCE

Choop Parties S 1 5 1 7 0 2 4 G

CHOONG MING LING SUSAN

Bith Date: 09 May 1962

Broad Date: 15 Mar 2004

5849386



NRIC No. S1517024G

Date of issue

09-01-2018

Address

APT BLK 325 JURONG EAST STREET 31 #06-198 SINGAPORE 600325

# YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DAT

Class 3 Motor Cars and Motor Tractors the weight of

Licence No: \$1517024G

NP 428A

# FIRST AUTOWORKS

### Repair Estimate

Date: 24/10/2018

To Whom It May Concern

Reference:

Make:

Opel

Astra

Dear Sir,

RE: VEHICLE .: SLS 3658R

CHASSIS NO.: W0LBE6EA2HG173874 ENGINE NO.: B1171497HRXX0526

Name of insured .: CHOONG MENG LING SUSAN

Date of accident.: 19/10/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

<b>Parts</b>				
No.	Qty	Part Description		Price (SGD)
1	1	REAR BUMPER UPPER Veler		1850.00
2	1	REAR BUMPER LOWER W		1450.00
3	1	LHR BUMPER REFLECTOR ZHEN		70.00 x
4	1	RHR BUMPER REFLECTOR		70.00 -
5	1	REAR BUMPER TOW COVER *** ~		60.00 *
12 3 4 5 6 7 8 9 0	1	REAR BUMPER REINFORCEMENT	2479	1599.00
7	1	REAR BUMPER GUIDE LH 2,	2.11	57.00 -
8	1	REAR BUMPER GUIDE RH	0.21.1.2	57.00 /
9	1	REAR BUMPER GUIDE CENTER /	3131.10	65.00
10	1	REAR TAILGATE		2,200.00 ∤
<u>11</u>	1	REAR OPEL EMBLEM NOT		120.00 -
			Douts Tatali	7 500 00

Parts Total: 7,598.00 Less 10%: 759.80

> Total: 6,838.20

Labour		
No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2,500.00 650
2	Carry out spray painting on accident affected area ( Rear Bumper)	2,300.00 /100
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00 30.
4	Remove and refit reverse sensor (Labour) 1840	130.00 60.
<u>5</u>	To conduct anti rust of under carriage tuff coat	80.00 1.

Labour Total:

5,090.00

Other No.			Other D	Description_		Price (SGD)
1	Sealant	me n	Joseph Jo			50.00 +
2	Rear Bum	per Clip Set	an	30		60.00 30
					Other Total:	110.00

Total: \$12,038.20 \$842.67

Gst (7%): GRAND TOTAL: \$12,880.87

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor Ronnie Tan

DID: 6844 1985 Fax:6844 5185

Abria Liger 19/19/18.
04 Apr
total. 5001:10

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before after spray painting.
- To display damaged partist during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



### 1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 ( South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

#### TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way

#07-16, Singapore 079120

GST Ref. No:

M2-0111811-5

Vehicle No: SLS 3658R

Chasis No: W0LBE6EA2HG173874

Invoice No:

Engine No: B1171497HRXX0526

Invoice Date:

DESCRIPTION AMOUNT SGD

Parts			
No.	Qty.	Description	Price (SGD)
1	1	REAR BUMPER UPPER	1850.00
2	1	REAR BUMPER LOWER	1450.00
3	1	REAR BUMPER GUIDE LH	57.00
4	1	REAR BUMPER GUIDE RH	57.00
5	1	REAR BUMPER GUIDE CENTER	65.00

Total: 3479.00 Less 10%: 347.90 Parts Total: 3131.10

Labour		
No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	650.00
2	Carry out spray painting on affect area Rear portion ( Rear bumper & tailgate )	1,100.00
3	To disconnect front wire harness of electrical component to facilitate repair, reconnect & check electrical function after repair	30.00
4	Remove and refit reverse sensor (Labour)	60.00

Labour Total: 1840.00

Other No.

Rear Bumper Clip Set

Other Description

Price (SGD)

30.00

Other Total:

30.00

Total: GST (7%) 5001.10

Grand Total:

350.08 **5351.18** 

Yours Faithfully,

Ronnie Tan Service Advisor

Tel: 68441985 Fax:68445185

### E&OE

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "I ST AUTOWORKS PTE LTD".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to	Federation	Internationale	Des	Experts	En Automobile	

ERGO INSURANCE PTE LTD

Ref : CS/EGI18019361/Avbn2

04-0	MASEK BOULEVA 11 SUNTEC TOWN APORE 038985	ARD ER FIVE	Date: 16-01-2019	
SING	AFORE 030303		Code: EGI	
1.		Policy Particula	rs :- THIRD PARTY CLA	IM
	Insured Veh.	YP 7908E	Veh. Inspected	SLS 3658R
	Policy No.		Coverage (\$)	0.00
	Claim No.	YP7908E/SL/pl	Excess (\$)	0.00
	Assign From	YEE PEI LI	Assign Date	24/10/2018
2.		Vehicle Pa	rticulars & Condition	
	Make & Model	OPEL ASTRA	c.c	999
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	W0LBE6EA2HG173874	Colour	RED
	Odometer	22303	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	MICHELIN	6 mm
	L/H Front Tyre	225/45 R17	MICHELIN	6 mm
	R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
	L/H Rear Tyre	225/45 R17	MICHELIN	6 mm
4.		Descri	iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
	DAMAGES SEE D	DETAILS.		
5.			eral Information	
	Accident Date	19/10/2018	Inspection Date	29/10/2018
	Survey held at	1ST AUTOWORKS PTE LTI	D	
		23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933		
5a.			Remarks	PACE AND ASSESSMENT
	A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A' CE TO YOUR INSTRUCTION	WITHOUT PREJUDICE" BA S, WE HAVE NOT AUTHOR	ASIS. ISED REPAIRS.
5b.	Same and the	Estim	ate Days of Repair	
	ESTIMATED NOF	RMAL PERIOD FOR REPAIR:	4 Working Da	ays



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 3658R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
- 1	REAR BUMPER UPPER	DEFORMED	1,850.00	1,850.00
	REAR BUMPER LOWER	CUT	1,450.00	1,450.00
	LHR BUMPER REFLECTOR	NOT NECESSARY	70.00	-
33	RHR BUMPER REFLECTOR	NOT NECESSARY	70.00	€
	REAR BUMPER TOW COVER	NOT NECESSARY	60.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	1,599.00	-
1	REAR BUMPER GUIDE LH	NECESSARY	57.00	57.00
	REAR BUMPER GUIDE RH	NECESSARY	57.00	57.00
1	REAR BUMPER GUIDE CENTER	NECESSARY	65.00	65.00
1	REAR TAILGATE	TO REPAIR SEE LABOUR	2,200.00	-
1	REAR OPEL EMBLEM	NOT NECESSARY	120.00	-
	LESS 10% DISCOUNT		-759.80	-347.90
			6,838.20	3,131.10
	SPECIAL NETT ITEMS			
1	SEALANT (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	60.00	30.00
	0004-153-153-1500000-004-2-14-00-00-05-1-15002-5-15-0-15-14-1		110.00	30.00
	LABOUR			
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR TAILGATE.		2,500.00	650.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (REAR BUMPER).		2,300.00	1,100.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		80.00	30.00
	REMOVE AND REFIT REVERSE SENSOR (LABOUR).		130.00	60.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.	NOT NECESSARY	80.00	0
	Torons.		5,090.0	1,840.00

Report Ref No. CS/EGI18019361/Avbn2



Page No.:2 of 2

GRAND TOTAL	12,038.20	5,001.10
	THE RESERVE THE PROPERTY OF THE PARTY OF THE	5,001.10
PECOMMENDED COST OF REPAIRS	THE REPORT OF THE PARTY OF THE	34 B

Report Ref No. CS/EGI18019361/Avbn2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.