



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD	Document No.	: SQT18004560	Page	1
	5 MAXWELL ROAD	Date	: 24. Oct 2018		
	#17-00 TOWER BLK MND BUILDING	Customer No.	: WZE011		
	SINGAPORE 069110	Svc Advisor	:		
Registration No	: SKT4347M	Engine No	: K24Z98501681		
Chassis No	: MRHRM3850GP000055	Date Time	: 24. Oct 2018 2:18:43 PM		
Model	: CRV 2.4L 2016 MODEL (EURO 4)	Surveyor Name	:		
Owner's Name	: PASTER FERNANDO	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 12/10/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:PASTER FERNANDO						
	OWNER INSURER:TOKIO						
	ACC DATE:12/10/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:EQ INSURANCE COMPANY LTD						
	TP VEH:GBD9661M						
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BKBU02R	REMOVE & RENEW RR BUMPER AND ALL DAMAGED PARTS.	1	2000.00	560	2000.00	140.00	2140.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	2000.00	900	2000.00	140.00	2140.00
					Sum Labor	4460.00	312.20
							4,772.20
RS-TMP3040L	VPC 4PCS REAR SENSORS	1	320.00		320.00	22.40	342.40
74890-TFA-U10	GARNISH ASSYRR.LICENSE	1	236.40	25	177.30	12.41	189.71
74895-T0N-T01ZJ	GARNISH ASSYTAILGATE NSE	1	274.90	25	206.17	14.43	220.60
75722-T0N-T00	EMBLEMRR.	1	20.30	25	15.22	1.07	16.29
84431-T0A-A01ZC	LINING ASSYTAILGATE LOWER	1	170.10	25	127.57	8.93	136.50
04715-T1W-A00ZZ	FACERR.BUMPER	1	609.40	25	457.05	31.99	489.04
33505-T1W-A01	REFLECTOR ASSYR.RR.	1	54.00	25	40.50	2.84	43.34
33555-T1W-A01	REFLECTOR ASSYL.RR.	1	54.00	25	40.50	2.84	43.34
71502-TFA-T00	FACERR.R.BUMPER LOWER	1	64.50	25	48.37	3.39	51.76
71503-S9A-000ZB	CAPREAR BUMPER	2	9.80	25	14.70	1.03	15.73
71507-TFA-T00	FACERR.L.BUMPER LOWER	1	64.50	25	48.37	3.39	51.76
71510-TFA-T20	GARNISHRR.BUMPER LOWER	1	144.80	25	108.60	7.60	116.20



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110
Registration No : SKT4347M
Chassis No : MRHRM3850GP000055
Model : CRV 2.4L 2016 MODEL (EURO 4)
Owner's Name : PASTER FERNANDO
Ins Policy No. :
Date of Accident : 12/10/2018

Document No. : SQT18004560
Date : 24. Oct 2018
Customer No. : WZE011
Svc Advisor :
Engine No : K24Z98501681
Date | Time : 24. Oct 2018 2:18:43 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71593-T1W-A01	SPACERR.RR.BUMPER SIDE <i>new</i>	1	13.40	25	10.05	0.70	10.75
71598-T1W-A01	SPACERL.RR.BUMPER SIDE <i>new</i>	1	13.40	25	10.05	0.70	10.75
91505-TM8-003	CLIP,BUMPER <i>new</i>	15	2.00	25	22.50	1.58	24.08
Sum Item					1646.95	115.30	1,762.25

Survey By

Date & Time

Excess

Status

Signature

RABUL - 14p 90010068
12/11/18 @ 1600hrs
3 days
Resin 6p paint

Total Amount 6,106.95 427.50 6,534.45

Total (Inclusive of GST) **6,534.45**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 24/10/2018 3:38:31 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)