

CHUAN LEE HIN TYRES & AUTOMOTIVE

SERVICES PTE LTD

7, Soon Lee Street, iSpace #01-45/46, Singapore 627608

T: 6862 6818 | GST REG NO.: 201308888K

F: 6862 6828 | CO. REG NO.: 201308888K

Date: _____

Vehicle: _____

Item	Description	Qty	Unit Price	Amount
1)	Rear Subframe	01	\$855	\$855 ?
2)	Rear Anti Roll Bar	01	\$129	\$129 ?
3)	Rear Anti Roll Bar Bush	02	\$15	\$30 ?
4)	Rear Right Rear Connecting Link	01	\$45	\$45 ?
5)	Rear Right Tie Rod	01	\$78	\$78 ?
6)	Rear Right Knuckle	01	\$495	\$495 ?
7)	Rear Right Stone Chip Guard	01	\$82.50	\$82.50 ?
8)	Rear Right Track Control Arm	01	\$165	\$165 ?
9)	Rear Right Trailing Arm	01	\$255	\$255 ?
10)	Rear Right Wish Bone	01	\$264	\$264 ?
11)	Rear Bumper	01	\$705	\$705 <i>del</i>
12)	Front Right Fender	01	\$442.50	\$442.50 <i>del</i>
13)	Right Door Hinge	02	\$52.5	\$105 ?
14)	18" Rims	04	\$500	\$2,000 <i>FRY, Rev R4 44</i>
15)	Front Right Lower Arm	01	\$487.50	\$487.50 ?
16)	Front Right Lower Arm Ball Joint	01	\$135	\$135 ?
17)	Front Right Lower Arm Bracket	01	\$108	\$108 ?
18)	Front Right Wheel Bearing Housing	01	\$705	\$705 ?
19)	Front Right Inner Tie Rod	01	\$57	\$57 ?
20)	Front Right Tie Rod End	01	\$87	\$87 ?
21)	Coilover Set	01	\$3,000	\$3,000 ?
22)	Labour Charges for Installing and Dismantling	01	\$2,000	\$2,000 <i>1000</i>
23)	Spray Painting	01	\$1,500	\$1,500 <i>1000</i>

Nivitha / Catherine
62563561

Tanpin 97495749
'WP'
24/10/18 @ 230pm

7 days

Limpsun

Resurvey after repair

sur @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature: _____

Date: _____

Surveyor: _____

Contact: _____