

PDI TUAS

PDI TUAS

BALAKRISHNAN JAYAPRAKASH  
 53 LIMAU GARDEN  
 Singapore, 467912  
 Singapore

Phone No.  
 Fax No.  
 E-Mail

VAT Registration No. M20098505-2  
 Tax No. 199101494Z

**Service Quote**

Customer No. CV033655  
 Quote No. SER/QUO/1801777  
 QuoteDate 24/10/18  
 Salesperson Anthony Yong  
 Page 1

**THIS IS NOT AN OFFICIAL TAX INVOICE**

<b>Make</b>	<b>Model Description</b>	<b>Mileage</b>	<b>Service Advisor</b>
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	63,274	Kong Charmaine
<b>License No.</b>	<b>VIN</b>	<b>Initial Registration</b>	<b>Sales Advisor</b>
SLC3542A	WVWZZZAUZGW078408	11/05/16	Anthony Yong
<b>Engine Code</b>	<b>Labor Type</b>	<b>Engine No.</b>	<b>Model Code</b>
	1T	CZC 063815	5G13HZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	R&R RIM & BALANCE	1	UNIT		50.00 ✓
P B&P ALEX LABOUR	LABOUR	8	UNIT		<del>6,720.00</del>
P B&P ALEX LABOUR	TRANSFER DOOR MECHANISM	2	UNIT		<del>1,680.00</del>
P B&P ALEX PAINT	SPRAY PAINT	8	UNIT		<del>6,400.00</del>
P B&P TYRE SALES	TYRE	2	Pieces		<del>1,360.00</del>
	PURCHASE OF TIRE				
P B&P WHEEL ALIGNMENT	B&P WHEEL ALIGNMENT -NETT	1			360.00 ✓
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00 ✓
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00 ✓
	Nett				
	<b>Sum Labor</b>				<b>17,330.00</b>
P 311601361	RUBBER VALVE <i>new</i>	2	Pieces		4.56
	Use Predecessor 281601361				
P 5G0805912J	WHEEL HOUS RH <i>?</i>	1	Pieces		43.25
	Use Predecessor 5G0805912H				
P 5G0805970G	FENDER LINER UPPER RH <i>?</i>	1	Pieces		124.48
P 5G0807050A	FRT BUMPER BRACKET RH <i>?</i>	1	Pieces		22.15
P 5G0807217BPGRU	FRT BUMPER COVER <i>repair</i>	1	Pieces		1,041.58
P 5G0807724D	FRT BUMPER SUPP.PART RH <i>?</i>	1	Pieces		58.69
P 5G0810972D	WHEEL HOUS RHR <i>?</i>	1	Pieces		203.46
	Predecessor 5G0810972C				
P 5G0821106A	FENDER RHF <i>repair Bl</i>	1	Pieces		626.54
	Use Predecessor 5G0821106				
P 5G0919491	REAR SENSOR BRACKET <i>X</i>	1	Pieces		15.49
	<b>Sum carried forward</b>				<b>19,470.20</b>

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

BALAKRISHNAN JAYAPRAKASH  
53 LIMAU GARDEN  
Singapore, 467912  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

**Service Quote**

Customer No. CV033655  
Quote No. SER/QUO/1801777  
QuoteDate 24/10/18  
Salesperson Anthony Yong  
Page 2

**THIS IS NOT AN OFFICIAL TAX INVOICE**

<b>Make</b>	<b>Model Description</b>	<b>Mileage</b>	<b>Service Advisor</b>
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP	63,274	Kong Charmaine
<b>License No.</b>	<b>VIN</b>	<b>Initial Registration</b>	<b>Sales Advisor</b>
SLC3542A	WVWZZZAUZGW078408	11/05/16	Anthony Yong
<b>Engine Code</b>	<b>Labor Type</b>	<b>Engine No.</b>	<b>Model Code</b>
	1T	CZC 063815	5G13HZ

				Continued	19,470.20
P	5G0919491	REAR SENSOR BRACKET	X	1 Pieces	15.49
P	5G0919491A	REAR SENSOR BRACKET	X	1 Pieces	15.49
P	5G0919492A	REAR SENSOR BRACKET	X	1 Pieces	15.49
P	5G0919493	SENSOR Bracket FRT	X	1 Pieces	15.49
P	5G0919493A	SENSOR Bracket FRT	X	2 Pieces	30.98
P	5G0919494	SENSOR Bracket FRT	X	1 Pieces	15.49
P	5G0998399 GRU	SENSOR Bracket FRT	X	1 Pieces	27.89
P	5G0998492 GRU	REAR SENSOR Bracket	X	1 Pieces	27.89
P	5G4831056AQ	DOOR RHF	Bt	1 Pieces	1,942.49
P	5G4833056AB	DOOR RHR	repair	1 Pieces	1,650.63
		Use Predecessor 5G4833056AA			
P	5G4837652B	DOOR SEAL RHF	re	1 Pieces	109.43
		Use Predecessor 5G4837652A			
P	5G6807394	REAR BUMPER BRACKET RH	X	1 Pieces	39.97
P	5G6807394A	REAR BUMPER GUIDE RH	X	1 Pieces	39.97
P	5G6807417APGRU	REAR BUMPER COVER	repair	1 Pieces	996.45
		Predecessor 5G6807417ARGRU			
P	5G6839700D	DOOR SEAL RHR	X	1 Pieces	109.43
		Use Predecessor 5G6839700C			
P	D 180KU2A1	2KADHESIVE	X	1 Pieces	89.84
P	D 378500A2	DOOR INSULATOR RHF	re	1 Pieces	46.22
P	D 378500A2	DOOR INSULATOR RHR	X	1 Pieces	46.22
P	D 822150A1	BONDAGENT	X	1 Pieces	64.27
<b>Sum carried forward</b>					<b>24,769.33</b>

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

BALAKRISHNAN JAYAPRAKASH  
53 LIMAU GARDEN  
Singapore, 467912  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

### Service Quote

Customer No. CV033655  
Quote No. SER/QUO/1801777  
QuoteDate 24/10/18  
Salesperson Anthony Yong  
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

<b>Make</b>	<b>Model Description</b>
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG) EQP
<b>License No.</b>	<b>VIN</b>
SLC3542A	WVWZZZAUZGW078408
<b>Engine Code</b>	<b>Labor Type</b>
	1T

<b>Mileage</b>	<b>Service Advisor</b>
63,274	Kong Charmaine
<b>Initial Registration</b>	<b>Sales Advisor</b>
11/05/16	Anthony Yong
<b>Engine No.</b>	<b>Model Code</b>
CZC 063815	5G13HZ

Continued 24,769.33

Sum Item 7,439.33

Sum Labor 17,330.00

Sum Item 7,439.33

Total SGD 24,769.33

7% GST 24,769.33 1,733.85

Total SGD Incl. GST 26,503.18

#### Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Rasul*  
*Hp 90010068*  
*12 days*  
*31/10/18 @ 1035*  
*Resurvey by paint*