

REF:

MSIG

CC3/msc18019386/Nsb2 TAX 10/18/2092

Surveyor: NAZ

ASSIGNMENT

- (quote) work

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SJR 4440Z

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SIC 4075Y Yr Regn: 30 OCT 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or _____

Make: TOYOTA PRIUS C.C. 1,798

Colour: MAROON A/C: Insured / Std / NI / NA

Sp. Reading: 626,545 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDEN364005699963

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 22/10/18

Survey held at SMART WOODLANDS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

SIC 4075Y - NS / INCL 8001524 / Sub 2

SJR 4440Z - CC3 / CAL 300249 / R/H

29/10/18 @ 12:01 p.m. revised IA to Jasmine Lok via messenger

29/10/18 Confirmed 4S \$ 500/- @ 2 days with Naz.

(\$ 1,766.18 Red - 78%)

RECEIVED 30 NOV 2018

[Signature]
30/11/2018

Date/Time, File Pass to? 30/11/18

1) Typ: 4

Date/Time, File Return to? _____

2) _____

Report Format: _____

Lump Sum / I.B.I: (\$ 500/- 4S)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

Survey Fee:	150
Transportation:	
S + RS	
Photos	
Others	10
TOTAL	160

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 23 November 2018 4:55 PM
To: Celine Fong (LKKAuto); Naz (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHC4075Y

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Celine Fong (LKKAuto) [mailto:celinefong@lkkauto.com]
Sent: Friday, 23 November 2018 3:37 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Naz (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHC4075Y

Dear Poh Suan,

Confirmed Lump Sum \$500.00 and 2 days.

Best Regards,
Celine Fong
LKK Auto Consultants Pte Ltd
phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 29 October 2018 2:15 PM
To: Naz (LKKAuto) <Naz@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHC4075Y

Hi Naz,

Attached herewith the repair estimate of SHC 4075Y having Case No: TAX/10/18/2092.

There is no change to the approved amount of \$500 @ 2 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))

Sent: Monday, 29 October 2018 2:10 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))

Subject: Scan Data from FX-D421D6

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 29 Oct 2018

Preliminary Advice

Insured Vehicle No	: SJR4440Z	Accident Date	: 22/10/2018
TP Vehicle No	: SHC4075Y	Assignment Date	: 29/10/2018
Make	: TOYOTA PRIUS TAXI	Est. Duration of Repair	: 2 days
Date of Inspection	: 23/10/2018		
Inspection At	: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,266.18
Revised Amount	:S\$	120.00
Check Items (Estimated)	:S\$	1,332.93
Total	:S\$	1,452.93

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/10/2018 15:03
Date Of Accident	22/10/2018 11:35
Exact Location Of Accident	JALAN EUNOS TOWARDS SIMS AVE EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4075Y
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	AMIRUDDIN BIN SHAHABUDDIN
NRIC No	S0039729F
Date Of Birth	05/11/1949
Occupation	OUTDOOR
Date Of Driving Pass	02/06/1973
Driving Experience	45 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	605
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG JALAN EUNOS TOWARDS SIMS AVE EAST AS IT WAS THE RED TRAFFIC LIGHT. WHILST STATIONARY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SJR4440Z HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR4440Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Handwritten Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

22 Oct 2018

[Handwritten Signature]
22/10/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Case Details

Case Reference Number : TAX/10/18/2092
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4075Y

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-4246-ID
 Assigned By : Kok Wah Wong

Insurance Company Name : MSIG insurance (S) Pte Ltd
 Accident Date and Time : 22/10/2018 03:35 AM
 Vehicle Age(In Months) : 60

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	30.00	343.95	Replace	1	0.00	Repair	XR
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	30.00	12.08	Replace	0	0.00	Not Giv	XSVC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	30.00	154.27	Replace	0	0.00	Not Giv	XSVC
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	30.00	104.70	Replace	0	0.00	Not Giv	XSVC
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	30.00	104.70	Replace	0	0.00	Not Giv	XSVC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0.00	Not Giv	XSVC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	NR
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	30.00	54.15	Replace	0	0.00	Check	?
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	30.00	171.68	Replace	0	0.00	Check	?
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	30.00	71.10	Replace	0	0.00	Check	?
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	30.00	71.10	Replace	0	0.00	Not Giv	XSVC
Total Spare Part Cost									1,387.73		Surveyor Total	120.00		
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20		
Final Spare Part Cost									1,110.18		Final Sur Total	96.00		

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR REAR PORTION	338.00	200.00	
Total:		338.00	200.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		558.00	200.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY REAR BUMPER	378.00	200.00	
2	TO RESPRAY BUMPER BEAM	180.00	0	NN
Total:		558.00	200.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	NN
2	TO REPLACE SUNDRY PARTS	60.00	0	NN
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20.00	
Total:		260.00	20.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,110.18	96.00
Total Labour Cost	338.00	200.00
Total Spray Painting	558.00	200.00
Other	260.00	20.00
Overall Total	2,266.18	516.00
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	2,250.00	500.00
Surveyor Approved Amount		500.00
No of Repair Days*	3	2
Remarks	-	2 DAYS. CHECK ITEMS PHOTOS AFTER REPAIR PHOTOS.
Surveyor Name		Naz
Signature		

Save Clear

Survey Date 23/10/2018

NAZ LKK
 23/10/18
 LLS
 2 DAYS
 CHECK ITEMS PHOTOS
 AFTER REPAIR PHOTOS



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

swmy

Section A - Accident Details	
Registration Number	SHC4075Y
Case Reference Number	TAX/10/18/2092
Registration Date	30/10/13
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	AMIRUDDIN BIN SHAHABUDDIN
Type of Accident	Head to Rear
Accident Date and Time	22/10/18 11:35 AM
Accident Reported Date and Time	22/10/18 2:43 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098421
Special Instruction to ARC, if any	MSIG - LKK
Prepared Date and Time	22/10/18 6:34 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Copy Print

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$1,110.18	\$96.00
Total Other Cost	\$260.00	\$20.00
TOTAL COST	\$2,266.18	\$516.00
Lump Sum Total	\$2,250.00	\$500.00 (L/S)
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Tuck Foo Kok	Naz (LKK) / MSIG
ARC / Surveyor Sign Off Date	25/10/2018 8:34 AM	24/10/2018 4:25 PM
Signature		
Remarks		LUMP SUM REPAIR. 2 DAYS. CHECK ITEMS PHOTOS. AFTER REPAIR PHOTOS.

Section C - Quotation and Accident Invoice Details			
Quotation Number	QN-1810-0591	Invoice Number	
Quotation Date	29.10.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$558.00	\$200.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 66662623
 Accident Reporting Number : 66662672

Date Generated : 25/10/2018
 User ID : PehBuan

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO REPLACE SUNDRY PARTS	\$60.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
Total Other Costs	\$260.00	\$20.00

Part 4 - Spare Parts / Material Usage										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair	R X Repair
		52161-16010	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given	X SVC
		52023-12240	BUMPER REINFORCEMENT	0.00	\$205.70	0.00	\$0.00	Replace	Not Given	X SVC
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X SVC
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	X SVC
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X SVC
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓ NEC
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Check	X SVC
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Check	X SVC
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Check	X SVC
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X SVC
Total					\$1,675.81		\$120.00			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

\$120.00
 - 20%
 \$96.00
 + \$200.00
 + \$220.00

 \$516.00
 US \$500/-

CONFIRMED LUMP SUM REPAIR
 \$500.00 / 2 DAYS. H
 8/11/18

28911-81

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Oct 2018		29 Oct 2018 15:17 Edit Adj Rpt	S\$500.00 Edit Estimates	S\$500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	KHOO MEOW LI, ID: S7433980H, Tel: +6581119244, Email: bellinda_khoo@yahoo.com.sg								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHC4075Y	Date of Loss: 22/10/2018 11:00 - :59 [59 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 573817	Policy/Cover Note No.: B29082359QMX (Comprehensive) Coverage: 24/06/2018 - 23/06/2019							
Vehicle Reg. No. (Insured):	SJR4440Z	Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 28/11/2018]								
Driver/Custodian (Insured):	KHOO MEOW LI (44 / Female), NRIC: S7433980H, Tel: +6581119244								
Adj Asg. Remarks:	Direct survey done on 23/10/2018.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC4075Y (573817)**
[SJR4440Z]
TP
SMRT TAXIS PTE LTD
Oct 22 2018 11:00AM
[KHOO MEOW LI]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	29/10/18 15:11	Accident Statement From:OD - Reg. No: SJR4440Z, Claimant: KHOO MEOW LI	<input checked="" type="checkbox"/> Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	29/10/18 17:01	Adjuster Immediate Advice	<input checked="" type="checkbox"/> Load HTM
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
2	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
3	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
4	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
5	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
6	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
7	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
8	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
9	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
10	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
11	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
12	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
13	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
14	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
15	30/11/18 16:10	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
16	30/11/18 16:10	Chassis Number	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
17	30/11/18 16:10	Odometer Reading	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
18	30/11/18 16:10	Photo After Spray	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
19	30/11/18 16:10	Photo After Spray	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
20	30/11/18 16:10	Photo After Spray	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
21	30/11/18 16:10	Photo After Spray	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	29/10/18 15:11	TP REPORT SHC4075Y From:OD - Reg. No: SJR4440Z, Claimant: KHOO MEOW LI	<input checked="" type="checkbox"/> Load PDF
2	29/10/18 15:16	Direct Survey Done -LKK	<input checked="" type="checkbox"/> Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18019386/NSBE2
Date: 04/12/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29082359QMX
Claimant Vehicle No : SHC4075Y	Insured Vehicle No :	SJR4440Z
Date of Loss: 22/10/2018	Nature of Claim:	TP Claim No: 573817

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4075Y	Engine No:	2ZR1317277
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U005699963
Reg. Date:	30/10/2013 (Man. Year: 2013)	Odometer:	626545 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,735.81	120.00	1,615.81	93.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,156.00	420.00	736.00	63.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,891.81	540.00	2,351.81	81.33
Approved Total (Overridden) (S\$)		500.00		
Nett Amount (S\$)	2,891.81	500.00	2,391.81	82.71

INSPECTION

Date of Assignment:	29/10/2018	
Date Inspected:	23/10/2018 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Dec 2018)
Parts: 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC4075Y)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
2	1		*BUMPER CLIPS	Serviceable	1.61 F	*- F
3	1		*BUMPER REINFORCEMENT	Serviceable	205.70 F	*- F
4	1		*ARM SUB-ASSY, RR BUMPER LH	Serviceable	139.60 F	*- F
5	1		*ARM SUB-ASSY, RR BUMPER RH	Serviceable	139.60 F	*- F
6	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
7	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
8	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
9	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
10	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
11	1		*BUMPER REAR	Repair	458.60 F	*- F
Total Parts (S\$)					1,735.81	120.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	338.00	200.00
2	SPRAY PAINT	New	558.00	200.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
4	TO REPLACE SUNDRY PARTS	New	60.00	0.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
Gross Labour Cost (\$\$)			1,156.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >