

ASS. REC. BY:

REF: CS/CT#18019388/Dcd302 Special Instruction:

Surveyor
Menimen

Boyer

ASSIGNMENT (Office)

From (Person):

Catherine flia

of

CTI

Date/Time:

25/10/18 @ 11:54am

Estimated Cost:

Bill to:

OD / ☒ TP / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 4767D

Insured:

SLP 9292 M

at Workshop m/s

Boon Hock Motor

Tel:

65425119

of

Blk 10, AMK Ind. Park 2A #01-05/06

Policy No:

OMPESN1745141801

Claim No:

8NM18D05059C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/10/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

11:58am @ 24/10/18

Person Contacted:

Irene

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 4767D - X
	SLP 9292M - X

REF:

ASSIGNMENT

COE July 2021

From _____ Date _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 ~~12~~ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: BHD 4767 D Yr Regn: 2013 July
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Hyundai I40 c.c. 1685Colour: Blue A/C Insured / Std / NI / NASp. Reading: 577931 T/Radio: Insured / Std / NI / NAEng/No: D4FDEU430044C/No: KMHLB41UMDU038709Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 24/10/2018 D.O.I. 25/10/2018Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Cunc Tarping SLP 9292 AM27/11/18 Insured L/S 25000/- with 14 days of rev (Red. 16,261.94, 39%)

RECEIVED 05 DEC 2018

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair: 14Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + PS \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)Report Format: TPLum Sum / I.B.I: (\$ 25,000/-)

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2018		25 Oct 2018 11:54 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM LI YI, ID: S83198708		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD4767D	Date of Loss:	24/10/2018 08:00 - :59
Claim Type:	TP / SNM18D05059C02	Policy/Cover Note No.:	DMPCSN1745141801 (Comprehensive)
Vehicle Reg. No. (Insured):	SLP9292M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/11/2018]		
Adj Asg. Remarks:	EST \$41,261.94, ASSIGN HENRY NG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3821R
Vehicle Details	
Vehicle No.:	SHD4767D
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7L CRDI AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	D4FDEU430044
Chassis No.:	KMHLB41UMDU038709
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$18,703.00
Original Registration Date:	31 Jul 2013
First Registration Date:	31 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$11,203.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2021
PARF Rebate Amount:	\$7,842.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$51,810.00
COE Rebate Amount:	\$17,182.00
Total Rebate Amount:	\$25,024.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Dec 2018

OK

MCD618139200 / ComfortDelGro Engineering Pte Ltd - Layang
ENTRY DATE & TIME: 24/10/2018 14:27
SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/10/2018 14:27
Date Of Accident	24/10/2018 09:15
Exact Location Of Accident	AYE TWDS CITY NEAR ALEXANDRA RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4767D
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	TANG BOON HIN
NRIC No	S7525011H
Date Of Birth	07/08/1975
Occupation	OUTDOOR
Date Of Driving Pass	30/07/1997
Driving Experience	21 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96436975
Fax Number	
Contact Number	
Email Address	TOMMYVTECH@YAHOO.COM

Address BLK 292B BUKIT BATOK EAST AVE 6 #24-218
 Postcode 652292
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP9292M
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver LIM LI YI
 NRIC/Passport Number S8319870B
 Contact Number
 Address
 Postcode
 Insurance Company Name CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
 Nature Of Damage FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHB4139C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TOH SENG LAM
NRIC/Passport Number	S1214625F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	REAR
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 24.10.2018 @ 11:00 Hrs

Reporting Centre Personnel's Signature
Name: *Rubbini*
NRIC/FIN No.:

SKETCH PLAN



A - SHD 4767D.

B - SLP 9292M.

C - SHB 4139C (CTPL).

Along AYE Twds City Near Alexandra Rd Exit.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24.10.2018 at about 09:15 hrs, I was travelling along AYE towards City near Alexandra Rd exit with one female passenger on board.

I was travelling on the extreme right lane. I saw in front of my vehicles slowing down and stopped. Therefore, I applied E-brake. Before I came to a complete stop, I felt an impact from behind and came to know that veh (B) (SLP 9292M) hit my taxi (A) rear portion.

I assessed the damages to my taxi (A) and come to know that there were 3 vehicles involved in the chain accident.

No one was conveyed by the ambulance as no injury in this accident.

Veh (A) (SHD 4767D).

Veh (B) (SLP 9292M). Ms. Lim Li Yi (Lin LiYi). NRIC : S 8319870B.

Veh (C) (SHB 4139C). Mr. Toh Seng Lam. NRIC : S 1214625F.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 24.10.2018 @ 11:00 Hrs

Reporting Centre Personnel's Signature

Name: *Rubini*

NRIC/FIN No.:

CHUNNI MOTOR WORKS PTE LTD

REPAIR ESTIMATE*

10 Issues by 1/1/18

VEHICLE NO : SHD 4767D

DATE : 24.10.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

ChinaTaiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>brk</i>			\$ 2,265.90	✓
	Bonnet Hinge (LH/RH) <i>brk</i>		\$ 41.00	\$ 82.00	✓
	Bonnet Lock <i>brk</i>			\$ 36.90	✓
	Bonnet Absorber <i>svc</i>		\$ 58.10	\$ 116.20	X
	Bonnet Insulator <i>svc</i>			\$ 196.50	X
	Bonnet Insulator Clips <i>svc</i>			\$ 8.40	X
	Radiator Grille <i>broken</i>			\$ 251.00	✓
	Radiator Grille H Emblem <i>new</i>			\$ 27.50	✓
	Front Bumper Cover <i>broken</i>			\$ 544.50	✓
	Front Bumper Sponge <i>torn</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>brk</i>			\$ 402.10	✓
	Front Bumper Centre Grille <i>broken</i>			\$ 178.60	✓
	Front Bumper Centre Grille Top Garnish <i>broken</i>		\$ 80.00	\$ 160.00	✓
	Front Bumper Bracket Top (LH/RH) <i>svc</i>		\$ 22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>svc</i>		\$ 24.60	\$ 49.20	X
	Headlamp Support Top Cover <i>damaged</i>			\$ 222.60	✓
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>broken mounting</i>		\$ 1,388.00	\$ 2,776.00	✓
	Radiator <i>brk</i>			\$ 698.30	X ✓
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95	X ✓
	Radiator Bracket (RH/LH) <i>new</i>		\$ 6.50	\$ 13.00	X
	Radiator Hose Upper <i>new</i>			\$ 36.50	X X
	Radiator Hose Lower <i>new</i>			\$ 36.50	X
	Radiator Expansion Tank <i>new</i>			\$ 28.30	X
	Radiator Guard <i>broken</i>		\$ 20.00	\$ 40.00	✓
	Horn Unit (LH/RH) <i>broken</i>		\$ 73.80	\$ 147.60	X ✓
	Horn Wire <i>torn</i>			\$ 156.50	X ✓
	Front Fender (LH/RH) <i>damaged</i>		\$ 566.30	\$ 1,132.60	✓
	Front Fender Shield (RH) <i>new</i>			\$ 174.90	X
	Air Cleaner Assy <i>broken</i>			\$ 118.60	✓
	Air Duct <i>broken</i>			\$ 134.60	✓
	Air Flow Sensor <i>broken</i>			\$ 502.20	✓
	Aircon Condenser <i>brk</i>			\$ 927.50	X ✓
	Aircon Suction & Liquid Hose <i>new</i>			\$ 624.00	X
	Aircon Discharge Hose <i>new</i>			\$ 162.60	X
	Inter Cooler <i>damaged</i>			\$ 1,032.50	X ✓
	Inter Cooler Mounting (2 PCS) <i>new</i>			\$ 25.90	X
	Hose B To Inter Cooler <i>new</i>			\$ 229.70	X
	Hose C To Inter Cooler Inlet <i>new</i>			\$ 294.50	X
	Pipe To Inter Cooler <i>new</i>			\$ 167.05	X
	Pipe To Inter Cooler Outlet <i>new</i>			\$ 244.55	X
			13597.05		
			13637.05		
			10909.64		
	SUB TOTAL			\$ 16,089.65	
	LESS 20%			\$ 3,217.93	
	DISCOUNTED TOTAL			\$ 12,871.72	

SHD 4767D

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Number Plate <i>broken</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>broken</i>		55.00	\$ 30.00	Nett ✓
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	700/-
	Spray Painting Charge			\$ 1,000.00	700/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	30/-
	Towing Charge		1540.00	\$ 50.00	44
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	44
	TOTAL LABOUR			\$ 2,830.00	
	Boot Lid <i>Distorted</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>distorted</i>			\$ 96.50	✓
	Boot Lid Hinge (LH/RH) <i>NH</i>	S	142.30	\$ 284.60	X
	Boot Lid Lock Upper <i>RT</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>RT</i>			\$ 31.70	X
	Boot Lid 'H' Emblem <i>NH</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>NH</i>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <i>Crack</i>	S	565.60	\$ 1,131.20	✓
	Licence Lamp Garnish (LH/RH) <i>NH</i>			\$ 380.80	X
	Rear Boot Protector <i>distorted</i>			\$ 980.80	✓
	Boot Lid Trimboard <i>torn</i>			\$ 116.40	✓
	Boot Lid Trimboard Clips (10pcs) <i>NH</i>			\$ 11.00	✓
	Bootlid Moulding <i>NH</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>NH</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>NH</i>			\$ 227.90	X
	Rear Bumper <i>distorted</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>2x Crack</i>			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>Distorted</i>	S	80.30	\$ 160.60	✓
	Rear Bumper Clip 10 pcs <i>NH</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>SVC</i>	S	35.60	\$ 71.20	X
	Rear Bumper Sponge <i>torn</i>			\$ 118.40	✓
	Rear Bumper Under Cover <i>distorted</i>			\$ 228.00	✓
	Tail Lamp (LH/RH) <i>Crack</i>	S	697.80	\$ 1,395.60	✓
	Tail Lamp Quarter Panel (LH/RH) <i>Distorted</i>	S	226.50	\$ 453.00	X ✓
	Rear Panel <i>SVC</i>			\$ 526.70	✓
	Rear Panel Garnish <i>distorted mounty</i>			\$ 57.70	✓
	Rear Panel Lower Panel <i>BNC</i>			\$ 495.50	✓
	Spare Tyre Holder <i>NH</i>			\$ 223.10	X
	Spare Tyre Panel <i>Distorted</i>			\$ 852.80	✓
	Spare Tyre Panel Cushion <i>NH</i>			\$ 209.05	X
	Rear Towing Hook <i>NH</i>			\$ 94.60	X
	Member Assy- Rear Floor Centre <i>NH</i>			\$ 570.40	X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Exhaust Pipe Insulator NH	S	58.55	\$ 117.10 X
	Exhaust Silencer NH 1st	S	967.70	\$ 1,935.40 ✓
	Exhaust Pipe Hanger NH	S	58.55	\$ 117.10 X
	Exhaust Pipe Centre NH			\$ 730.10 X
	Rear Fender With Housing (LH/RH) Dental	S	4,736.80	\$ 9,473.60 ✓
	Rear Fender Inner Lining (LH/RH) NH	S	169.30	\$ 338.60 X
	Rear Fender Trim Board (LH/RH) NH	S	188.75	\$ 377.50 X
	Rear Windscreen Moulding NH			\$ 28.30 ✓
	SUB TOTAL		21399.00	\$ 25,285.65
	LESS 20%		17119.20	\$ 5,057.13
	DISCOUNTED TOTAL			\$ 20,228.52
	Boot Lid Comfort Logo & Tel No. Sticker NH			\$ 30.00 Nett ✓
	Rear No.Plates broken			\$ 25.00 Nett ✓
	Rear Bumper Reverse Sensor Dam			\$ 135.70 Nett ✓
	Rear Bumper Rubber Mat NH			\$ 50.00 Nett ✓
	Rear Windscreen Sealant NH			\$ 46.00 Nett ✓
			286.70	\$ 286.70
	Labour Charge			
	Panel Beating			\$ 2,400.00 1000/-
	Spray Painting Charge			\$ 1,750.00 800/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Exhaust Pipe			\$ 300.00 60/-
	TOTAL LABOUR		2130.00	\$ 4,990.00
	ESTIMATE TOTAL		32040.54	\$ 41,261.94
		Supp	1613.04	11525000/-
			33653.58	6346.98
	25/10 prix @ 153m NH Antenn 2/Sent 12 days. 1 Jan <u>LKK Auto</u>			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHD 4767D (Supplementary)

DATE : 1.11.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Windscreen Pillar Outer <i>Done</i> N/S			\$ 1,745.50	✓
	Front Windscreen Moulding <i>Nee</i>			\$ 113.30	✓
			1858.80	\$ 1,858.80	
	SUB TOTAL			\$ 371.76	
	LESS 20%		1487.04	\$ 1,487.04	
	DISCOUNTED TOTAL				
	Front Windscreen Sealant <i>Nee</i>		46.00	\$ 46.00	Nett
	Labour Charge				
	Remove/Refix Dashboard			\$ 450.00	NH
	Remove/Refix Front Windscreen Glass		80.00	\$ 120.00	80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00	NH
	TOTAL LABOUR			\$ 660.00	
	ESTIMATE TOTAL		1613.04	\$ 2,193.04	
	01/11/2018				
	<i>[Signature]</i>				
	2KK Auto				
	<i>[Signature]</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Oct 2018		25 Oct 2018 11:54 Edit Adj Rpt	S\$25,000.00 Edit Estimates	S\$25,000.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM LI YI , ID: S8319870B								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHD4767D	Date of Loss:	24/10/2018 08:00 - :59 [62 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05059C02	Policy/Cover Note No.:	DMPCSN1745141801 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLP9292M	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 05/11/2018]								
Adj Asg. Remarks:	EST \$41,261.94, ASSIGN HENRY NG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



















































Claim Documents



















































***SHD4767D (SNM18D05059C02)**
[SLP9292M]
TP
COMFORT TRANSPORTATION PTE LTD
Oct 24 2018 8:00AM
[LIM LI YI]
Soon Hock Motor Pte Ltd



















































Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	24/10/18 15:45	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	24/10/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	24/10/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	24/10/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	24/10/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	24/10/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	24/10/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	24/10/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	24/10/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	24/10/18 15:44	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/11/18 16:46	Rear View Left	 Load JPG	<input checked="" type="checkbox"/>
2	24/11/18 16:46	Rear View Right	 Load JPG	<input checked="" type="checkbox"/>
3	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
22	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
26	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
27	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
28	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
29	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
56	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
57	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
58	24/11/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
59	24/11/18 16:47	Front View Right	 Load JPG	<input checked="" type="checkbox"/>
60	24/11/18 16:47	Front View Left	 Load JPG	<input checked="" type="checkbox"/>
61	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
62	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
63	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
64	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
65	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
66	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
67	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
68	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
69	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
70	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
71	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
72	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
73	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
74	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
75	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
76	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
77	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
78	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
79	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
80	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
81	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
82	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
83	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
84	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
85	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
86	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
87	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
88	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
89	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
90	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
91	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
92	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
93	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
94	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
95	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
96	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
97	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
98	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
99	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
100	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
101	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
102	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
103	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
104	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
105	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
106	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
107	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
108	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
109	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
110	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
111	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
112	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
113	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
114	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
115	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
116	24/11/18 16:48	General View	 Load JPG	<input checked="" type="checkbox"/>
117	24/11/18 16:48	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
118	24/11/18 16:48	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
119	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
122	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
131	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
143	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
144	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
145	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
146	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
147	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
148	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
149	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
150	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
151	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
152	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
153	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
154	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
155	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
156	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
157	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
158	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
159	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
160	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
161	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
162	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
163	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
164	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
165	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
166	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
167	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
168	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
169	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
170	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
171	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
172	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
173	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
174	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
175	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
176	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
177	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
178	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
179	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
180	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
181	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
182	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
183	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
184	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
185	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
186	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
187	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
188	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
189	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
190	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
191	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
192	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
193	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
194	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
195	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
196	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
197	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
198	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
199	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
200	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
201	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
202	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
203	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
204	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
205	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
206	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
207	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
208	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
209	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
210	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
211	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
212	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
213	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
214	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
215	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
216	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
217	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
218	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
219	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
220	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
221	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
222	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
223	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
224	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
225	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
226	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
227	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
228	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
229	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
230	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
231	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
232	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
233	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
234	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
235	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
236	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
237	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
238	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
239	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
240	24/11/18 16:50	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
241	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
242	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
243	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
244	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
245	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
246	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
247	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
248	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
249	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
250	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
251	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
252	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
253	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
254	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
255	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
256	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
257	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
258	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
259	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
260	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
261	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
262	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
263	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
264	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
265	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
266	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
267	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
268	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
269	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
270	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
271	24/11/18 16:51	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
272	24/11/18 16:51	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
273	24/11/18 16:51	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
274	24/11/18 16:51	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
275	24/11/18 16:51	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
276	24/11/18 16:51	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
277	24/11/18 16:51	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
278	24/11/18 16:51	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
279	24/11/18 16:51	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
280	24/11/18 16:51	Finishing Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	25/10/18 11:53	REPAIR EST WITH TP GIA		Load PDF	
2	25/10/18 11:54	OI GIA		Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	24/10/18 15:43	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	24/10/18 15:44	IC,CI,DL.3 [Linked Accident Report Documents]		Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/12/18 10:57	Supplementary		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	24/10/18 15:45	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	24/10/18 15:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	24/10/18 15:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	24/10/18 15:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	24/10/18 15:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	24/10/18 15:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	24/10/18 15:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	24/10/18 15:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	24/10/18 15:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	24/10/18 15:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	24/10/18 15:43	Sketch Plan		Load TIF	
2	24/10/18 15:44	IC,CI,DL.3		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019388/DRD3E2

Date: 12/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1745141801
Claimant Vehicle No :	SHD4767D	Insured Vehicle No :	SLP9292M
Date of Loss:	24/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05059C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4767D		
Make & Model:	HYUNDAI I40, 1.7 D (A)	Engine No:	D4FDEU430044
Reg. Date:	31/07/2013 (Man. Year: 2013)	Chassis No:	KMHLB41UMDU038709
Colour:	Blue	Odometer:	577931 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,974.98	29,903.58	5,071.40	14.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,480.00	3,750.00	4,730.00	55.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,454.98	33,653.58	9,801.40	22.56
Approved Total (Overridden) (S\$)		25,000.00		
(S\$)	43,454.98	25,000.00	18,454.98	42.47
+ GST 7.00/7.00% (S\$)	3,041.85	1,750.00	1,291.85	42.47
Nett Amount (S\$)	46,496.83	26,750.00	19,746.83	42.47

INSPECTION

Date of Assignment:	25/10/2018
Date Inspected:	25/10/2018 Inspected At:

CHUNNI MOTOR WORK PTE LTD
BLK 10 ANG MO KIO IND. PARK 2A,
#03-19 AMK AUTOPOINT
SINGAPORE 568047

Estimated Period of Repair: 14.0 days

Adjuster: BRYAN TANI**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Dec 2018)
Parts:	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD4767D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Bent	82.00 FL	*82.00 FL
3	1		*BONNET LOCK	Bent	36.90 FL	*36.90 FL
4	2		*BONNET ABSORBER	Serviceable	116.20 FL	*- FL
5	1		*BONNET INSULATOR	Serviceable	196.50 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Serviceable	8.40 FL	*- FL
7	1		*RADIATOR GRILLE	Broken	251.00 FL	*251.00 FL
8	1		*RADIATOR GRILLE H EMBLEM	Necessary	27.50 FL	*27.50 FL
9	1		*FRONT BUMPER COVER	Broken	544.50 FL	*544.50 FL
10	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	402.10 FL	*402.10 FL
12	1		*FRONT BUMPER CENTRE GRILLE	Broken	178.60 FL	*178.60 FL
13	2		*FRONT BUMPER CENTRE GRILLE TOP GARNISH	Broken	160.00 FL	*160.00 FL
14	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Serviceable	44.80 FL	*- FL
15	2		*FRONT BUMPER BRACKET (LH/RH)	Serviceable	49.20 FL	*- FL
16	1		*HEADLAMP SUPPORT TOP COVER	Deformed	222.60 FL	*222.60 FL
17	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
18	2		*HEADLAMP (LH/RH)	Broken Mounting	2,776.00 FL	*2,776.00 FL
19	1		*RADIATOR	Bent	698.30 FL	*698.30 FL
20	1		*RADIATOR FAN BLADE, COWLING, MOTOR ASSY	Broken	792.95 FL	*792.95 FL
21	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
22	1		*RADIATOR HOSE UPPER	Not Necessary	36.50 FL	*- FL
23	1		*RADIATOR HOSE LOWER	Not Necessary	36.50 FL	*- FL
24	1		*RADIATOR EXPANSION TANK	Not Necessary	28.30 FL	*- FL
25	2		*RADIATOR GUARD	Broken	40.00 FL	*40.00 FL
26	2		*HORN UNIT (LH/RH)	Broken	147.60 FL	*147.60 FL
27	1		*HORN WIRE	Torn	156.50 FL	*156.50 FL
28	2		*FRONT FENDER (LH/RH)	Dented	1,132.60 FL	*1,132.60 FL
29	1		*FRONT FENDER SHIELD (RH)	Not Necessary	174.90 FL	*- FL
30	1		*AIR CLEANER ASSY	Broken	118.60 FL	*118.60 FL
31	1		*AIR DUCT	Broken	134.60 FL	*134.60 FL
32	1		*AIR FLOW SENSOR	Broken	502.20 FL	*502.20 FL
33	1		*AIRCON CONDENSER	Bent	927.50 FL	*927.50 FL
34	1		*AIRCON SUCTION & LIQUID HOSE	Not Necessary	624.00 FL	*- FL
35	1		*AIRCON DISCHARGE HOSE	Not Necessary	162.60 FL	*- FL
36	1		*INTERCOOLER	Punctured	1,032.50 FL	*1,032.50 FL
37	2		*INTER COOLER MOUNTING	Not Necessary	25.90 FL	*- FL
38	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	*- FL
40	1		*PIPE TO INTER COOLER	Not Necessary	167.05 FL	*- FL
41	1		*PIPE TO INTER COOLER OUTLET	Not Necessary	244.55 FL	*- FL
42	1		*FRONT NUMBER PLATE	Broken	25.00 FS	*25.00 FS
43	1		*FRONT NO PLATE TRIM COVER	Broken	30.00 FS	*30.00 FS
44	1		*BOOT LID	Dented	2,174.90 FL	*2,174.90 FL
45	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
46	2		*BOOT LID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
47	1		*BOOT LID LOCK UPPER	Bent	102.60 FL	*102.60 FL
48	1		*BOOT LID LOCK LOWER	Repair	31.70 FL	*- FL
49	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
50	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
51	2		*BOOT LID LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
52	1		*LICENCE LAMP GARNISH (LH/RH)	Not Necessary	380.80 FL	*- FL
53	1		*REAR BOOT PROTECTOR	Distorted	980.80 FL	*980.80 FL
54	1		*BOOT LID TRIMBOARD	Torn	116.40 FL	*116.40 FL
55	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
56	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
57	1		*BOOTLID I40 EMBLEM	Not Necessary	27.90 FL	*- FL
58	1		*BOOTLID LOWER GARNISH	Not Necessary	227.90 FL	*- FL
59	1		*REAR BUMPER	Distorted	553.00 FL	*553.00 FL
60	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
61	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Dented	160.60 FL	*160.60 FL
62	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
63	2		*REAR BUMPER BRACKET	Serviceable	71.20 FL	*- FL
64	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
65	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
66	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL
67	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Dented	453.00 FL	*453.00 FL
68	1		*REAR PANEL	Buckled	526.70 FL	*526.70 FL
69	1		*REAR PANEL GARNISH	Deformed Mounting	57.70 FL	*57.70 FL
70	1		*REAR PANEL LOWER PANEL	Buckled	495.50 FL	*495.50 FL
71	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
72	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
73	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
74	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
75	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
76	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
77	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
78	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
79	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
80	2		*REAR FENDER (LH/RH)	Dented	9,473.60 FL	*9,473.60 FL
81	2		*REAR FENDER INNER LINING (LH/RH)	Not Necessary	338.60 FL	*- FL
82	2		*REAR FENDER TRIM BOARD (LH/RH)	Not Necessary	377.50 FL	*- FL
83	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
84	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
85	1		*REAR NO. PLATE	Broken	25.00 FS	*25.00 FS
86	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
87	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
88	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
89	1		*FRONT WINDSCREEN PILLAR OUTER N/S	Dented	1,745.50 FL	*1,745.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
90	1		*FRONT WINDSCREEN MOULDING	Necessary	113.30 FL	*113.30 FL
91	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)						43,621.80 37,282.55
- List Item Discount on L Items 20.00/20.00% (\$\$)						8,646.82 7,378.97
Total Parts (\$\$)						34,974.98 29,903.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	3,400.00	1,700.00
2	SPRAY PAINTING CHARGE	New	2,750.00	1,500.00
3	WIRING CHARGE	New	100.00	60.00
4	TUFF KOTE	New	200.00	70.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE / REFIX AIRCON & REFILL GAS	New	150.00	80.00
7	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
8	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
9	REMOVE / REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
10	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
11	REMOVE / REFIX EXHAUST PIPE	New	300.00	60.00
12	REMOVE / REFIX DASHBOARD	New	450.00	0.00
13	REMOVE / REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
14	REMOVE / REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	0.00
Gross Labour Cost (\$\$)			8,480.00	3,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >