

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7682E

AAD1810-231

*Not Authorized
1/Sup @ 2100/*

Vehicle No.:	SHB 7682E
Chassis No.:	KL1LA69RJB092379
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0
Date of Accident :	19.10.18
Third Party Insurer :	AIG

PART		LIST	
1	1 Front Bumper	\$	<i>Bucln</i> 1,202.00
2	1 Front Bumper Lower Absorber	\$	<i>Sn</i> 180.00
3	1 Front Bumper Reinforcement	\$	<i>R</i> 356.00
4	1 Front Bumper Retainer RH	\$	<i>Sn</i> 102.00
5	1 Front Bumper Retainer LH	\$	<i>Sn</i> 102.00
6	1 Front Bumper Lower Grille	\$	<i>Sn</i> 78.00
7	1 Front Bumper Lower Stiffener	\$	<i>R</i> 134.37
8	1 Front Bumper Bracket LH	\$	<i>R</i> 10.00
9	1 Front Bumper Bracket RH	\$	<i>R</i> 10.00
10	1 Bumper Fog Lamp Cover RH	\$	<i>Sn</i> 32.40
11	1 Bumper Fog Lamp Cover LH	\$	<i>Sn</i> 32.40
12	1 Headlamp RH	\$	<i>Sn</i> 816.00
13	1 Headlamp RH inner panel	\$	<i>R</i> 611.16
14	1 Front Fender RH	\$	<i>R</i> 837.60
15	1 Front Fender Liner RH	\$	<i>Sn</i> 47.00
16	1 Front Fender Inner Wheel House Panel RH	\$	<i>R</i> 1,437.00
17	1 Front Shock Absorber Assy RH	\$	<i>Sn</i> 216.17
18	1 Front Shock Absorber Top Mounting RH	\$	<i>Sn</i> 48.32
19	1 Front Lower Arm RH	\$	<i>Sn</i> 283.00
20	1 Front Knuckle Arm RH	\$	<i>Sn</i> 230.00
21	1 Front Door RH	\$	<i>R</i> 1,133.00
22	1 Front Door Glass Guide RH Chrome Moulding	\$	<i>Sn</i> 60.00
23	1 Front Door Outer Moulding	\$	<i>Sn</i> 220.00
24	1 Front Door Outer Handle	\$	<i>Sn</i> 125.00
25	1 Front Door Handle Support	\$	<i>Sn</i> 3.00
26	1 Front Door outer handle inner seal	\$	<i>Sn</i> 89.15
27	1 Front Door outer key lock	\$	<i>Sn</i> 25.00
28	1 Front Door Hinge Upper	\$	<i>R</i> 65.00

Trans-cab Auto Services Pte Ltd

AAD1810-231

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7682E

29	1	Front Door Hinge Lower	\$	<i>N</i>	65.00	}
30	1	Front Door inner lock	\$	<i>N</i>	586.00	
31	1	Front Door Inner Lock Latch RH	\$	<i>N</i>	206.00	
32	1	Front Door Check / Arrestor	\$	<i>Su</i>	67.50	
33	1	Front Door Weatherstrip RH	\$	<i>Su</i>	138.79	
34	1	Front Door glass channel weatherstrip	\$	<i>Su</i>	160.00	
35	1	Front Door inner trim board	\$	<i>Su</i>	455.69	
36	1	Front Door window glass	\$	<i>Su</i>	456.12	
37	1	Front Door Power Window Motor (Master) RH	\$	<i>Su</i>	284.97	
38	1	Front Door power window motor switch	\$	<i>Su</i>	145.00	
39	1	Front Door Window Regulator Gear RH	\$	<i>N</i>	84.58	
40	1	Front Door Outer Pillar Panel RH	\$	<i>N</i>	715.00	
41	1	Front Door Pillar Inner Panel RH	\$	<i>N</i>	850.00	
42	1	Front Door Center Pillar Panel RH	\$	<i>N</i>	698.15	
43	1	Front Side View Mirror Assy RH	\$	<i>Su</i>	1,191.00	
44	1	Front Side Rocker Panel Garnish RH	\$	<i>Su</i>	236.40	
45	1	Front Side Rocker Panel Outer RH	\$	<i>N</i>	600.00	
46	1	Front Side Rocker Panel Inner RH	\$	<i>N</i>	519.30	
TOTAL			\$		15,945.07	
			10%	\$	1,594.51	
				\$	14,350.56	

Special Nett

1 Set	Front Bumper Fastener Clip	\$	<i>Nu</i>	24.00	}	
1 Set	Front licence plate with holder	\$	<i>Su</i>	192.00		
1 Set	Radiator Grille clip	\$	<i>Nu</i>	35.00		
1 Set	Front Fender Liner clip	\$	<i>Nu</i>	30.00		
1	Front Fender RR Bracket RH	\$	<i>N</i>	7.10		
1	Front Wheel Rim Hub Cap RH	\$	<i>Su</i>	166.30		
1	Front Tyre RH	\$	<i>Su</i>	180.00		
1	Front Tyre Rim RH	\$	<i>Su</i>	126.00		
TOTAL			\$		760.40	
TOTAL PARTS			\$		15,110.96	

Trans-cab Auto Services Pte Ltd

AAD1810-231

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7682E

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	<i>1cd</i>
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00	<i>X</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	<i>3cd</i>
Putty and spray painting of the affected portion.	\$	4,500.00	<i>4cd</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nr</i> 380.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00	<i>X</i>
To rust-proofing of the affected areas.	\$	170.00	<i>3cd</i>
To check steering geometry and computer wheel alignment	\$	<i>nr</i> 220.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00	<i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00	<i>X</i>
To transfer of fender fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00	<i>X</i>

TOTAL \$ 10,840.00

Over All Total \$ 25,950.96

**Repair Days (Lump Sum) 15 days
2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-confirmed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: