

2/03/2002

ASS. REC. BY:

REF: CS/SMO 18019100/Dtd3m Special Instruction:

Surveyor  
Merriman

Bryen

## ASSIGNMENT (Office)

From (Person): Thelma Choo

of

SMO

Date/Time: 2/10/18 @ 4:37pm

Estimated Cost:

Bill to:

OD ~~(TP)~~ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJO 7267T

Insured:

SLR 4025R

at Workshop m/s

Rally Pitstop

Tel:

64616985

of

176 Sin Ming Drive #04-17

Policy No:

D17MTPV01011975

Claim No:

CMTD1804645

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/6/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

9:11am @ 25/10/18

Person Contacted:

Angela

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJO 7267T - X
	SLR 4025R - X
2/11/18	Report IA thru Merriman

REF:

## ASSIGNMENT

COE June 2023

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SSQ 7267T

Yr Regn:

2008 June

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota PREVIA

C.C. 2362

Colour:

Gold

A/C: Insured / Std / NI / NA

Sp. Reading:

183619

T/Radio: Insured / Std / NI / NA

Eng/No:

2AZH143386

C/No:

JTEGD544 M007065544

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

23/10/2018

D.O.I.

25/10/2018

Survey held at

Rally Pitstop Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front y Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Sampo SLR 40252

MV 30K

LTA 17.5K

NL 12.5K

27/11/18

Insured 2/5 7100/- with 7 days of work  
Red: \$4762.05, 40%.

RECEIVED 09 NOV 2018

Date/Time, File Pass to?



Preli. Report

1) typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Invs (\$)



Weekend (\$)

Report Format :

TP

Lump Sum / H.S. (\$ 7100.00 )

350

10

360

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2018		24 Oct 2018 16:37 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE WEI LI PHILIP, ID: S8410292Z		
Main Claimant:	MOHD RAHMAN BIN ABIDIN, ID: S1488569B		
Vehicle Reg. No.:	SJQ7267T	Date of Loss:	23/10/2018 00:00 - :59
Claim Type:	TP / CMTD1804645	Policy/Cover Note No.:	D17MTPV01011975 (Comprehensive)
Vehicle Reg. No. (Insured):	SLR4025R	Policy No. (Claimant):	
		Excess:	
Repairer:	Rally Pitstop (HQ) 176 SIN MING DRIVE #04-17 SINMING AUTO CARE, 787525 Sin Ming - Tel: 64516985		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/11/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Thelma Choo

Date: 02 Nov 2018

## Preliminary Advice

Insured Vehicle No	: SLR4025R	Accident Date	: 23/10/2018
TP Vehicle No	: SJQ7267T	Assignment Date	: 24/10/2018
Make	:	Est. Duration of Repair	: 7.00
Date of Inspection	: 25/10/2018		
Inspection At	: RALLY PITSTOP (HQ) 176 SIN MING DRIVE #04-17 SINMING AUTO CARE SINGAPORE 787525		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,862.05
Revised Amount	:S\$	8,875.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,875.80

Lump Sum Repair	:S\$
-----------------	------

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The vehicle survey on "without prejudice" basis.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	8569B
<b>Vehicle Details</b>	
Vehicle No.:	SJQ7267T
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA PREVIA 7 SEATER
Primary Colour:	Gold
Manufacturing Year:	2008
Engine No.:	2AZH143386
Chassis No.:	JTEGD54M007065544
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$37,936.00
Original Registration Date:	19 Jun 2008
First Registration Date:	19 Jun 2008
Transfer Count:	3
Actual ARF Paid:	\$37,936.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	18 Jun 2023
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$18,953.00
COE Rebate Amount:	\$17,542.00
<b>Total Rebate Amount:</b>	<b>\$17,542.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/10/2018 12:28
Date Of Accident	23/10/2018 21:20
Exact Location Of Accident	WOODLANDS AVE 3 TWDS AVE 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ7267T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MOHD RAHMAN BIN ABIDIN
NRIC No	S1488569B
Email Address	MDRAHMAN@GLOBALPSA.COM
Mobile Phone No	(LOCAL) +65-90880219
Alternative Phone No	OTHERS-90880219
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PREVIA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080335472-02 (DRIVO CLASSIC)
Cover Note Number	
<b>Driver</b>	
Name of Driver	MOHD RAHMAN BIN ABIDIN
NRIC No	S1488569B
Date Of Birth	16/06/1961
Occupation	INDOOR
Date Of Driving Pass	27/05/1998
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90880219
Fax Number	
Contact Number	OTHERS-90880219
Email Address	MDRAHMAN@GLOBALPSA.COM

Address	BLK 818 #12-401 WOODLANDS STREET 82
Postcode	730818
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT ATTACHED. (ATTENDED BY CHRISTINA)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR4025R
Vehicle Make/Model/Colour	PEUGEOT 308
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DAVIS LEE
NRIC/Passport Number	S9133924B
Contact Number	90281186
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2


Vehicle Registration Number	SMD5314L
Vehicle Make/Model/Colour	HONDA FREED

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	81558485
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was driving along woodland Ave 3 towards Ave 5,  
 the vehicle (C) SMD5314L stop and I also stopped.  
 Suddenly I felt an impact from my car rear and  
 the car move forward and hit into vehicle C.


DECLARATION

I/We declare the foregoing particulars are true in every respect.

24 OCT 2018

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

176 Sin Ming Drive  
#04-17 Sin Ming Autocare  
Singapore 575721  
Tel: 64516985  
Email: tar6985@hotmail.com

To: Sampo Insurance (Motor Claims Department)  
Tel: 64616555

RE: Estimate repair cost of SJQ7267T

Dear Sir/Madam,  
Vehicle No: SJQ7267T  
Make Model: Toyota Previa  
Date of accident: 23-10-2018

[illegible]

LABOUR CHARGES & MISC			1000/-
1	Labour to dismantle and change all damaged parts	1800.00	800/-
2	To putty and spray paint	1500.00	1000/-
3	To remove and reinstall rear windscreen	120.00	80/-
4	To vacuum and top up aircon gas	80.00	20/-
5	Under coating	60.00	40/-
LABOUR TOTAL		3560.00	
LABOUR & PARTS TOTAL		11862.05	

11924.55

Regards,  
Terrence Lim

Parts 8614.40

25% 6460.80

SW 295.00

Labw 2120.00


8875.80

21% 7100.00

25/10/2018 @ 1300h

LIA Andrew

2/5m 7 days



LKK Auto



LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18019400/DRD3N2

Date: 12/11/2018

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D17MTPV01011975
Claimant Vehicle No :	SJQ7267T	Insured Vehicle No :	SLR4025R
Date of Loss:	23/10/2018	Nature of Claim:	TP
		Claim No:	CMTD1804645

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJQ7267T	Engine No:	2AZH143386
Make & Model:	TOYOTA PREVIA, 2.4 7-seater (A)	Chassis No:	JTEGD54M007065544
Reg. Date:	19/06/2008 (Man. Year: 2008)	Odometer:	183619 km
Colour:	Gold		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,364.55	6,755.80	1,608.75	19.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	2,120.00	1,440.00	40.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,924.55</b>	<b>8,875.80</b>	<b>3,048.75</b>	<b>25.57</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>7,100.00</b>		
<b>Nett Amount (\$\$)</b>	<b>11,924.55</b>	<b>7,100.00</b>	<b>4,824.55</b>	<b>40.46</b>

## INSPECTION

Date of Assignment:	24/10/2018	
Date Inspected:	25/10/2018 Inspected At:	Rally Pitstop (HQ) 176 SIN MING DRIVE #04-17 SINMING AUTO CARE Singapore 787525

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2018)
<b>Parts:</b> M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJQ7267T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	789.60 FL	*789.60 FL
2	2		*FRONT BUMPER RETAINERS	Serviceable	137.80 FL	*- FL
3	1		*FRONT LOGO	Necessary	98.60 FL	*98.60 FL
4	1		*FRONT GRILLE	Cracked	485.70 FL	*485.70 FL
5	1		*FRONT BUMPER LOWER GRILLE	Cracked	185.60 FL	*185.60 FL
6	2		*HEAD-LAMPS	O/s Mtg Broken/N/s Cracked	1,916.80 FL	*1,916.80 FL
7	2		*FOG-LAMP COVERS	Not Necessary	220.40 FL	*- FL
8	1		*FRONT REINFORCEMENT	Bent	586.30 FL	*586.30 FL
9	1		*FRONT SUPPORT PANEL	Not Necessary	485.90 FL	*- FL
10	1		*AIR-CON CONDENSER	Not Necessary	685.10 FL	*- FL
11	1		*FRONT BUMPER SPONGE	Torn	125.10 FL	*125.10 FL
12	1		*BOOT-LID INNER GARNISH	Mtg Cracked	253.80 FL	*253.80 FL
13	1		*BOOT-LID UPPER LOCK	Bent	85.20 FL	*85.20 FL
14	1		*BOOT-LID	Dented	1,223.80 FL	*1,223.80 FL
15	1		*TOYOTA EMBLEM	Necessary	48.60 FL	*48.60 FL
16	1		*PREVIA GL EMBLEM	Necessary	48.60 FL	*48.60 FL
17	1		*TOYOTA LOGO	Necessary	60.30 FL	*60.30 FL
18	1		*REAR BUMPER	Dented	785.30 FL	*785.30 FL
19	2		*REAR BUMPER SIDE RETAINERS	Serviceable	130.60 FL	*- FL
20	1		*REAR END PANEL	Buckled	588.60 FL	*588.60 FL
21	1		*REAR END PANEL INNER GARNISH	Mtg Deformed	125.20 FL	*125.20 FL
22	1		*WEATHER-STRIPE	Deformed	142.50 FL	*142.50 FL
23	1		*REAR REINFORCEMENT	No such part	485.20 FL	*- FL
24	1		*FLOOR BOARD PANEL	Dented	885.60 FL	*885.60 FL
25	2		*REAR WINDSCREEN MOULDING	Necessary	179.20 FL	*179.20 FL
26	5		*FRONT BUMPER CLIPS	Necessary	25.00 FS	*25.00 FS
27	1		*FRONT NUMBERS PLATE WITH HOLDER	Broken	45.00 FS	*45.00 FS
28	1		*SET REVERSE SENSOR	Damaged	200.00 FS	*200.00 FS
29	5		*REAR BUMPER CLIPS	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,054.40</b>	<b>8,909.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,689.85</b>	<b>2,153.60</b>
<b>Total Parts (\$\$)</b>	<b>8,364.55</b>	<b>6,755.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO DISMANTLE AND CHANGE ALL DAMAGED PARTS	New	1,800.00	1,000.00
2	TO PUTTY AND SPRAY PAINT	New	1,500.00	1,000.00
3	TO REMOVE AND REINSTALL REAR WINDSCREEN	New	120.00	80.00
4	TO VACUUM AND TOP UP AIRCON GAS	New	80.00	-
5	UNDER COATING	New	60.00	40.00
Gross Labour Cost (S\$)			3,560.00	2,120.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;