



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJK5171E

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
63476100

Vehicle & Document Information

WIP No	27815
Reg No/Reg Date	SJK5171E / 18/10/2016
Date In/Mileage	/ 0
Chassis No	WDD1760422J456087
Engine No	27091030940683
Make/Model	MB/MB A 180 (W176) "STYLE"
Colour/Trim	027 787 Mountain Gr/ 044 471 ARTICO/Fabr

Account No	Terms	Date/Time Printed	CSE	Operator
WI000576	Credit	24/10/2018/ 12:26	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :1800041071// 23-10-2018 DRIVE IN:23-10-2018 // TP CAR NO:SHD6641U (INDIA INTERNATIONAL INS) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	✓ 380.00
S BPNSUB SUPPLY 1 PC REG. PLATE WITH HOUSING.NETT				60.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REPAIR FRONT BUMPER AND REMOVE FRONT & REAR SUPPORT ASSY COMPONENTS & REFINISH.				1920 2880.00
A BPIRES RESPRAY REAR BUMPER & FRONT BUMPER				1200 1500.00
M FRT LICENSE PLATE BASE	1.00	58.68	00.00	58.68
M REAR BUMPER	1.00	1275.24	00.00	1275.24
M REAR BOTTOM PANEL BRACKET	1.00	127.76	00.00	127.76
M REAR BOTTOM PANEL	1.00	221.21	00.00	221.21
M LH/R BASIC MOUNTING FOR BUMPER	1.00	47.75	00.00	47.75
M RH/R BASIC MOUNTING FOR BUMPER	1.00	47.75	00.00	47.75
M REAR CROSS MEMBER	1.00	454.00	00.00	454.00
M CT/R BASIC MOUNTING FOR BUMPER	1.00	104.42	00.00	104.42
M CT/R PARKING SENSOR SEAL	4.00	6.42	00.00	25.68
M CT/R PARKING SENSOR	4.00	172.07	00.00	688.28

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
ID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation

Confirmed & accepted by survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Authorized signatory and company stamp
Signature:

7% GST on **Nett 7,870.77**
550.95
Total Payable 8,421.72

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg