

ESTIMATE FOR SJK5171E

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

INDIA INTERNATIONAL INSURANCE P/L

ATTN: MOTOR CLAIM DEPARTMENT **64 CECIL STREET** #04/#05 IOB BUILDING SINGAPORE 049711 63476100

Vehicle & Document Information

WIP No 27815

Reg No/Reg Date SJK5171E / 18/10/2016

Date In/Mileage

Chassis No

Engine No

Make/Model Colour/Trim

/ 0 WDD1760422J456087

27091030940683

MB/MB A 180 (W176) "STYLE"

027 787 Mountain Gr/ 044 471 ARTICO/Fabr

IO00576 Credit 24/10/2018/ 12:26 AQ 305	/ Alan Quek Ai Lun
Description of Goods / Services	Qty Unit Price Disc% Amount
BPNSUN	
POLICY NO/ACC DATE :1800041071 // 23-10-2018 DRIVE IN:23-10-2018 // TP CAR NO:SHD6641U (INDIA INTERNA DATE IN/DATE SURVEY:	FIONAL TAXINVOCE
BY/AUTHRIZED ON :	Same .
BPILAB	0.10 380.0
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO	
STANDARD SETTINGS.NETT	60.0
BPNSUB SUPPLY 1 PC REG. PLATE WITH HOUSING.NETT	00.0
BPILAB	2880.0
REMOVE & REPLACE REAR BUMPER & REAPIR FRONT BUMPER AND R	MOVE FRONT
& REAR SUPPORT ASSY COMPONENTS & REFINISH.	VI/\U
BPIRES RESPRAY REAR BUMPER & FRONT BUMPER	1500.0
FRI LICENSE PLATE BASE	1.00 58.68 00.00 58.6
REAR BUMPER	1.00 1275.24 00.00 1275.2
REAR BOTTOM PANEL BRACKET	1.00 127.76 00.00 127.7
REAR BOTTOM PANEL	1.00 221.21 00.00 221.2
LH/R BASIC MOUNTING FOR BUMPER	1.00 47.75 00.00 47.7 1.00 47.75 00.00 47.7
RH/R BASIC MOUNTING FOR BUMPER REAR CROSS MEMBER	1.00 454.00 00.00 454.0
CT/R BASIC MOUNTING FOR BUMPER	1.00 104.42 00.00 104.4
CT/R PARKING SENSOR SEAL	4.00 6.42 00.00 25.6
CT/R PARKING SENSOR	4.00 172.07 00.00 688.2
A	lan Quek
	riage Industries Pte Ltd
Body Ca	re & Repair Center
)1D: 6771 4377 H	P: 9186 5112 Fax: 6872 1272
Email: alan on	d-Govelecarriage.com.sg

7% GST on 7870.77

550.95

Total Payable

8,421.72

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg