

ASS. REC. BY:

REF:

CSLC7118019404/Gtd3n2

Special Instruction:

Surveyor:

Meimen

## ASSIGNMENT (Office)

From (Person):

Catherine Chia

of

CPI

Date/Time:

25/10/2018 @ 9.54am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 9790G

Insured:

GBH 752Y

at Workshop m/s

Comfort (Braddell)

Tel:

6383 8115

of

205 Braddell Road

Policy No:

DMCVSN1801101800

Claim No:

3NM18D05053C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/10/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

11.33am @ 25/10/18

Person Contacted:

William

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 9790G - x
	GBH 752Y - x
	Part by part \$7245.48. (Red: 5404.32, 42%)

Hand.

REF: C9i

C 4597K

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s **Comfort Braddell**  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **10** days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **C 4597K** Yr Regt: **31 Aug 2017**  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Handy Grace** C.C. **1496**  
 Colour: **white** A/C: Insured / Std / NI / NA  
 Sp. Reading: **123486** T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **GM 41105361**  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: **185/60 R15**  
 R: **11**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Giti**  
 Front Rear  
 R/Bal. **6** mm R/Bal. **6** mm  
 L/Bal. **6** mm L/Bal. **6** mm  
 D.O.A. \_\_\_\_\_ D.O.I. **25-10-18**  
 Survey held at **w/s** **2pm**  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 DEC 2018

Date/Time, File Pass to? ☐ : Preli. Report  
 1) **24/12 Typ184** ☒ : Final Report  
 Date/Time, File Return to?

Days Of Repair: **7**  
 Resurvey No. of Trip: **1**

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Others: \_\_\_\_\_

Report Format: **TP**  
 Lump Sum / I.E.: (\$ **7245.48**)

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2018		25 Oct 2018 09:54 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SENG LEONG STEEL (ENT) PTE LTD, Co. Reg. No.: 200617184M		
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SLR9790G	Date of Loss:	22/10/2018 22:00 - :59
Claim Type:	TP / SNM18D05053C02	Policy/Cover Note No.:	DMCVSN1801101800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH752Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837168 /63837118		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/11/2018]		
Adj Asg. Remarks:	EST \$6350, CASE WITH SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## Denise Tay (LKKAUTO)

---

**From:** Kristy Tay Siew Hwa <kristytay@sparkcarcare.com>  
**Sent:** Friday, 21 December 2018 1:34 PM  
**To:** Denise Tay (LKKAUTO); Guo Qiang (LKKAUTO); Admin-D (LKKAUTO); SUR; CS A Team  
**Subject:** Re: SLR9790G - Finalize - Reminder

Hi Denise

COR confirmed with thanks.

---

**From:** Denise Tay (LKKAUTO) <denisetay@lkkauto.com>  
**Sent:** Friday, 21 December 2018 12:18 PM  
**To:** Kristy Tay Siew Hwa; Guo Qiang (LKKAUTO); Admin-D (LKKAUTO); SUR; CS A Team  
**Subject:** RE: SLR9790G - Finalize - Reminder

Dear Kristy,

As per conversation with Guo Qiang.

Final figure part by part \$7245.48, 7days

Please check and confirm

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Kristy Tay Siew Hwa <kristytay@sparkcarcare.com>  
**Sent:** Monday, 17 December 2018 8:59 AM  
**To:** Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>  
**Subject:** Fw: SLR9790G - Finalize - Reminder

---

**From:** Kristy Tay Siew Hwa  
**Sent:** Wednesday, 28 November 2018 5:30 PM  
**To:** [guoqiang@lkkauto.com](mailto:guoqiang@lkkauto.com)  
**Cc:** CDGE Braddell Private Cars Crash Repair Operation  
**Subject:** SLR9790G - Finalize

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/10/2018 13:58
Date Of Accident	22/10/2018 22:45
Exact Location Of Accident	ALONG ULU PANDAN RD TWD CLEMENTI NEAR PINE GROVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR9790G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584769

### Vehicle Particulars

Manufacturer	HONDA
Model	GRACE HYBRID-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

### Driver

Name of Driver	NOR EKHSAN BIN HOSNI
NRIC No	S9221750G
Date Of Birth	24/06/1992
Occupation	OUTDOOR
Date Of Driving Pass	23/06/2011
Driving Experience	7 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87678730
Fax Number	
Contact Number	
Email Address	UNNARY69GTR@GMAIL.COM

Address	BLK 657A JURONG WEST ST 65 #03-674
Postcode	641657
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : THOMAS GENDER: : MALE

### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 25 SIN MING ROAD , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4529999 - FAX NO: 6 5535740
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH752Y
Vehicle Make/Model/Colour	NISSAN NV 200
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WONG JING WEN
NRIC/Passport Number	S9427412E
Contact Number	96546780
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name NOR EKHSAN BIN HOSNI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLR9790G

Were seat belts worn? YES


Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

# Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/10/2018 at about 2545hrs, I was travelling along extreme ~~line~~ left lane of Ulu Panan Road towards Clementi Road. At the T-junction of Ulu Panan Road and Pine Grove, one vehicle stopped and I intend to turn left, as such I also stopped my vehicle and did not collide with the vehicle in front. However, I was about to move off after the vehicle in front moved off. I felt an impact from behind, then I stepped out of my vehicle and realized one van collided with my vehicle from behind.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]* 23/10/18

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



## Sketch Plan Pg. 2

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Relief Drive



Sketch Plan Pg. 4

Main Hirev

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S0150631E



Name

HOSNI BIN SOHOR

حوسني بن شيور

Race

BOYANESE

Date of birth

15-06-1952

Sex

M

S0150631E

Country/Place of birth

SINGAPORE

5721120



SERIAL NO. S0150631E

Date of issue

29-03-2017

Address

APT BLK 657A JURONG WEST STREET 65  
#03-674  
SINGAPORE 641657



**SINGAPORE  
POLICE FORCE**



T/20181023/2038

1 of 3

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

Report No. T/20181023/2038

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/10/2018 12:07	Vide Report No.:	Station Diary No.: 11
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: NOR EKHSAN BIN HOSNI		Address: APT BLK 657A JURONG WEST STREET 65 #03-674 SINGAPORE 641657	
ID Type / ID No.: NRIC NO / S9221750G		Contact No.: Home/Office: Mobile: 87678730	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 26	Date of Birth: 24/06/1992	Type of Informant: Driver
Race: Boyanesse		Language: English	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: 3,4A Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/10/2018 22:45	Type of Location: T-Junction
Location:  ULU PANDAN ROAD  Ulu Pandan Road towards Clementi Road, near T-Junction of Ulu Pandan Road and Pine Grove				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBH752Y	Van					0
SLR9790G	Car				Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLR9790G
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	GRACE HYBRID 1.5DX AUTO
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	LEB5255376
Chassis No.:	GM41105361
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$21,724.00
Original Registration Date:	31 Aug 2017
First Registration Date:	31 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$49,899.00
COE Rebate Amount:	\$44,045.00
<b>Total Rebate Amount:</b>	<b>\$47,795.00</b>

The information contained herein is correct as at 26 Oct 2018

OK

**Tel: 63837168 / 63837466 Fax:62815767**

**ComfortDelgro Engineering Pte Ltd**  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

**Bill To** : CHINA TAIPING **Vehicle Number** : SLR9790G  
**Attn to** : GUO QIANG **Type Of Claim** : TP

**A. Spare parts** \$ 4,338.10

**F. Total Parts** \$ 3,795.48

3715.48

**B. Supplementary** \$ -

**G. Total Labour** \$ 3,900.00

3530

**C. Nett Price** \$ -

**H. Total Repair** \$ 7,695.48

**D. Supp Nett Price** \$ -

**I. Excess**                     

**E. S/Nett** \$ 325.00

**P/P Total** 7,695.48

245

Total Spare Parts Price		\$ 4,338.10
Cost plus / List Down	20%	867.62
Total		3,470.48

**Lump Sum Less** \$ -

Total Nett Price		\$ -
Nett Price Less		\$ -
Total		-

**Lump Sum Rounding**                     

**Total Finalized** \$ 7,695.48

7245.48

**N.B. If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & correct.**

Remarks : Please confirm and revert by Fax or Email

**Date In** :                      **Total Repair Day** 7

**Date Survey** :                      **LOU/ Day**                     

**Date Out** :                      **Total LOU**                     

**Sat/Sun/Ph.** :                      **Rental/Day**                     

**Authorized Repair Day**                      **Total Rental**                     

**Submitted By / Date :**                      **Confirmed By / Date :**                     

28.11.18 - KRISTY



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : **TP**Ins Company : **AIG / CHINA TAIPING**

Excess : \_\_\_\_\_

Date of Accident : **22/10/2018**

Suggested Days of Repair : \_\_\_\_\_

**Repair Estimate**

Parts (a) Cost / List Price Items	<b>S 7,468.50</b>
Plus/Less 20%	<b>S 1,493.70</b>
Total of Cost / List	<b>S 5,974.80</b>
(b) Nett Price Items	<b>S -</b>
Less	<b>S -</b>
Total of Nett Item	<b>S -</b>
(c) Special Nett Items	<b>S 325.00</b>
<b>Total Parts Cost (Appendix A)</b>	<b>S 6,299.80</b>
<b>Labour (Appendix B)</b>	<b>S 6,350.00</b>
<b>Total Repair Cost</b>	<b>S 12,649.80</b>

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurer

Vehicle No. **SLR9790G**Make & Model : **HONDA GRACE HYB 1.5DX A**

Signature: \_\_\_\_\_

Date: Year of Manufacture : **2016**Chassis No. : **GM41105361**

Engine No. : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Time of Accident : \_\_\_\_\_

**In-house Vehicle Assessor**Case Owner : **Andrew**

Signature : \_\_\_\_\_

**Contact No****Frt Counter Operation**

6383 7466 - Patrick Tia

6383 7730 - Brenda Ng

6383 7890 - Rohani

[braddell\\_cr@sparkcarcare.com](mailto:braddell_cr@sparkcarcare.com)**Workshop Operation**

63837656 - Ngo Toh Wee

**63837362 - Andrew Goh**

63838115 - William Wang

[braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)Name of Surveyor : **Guo Q: P.**Company : **LKK**Survey conducted on : **25/10/18** at \_\_\_\_\_**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : **10** day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: **26/10/18**part by rt.  
before paint photo S.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLR9790G Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105361 Engine No : 0

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear number plate with casing <i>ser</i>	1				\$ 45.00	
2	Rear bumper <i>re</i>	1		\$ 937.00	✓		
3	Rear bumper reflector LH <i>ser</i>	1		\$ 48.00	✓		
4	Rear bumper reflector RH <i>ser</i>	1		\$ 48.00	✓		
5	Rear bumper side retainer LH <i>ser</i>	1		\$ 13.90	✓		
6	Rear bumper side retainer RH <i>ser</i>	1		\$ 13.90	✓		
7	Rear bumper clips <i>re</i>	10		\$ 50.00	✓		
8	Bootlid <i>ser</i>	1		\$ 675.20	✓		
9	Bootlid spoiler <i>NN</i>	1		\$ 364.90	✓		
10	Bootlid hinge LH <i>ser</i>	1		\$ 68.40	✓		
11	Bootlid hinge RH <i>ser</i>	1		\$ 68.40	✓		
12	Bootlid inner trim <i>NN</i>	1		\$ 99.70	✓		
13	Bootlid inner trim clips <i>re</i>	10		\$ 50.00	✓		
14	Bootlid lock <i>BT</i>	1		\$ 95.30	✓		
15	Bootlid weatherstrip <i>ser</i>	1		\$ 75.90	✓		
16	Bootlid lamp LH <i>ser</i>	1		\$ 306.70	✓		
17	Bootlid lamp RH <i>ser</i>	1		\$ 306.70	✓		
18	Bootlid emblem logo H <i>ser</i>	1		\$ 24.70	✓		
19	Bootlid emblem HYBRID <i>re</i>	1		\$ 58.70	✓		
20	Bootlid emblem GRACE <i>re</i>	1		\$ 45.00	✓		
21	Bootlid chrome moulding <i>NN</i>	1		\$ 165.00	✓		
22	Bootlid chrome moulding clips <i>NN</i>	4		\$ 20.00	✓		
23	Taillamp LH <i>ser</i>	1		\$ 381.70	✓		
24	Taillamp RH <i>ser</i>	1		\$ 381.70	✓		
25	Taillamp side clips <i>re</i>	2		\$ 10.00	✓		
26	Taillamp panel LH <i>NN</i>	1		\$ 89.60	✓		
27	Taillamp panel RH <i>NN</i>	1		\$ 89.60	✓		
28	Rear end panel <i>re</i>	1		\$ 395.00	✓		
29	Rear end panel top garnish <i>re</i>	1		\$ 86.40	✓		
30	Rear cargo tools tray <i>re</i>	1		\$ 168.50	✓		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



**Spark Car Care**  
**ComfortDelGro Engineering Pte Ltd**  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

**Spare Parts**

Vehicle No : SLR9790G Case Owner : Andrew

Make & Model : HONDA GRACE HYB 1.5D Year Manufacture : 2016

Chassis No : GM41105361 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/N	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
31	Rear cargo top cover <del>X</del>	1		\$ 254.30	<del>X</del>		
32	LH rear fender inner trim <del>X</del> } NN	1		\$ 265.00	<del>X</del>		
33	RH rear fender inner trim <del>X</del>	1		\$ 265.00	<del>X</del>		
34	Rear floor under cover <del>ee</del>	1		\$ 125.00	<del>X</del>		
35	Rear floor panel <del>X</del> Base Repair.	1		\$ 855.60	<del>X</del>		
36	IPU Duct assy front <del>X</del>	1		\$ 98.50	<del>X</del>		
37	IPU Duct assy <del>X</del>	1		\$ 135.60	<del>X</del>		
38	IPU Tube joint comm <del>X</del> } NN	1		\$ 65.20	<del>X</del>		
39	IPU Tube assy <del>X</del>	1		\$ 185.90	<del>X</del>		
40	Rear end panel buzzer <del>X</del>	1		\$ 80.50	<del>X</del>		
41	Reverse sensor / PM.	1				\$ 280.00	✓ 200
42	0	0					
43	0	0					
44	0	0					
45	0	0					
46	0	0					
47	0	0					
48	0	0					
49	0	0					
50	0	0					
51	0	0					
52	0	0					
53	0	0					
54	0	0					
55	0	0					
56	0	0					
57	0	0					
58	0	0					
59	0	0					
60	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

## Labour

Vehicle No. : **SLR9790G** Case Owner : **Andrew**  
 Make & Model : **ONDA GRACE HYB 1.5DX A** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove and refit cushions and upholstery to facilitate repairs	\$ 280.00	250 /
2	To transfer bootlid parts and mechanisms to new bootlid	\$ 250.00	150 /
3	To remove, reinstall Hybrid Electronic Module connection and to reset and synchronization the electronic system	\$ 550.00	250 /
4	Labor charges to repair, panel beat and to replace Rear bumper, Bootlid, cut and weld on Rear end panel, Rear floor panel and affected areas	\$ 1,680.00	1250 / 960 .
5	To check wiring functions	\$ 120.00	60 /
6	To install reverse sensor	\$ 120.00	60 /
7	To putty and spray paint Bootlid, Rear bumper, Rear end panel, Rear floor panel, Taillamp panel LH, Taillamp panel RH, LH rear fender, RH rear fender, Spoiler and all affected areas	\$ 2,500.00	1500 /
8	To apply rust proofing on replaced and repaired panels	\$ 300.00	150 /
9	To diagnose, reset and re-programme electronic systems	\$ 300.00	150 /
10	To remove and replace rear exhaust pipe assy	\$ 250.00	<del>250</del> / X NN

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118019404/GTD3N2

Date: 28/12/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1801101800
Claimant Vehicle No :	SLR9790G	Insured Vehicle No :	GBH752Y
Date of Loss:	22/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05053C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLR9790G	Engine No:	LEB5255376
Make & Model:	HONDA GRACE HYBRID, 1.5 (A)	Chassis No:	GM41105361
Reg. Date:	31/08/2017 (Man. Year: 2016)	Odometer:	123486 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,299.80	3,715.48	2,584.32	41.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,350.00	3,530.00	2,820.00	44.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>12,649.80</b>	<b>7,245.48</b>	<b>5,404.32</b>	<b>42.72</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>885.49</b>	<b>507.18</b>	<b>378.31</b>	<b>42.72</b>
<b>Nett Amount (\$\$)</b>	<b>13,535.29</b>	<b>7,752.66</b>	<b>5,782.63</b>	<b>42.72</b>

## INSPECTION

Date of Assignment:	25/10/2018	
Date Inspected:	25/10/2018 Inspected At:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road Singapore 579701

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2018)
<b>Parts:</b>	143	HONDA GRACE HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLR9790G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	937.00 FL	*937.00 FL
2	1		*REAR BUMPER REFLECTOR LH	Not Necessary	48.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR RH	Not Necessary	48.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER LH	Deformed	13.90 FL	*13.90 FL
5	1		*REAR BUMPER SIDE RETAINER RH	Deformed	13.90 FL	*13.90 FL
6	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
7	1		*BOOTLID	Buckled	675.20 FL	*675.20 FL
8	1		*BOOTLID SPOILER	Not Necessary	364.90 FL	*- FL
9	1		*BOOTLID HINGE LH	Bent	68.40 FL	*68.40 FL
10	1		*BOOTLID HINGE RH	Bent	68.40 FL	*68.40 FL
11	1		*BOOTLID INNER TRIM	Not Necessary	99.70 FL	*- FL
12	10		*BOOTLID INNER TRIM CLIPS	Necessary	50.00 FL	*50.00 FL
13	1		*BOOTLID LOCK	Bent	95.30 FL	*95.30 FL
14	1		*BOOTLID WEATHERSTRIP	Twisted	75.90 FL	*75.90 FL
15	1		*BOOTLID LAMP LH	Scratched	306.70 FL	*306.70 FL
16	1		*BOOTLID LAMP RH	Scratched	306.70 FL	*306.70 FL
17	1		*BOOTLID EMBLEM LOGO H	Necessary	24.70 FL	*24.70 FL
18	1		*BOOTLID EMBLEM HYBRID	Necessary	58.70 FL	*58.70 FL
19	1		*BOOTLID EMBLEM GRACE	Necessary	45.00 FL	*45.00 FL
20	1		*BOOTLID CHROME MOULDING	Not Necessary	165.00 FL	*- FL
21	4		*BOOTLID CHROME MOULDING CLIPS	Not Necessary	20.00 FL	*- FL
22	1		*TAILLAMP LH	Scratched	381.70 FL	*381.70 FL
23	1		*TAILLAMP RH	Scratched	381.70 FL	*381.70 FL
24	2		*TAILLAMP SIDE CLIPS	Necessary	10.00 FL	*10.00 FL
25	1		*TAILLAMP PANEL LH	Not Necessary	89.60 FL	*- FL
26	1		*TAILLAMP PANEL RH	Not Necessary	89.60 FL	*- FL
27	1		*REAR END PANEL	Buckled	395.00 FL	*395.00 FL
28	1		*REAR END PANEL TOP GARNISH	Deformed	86.40 FL	*86.40 FL
29	1		*REAR CARGO TOOLS TRAY	Deformed	168.50 FL	*168.50 FL
30	1		*REAR CARGO TOP COVER	Not Necessary	254.30 FL	*- FL
31	1		*LH REAR FENDER INNER TRIM	Not Necessary	265.00 FL	*- FL
32	1		*RH REAR FENDER INNER TRIM	Not Necessary	265.00 FL	*- FL
33	1		*REAR FLOOR UNDER COVER	Deformed	125.00 FL	*125.00 FL
34	1		*REAR FLOOR PANEL	Repair	855.60 FL	*- FL
35	1		*IPU DUCT ASSY FRONT	Not Necessary	98.50 FL	*- FL
36	1		*IPU DUCT ASSY	Not Necessary	135.60 FL	*- FL
37	1		*IPU TUBE JOINT COMM	Not Necessary	65.20 FL	*- FL
38	1		*IPU TUBE ASSY	Not Necessary	185.90 FL	*- FL
39	1		*REAR END PANEL BUZZER	Not Necessary	80.50 FL	*- FL
40	1		*REAR NUMBER PLATE WITH CASING	Scratched	45.00 FS	*45.00 FS
41	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)      7,793.50      4,583.10  
 - List Item Discount on L Items 20.00/20.00% (S\$)      1,493.70      867.62

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	6,299.80	3,715.48

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT CUSHIONS AND UPHOLSTERY TO FACILITATE REPAIRS	New	280.00	250.00
2	TO TRANSFER BOOTLID PARTS AND MECHANISMS TO NEW BOOTLID	New	250.00	150.00
3	TO REMOVE,REINSTALL HYBRID ELECTRONIC MODULE CONNECTION AND TO RESET AND SYNCHRONIZATION THE ELECTRONIC SYSTEM	New	550.00	250.00
4	LABOUR CHARGES TO REPAIR,PANEL BEAT AND TO REPLACE REAR BUMPER,BOOTLID,CUT AND WELD ON REAR END PANEL,REAR FLOOR PANEL AND AFFECTED AREAS	New	1,680.00	960.00
5	TO CHECK WIRING FUNCTIONS	New	120.00	60.00
6	TO INSTALL REVERSE SENSOR	New	120.00	60.00
7	TO PUTTY AND SPRAY PAINT BOOTLID,REAR BUMPER,REAR END PANEL,REAR FLOOR PANEL,TAILLAMP PANEL LH,TAILLAMP PANEL RH,LH REAR FENDER,RH REAR FENDER,SPOILER AND ALL AFFECTED AREAS	New	2,500.00	1,500.00
8	TO APPLY RUST PROOFING ON REPLACED AND REPAIRED PANELS	New	300.00	150.00
9	TO DIAGNOSE,RESET AND RE-PROGRAMME ELECTRONIC SYSTEMS	New	300.00	150.00
10	TO REMOVE AND REPLACE REAR EXHAUST PIPE ASSY	New	250.00	-
<b>Gross Labour Cost (\$\$)</b>			<b>6,350.00</b>	<b>3,530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >