

ASS. REC. BY:

REF: CS/CTI18019409

RISD3⁷²

Special Instruction:

Surveyor:

Pasul

ASSIGNMENT (Office)

From (Person):

Irene tay

of CTI

Date/Time: 24/10/18 @ 2:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGV 633A

Insured:

SLQ647C

at Workshop m/s

Borneo Motors

Tel:

9847 6171

of

2 pandan Crescent

Policy No:

DMPCSN 3051811801

Claim No:

SNM18D05040C02

Sum Insured:

Excess:

D.O.A.

20/10/2018

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:54am @ 25/10/18

Person Contacted:

thomas

Vehicle IN

(OUT)

Date/Time	Action/Instruction (✓) Estimate
	SGV 633A - X
	SLQ 647C - CS3/CTI18019409 / Uzabe2 DOR: 13/06/18
25/10/18-	VNI
2/11/18-	vehicle not ln.

Pam

ASSIGNMENT

From: _____ Date: 19/11/2018

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGV 633A

at Workshop m/s Borneo Motor
of 2 pandan Crescent

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGV 633A Yr Regn: 2017 / ADK

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA with 1.8 CRT c.c 1798

Colour: GREEN A/C: Insured / Std / NI / NA

Sp. Reading: 34424 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JT DGH 20W 80J 0066 79.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15 R: _____

BS / DUN / EXNOVA GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 20/10/18

Survey held at Borneo Motor

Des. of Damages Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
26/11/18	Confirmed P/P \$ 4,690.20 @ 5 days with Rasul. (\$ 7,229.26 Red - 61%)
RECEIVED 26 NOV 2018	

Date/Time, File Pass to? 26/11/18

1) Preli. Report Final Report

Date/Time, File Return to? _____

2) _____

Report Format : Lump Sum / I.B.I: (\$ 4,690.20 P/P)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee: _____

Transportation: \$ + RS, SI 220

Photos _____

Others _____

TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						Status	
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	
Main	24 Oct 2018		24 Oct 2018 14:40 Assign				New Assignment Cancel Case

Main
Reference
Claim Details
Documents
[Show All](#)

[Created by insurer]

CLAIM SUBFOLDER DETAILS

Insured:	
Main Claimant:	MA LI
Vehicle Reg. No.:	SGV633A
Claim Type:	TP / SNM18D05040C02
Vehicle Reg. No. (Insured):	SLQ647C
Date of Loss:	20/10/2018 00:00 - :59
Policy/Cover Note No.:	DMPCSN3051811801
Policy No. (Claimant):	
Excess:	\$0.00
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/11/2018]
Adj Asg. Remarks:	EST \$312,753.82 , CASE WITH SJE.

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 26 November 2018 11:53 AM
To: 'Thomas Pang PTCBC'
Cc: Rasul (LKKAuto); Admin A; SUR
Subject: RE: Finalize Report for SGV 633A

Hi Thomas,

Confirmed final fig of \$ 4,690.20 (part by part) @ 5 days of repairs before GST.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Thomas Pang PTCBC [mailto:Thomas.Pang@borneomotors.com.sg]

Sent: Thursday, 22 November 2018 3:59 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: Finalize Report for SGV 633A

Dear Rasul,

Attach finalize report for your perusal. 05 working days.

Thank you

Regards

thomas

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.



Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

U.K.K.
ESTIMATE

Online Service Booking :
 www.toyota-singapore.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no. : 6631 1188

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept.		S1000003 / ICCI1	Mr Ma Li 246 Simei Street 5 #03-66 Singapore 520246 Mobile: 81829736	
		Document No		
		0		
		Document Date		
		23/10/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	26/04/2017	SGV0633A	0	36791	72/DS/SGV0633A
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W80J006679	2ZR1939100		60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Gd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: CHINA TAIPING INSURANCE TP VEH: SLQ647C DATE OF ACC: 20.10.2018			net	50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)			net	100.00 ✓
3	B	BP-LAB R/I AND REFOCUS HEADLAMP (NETT)			119.26	115.26 ✓
4	B	BP-MECH R/I AC CONDENSOR, PIPING AND REGAS (NETT)			339.00	339.00 ✓
5	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				169.50 ✓
6	L	BP-LPO SUPPLY REGN PLATE (PO#) (NETT)				80.00 ✓
7	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				1356 2024.00
8	B	BP-RES RESPRAY ACC AFFECTED AREAS				1112 2224.00
9	1	T52119-68909 FRONT BUMPER COVER, <i>net</i>	1.00	581.20		581.20
10	2	T52115-68031 R/FRT BUMPER SUPPORT, <i>net</i>	1.00	61.60		61.60
11	3	T52116-68031 L/FRT BUMPER SUPPORT, <i>net</i>	1.00	61.60		61.60
12	4	T52611-68030 FRT BUMPER ABSORBER, <i>net</i>	1.00	99.60		99.60
13	5	T52021-68020 F/BPR REINFORCEMENT, <i>net</i>	1.00	299.40		299.40
14	6	T90159-50353 SCREW, W/WASHER <i>net</i>	2.00	1.70		3.40
15	7	T53879-28010 FRT FENDER RETAINER, <i>net</i>	2.00	10.30		20.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3804479

TO SECURITY GUARD

3804479

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 23/10/2018
 TIME 15:03

VEHICLE NO SGV0633A

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
 www.toyotasingsapore.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Ma Li 246 Simei Street 5 #03-66 Singapore 520246 Mobile: 81829736	
		Document No		
		0		
		Document Date		
		23/10/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	26/04/2017	SGV0633A	0	36791	72/DS/SGV0633A
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W80J006679	2ZR1939100	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	8	T53101-68010 GRILLE SUB-ASSY, <i>X 1/1</i>	1.00	407.00		407.00
17	9	S52161-0K040 PIECE, RR BUMPER, <i>re-</i>	10.00	4.00		40.00
18	0	T53301-68020 FRONT BONNET ASSY, <i>re-</i>	1.00	958.10		958.10
19	1	T53381-68020 FRONT BONNET SEAL, <i>re-</i>	1.00	32.00		32.00
20	2	T90467-09050 CLIP <i>re-</i>	10.00	2.40		24.00
21	3	T53208-68020 F/BRACE LOCK SUPPORT, <i>re-</i>	1.00	91.20		91.20
22	4	T90975-02086 TOYOTA SYMBOL EMBLEM, <i>re-</i>	1.00	72.20		72.20
23	5	T81145-68100 UNIT, HEADLAMP <i>re-</i>	1.00	1239.50	X	1239.50
24	6	T81185-68100 UNIT, HEADLAMP LH <i>re-</i>	1.00	1239.50	X	1239.50
25	7	T88450-12280 A/C CONDENSER ASSY, <i>re-</i>	1.00	1526.80	X	1526.80

Handwritten notes:
 2/11/18
 Repair
 Hp 900000000
 Soday
 19/11/18 @ 1100hrs
 Reg 68 point

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.
 Acknowledged by Repairer

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	11,919.46
Date:	Please acknowledge receipt of vehicle	Parts 6,757.70	GST 7.00%	834.36
		Labour 5,081.76	Less	0.00
		Materials 80.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	12,753.82

PLEASE TEAR ALONG PERFORATED LINE **3804480**
3804480

TO SECURITY GUARD
 PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 23/10/2018
 TIME 15:03

VEHICLE NO SGV0633A

CUSTOMER SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD





Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
 www.toyotasingapore.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Ma Li 246 Simei Street 5 #03-66 Singapore 520246 Mobile: 81829736		
		Document No			0
		Document Date			22/11/2018

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	26/04/2017	SGV0633A	0	36791	72/DS/SGV0633A

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W80J006679	22R1939100	60	60	Thomas Pang W T	19/11/2018 8.00	22/11/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: CHINA TAIPING INSURANCE TP VEH: SLQ647C DATE OF ACC: 20.10.2018 BY:LKK-RASUL @ 19.11.2018 05 WORKING DAYS				50.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
3	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT) 18				169.50
4	L	BP-LPO SUPPLY REGN PLATE (PO# 19298) (NET E33				80.00
5	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	*			1356.00
6	B	BP-RES RESPRAY ACC AFFECTED AREAS	*			1112.00
7	1	T52119-68909 COVER, FR BUMPER	1.00	581.20		581.20
8	2	T90159-50353 SCREW, W/WASHER	2.00	1.70		3.40
9	3	T53879-28010 RETAINER, FR FENDER	2.00	10.30		20.60
10	4	S52161-0K040 PIECE, RR BUMPER	10.00	4.00		40.00
11	5	T53301-68020 HOOD SUB ASSY	1.00	958.10		958.10
12	6	T53381-68020 SEAL HOOD	1.00	32.00		32.00
13	7	T90467-09050 CLIP	10.00	2.40		24.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

3826415

PLEASE TEAR ALONG PERFORATED LINE

3826415

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2018
 TIME 15:39

VEHICLE NO SGV0633A

SIGNATURE



Borneo Motors



Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd
 Online Service Booking :
 www.toyotasingapore.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr Ma Li 246 Simei Street 5 #03-66 Singapore 520246 Mobile: 81829736	
		Document No		
		0		
		Document Date		
		22/11/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	26/04/2017	SGV0633A	0	36791	72/DS/SGV0633A

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W80J006679	2ZR1939100	60	Thomas Pang W T	19/11/2018	8.00	22/11/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	B	T53208-68020	1.00	91.20		91.20
15	9	T90975-02086	1.00	72.20		72.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	4,690.20
	Please acknowledge receipt of vehicle	Parts 1,822.70 Labour 2,787.50 Materials 80.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00%	328.31
			Less	0.00
			Amount Due	5,018.51

3826416

PLEASE TEAR ALONG PERFORATED LINE

3826416

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 22/11/2018
 TIME 15:39

VEHICLE NO SGV0633A

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118019409/R1SD3N2
Date: 28/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3051811801
Claimant Vehicle No :	SGV633A	Insured Vehicle No :	SLQ647C
Date of Loss:	20/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05040C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV633A	Engine No:	2ZR1939100
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDGG20W80J006679
Reg. Date:	26/04/2017 (Man. Year: 2017)	Odometer:	34424 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,037.70	2,052.70	4,985.00	70.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,881.76	2,637.50	2,244.26	45.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,919.46	4,690.20	7,229.26	60.65
+ GST 7.00/7.00% (\$\$)	834.36	328.31	506.05	60.65
Nett Amount (\$\$)	12,753.82	5,018.51	7,735.31	60.65

INSPECTION

Date of Assignment:	24/10/2018		
Date Inspected:	19/11/2018	Inspected At:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Nov 2018)
 Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SGV633A)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	581.20 FS	*581.20 FS
2	1		*R/FRT BUMPER SUPPORT	Serviceable	61.60 FS	*- FS
3	1		*L/FRT BUMPER SUPPORT	Serviceable	61.60 FS	*- FS
4	1		*FRT BUMPER ABSORBER	Not Necessary	99.60 FS	*- FS
5	1		*F/BPR REINFORCEMENT	Not Necessary	299.40 FS	*- FS
6	2		*SCREW,W/WASHER	Necessary	3.40 FS	*3.40 FS
7	2		*FRT FENDER RETAINER	Necessary	20.60 FS	*20.60 FS
8	1		*GRILLE SUB-ASSY	Not Necessary	407.00 FS	*- FS
9	10		*PIECE,RR BUMPER	Necessary	40.00 FS	*40.00 FS
10	1		*FRONT BONNET ASSY	Bent	958.10 FS	*958.10 FS
11	1		*FRONT BONNET SEAL	Necessary	32.00 FS	*32.00 FS
12	10		*CLIP	Necessary	24.00 FS	*24.00 FS
13	1		*F/BRACE LOCK SUPPORT	Bent	91.20 FS	*91.20 FS
14	1		*TOYOTA SYMBOL EMBLEM	Necessary	72.20 FS	*72.20 FS
15	1		*UNIT,HEADLAMP	Not Necessary	1,239.50 FS	*- FS
16	1		*UNIT,HEADLAMP LH	Not Necessary	1,239.50 FS	*- FS
17	1		*A/C CONDENSER ASSY	Not Necessary	1,526.80 FS	*- FS
18	1		*REGN PLATE	Bent	80.00 FS	*80.00 FS
19	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
20	1		*SEALANT	Necessary	100.00 FS	*100.00 FS
Total Parts (S\$)					7,037.70	2,052.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R/I AND REFOCUS HEADLAMP	New	115.26	-
2	R/I AC CONDENSOR, PIPING AND REGAS	New	339.00	-
3	TO RESET ECU AND REPROGRAMME	New	169.50	169.50
4	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	New	2,034.00	1,356.00
5	RESPRAY ACC AFFECTED AREAS	New	2,224.00	1,112.00
Gross Labour Cost (S\$)			4,881.76	2,637.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >