

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLD7335A

TP/AXA

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1891219/WL

Date: 24 Oct 2018

Policy No: 5102699584

Veh Reg No: SLD7335A

Make/Model: HONDA SHUTTLE 1.5G
A

WS Ref: TP/AXA/WL

Claim Type: Third Party

Accident Date: 24/10/2018

TP Veh Reg No: SKH8964T

Chassis No: GK81005321

Engine No: L15B3536235

Reg. Date: 28/06/2016

Estimate Repair Cost to Vehicle No :SLD7335A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	1,150.60	1 PC	By 1,150.60	✓
2 REAR BUMPER RH REFLECTOR	45.00	1 PC	cm 45.00	✓
3 REAR BUMPER RH REFLECTOR GARNISH	45.30	1 PC	bd 45.30	✓
4 REAR BUMPER TOW COVER	16.50	1 PC	ms 16.50	✓
5 REAR BUMPER CLIPS	3.90	10 PCS	ms 39.00	✓
6 REAR BUMPER RH LOWER COVER	76.10	1 PC	pd 76.10	✓
7 REAR BUMPER RH LOWER COVER CLIPS	3.90	5 PCS	ms 19.50	✓
8 REAR TAILGATE	1,193.30	1 PC	By 1,193.30	✓
9 TAILGATE LOGO	38.00	1 PC	ms 38.00	✓
10 TAILGATE EMBLEM (SHUTTLE)	55.00	1 PC	ms 55.00	✓
11 TAILGATE INNER LOCK	151.80	1 PC	pd 151.80	✓
12 TAILGATE INNER RUBBER	168.50	1 PC	Dis/pd 168.50	✓
13 REAR WINDSCREEN GLASS MOULDING	151.90	1 PC	ms 151.90	✓
14 REAR PANEL	560.80	1 PC	By 560.80	✓
15 REAR PANEL INNER TOP GARNISH	155.50	1 PC	pd 155.50	✓
16 REAR SPARE TYRE COMPARTMENT	956.00	1 PC	By 956.00	✓
17 REAR SPARE TYRE TOP BOARD	655.00	1 PC	655.00	✓
18 REAR EXHAUST PIPE	745.00	1 PC	By 745.00	✓
19 REAR RH REFLECTOR	395.80	1 PC	cm 395.80	✓
20 TAILLAMP RH	520.50	1 PC	cm 520.50	✓
21 TAILGATE OUTER MOULDING	383.60	1 PC	ms 383.60	✓
			7,522.70	
Less 20%			1,504.54	6,018.16
Special Net				
22 REAR WINDSCREEN GLASS GUM	40.00	1 PC	ms 40.00	✓
23 REVERSE SENSOR	200.00	1 SET	short 200.00	✓
24 REAR NUMBER PLATE	45.00	1 PC	pd 45.00	✓
			285.00	285.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/WL

Claim Type: Third Party

Accident Date: 24/10/2018

TP Veh Reg No: SKH8964T

Estimate No: ES1891219/WL

Date: 24 Oct 2018

Policy No: 5102699584

Veh Reg No: SLD7335A

Make/Model: HONDA SHUTTLE 1.5G
A

Chassis No: GK81005321

Engine No: L15B3536235

Reg. Date: 28/06/2016

Estimate Repair Cost to Vehicle No :SLD7335A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
25 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
26 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REFLECTORS, TOP SPOILER, REAR WIPER ARM, TAILLAMP, TO CUT, WELD & RENEW REAR PANEL, REAR SPARE TYRE COMPARTMENT, STRAIGHTEN, KNOCK & REPAIR REAR BOTH FENDERS, REAR BOTH CHASSIS & REALIGN THE SAME	1,700.00	1 LA	1,700.00	1400
27 REMOVE & REFIX REAR UNDER CARRIAGE, REAR EXHAUST PIPE	250.00	1 LA	250.00	200
28 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, TAILGATE, REAR BUMPER, REAR FENDER	1,300.00	1 LA	1,300.00	1080
29 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	60.00	1 LA	60.00	✓
30 RUSTPROOFING	90.00	1 LA	90.00	✓
31 REMOVE & REFIX SEAT, CARPET, GARNISH, ETC	100.00	1 LA	100.00	80
			3,620.00	3,620.00
Total				S\$ 9,923.16
Add GST @ 7%				694.62
Total Amount Payable				S\$ 10,617.78

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLD7335A

SUPP 1

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1891219/WL

Date: 27 Oct 2018

Policy No: 5102699584

Veh Reg No: SLD7335A

Make/Model: HONDA SHUTTLE 1.5G

A

Chassis No: GK81005321

Engine No: L15B3536235

Reg. Date: 28/06/2016

WS Ref: TP/AXA/WL

Claim Type: Third Party

Accident Date: 24/10/2018

TP Veh Reg No: SKH8964T

Estimate Repair Cost to Vehicle No :SLD7335A

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 REAR LH FENDER INNER GARNISH	455.60	1 PC	455.60	
2 TAILLAMP PANELS	210.00	2 PCS	420.00	
3 smart key sensor			875.60	
		Less 20%	175.12	700.48
Total				S\$ 700.48
GST Amount				S\$ 49.03
Total Amount Payable				S\$ 749.51

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

875.60
72.30

947.90
189.58

Less 20%

758.32