

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1213/2018/PH
Date : 241/10/2018

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tin Pei Ling
Address : 9 Mount Faber Road
#02-05 The Pearl
Singapore 099208
Telephone : HP +65 97324904
Type of Claim : Own Damage Claim
Policy No. : 1800007839
Vehicle No : **SLW 2909 C**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Feb-18
Engine No : CHZ 417559
Chassis No : WAUZZZ8V7J1035998
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Oct-18
Place of Accident : OUTSIDE CARRIBEAM @ KEPPEL BAY

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2909 C .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid.Check function.	S/N \$ 280.00 ✓	
2	To carry out first measurement on car-o-liner	S/N \$ 800.00 ✓	
3	To renew rhs 1/4 glass and rear windscreen.	S/N \$ 600.00 ✓	
4	To remove and transfer front wire harness for headlights,horns,fog lamps,outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
5	To remove and transfer front and rear door's multi-lock systems and power window devices.Inspect for damages and renew if necessary.	S/N \$ 720.00 ✓	
6	To remove and reinstall rhs front seat assy,ABCD pillar trims,floor carpets,electronic components and fuse trays.	S/N \$ 1,400.00 ✓	
7	To dislodge and reinstall rear wire harness for lights,battery manager,fuse and relay trays,electrical and audio equipment.Inspect for damage and renew where necessary.	S/N \$ 1,400.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 5,560.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2909 C .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
8	To remove and reinstall rear seat,back rest,hatch tray,abcd pillar trims,luggage compartment trims,rear seat belts.	S/N \$ 1,400.00	✓
9	To remove and reinstall centre console,renew airbag control unit,roof liner,both curtain airbaqs,and both front seat belts.	S/N \$ 2,800.00	✓
10	To renew driver seat air bag and leather cover.	S/N \$ 800.00	✓
11	To remove and reinstall front suspension for car-o-liner repairs.	S/N \$ 2,400.00	✓
12	To remove and reinstall rear exhaust silencer assy,rear suspension assy and fuel tank,for car-o-liner repairs.	S/N \$ 2,800.00	✓
13	To place vehicle on car-o-liner.	S/N \$ 1,800.00	✓
14	To dismantle front and rear bumpers,rhs front fender,rhs front and rear doors and rear lid.Inspect rhs floor pan for damages.Cut out andweld rhs B-pillar,inner reinforcements,sill panel and rhs rear	\$ 12,600.00 6500 .	
SUB TOTAL LABOUR CHARGES		: \$ 24,600.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2909 C .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
✓✓ 15	To respray front bumper, rhs front fender and rear doors, door handles, rhs B pillar, sill panel, door entrances, inner reinforcements, rhs rear fender, drain panel, roof channel and end panelling. To carry out joint sealer works and stone chip treatment. + 1 (miscellaneous)	\$ 8,500.00	4340. 4000 8 panel 2 Handle 170. 2 Hinge 170.
16	To renew lhs front rim and tyre and carry out wheel alignment.	S/N \$ 280.00 ✓	
17	To carry out diagnostic check.	S/N \$ 576.00 ✓ 384.	
TOTAL LABOUR CHARGES		: \$ 39,516.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - RH <i>Repair</i>	\$ 746.00	*
2	BRACKET FOR FENDER - RH	\$ 34.00	*
3	BRACKET FOR FENDER - RH	\$ 24.00	*
4	CLOSING ELEMENT WING - RH	\$ 29.00	*
5	INSULATION FOR FRONT FENDER - RH	\$ 36.00	*
6	WHEEL HOUSING LINER - RH	\$ 151.00	*
7	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>new</i>	\$ 77.00	*
8	FRONT DOOR - RH <i>Distorted</i>	\$ 2,190.00	✓
9	OUTER DOOR SEAL - FRONT RH <i>new</i>	\$ 139.00	✓
10	BONDING AGENT ?	\$ 43.00	?
11	CLEANING SOLUTION ?	\$ 64.00	?
12	ATTACHMENT PARTS FOR DOOR ?	\$ 206.00	?
13	DOOR HINGE HALF-UPPER PART - RH UPPER	\$ 72.00	+
14	DOOR HINGE HALF - LOWER PART - RH UPPER	\$ 44.00	✓
15	DOOR HINGE HALF - UPPER PART - RH LOWER	\$ 108.00	✓
16	DOOR HINGE HALH - LOWER PART	\$ 44.00	*
17	DOOR CATCH <i>new</i>	\$ 92.00	+
18	COVER FOR DOOR CATCH <i>new</i>	\$ 13.00	+
19	DOOR SEAL, INNER ?	\$ 139.00	?
20	SECURING BRACKET DOOR PANEL ?	\$ 11.00	?
21	DOOR HANDLE, EXTERIOR PRIMED <i>new</i>	\$ 207.00	✓
SUB - TOTAL SPARE PARTS		\$ 4,469.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
22	DOOR HANDLE CAP- RH <i>new</i>	\$ 26.00	X
23	SLIDE VALVE - RH <i>new</i>	\$ 11.00	f
24	SENSOR FOR DOOR HANDLE <i>new</i>	\$ 200.00	f
25	FRONT DOOR LOCK CYLINDER - RH ?	\$ 457.00	?
26	MOUNTING BAR <i>new</i>	\$ 143.00	f
27	BOWDEN CABLE <i>new</i>	\$ 48.00	f
28	FRONT DOOR LOCK - RH ?	\$ 466.00	?
29	DOOR LOCK COVER - <i>new</i>	\$ 13.00	f
30	STRIKER ?	\$ 57.00	?
31	UNDERLAY ?	\$ 30.00	?
32	BOWDEN CABLE <i>new</i>	\$ 34.00	f
33	COVER FOR DOOR INNER PANEL - RH ?	\$ 22.00	?
34	WINDOW GUIDE - RH ?	\$ 365.00	?
35	TRIM STRIP FOR WINDOW GUIDE HIGH CHROME ?	\$ 222.00	?
36	WINDOW APERTURE SEAL - RH INNER ?	\$ 113.00	?
37	TRIM FOR B PILLAR BLACK GLOSSY - RH <i>new</i>	\$ 85.00	f
38	WINDOW SLOT SEAL WITH TRIM STRIP CHROME <i>new cut</i>	\$ 268.00	f
39	WINDOW LIFTER W/O MOTOR ?	\$ 232.00	?
40	WINDOW MOTOR ?	\$ 212.00	?
SUB TOTAL SPARE PARTS		\$ 3,004.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	FRONT DOOR CONBTROL UNIT - RH <i>new</i>	\$ 438.00	+
42	COVER - SATIN BLACK - RH <i>new</i>	\$ 15.00	+
43	COVER ?	\$ 11.00	?
44	ADHESIVE TAPE <i>new</i>	\$ 55.00	✓
45	DOOR PANEL SOUL (BLACK) - RH ?	\$ 1,577.00	?
46	SWITCH MOUNTING - RH ?	\$ 80.00	?
47	ARM REST RH PLASTIC <i>new</i>	\$ 443.00	+
48	TRIM FOR DOOR WINDOW FRAME - RH <i>new</i>	\$ 97.00	+
49	WIRING HARDNESS FOR DOOR TRIM PANEL <i>new</i>	\$ 550.00	+
50	DOOR WINDOW - FRONT RH <i>new</i>	\$ 204.00	+
51	REAR DOOR - LH <i>Distalad</i>	\$ 2,190.00	✓
52	REAR DOOR OUTER SEAL - RH <i>new</i>	\$ 139.00	✓
53	BONDING AGENT ?	\$ 43.00	?
54	CLEANING SOLUTION?	\$ 64.00	?
55	DOOR HINGE HALF - UPPER PART - RH UPPER	\$ 72.00	✓
56	DOOR HINGE HALF - LOWER PART - RH UPPER	\$ 44.00	✓
57	DOOR HINGE HALF - UPPER PART - RH LOWER	\$ 108.00	✓
58	DOOR HINGE HALF - LOWER PART - RH LOWER	\$ 72.00	✓
59	SOUND ABSORBER <i>new</i>	4 \$ 432.00	✓
60	DOOR CATCH <i>new</i>	\$ 82.00	✓
SUB TOTAL SPARE PARTS		\$ 6,716.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	COVER FOR DOOR CATCH <i>eng</i>	\$ 14.00	✓
62	DOOR SEAL, INNER ?	\$ 165.00	?
63	DOOR HANDLE, PRIMED - RH REAR <i>cut</i>	\$ 207.00	✓
64	SLIDE VALVE <i>new</i>	\$ 11.00	+
65	HOUSING PRIMED - RH <i>new</i>	\$ 26.00	+
66	MOUNTING BAR <i>new</i>	\$ 143.00	+
67	BOWDEN CABLE <i>new</i>	\$ 48.00	+
68	DOOR LOCK - RH REAR ?	\$ 473.00	?
69	STRIKER <i>new</i>	\$ 57.00	+
70	UNDERLAY <i>new</i>	\$ 30.00	+
71	BOWDEN CABLE <i>new</i>	\$ 34.00	+
72	COVER FOR DOOR INNER PANEL - RH ?	\$ 22.00	?
73	WINDOW LIFTER W/O MOTOR - REAR RH ?	\$ 220.00	?
74	WINDOW MOTOR - REAR RH ?	\$ 230.00	?
75	DOOR CONTROL UNIT <i>new</i>	\$ 363.00	+
76	GUIDE RAIL - REAR RH ?	\$ 45.00	?
77	WINDOW GUIDE - REAR RH ?	\$ 365.00	?
78	TRIM STRIP FOR WINDOW GUIDE HIGH CHROME - LH <i>new</i>	\$ 193.00	+
79	TRIM STRIP FOR WINDOW GUIDE - HIGH CHROME <i>new</i>	\$ 193.00	+
80	WINDOW APERTURE SEAL - RH INNER ?	\$ 97.00	?
SUB TOTAL SPARE PARTS		\$ 2,936.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	B PILLAR TRIM COVER - RH REAR <i>new</i>	\$ 101.00	X
82	C PILLAR TRIM COVER - RH <i>new</i>	\$ 101.00	X.
83	WINDOW SLOT SEAL WITH TRIM STRIP CHROME - REAR RH <i>lit</i>	\$ 256.00	✓
84	DOOR PANEL SOUL (BLACK)/MAROON BROWN ?	\$ 1,430.00	?
85	ARM REST - RH PLASTIC <i>new</i>	\$ 443.00	X
86	SWITCH MOUNTING SOUL(BLACK) <i>new</i>	\$ 80.00	X
87	SOUND ABSORBER FOR DOOR TRIM PANEL <i>new</i>	\$ 92.00	X.
88	LOUD SPEAKER TRIM CHESTNUT BROWN - RH ?	\$ 40.00	?
89	TRIM INSERT SILVER FLEX METALLIC - RH <i>new</i>	\$ 135.00	X
90	TRIM FOR DOOR WINDOW FRAME SOUL(BLACK) - RH <i>new</i>	\$ 97.00	X
91	REAR LIGHT REFLECTOR - RED REAR <i>new</i>	\$ 18.00	X.
92	INNER ACTUATOR - RH ?	\$ 145.00	?
93	FIBRE OPTIC CONDUCTOR - RH ?	\$ 52.00	?
94	STICKER WITH FOR AIR BAG/CHILD'S SEAT <i>new</i>	\$ 21.00	✓
95	DATA PLATE FOR TYRE PRESSURE <i>new</i>	\$ 25.00	✓
96	DATA TAG (SILVER) ?	\$ 406.00	?
97	DOOR WINDOW - REAR RH <i>new</i>	\$ 204.00	X
98	SIDE PART - RH <i>Distorted</i>	\$ 3,190.00	✓
99	B PILLAR, INNER FRAME- RH ?	\$ 831.00	?
100	CLOSING ELEMENT - RH ?	\$ 461.00	?
SUB TOTAL SPARE PARTS		\$ 8,128.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
101	B PILLAR PLATE - RH ?	\$ 13.00	7
102	SIDE MEMBER - RH ?	\$ 353.00	7
103	SOUND ABSORBER FOR SIDE MEMBER - RH ?	2 \$ 22.00	7
104	GUIDE SECTION - LH/RH <i>neu</i>	2 \$ 28.00	7
105	LOCKING MECHANISM <i>neu</i>	2 \$ 50.00	*
106	RH REAR 1/4 GLASS <i>neu</i>	\$ 502.00	✓
107	REAR WINDSCREEN <i>neu</i>	\$ 704.00	✓
108	PRIMER <i>neu</i>	2 \$ 38.00	✓
109	FRONT BUMPER <i>Rehnd</i>	\$ 1,739.00	✓
110	GUIDE SECTION - RH <i>neu</i>	\$ 33.00	7
111	AIR GUIDE GRILLE - SATIN BLACK <i>cut</i>	\$ 164.00	✓
112	LED HEADLIGHT - RH <i>cut</i>	\$ 4,888.00	✓
113	1/4 GLASS SEALANT	S/N \$ 100.00	✓
114	REAR WINDSCREEN SEALANT	S/N \$ 200.00	✓
115	ARCYLIC SEALANT	S/N \$ 360.00	✓
116	CAVITY WAX	S/N \$ 280.00	✓
117	STONE CHIP TREATMENT	S/N \$ 180.00	✓
118	METAL FILLER POWDER	S/N \$ 280.00	✓
119	HEAD AIR BAG UNIT - LH <i>Activated</i>	\$ 1,692.00	✓
120	HEAD AIR BAG UNIT - RH <i>Activated</i>	\$ 1,692.00	✓
SUB TOTAL SPARE PARTS		\$ 13,318.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
121	SIDE AIR BAG UBIT - FRONT RH <i>Activated</i>	\$ 1,378.00	✓
122	CRASH SENSOR FOR AIR BAG	\$ 239.00	✓
123	PRESSURE SENSOR <i>} Activated</i>	\$ 145.00	✓
124	CONTROL UNIT FOR AIR BAG	\$ 1,538.00	✓
125	BACKREST COVER(LEATHER) CHESTNUT BROWN - RH <i>torn</i>	\$ 1,933.00	✓
126	SEAT BELT - LH <i>} Activated</i>	\$ 956.00	✓
127	SEAT BELT - RH	\$ 956.00	✓
128	SEAT BELT HEIGHT ADJUSTER ?	2 \$ 343.00	?
129	A PILLAR TRIM ROCK GREY - LH / RH ?	2 \$ 282.00	?
130	SILL TRIM STRIP - RH INNER <i>new</i>	\$ 183.00	✗
131	B-PILLAR TRIM SOUL(BLACK) <i>new</i>	\$ 102.00	✗
132	B-PILLARTRIM ROCK GREY -RH UPPER <i>new</i>	\$ 190.00	✗
133	WHEEL HOUSING TRIM SOUL(BLACK) <i>new</i>	\$ 93.00	✗
134	MOULDED HEADLINER <i>crumpled</i>	\$ 1,551.00	✓
135	GRAB HANDLE,FOLDING - FRONT <i>} new</i>	2 \$ 248.00	✗
136	GRAB HANDLE,FOLDING - REAR LH/RH	2 \$ 248.00	✗
137	ALUMINIUM RIM - LH FRONT <i>new</i>	\$ 659.00	✓
138	SEAT FRAME TRIM SOUL(BLACK) <i>new</i>	\$ 142.00	✗
139	SUNDRIES ?	\$ 2,000.00	?
TOTAL SPARE PARTS		:	\$ 51,757.00
TOTAL LABOUR CHARGES		:	\$ 39,516.00
GRAND TOTAL		:	\$ 91,273.00

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Ling*
Surveyed Date : *25/10/18.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 28 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant