

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	FRONT DOOR CONBTROL UNIT - RH <i>new</i>	\$ 438.00	+
42	COVER - SATIN BLACK - RH <i>new</i>	\$ 15.00	+ 12.32
43	COVER <i>new</i>	\$ 11.00	? 8.72
44	ADHESIVE TAPE <i>new</i>	\$ 55.00	✓ 44.64
45	DOOR PANEL SOUL (BLACK) - RH <i>Delivered</i>	\$ 1,577.00	? 1261.60
46	SWITCH MOUNTING - RH <i>not new</i>	\$ 80.00	? X
47	ARM REST RH PLASTIC <i>new</i>	\$ 443.00	+
48	TRIM FOR DOOR WINDOW FRAME - RH <i>new</i>	\$ 97.00	+
49	WIRING HARDNESS FOR DOOR TRIM PANEL <i>new</i>	\$ 550.00	+
50	DOOR WINDOW - FRONT RH <i>not new</i>	\$ 204.00	+
51	REAR DOOR - LH <i>Disturbed</i>	\$ 2,190.00	✓ 1752
52	REAR DOOR OUTER SEAL - RH <i>new</i>	\$ 139.00	✓ 111.20
53	BONDING AGENT <i>new</i>	\$ 43.00	? X
54	CLEANING SOLUTION <i>new</i>	\$ 64.00	? X
55	DOOR HINGE HALF - UPPER PART - RH UPPER	\$ 72.00	✓ 56.88
56	DOOR HINGE HALF - LOWER PART - RH UPPER	\$ 44.00	✓ 86
57	DOOR HINGE HALF - UPPER PART - RH LOWER	\$ 108.00	✓ 86
58	DOOR HINGE HALF - LOWER PART - RH LOWER	\$ 72.00	✓ 56.88
59	SOUND ABSORBER <i>new</i>	4 \$ 432.00	✓ 345.60
60	DOOR CATCH <i>new</i>	\$ 82.00	✓ 67.92
SUB TOTAL SPARE PARTS		\$ 6,716.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	COVER FOR DOOR CATCH <i>eng</i>	\$ 14.00 ✓	11.04
62	DOOR SEAL, INNER <i>But</i>	\$ 165.00 ?	138.80
63	DOOR HANDLE, PRIMED - RH REAR <i>cut</i>	\$ 207.00 ✓	165.60
64	SLIDE VALVE <i>new</i>	\$ 11.00 *	
65	HOUSING PRIMED - RH <i>new</i>	\$ 26.00 *	
66	MOUNTING BAR <i>new Darg d.</i>	\$ 143.00 +	114
67	BOWDEN CABLE <i>new</i>	\$ 48.00 +	
68	DOOR LOCK - RH REAR <i>Not new</i>	\$ 473.00 ? X	
69	STRIKER <i>new</i>	\$ 57.00 +	
70	UNDERLAY <i>new</i>	\$ 30.00 +	
71	BOWDEN CABLE <i>new</i>	\$ 34.00 +	
72	COVER FOR DOOR INNER PANEL - RH <i>Not new</i>	\$ 22.00 ? X	
73	WINDOW LIFTER W/O MOTOR - REAR RH <i>Not new</i>	\$ 220.00 ? X	
74	WINDOW MOTOR - REAR RH <i>Not new</i>	\$ 230.00 ? X	
75	DOOR CONTROL UNIT <i>new</i>	\$ 363.00 +	
76	GUIDE RAIL - REAR RH <i>Not new</i>	\$ 45.00 ? X	
77	WINDOW GUIDE - REAR RH <i>Not new</i>	\$ 365.00 ? X	
78	TRIM STRIP FOR WINDOW GUIDE HIGH CHROME - LH <i>new</i>	\$ 193.00 +	
79	TRIM STRIP FOR WINDOW GUIDE - HIGH CHROME <i>Not new</i>	\$ 193.00 +	
80	WINDOW APERTURE SEAL - RH INNER <i>Not new</i>	\$ 97.00 ? X	
SUB TOTAL SPARE PARTS		\$ 2,936.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	B PILLAR TRIM COVER - RH REAR <i>new</i>	\$ 101.00	X
82	C PILLAR TRIM COVER - RH <i>new</i>	\$ 101.00	X
83	WINDOW SLOT SEAL WITH TRIM STRIP CHROME - REAR RH <i>Lot</i>	\$ 256.00	✓ 3CH40
84	DOOR PANEL SOUL (BLACK)/MAROON BROWN <i>Re-laminated</i>	\$ 1,430.00	? 11144
85	ARM REST - RH PLASTIC <i>new</i>	\$ 443.00	X
86	SWITCH MOUNTING SOUL(BLACK) <i>new</i>	\$ 80.00	X
87	SOUND ABSORBER FOR DOOR TRIM PANEL <i>new</i>	\$ 92.00	X
88	LOUD SPEAKER TRIM CHESTNUT BROWN - RH <i>new</i>	\$ 40.00	? X
89	TRIM INSERT SILVER FLEX METALLIC - RH <i>new</i>	\$ 135.00	X
90	TRIM FOR DOOR WINDOW FRAME SOUL(BLACK) - RH <i>new</i>	\$ 97.00	X
91	REAR LIGHT REFLECTOR - RED REAR <i>new</i>	\$ 18.00	X
92	INNER ACTUATOR - RH <i>new</i>	\$ 145.00	? X
93	FIBRE OPTIC CONDUCTOR - RH <i>new</i>	\$ 52.00	? X
94	STICKER WITH FOR AIR BAG/CHILD'S SEAT <i>new</i>	\$ 21.00	✓ 17.76
95	DATA PLATE FOR TYRE PRESSURE <i>new</i>	\$ 25.00	✓ 19.76
96	DATA TAG (SILVER) <i>new</i>	\$ 406.00	? X
97	DOOR WINDOW - REAR RH <i>new</i>	\$ 204.00	X
98	SIDE PART - RH <i>Distorted</i>	\$ 3,190.00	✓ 3552
99	B PILLAR, INNER FRAME- RH <i>Best</i>	\$ 831.00	? 1664.40
100	CLOSING ELEMENT - RH <i>new</i>	\$ 461.00	? X
SUB TOTAL SPARE PARTS		\$ 8,128.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
101	B PILLAR PLATE - RH <i>new</i>	\$ 13.00	7 <i>9.68</i>
102	SIDE MEMBER - RH <i>new</i>	\$ 353.00	7 <i>IX</i>
103	SOUND ABSORBER FOR SIDE MEMBER - RH <i>new</i>	2 \$ 22.00	7 <i>IX</i>
104	GUIDE SECTION - LH/RH <i>new</i>	2 \$ 28.00	<i>X</i>
105	LOCKING MECHANISM <i>new</i>	2 \$ 50.00	<i>X</i>
106	RH REAR 1/4 GLASS <i>new</i>	\$ 502.00	<i>✓</i> <i>401.20</i>
107	REAR WINDSCREEN <i>new</i>	\$ 704.00	<i>✓</i> <i>563.20</i>
108	PRIMER <i>new</i>	2 \$ 38.00	<i>✓</i> <i>29.76</i>
109	FRONT BUMPER <i>Rehd</i>	\$ 1,739.00	<i>✓</i> <i>1391.20</i>
110	GUIDE SECTION - RH <i>new</i>	\$ 33.00	<i>X</i>
111	AIR GUIDE GRILLE - SATIN BLACK <i>lot</i>	\$ 164.00	<i>✓</i> <i>131.20</i>
112	LED HEADLIGHT - RH <i>lot</i>	\$ 4,888.00	<i>✓</i> <i>3912.40</i>
113	1/4 GLASS SEALANT	S/N \$ 100.00	<i>✓</i> <i>100</i>
114	REAR WINDSCREEN SEALANT	S/N \$ 200.00	<i>✓</i> <i>200</i>
115	ARCYLIC SEALANT	S/N \$ 360.00	<i>✓</i> <i>360</i>
116	CAVITY WAX	S/N \$ 280.00	<i>✓</i> <i>280</i>
117	STONE CHIP TREATMENT	S/N \$ 180.00	<i>✓</i> <i>180</i>
118	METAL FILLER POWDER	S/N \$ 280.00	<i>✓</i> <i>280</i>
119	HEAD AIR BAG UNIT - LH <i>Activated</i>	\$ 1,692.00	<i>✓</i> <i>1353.60</i>
120	HEAD AIR BAG UNIT - RH <i>Activated</i>	\$ 1,692.00	<i>✓</i> <i>1353.60</i>
SUB TOTAL SPARE PARTS		\$ 13,318.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
121	SIDE AIR BAG UBIT - FRONT RH <i>Activated</i>	\$ 1,378.00 ✓	1102.40
122	CRASH SENSOR FOR AIR BAG	\$ 239.00 ✓	190.80
123	PRESSURE SENSOR <i>} Activated</i>	\$ 145.00 ✓	116
124	CONTROL UNIT FOR AIR BAG	\$ 1,538.00 ✓	1230.40
125	BACKREST COVER(LEATHER) CHESTNUT BROWN - RH <i>torn</i>	\$ 1,933.00 ✓	1546.40
126	SEAT BELT - LH <i>} Activated</i>	\$ 956.00 ✓	764.80
127	SEAT BELT - RH	\$ 956.00 ✓	764.80
128	SEAT BELT HEIGHT ADJUSTER <i>Buy d</i>	2 \$ 343.00 ?	1137.20
129	A PILLAR TRIM ROCK GREY - LH / RH <i>201 ne</i>	2 \$ 282.00 ?	X
130	SILL TRIM STRIP - RH INNER <i>ne w</i>	\$ 183.00 *	146.40
131	B-PILLAR TRIM SOUL(BLACK) <i>ne w</i>	\$ 102.00 *	
132	B-PILLARTRIM ROCK GREY -RH UPPER <i>ne w</i>	\$ 190.00 *	
133	WHEEL HOUSING TRIM SOUL(BLACK) <i>ne w</i>	\$ 93.00 *	
134	MOULDED HEADLINER <i>crumpled</i>	\$ 1,551.00 ✓	1240.80
135	GRAB HANDLE,FOLDING - FRONT <i>} ne w</i>	2 \$ 248.00 *	
136	GRAB HANDLE,FOLDING - REAR LH/RH	2 \$ 248.00 *	
137	ALUMINIUM RIM - LH FRONT <i>cut</i>	\$ 659.00 ✓	527.20
138	SEAT FRAME TRIM SOUL(BLACK) <i>ne w</i>	\$ 142.00 *	
139	SUNDRIES <i>214/</i>	\$ 2,000.00 ?	84.95
TOTAL SPARE PARTS		: \$ 51,757.00	
TOTAL LABOUR CHARGES		: \$ 39,516.00	
GRAND TOTAL		: \$ 91,273.00	91,405

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

91298 76

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King.
Surveyed Date : 25/10/18. ✓
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 28 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 29 October 2018 11:27 AM
To: 'Fong, Andy-SY'
Cc: Olivia Lau (LKKAUTO); Bryan Ang (LKKAUTO); Simon Ho (LKKAUTO); SUR
Subject: RE: [AIG]: SLW2909C/ OD / 5937930288SG / DOA 22 OCT 2018

Dear Andy,

We have clarify with repairer, the price for both Rear RH door and Rear LH door is correct.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Sent: Monday, 29 October 2018 10:47 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>; Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: [AIG]: SLW2909C/ OD / 5937930288SG / DOA 22 OCT 2018

Hi Veron

Thank you for your clarification. May you please assist to check with repairer that the list price for both Rear RH door and Rear LH door is the same as our internal system reflects otherwise.

Andy Fong
AIG
Claims Technical Control Manager
Singapore | Hong Kong
AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1708|M: +(65) 9138 1785
Andy-SY.Fong@AIG.com | www.AIG.com.sg

Follow us:



Get up to 15% OFF your AIG vehicle insurance premium and stand a chance to win amazing prizes when you download AIG On the Go [now!](#)

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Monday, October 29, 2018 10:35 AM
To: Fong, Andy-SY

Cc: Olivia Lau (LKKAUTO); Bryan Ang (LKKAUTO); Simon Ho (LKKAUTO); SUR
Subject: RE: [AIG]: SLW2909C/ OD / 5937930288SG / DOA 22 OCT 2018

Dear Andy,

Thank you for the email.

It should have been the rear RH door instead of the rear LH door.

Referring to photos No 30-No 32, the front LH rim sustained fresh cut marks and judging from the recorded statement and narrates that after impact, vehicle spun and landed 20-50 metres away, it is very likely that the damages to the front LH rim is due to the accident.

Best Regards,

Veron Chen | Case Handler on Behalf of Adrian Ling

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Olivia Lau (LKKAUTO)

Sent: Sunday, 28 October 2018 3:30 PM

To: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: [AIG]: SLW2909C/ OD / 5937930288SG / DOA 22 OCT 2018

----- Forwarded message -----

From: Fong, Andy-SY <Andy-SY.Fong@aig.com>

Date: 28 Oct 2018, 10:27 AM +0800

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>

Cc: Nora Khai <nora.khai@premiumauto.com.sg>, Celine Fong (LKKAUTO) <celinefong@lkkauto.com>, Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>, Koh, Victor-CK <Victor-CK.Koh@aig.com>

Subject: SLW2909C/ OD / 5937930288SG / DOA 22 OCT 2018

Adrian

I was reviewing captioned mandate request and will like to seek some clarity from you before we can allow repairs to commence. Insured was travelling straight when third party struck insured's right portion, insured spun and vehicle landed a distant away.

Part. No. 51 – Rear Door LH. Consistent to accident? No damage photos on rear door LH for our review.
Or is it a typo? If it is typo and should be rear door RH, then please confirm price is same.

Part. No. 137 – Aluminum Rim LH Front – Consistent to accident?

Please assist to clarify before we can advice.

Thanks

Andy Fong

AIG

Claims Technical Control Manager

Singapore | Hong Kong

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel: +(65) 6419 1708 | M: +(65) 9138 1785

Andy-SY.Fong@AIG.com | www.AIG.com.sg

Follow us:



Get up to 15% OFF your AIG vehicle insurance premium and stand a chance to win amazing prizes when you download AIG On the Go [now!](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 29 October 2018 10:35 AM
To: Fong, Andy-SY
Cc: Olivia Lau (LKKAUTO); Bryan Ang (LKKAUTO); Simon Ho (LKKAUTO); SUR
Subject: RE: [AIG]: SLW2909C/ OD / 5937930288SG / DOA 22 OCT 2018

Dear Andy,

Thank you for the email.

It should have been the rear RH door instead of the rear LH door.

Referring to photos No 30-No 32, the front LH rim sustained fresh cut marks and judging from the recorded statement and narrates that after impact, vehicle spun and landed 20-50 metres away, it is very likely that the damages to the front LH rim is due to the accident.

Best Regards,

Veron Chen | Case Handler on Behalf of Adrian Ling

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Olivia Lau (LKKAUTO)
Sent: Sunday, 28 October 2018 3:30 PM
To: Bryan Ang (LKKAUTO) <bryanang@lkkauto.com>; Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: [AIG]: SLW2909C/ OD / 5937930288SG / DOA 22 OCT 2018

----- Forwarded message -----

From: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Date: 28 Oct 2018, 10:27 AM +0800
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>
Cc: Nora Khai <nora.khai@premiumauto.com.sg>, Celine Fong (LKKAUTO) <celinefong@lkkauto.com>, Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>, Koh, Victor-CK <Victor-CK.Koh@aig.com>
Subject: SLW2909C/ OD / 5937930288SG / DOA 22 OCT 2018

Adrian

I was reviewing captioned mandate request and will like to seek some clarity from you before we can allow repairs to commence. Insured was travelling straight when third party struck insured's right portion, insured spun and vehicle landed a distant away.

Part. No. 51 – Rear Door LH. Consistent to accident? No damage photos on rear door LH for our review.
Or is it a typo? If it is typo and should be rear door RH, then please confirm price is same.

Part. No. 137 – Aluminum Rim LH Front – Consistent to accident?

Please assist to clarify before we can advice.

Thanks

Andy Fong

AIG

Claims Technical Control Manager

Singapore | Hong Kong

AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel: +(65) 6419 1708 | M: +(65) 9138 1785

Andy-SY.Fong@AIG.com | www.AIG.com.sg

Follow us:



Get up to 15% OFF your AIG vehicle insurance premium and stand a chance to win amazing prizes when you download AIG On the Go [now!](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Olivia Lau (LKKAUTO)
Sent: Sunday, 28 October 2018 3:30 PM
To: Bryan Ang (LKKAUTO); Simon Ho (LKKAUTO); SUR
Subject: [AIG]: SLW2909C/ OD / 5937930288SG / DOA 22 OCT 2018

----- Forwarded message -----

From: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Date: 28 Oct 2018, 10:27 AM +0800
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>
Cc: Nora Khai <nora.khai@premiumauto.com.sg>, Celine Fong (LKKAUTO) <celinefong@lkkauto.com>, Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>, Koh, Victor-CK <Victor-CK.Koh@aig.com>
Subject: SLW2909C/ OD / 5937930288SG / DOA 22 OCT 2018

Adrian

I was reviewing captioned mandate request and will like to seek some clarity from you before we can allow repairs to commence. Insured was travelling straight when third party struck insured's right portion, insured spun and vehicle landed a distant away.

Part. No. 51 – Rear Door LH. Consistent to accident? No damage photos on rear door LH for our review. Or is it a typo? If it is typo and should be rear door RH, then please confirm price is same.

Part. No. 137 – Aluminum Rim LH Front – Consistent to accident?

Please assist to clarify before we can advice.

*It should have been the rear RH door
instead of the rear LH door.*

Thanks

Andy Fong

AIG

Claims Technical Control Manager

Singapore | Hong Kong

AIG Asia Pacific Insurance Pte. Ltd.

*Referring to photo 30-32, the
front LH rim sustained fresh cut
marks and judging from the recorded
statement and narrates that after impact,
vehicle spun and landed 20-50 metres away,
it is very likely that the damages to
the front LH rim is due to the accident.*

Tel: +(65) 6419 1708 | M: +(65) 9138 1785

Andy-SY.Fong@AIG.com | www.AIG.com.sg

Follow us:



Get up to 15% OFF your AIG vehicle insurance premium and stand a chance to win amazing prizes when you download AIG On the Go [now!](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - RH <i>Repair</i>	\$	746.00 <i>X</i>
2	BRACKET FOR FENDER - RH	\$	34.00 <i>X</i>
3	BRACKET FOR FENDER - RH	\$	24.00 <i>X</i>
4	CLOSING ELEMENT WING - RH	\$	29.00 <i>X</i>
5	INSULATION FOR FRONT FENDER - RH	\$	36.00 <i>X</i>
6	WHEEL HOUSING LINER - RH	\$	151.00 <i>X</i>
7	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>the new</i>	\$	77.00 <i>X</i>
8	FRONT DOOR - RH <i>Distorted</i>	\$	2,190.00 <i>✓</i>
9	OUTER DOOR SEAL - FRONT RH <i>new</i>	\$	139.00 <i>✓</i>
10	BONDING AGENT <i>?</i>	\$	43.00 <i>?</i>
11	CLEANING SOLUTION <i>?</i>	\$	64.00 <i>?</i>
12	ATTACHMENT PARTS FOR DOOR <i>?</i>	\$	206.00 <i>?</i>
13	DOOR HINGE HALF-UPPER PART - RH UPPER	\$	72.00 <i>X</i>
14	DOOR HINGE HALF - LOWER PART - RH UPPER	\$	44.00 <i>X</i>
15	DOOR HINGE HALF - UPPER PART - RH LOWER	\$	108.00 <i>X</i>
16	DOOR HINGE HALH - LOWER PART	\$	44.00 <i>X</i>
17	DOOR CATCH <i>new</i>	\$	92.00 <i>+</i>
18	COVER FOR DOOR CATCH <i>new</i>	\$	13.00 <i>+</i>
19	DOOR SEAL, INNER <i>? TUES</i>	\$	139.00 <i>?</i>
20	SECURING BRACKET DOOR PANEL <i>?</i>	\$	11.00 <i>?</i>
21	DOOR HANDLE, EXTERIOR PRIMED <i>new</i>	\$	207.00 <i>✓</i>
SUB - TOTAL SPARE PARTS		\$	4,469.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
22	DOOR HANDLE CAP- RH <i>new</i>	S 26.00	<i>X</i>
23	SLIDE VALVE - RH <i>new</i>	S 11.00	<i>X</i>
24	SENSOR FOR DOOR HANDLE <i>new</i>	S 200.00	<i>X</i>
25	FRONT DOOR LOCK CYLINDER - RH ?	S 457.00	<i>?</i>
26	MOUNTING BAR <i>new</i> <i>X</i>	S 143.00	<i>X</i>
27	BOWDEN CABLE <i>new</i>	S 48.00	<i>X</i>
28	FRONT DOOR LOCK - RH ?	S 466.00	<i>?</i>
29	DOOR LOCK COVER - <i>new</i>	S 13.00	<i>X</i>
30	STRIKER ?	S 57.00	<i>?</i>
31	UNDERLAY ?	S 30.00	<i>?</i>
32	BOWDEN CABLE <i>new</i>	S 34.00	<i>X</i>
33	COVER FOR DOOR INNER PANEL - RH ?	S 22.00	<i>?</i>
34	WINDOW GUIDE - RH ?	S 365.00	<i>?</i>
35	TRIM STRIP FOR WINDOW GUIDE HIGH CHROME ?	S 222.00	<i>?</i>
36	WINDOW APERTURE SEAL - RH INNER ?	S 113.00	<i>?</i>
37	TRIM FOR B PILLAR BLACK GLOSSY - RH <i>new</i>	S 85.00	<i>X</i>
38	WINDOW SLOT SEAL WITH TRIM STRIP CHROME <i>new cut</i>	S 268.00	<i>X</i>
39	WINDOW LIFTER W/O MOTOR ?	S 232.00	<i>?</i>
40	WINDOW MOTOR ?	S 212.00	<i>?</i>
SUB TOTAL SPARE PARTS		S 3,004.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
41	FRONT DOOR CONBTROL UNIT - RH <i>new</i>	\$ 438.00	✓
42	COVER - SATIN BLACK - RH <i>new cut</i>	\$ 15.00	✓
43	COVER ?	\$ 11.00	?
44	ADHESIVE TAPE <i>new</i>	\$ 55.00	✓
45	DOOR PANEL SOUL (BLACK) - RH ? <i>new</i>	\$ 1,577.00	?
46	SWITCH MOUNTING - RH ?	\$ 80.00	?
47	ARM REST RH PLASTIC <i>new</i>	\$ 443.00	✓
48	TRIM FOR DOOR WINDOW FRAME - RH <i>new</i>	\$ 97.00	✓
49	WIRING HARDNESS FOR DOOR TRIM PANEL <i>new</i>	\$ 550.00	✓
50	DOOR WINDOW - FRONT RH <i>short new</i>	\$ 204.00	✓
51	REAR DOOR - LH <i>Distalund</i>	\$ 2,190.00	✓
52	REAR DOOR OUTER SEAL - RH <i>new</i>	\$ 139.00	✓
53	BONDING AGENT ?	\$ 43.00	?
54	CLEANING SOLUTION?	\$ 64.00	?
55	DOOR HINGE HALF - UPPER PART - RH UPPER ?	\$ 72.00	✓
56	DOOR HINGE HALF - LOWER PART - RH UPPER	\$ 44.00	✓
57	DOOR HINGE HALF - UPPER PART - RH LOWER	\$ 108.00	✓
58	DOOR HINGE HALF - LOWER PART - RH LOWER	\$ 72.00	✓
59	SOUND ABSORBER <i>new</i>	4 \$ 432.00	✓
60	DOOR CATCH <i>new</i>	\$ 82.00	✓
SUB TOTAL SPARE PARTS		\$ 6,716.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	COVER FOR DOOR CATCH <i>md</i>	\$ 14.00	✓
62	DOOR SEAL, INNER <i>? pur</i>	\$ 165.00	?
63	DOOR HANDLE, PRIMED - RH REAR <i>cut</i>	\$ 207.00	✓
64	SLIDE VALVE <i>see in</i>	\$ 11.00	+
65	HOUSING PRIMED - RH <i>see in</i>	\$ 26.00	+
66	MOUNTING BAR <i>see in</i>	\$ 143.00	+
67	BOWDEN CABLE <i>see in</i>	\$ 48.00	+
68	DOOR LOCK - RH REAR <i>?</i>	\$ 473.00	?
69	STRIKER <i>see in</i>	\$ 57.00	+
70	UNDERLAY <i>see in</i>	\$ 30.00	+
71	BOWDEN CABLE <i>see in</i>	\$ 34.00	+
72	COVER FOR DOOR INNER PANEL - RH <i>?</i>	\$ 22.00	?
73	WINDOW LIFTER W/O MOTOR - REAR RH <i>?</i>	\$ 220.00	?
74	WINDOW MOTOR - REAR RH <i>? by</i>	\$ 230.00	?
75	DOOR CONTROL UNIT <i>see in</i>	\$ 363.00	+
76	GUIDE RAIL - REAR RH <i>?</i>	\$ 45.00	?
77	WINDOW GUIDE - REAR RH <i>?</i>	\$ 365.00	?
78	TRIM STRIP FOR WINDOW GUIDE HIGH CHROME - LH <i>see in</i>	\$ 193.00	+
79	TRIM STRIP FOR WINDOW GUIDE - HIGH CHROME <i>see in</i>	\$ 193.00	+
80	WINDOW APERTURE SEAL - RH INNER <i>?</i>	\$ 97.00	?
SUB TOTAL SPARE PARTS		\$ 2,936.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	B PILLAR TRIM COVER - RH REAR <i>new</i>	\$ 101.00	<i>x</i>
82	C PILLAR TRIM COVER - RH <i>new</i>	\$ 101.00	<i>x</i>
83	WINDOW SLOT SEAL WITH TRIM STRIP CHROME - REAR RH <i>lit</i>	\$ 256.00	<i>✓</i>
84	DOOR PANEL SOUL (BLACK)/MAROON BROWN ? <i>CR4</i>	\$ 1,430.00	<i>?</i>
85	ARM REST - RH PLASTIC <i>new</i>	\$ 443.00	<i>x</i>
86	SWITCH MOUNTING SOUL (BLACK) <i>new</i>	\$ 80.00	<i>x</i>
87	SOUND ABSORBER FOR DOOR TRIM PANEL <i>new</i>	\$ 92.00	<i>x</i>
88	LOUD SPEAKER TRIM CHESTNUT BROWN - RH <i>?</i>	\$ 40.00	<i>?</i>
89	TRIM INSERT SILVER FLEX METALLIC - RH <i>new</i>	\$ 135.00	<i>x</i>
90	TRIM FOR DOOR WINDOW FRAME SOUL (BLACK) - RH <i>new</i>	\$ 97.00	<i>x</i>
91	REAR LIGHT REFLECTOR - RED REAR <i>new</i>	\$ 18.00	<i>x</i>
92	INNER ACTUATOR - RH <i>?</i>	\$ 145.00	<i>?</i>
93	FIBRE OPTIC CONDUCTOR - RH <i>?</i>	\$ 52.00	<i>?</i>
94	STICKER WITH FOR AIR BAG/CHILD'S SEAT <i>new</i>	\$ 21.00	<i>✓</i>
95	DATA PLATE FOR TYRE PRESSURE <i>new</i>	\$ 25.00	<i>✓</i>
96	DATA TAG (SILVER) <i>?</i>	\$ 406.00	<i>?</i>
97	DOOR WINDOW - REAR RH <i>new</i>	\$ 204.00	<i>x</i>
98	SIDE PART - RH <i>Distorted</i>	\$ 3,190.00	<i>✓</i>
99	B PILLAR, INNER FRAME - RH <i>?</i>	\$ 831.00	<i>?</i>
100	CLOSING ELEMENT - RH <i>?</i>	\$ 461.00	<i>?</i>
SUB TOTAL SPARE PARTS		\$ 8,128.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
101	B PILLAR PLATE - RH ?	S	13.00 ?
102	SIDE MEMBER - RH ?	S	353.00 ?
103	SOUND ABSORBER FOR SIDE MEMBER - RH ?	2 S	22.00 ?
104	GUIDE SECTION - LH/RH <i>per</i>	2 S	28.00 ✓
105	LOCKING MECHANISM <i>per</i>	2 S	50.00 ✓
106	RH REAR 1/4 GLASS <i>per</i>	S	502.00 ✓
107	REAR WINDSCREEN <i>Ne</i>	S	704.00 ✓
108	PRIMER <i>on</i>	2 S	38.00 ✓
109	FRONT BUMPER <i>Rehnd</i>	S	1,739.00 ✓
110	GUIDE SECTION - RH <i>per on</i>	S	33.00 ✓
111	AIR GUIDE GRILLE - SATIN BLACK <i>et</i>	S	164.00 ✓
112	LED HEADLIGHT - RH <i>et</i>	S	4,888.00 ✓
113	1/4 GLASS SEALANT	S/N S	100.00 ✓
114	REAR WINDSCREEN SEALANT	S/N S	200.00 ✓
115	ARCYLIC SEALANT	S/N S	360.00 ✓
116	CAVITY WAX	S/N S	280.00 ✓
117	STONE CHIP TREATMENT	S/N S	180.00 ✓
118	METAL FILLER POWDER	S/N S	280.00 ✓
119	HEAD AIR BAG UNIT - LH } <i>Activated</i>	S	1,692.00 ✓
120	HEAD AIR BAG UNIT - RH }	S	1,692.00 ✓
SUB TOTAL SPARE PARTS		S	13,318.00

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
121	SIDE AIR BAG UBIT - FRONT RH <i>Activated</i>	\$ 1,378.00	✓
122	CRASH SENSOR FOR AIR BAG	\$ 239.00	✓
123	PRESSURE SENSOR <i>} Activated</i>	\$ 145.00	✓
124	CONTROL UNIT FOR AIR BAG	\$ 1,538.00	✓
125	BACKREST COVER(LEATHER) CHESTNUT BROWN - RH <i>torn</i>	\$ 1,933.00	✓
126	SEAT BELT - LH <i>} Activated</i>	\$ 956.00	✓
127	SEAT BELT - RH	\$ 956.00	✓
128	SEAT BELT HEIGHT ADJUSTER ?	2 \$ 343.00	?
129	A PILLAR TRIM ROCK GREY - LH / RH ?	2 \$ 282.00	?
130	SILL TRIM STRIP - RH INNER <i>not in</i>	\$ 183.00	✗
131	B-PILLAR TRIM SOUL(BLACK) <i>not in</i>	\$ 102.00	✗
132	B-PILLARTRIM ROCK GREY - RH UPPER <i>not in</i>	\$ 190.00	✗
133	WHEEL HOUSING TRIM SOUL(BLACK) <i>not in</i>	\$ 93.00	✗
134	MOULDED HEADLINER <i>crumpled</i>	\$ 1,551.00	✓
135	GRAB HANDLE,FOLDING - FRONT <i>} not in</i>	2 \$ 248.00	✗
136	GRAB HANDLE,FOLDING - REAR LH/RH	2 \$ 248.00	✗
137	ALUMINIUM RIM - LH FRONT <i>not</i>	\$ 659.00	✓
138	SEAT FRAME TRIM SOUL(BLACK) <i>not in</i>	\$ 142.00	✗
139	SUNDRIES ?	\$ 2,000.00	?
TOTAL SPARE PARTS		\$ 51,757.00	
TOTAL LABOUR CHARGES		\$ 39,516.00	
GRAND TOTAL		\$ 91,273.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Net.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1213/2018/PH 5-Nov-18 Kee Siang 1 of 1 SLW 2909 C Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	BOWDEN CABLE HOLDER <i>Part</i>	\$ 7.00	✓
2	DOOR LOCK COVER <i>replaced</i>	\$ 13.00	✓
3	DOOR COVER <i>replaced</i>	\$ 39.00	✓
4	DOOR END COVER <i>for</i>	\$ 6.00	✓
TOTAL		\$ 58.00	

For Premium Automobiles Pte Ltd

Adrian Ling
HL

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1213/2018/PH
Date : 241/10/2018

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
29 days of repairs - ok - jb -23 Jan

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tin Pei Ling
Address : 9 Mount Faber Road
#02-05 The Pearl
Singapore 099208
Telephone : HP +65 97324904
Type of Claim : Own Damage Claim
Policy No. : 1800007839
Vehicle No : **SLW 2909 C**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Feb-18
Engine No : CHZ 417559
Chassis No : WAUZZZ8V7J1035998
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Oct-18
Place of Accident : OUTSIDE CARRIBEAM @ KEPPEL BAY

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2909 C.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00	\$ 280.00
2	To carry out first measurement on car-o-liner	S/N	\$ 800.00	\$ 800.00
3	To renew rhs 1/4 glass and rear windscreen.	S/N	\$ 600.00	\$ 600.00
4	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
5	To remove and transfer front and rear door's multi-lock systems and power window devices. Inspect for damages and renew if necessary.	S/N	\$ 720.00	\$ 720.00
6	To remove and reinstall rhs front seat assy, ABCD pillar trims, floor carpets, electronic components and fuse trays.	S/N	\$ 1,400.00	\$ 1,400.00
7	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. Inspect for damage and renew where necessary.	S/N	\$ 1,400.00	\$ 1,400.00
SUB TOTAL LABOUR CHARGES		:	\$ 5,560.00	\$ 5,560.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2909 C .

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 5,560.00
8	To remove and reinstall rear seat,back rest,hat tray,abcd pillar trims,luggage compartment trims,rear seat belts.	S/N	\$ 1,400.00	\$ 1,400.00
9	To remove and reinstall centre console,renew airbag control unit,roof liner,both curtain airbags,and both front seat belts.	S/N	\$ 2,800.00	\$ 2,800.00
10	To renew driver seat air bag and leather cover.	S/N	\$ 800.00	\$ 800.00
11	To remove and reinstall front suspension for car-o- liner repairs.	S/N	\$ 2,400.00	\$ 2,400.00
12	To remove and reinstall rear exhaust silencer assy,rear suspension assy and fuel tank,for car-o-liner repairs.	S/N	\$ 2,800.00	\$ 2,800.00
13	To place vehicle on car-o-liner.	S/N	\$ 1,800.00	\$ 1,800.00
14	To dismantle front and rear bumpers,rhs front fender,rhs front and rear doors and rear lid.Inspect rhs floor pan for damages.Cut out andweld rhs B- pillar,inner reinforcements,sill panel and rhs rear fender.Renew all damaged panels.Reinstall all parts removed. (Added \$1000/- for B pillar reinforcement)		\$ 12,600.00	\$ 7,500.00
SUB TOTAL LABOUR CHARGES			\$ 24,600.00	\$ 25,060.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2909 C .

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		c/f		\$ 25,060.00
15	To respray front bumper,rhs front fender and rear doors,door handles,rhs B pillar,sill panel,door entrances,inner reinforcements,rhs rear fender,drain panel,roof channeland end panelling.To carry out joint sealer works and stone chip treatment.		\$ 8,500.00	\$ 4,340.00
16	To renew lhs front rim and tyre and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
17	To carry out diagnostic check.	S/N	\$ 576.00	\$ 384.00
TOTAL LABOUR CHARGES		:	<u>\$ 39,516.00</u>	<u>\$ 30,064.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT FENDER - RH	\$ 746.00	
2	BRACKET FOR FENDER - RH	\$ 34.00	
3	BRACKET FOR FENDER - RH	\$ 24.00	
4	CLOSING ELEMENT WING - RH	\$ 29.00	
5	INSULATION FOR FRONT FENDER - RH	\$ 36.00	
6	WHEEL HOUSING LINER - RH	\$ 151.00	
7	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 77.00	
8	FRONT DOOR - RH	\$ 2,190.00	\$ 1,823.20
9	OUTER DOOR SEAL - FRONT RH	\$ 139.00	\$ 116.80
10	BONDING AGENT	\$ 43.00	\$ 35.92
11	CLEANING SOLUTION	\$ 64.00	
12	ATTACHMENT PARTS FOR DOOR	\$ 206.00	
13	DOOR HINGE HALF-UPPER PART - RH UPPER	\$ 72.00	\$ 56.88
14	DOOR HINGE HALF - LOWER PART - RH UPPER	\$ 44.00	\$ 34.48
15	DOOR HINGE HALF - UPPER PART - RH LOWER	\$ 108.00	\$ 86.00
16	DOOR HINGE HALF - LOWER PART	\$ 44.00	\$ 34.48
17	DOOR CATCH	\$ 92.00	
18	COVER FOR DOOR CATCH	\$ 13.00	
19	DOOR SEAL, INNER	\$ 139.00	\$ 111.20
20	SECURING BRACKET DOOR PANEL	\$ 11.00	
21	DOOR HANDLE, EXTERIOR PRIMED	\$ 207.00	\$ 165.60
SUB - TOTAL SPARE PARTS		\$ 4,469.00	\$ 2,464.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SLW 2909 C .

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Net.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SLW 2909 C.

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Neff.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
			\$ 6,798.80
61	COVER FOR DOOR CATCH	\$ 14.00	\$ 11.04
62	DOOR SEAL, INNER	\$ 165.00	\$ 138.80
63	DOOR HANDLE, PRIMED - RH REAR	\$ 207.00	\$ 165.60
64	SLIDE VALVE	\$ 11.00	
65	HOUSING PRIMED - RH	\$ 26.00	
66	MOUNTING BAR	\$ 143.00	\$ 114.00
67	BOWDEN CABLE	\$ 48.00	
68	DOOR LOCK - RH REAR	\$ 473.00	
69	STRIKER	\$ 57.00	
70	UNDERLAY	\$ 30.00	
71	BOWDEN CABLE	\$ 34.00	
72	COVER FOR DOOR INNER PANEL - RH	\$ 22.00	
73	WINDOW LIFTER W/O MOTOR - REAR RH	\$ 220.00	
74	WINDOW MOTOR - REAR RH	\$ 230.00	
75	DOOR CONTROL UNIT	\$ 363.00	
76	GUIDE RAIL - REAR RH	\$ 45.00	
77	WINDOW GUIDE - REAR RH	\$ 365.00	
78	TRIM STRIP FOR WINDOW GUIDE HIGH CHROME - LH	\$ 193.00	
79	TRIM STRIP FOR WINDOW GUIDE - HIGH CHROME	\$ 193.00	
80	WINDOW APERTURE SEAL - RH INNER	\$ 97.00	
SUB TOTAL SPARE PARTS		\$ 2,936.00	\$ 7,228.24

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 7,228.24
81	B PILLAR TRIM COVER - RH REAR	\$ 101.00	
82	C PILLAR TRIM COVER - RH	\$ 101.00	
83	WINDOW SLOT SEAL WITH TRIM STRIP CHROME - REAR RH	\$ 256.00	\$ 204.40
84	DOOR PANEL SOUL (BLACK)/MAROON BROWN	\$ 1,430.00	\$ 1,144.00
85	ARM REST - RH PLASTIC	\$ 443.00	
86	SWITCH MOUNTING SOUL(BLACK)	\$ 80.00	
87	SOUND ABSORBER FOR DOOR TRIM PANEL	\$ 92.00	
88	LOUD SPEAKER TRIM CHESTNUT BROWN - RH	\$ 40.00	
89	TRIM INSERT SILVER FLEX METALLIC - RH	\$ 135.00	
90	TRIM FOR DOOR WINDOW FRAME SOUL(BLACK) - RH	\$ 97.00	
91	REAR LIGHT REFLECTOR - RED REAR	\$ 18.00	
92	INNER ACTUATOR - RH	\$ 145.00	
93	FIBRE OPTIC CONDUCTOR - RH	\$ 52.00	
94	STICKER WITH FOR AIR BAG/CHILD'S SEAT	\$ 21.00	\$ 17.76
95	DATA PLATE FOR TYRE PRESSURE	\$ 25.00	\$ 19.76
96	DATA TAG (SILVER)	\$ 406.00	
97	DOOR WINDOW - REAR RH	\$ 204.00	
98	SIDE PART - RH	\$ 3,190.00	\$ 2,552.00
99	B PILLAR, INNER FRAME- RH	\$ 831.00	\$ 664.40
100	CLOSING ELEMENT - RH	\$ 461.00	
SUB TOTAL SPARE PARTS		\$ 8,128.00	\$ 11,830.56

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f		\$ 11,830.56
101	B PILLAR PLATE - RH		\$ 13.00	\$ 9.68
102	SIDE MEMBER - RH		\$ 353.00	
103	SOUND ABSORBER FOR SIDE MEMBER - RH	2	\$ 22.00	
104	GUIDE SECTION - LH/RH	2	\$ 28.00	
105	LOCKING MECHANISM	2	\$ 50.00	
106	RH REAR 1/4 GLASS		\$ 502.00	\$ 401.20
107	REAR WINDSCREEN		\$ 704.00	\$ 563.20
108	PRIMER	2	\$ 38.00	\$ 29.76
109	FRONT BUMPER		\$ 1,739.00	\$ 1,391.20
110	GUIDE SECTION - RH		\$ 33.00	
111	AIR GUIDE GRILLE - SATIN BLACK		\$ 164.00	\$ 131.20
112	LED HEADLIGHT - RH		\$ 4,888.00	\$ 3,910.40
113	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
114	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
115	ARCYLIC SEALANT	S/N	\$ 360.00	\$ 360.00
116	CAVITY WAX	S/N	\$ 280.00	\$ 280.00
117	STONE CHIP TREATMENT	S/N	\$ 180.00	\$ 180.00
118	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
119	HEAD AIR BAG UNIT - LH		\$ 1,692.00	\$ 1,353.60
120	HEAD AIR BAG UNIT - RH		\$ 1,692.00	\$ 1,353.60
SUB TOTAL SPARE PARTS			\$ 13,318.00	\$ 22,374.40

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.