

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2909 C .

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 22,374.40
121	SIDE AIR BAG UBIT - FRONT RH		\$ 1,378.00	\$ 1,102.40
122	CRASH SENSOR FOR AIR BAG		\$ 239.00	\$ 190.80
123	PRESSURE SENSOR		\$ 145.00	\$ 116.00
124	CONTROL UNIT FOR AIR BAG		\$ 1,538.00	\$ 1,230.40
125	BACKREST COVER(LEATHER) CHESTNUT BROWN - RH		\$ 1,933.00	\$ 1,546.40
126	SEAT BELT - LH		\$ 956.00	\$ 764.80
127	SEAT BELT - RH		\$ 956.00	\$ 764.80
128	SEAT BELT HEIGHT ADJUSTER	2	\$ 343.00	\$ 137.20
129	A PILLAR TRIM ROCK GREY - LH / RH	2	\$ 282.00	
130	SILL TRIM STRIP - RH INNER		\$ 183.00	\$ 146.40
131	B-PILLAR TRIM SOUL(BLACK)		\$ 102.00	
132	B-PILLARTRIM ROCK GREY -RH UPPER		\$ 190.00	
133	WHEEL HOUSING TRIM SOUL(BLACK)		\$ 93.00	
134	MOULDED HEADLINER		\$ 1,551.00	\$ 1,240.80
135	GRAB HANDLE,FOLDING - FRONT	2	\$ 248.00	
136	GRAB HANDLE,FOLDING - REAR LH/RH	2	\$ 248.00	
137	ALUMINIUM RIM - LH FRONT		\$ 659.00	\$ 527.20
138	SEAT FRAME TRIM SOUL(BLACK)		\$ 142.00	
140	SUPPLEMENTARY		\$ 90.00	\$ 44.76
141	SUNDRIES		\$ 2,000.00	\$ 84.92
	TOTAL SPARE PARTS	:	\$ 51,847.00	\$ 30,271.28
	TOTAL LABOUR CHARGES	:	\$ 39,516.00	\$ 30,064.00
	GRAND TOTAL	:	\$ 91,363.00	\$ 60,335.28

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1213/2018/PH 5-Nov-18 Kee Siang 1 of 1 SLW 2909 C Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	BOWDEN CABLE HOLDER <i>3 and</i>	\$ 7.00	\$ 5.12
2	DOOR LOCK COVER	\$ 13.00	\$ 10.16
3	DOOR COVER <i>X non</i>	\$ 39.00	
4	DOOR END COVER <i>new</i>	\$ 6.00	\$ 4.48
* 5	NO PLATE - FRONT <i>new</i> S/N	\$ 25.00	\$ 25.00
TOTAL		\$ 90.00	\$ 44.76

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 25 March 2019 5:54 PM
To: 'Boo seng yak'; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SLW2909C - OD AIG - SURVEYED 26 OCT 18

Dear Mr Boo,

Confirm repair cost of \$60,310.28 before excess \$3700 and GST @ 29 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Please note Front no plate take out.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Wednesday, 23 January 2019 4:44 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLW2909C - OD AIG - SURVEYED 26 OCT 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$60,335.28 @ 29 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 8 November 2018 11:11 AM
To: 'PAL Claim'; glory.tan@premiumauto.com.sg; SUR
Cc: Adrian Ling (LKKAUTO)
Subject: RE: Supplementary item photos for SLW 2909 C
Attachments: SUPP MARKING.pdf

Dear Kee Siang,

Refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PAL Claim <claims@premiumauto.com.sg>
Sent: Thursday, 8 November 2018 10:10 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; glory.tan@premiumauto.com.sg; SUR <sur@lkkauto.com>
Cc: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; 'Claims' <claims@premiumauto.com.sg>
Subject: RE: Supplementary item photos for SLW 2909 C

Dear Veron,

Attached for your kind reference. Kindly scan us back a copy after surveyor have done marking.

Best Regards,

Kee Siang
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

24 Benoi Sector, Singapore 629857

p. +65 6474 3323 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, 8 November 2018 8:01 AM
To: glory.tan@premiumauto.com.sg; SUR <sur@lkkauto.com>
Cc: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; claims@premiumauto.com.sg
Subject: RE: Supplementary item photos for SLW 2909 C

Dear Glory,

Please provides us supplementary list with parts prices.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: glory.tan@premiumauto.com.sg <glory.tan@premiumauto.com.sg>
Sent: Wednesday, 7 November 2018 7:18 PM
To: SUR <sur@lkkauto.com>
Cc: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; claims@premiumauto.com.sg
Subject: Supplementary item photos for SLW 2909 C

Hi all,

Please refer attached for supplementary item photos. Thank you.

1. Bowden cable holder
2. Dock lock cover
3. Door end cover
4. Bellow with retaining frame

Best Regards,
Glory Tan.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLW 2909 C

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1213/2018/MAS

17 April 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLW 2909 C, Audi A3 Sedan 1.0 TFSI

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLW 2909 C**, claimant, **Ms. Tin Pei Ling**, please find the related document per attached.

1. A copy of the Original invoice no. 85013687 – S\$60,537.00
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLW 2909 C



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6386 2223
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408723
Telephone: 6386 2223
Telefax: 6471 3733

Customer Service
Service Appointment
Hour Breakdown Service
(Email)

6386 2223
6471 3733
customers@premiumauto.com.sg

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 17:39

RIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT A16 BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013687 Date : 11/04/2019 Order : SLM2909C Term : 30	Account: A0006 IT 01 RIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT A16 BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLM2909C IV 367851	Regn Date: 05/02/2010	Mileage: 501	WTP No.: 29409
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V7J1035998	Engine: CHZ 417559	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO RE-WORK DRIVER SEAT COVER	800.00	1.00	800.00
G	EXC	M: 8888 Insurance Excess/Liability	-3700.00	1.00	-3,700.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT FIRST MEASUREMENT ON CAR-Q-LINER	800.00	1.00	800.00
S	BODYWORK	M: TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN	600.00	1.00	600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT AND REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES.	720.00	1.00	720.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6346 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6346 2221
Telefax: 6471 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408731
Telephone: 6346 2211
Telefax: 6471 1033

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6346 2323
6471 1233

INSURANCE INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 17:39

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013687 Date : 11/04/2019 Order : SLW2909C Term : 30	Account: A0006 (T 8) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLW2909C (V 36785)	Regn Date: 05/02/2018	Mileage: 581	WIP No.: 29409
Model: A3 SEDAN 1.0 TFSI 8VWANG	Chassis: WAUZZZ8V7J1035998	Engine: CHZ 417559	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	INSPECT FOR DAMAGES AND RENEW IF NECESSARY M:	1400.00	1.00	1,400.00
S	BODYWORK	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS M:	1400.00	1.00	1,400.00
S	BODYWORK	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGES AND RENEW WHERE NECESSARY M:	1400.00	1.00	1,400.00
S	BODYWORK	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIM, LUGGAGE COMPARTMENT TRIMS AND REAR SEAT BELTS M:	2800.00	1.00	2,800.00
		TO REMOVE AND REINSTALL CENTRE CONSOLE. RENEW AIRBAG CONTROL UNIT, ROOF LINER, BOTH CURTAIN AIRBAGS AND BOTH FRONT SEAT BELTS			

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6386 2223
Telefax: 6475 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6188 2334
Telefax: 6188 1999

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
6475 1033

INSURANCE TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 3 17:39

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013687 Date : 11/04/2019 Order : SLW2909C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLW2909C (V 36785)	Regn Date: 05/02/2018	Mileage: 581	WIP No.: 29409
Model: A3 SEDAN 1.0 TFSI 80KW	Chassis: WAUZZZ8V7J1035998	Engine: CHZ 417559	Dept: U
USB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND REINSTALL FRONT SUSPENSION FOR CAR-O-LINER REPAIR	2400.00	1.00	2,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR EXHAUST SILENCER ASSY, REAR SUSPENSION ASSY AND FUEL TANK, FOR CAR-O-LINER REPAIR	2800.00	1.00	2,800.00
S	BODYWORK	M: TO PLACE VEHICLE ON CAR-O-LINER	1800.00	1.00	1,800.00
S	BODYWORK	M: TO DISMANTLE FRONT AND REAR BUMPERS, RHS FRONT FENDER, REAR LID, RHS FRONT AND REAR DOORS. INSPECT RHS FLOOR PAN FOR DAMAGES. CUT OUT AND WELD RHS B PILLAR, INNER REINFORCEMENT, SILL PANEL AND RHS REAR FENDER. RENEW ALL DAMAGED PANEL. REINSTALL ALL PARTS REMOVED	7500.00	1.00	7,500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, RHS FRONT AND REAR	4340.00	1.00	4,340.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119908
Main Telephone: 6386 2222
Main Telefax: 6475 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119908
Telephone: 6386 2221
Telefax: 6475 1031

Ubi Service Centre
55 Ubi Road 1
Singapore 408721

Customer Service
Service Appointment
Your breakdown Service
(Email: customer.care@premiumaudis.com.sg)

6386 2221
6475 1215

INSURANCE INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 4 17:39

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013687 Date : 11/04/2019 Order : SLW2909C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLW2909C (V 36785) Regn Date: 05/02/2018 Mileage: 581 WIP No.: 29409
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V7J1035998 Engine: CHZ 417559 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	DOORS, DOOR HANDLES, RHS B PILLAR, SILL PANEL, DOOR ENTRANCE, RHS REAR FENDER, END PANNELLING AND DOOR HINGES. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT M:	280.00	1.00	280.00
S	BODYWORK	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT M:	384.00	1.00	384.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	1400.00	1.00	1,400.00
X	ABX0831404B	(A) (SK)HINGE Less 020%	1.00	43.10	34.48
X	ABV0837885	(A) (SK)SUPPORT Less 020%	1.00	142.50	114.00
X	ABV0837199	(V) (GER)BRACKET Less 020%	2.00	3.20	5.12
X	ABX0831404B	(A) (SK)HINGE Less 020%	1.00	43.10	34.48
X	ABX4833406B	(A) (SK)HINGE Less 020%	1.00	107.50	86.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6471 3733

Ubi Service Centre
35 Ubi Road 1
Singapore 408722
Telephone: 6386 2223
Telefax: 6471 3733

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
6471 3733

INS-TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 5 17:39

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013687 Date : 11/04/2019 Order : SLW2909C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLW2909C (V 36785)	Regn Date: 05/02/2018	Mileage: 581	WIP No.: 29409
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V7J1035998	Engine: CHZ 417559	Dept: U
VS8 No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
X	ABV5839096	(V) (GER) COVER Less 020%	1.00	5.60	4.48
X	ABV5810076TA	(A) (GER) SIDE PANEL Less 020%	1.00	3190.00	2,552.00
X	ABV5880741D	(A) (GER) AIRBAG (TECH) Less 020%	1.00	1692.00	1,353.60
X	ABV5880742D	(A) (SK) AIRBAG (TECH) Less 020%	1.00	1692.00	1,353.60
X	ABV4880242B	(A) (GER) SIDEAIRBAG (T Less 020%	1.00	1378.00	1,102.40
X	A500959354	(SK) PRESSSENS (TECH) Less 020%	1.00	145.00	116.00
X	A500959655BJ	(A) (SK) MODULE (TECH) Less 020%	1.00	1538.00	1,230.40
X	ABV5857705E V04	(A) (SK) SEAT BELT (TEC Less 020%	1.00	956.00	764.80
X	ABV5857706E V04	(A) (SK) SEAT BELT (TEC Less 020%	1.00	956.00	764.80
X	ABV5867505G YX7	(A) (GER) ROOFLINING (T Less 020%	1.00	1551.00	1,240.80
X	ABV5837350	(V) (GER) COVER Less 020%	1.00	12.70	10.16
X	ABV5867104J ADI	(V) (GER) DOOR PANEL Less 020%	1.00	1577.00	1,261.60
X	ABV5833404B	(A) (SK) HINGE Less 020%	1.00	71.10	56.88
X	ABV5809224TA	(V) (GER) PILLAR B (12/ Less 020%	1.00	630.50	504.40
X	ABV5810252	(V) (GER) DEADENER (12/ Less 020%	1.00	12.10	9.68
X	ABV4881806AEIMZ	(A) (GER) COVER (TECH) Less 020%	1.00	1933.00	1,546.40
X	ABV5867304J ADI	(V) (GER) DOOR PANEL Less 020%	1.00	1430.00	1,144.00
X	ABX4833400B	(A) (SK) HINGE Less 020%	2.00	71.10	113.76
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159188
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159188
Telephone: 6386 2223
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6386 2223
Telefax: 6471 3733

Customer Service
Service Appointment
Singapore 159188
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
6386 1233

INSURANCE INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 6 17:39

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013687 Date : 11/04/2019 Order : SLW2909C Term : 30	Account: A0006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLW2909C (V 36785)	Regn Date: 05/02/2018	Mileage: 581	WIP No.: 29409
Model: A3 SEDAN 1.8 TFSI 8VWANG	Chassis: WAUZZZ8V7J1035998	Engine: CHZ 417559	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details		Qty	Unit Price	Amount
X	ABX4833406B	(A) (SK)HINGE	Less 020%	2.00	107.50	172.00
X	ABK0972701	(A) (SK)HOUSING	Less 020%	1.00	18.50	14.80
X	ABV5837300A 989	(A) (SK)COVER	Less 020%	1.00	15.40	12.32
X	ASC6827713	(A) (SK)PLUG	Less 020%	1.00	0.60	0.48
X	AN 10515101	PLUG	Less 020%	1.00	1.40	1.12
X	ABV5853906A 4PH	SCUFF PLAT	Less 020%	1.00	183.00	146.40
X	A3C0837033C	(V) (SK)CATCH	Less 020%	1.00	56.60	45.28
X	ABV0941774D	HEADLIGHT	Less 020%	1.00	4888.00	3,910.40
X	ABV5845298K NVB	SIDE WINDOW	Less 020%	1.00	501.50	401.20
X	ABV4837462	REGULATOR	Less 020%	1.00	231.50	185.20
X	ABV5833721A	(V) (GER)DOOR SEAL	Less 020%	1.00	173.50	138.80
X	ABV5831052D	(A) (GER)DOOR	Less 020%	1.00	2279.00	1,823.20
X	ABV5833052C	(V) (G)DOOR	Less 020%	1.00	2190.00	1,752.00
X	ABV5845501E NVB	REARWINDOW	Less 020%	1.00	704.00	563.20
X	ABV5807065R GRU	COVER	Less 020%	1.00	1739.00	1,391.20
X	ABV0601025DC	(A) (GER)RIM 16" C4E1	Less 020%	1.00	659.00	527.20
X	ABK0837199	CLIP	Less 020%	12.00	0.70	8.40
X	ABV0857819	ADJUSTER	Less 020%	1.00	171.50	137.20
					Sub-Total	
					7% GST	
					Grand Total	



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6896 2222
Fax: 6471 3733
Page 7 17:39

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2222
Fax: 6471 1523

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6388 2222
Fax: 6471 1523

Customer Service
Service Appointment
Email: customer.care@premiumauto.com.sg

6388 2222
6471 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013687 Date : 11/04/2019 Order : SLW2909C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLW2909C (V 36785)	Regn Date: 05/02/2018	Mileage: 581	WIP No.: 29409
Model: A3 SEDAN 1.8 TFSI 8VMANG	Chassis: WAUZZZ8V7J1035998	Engine: CHZ 417559	Dept: U
VSF No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
X	A8V5839249	CHECK ROD Less 020%	1.00	84.90	67.92
X	A323863950	SOUND ABS Less 020%	4.00	100.00	345.60
X	A8H0631701	(A) (SK) BOLT Less 020%	2.00	3.30	5.28
X	A8V0637903	(A) (SK) COVER Less 020%	1.00	10.90	8.72
X	A8T0637691C	(A) (SK) BOLT Less 020%	1.00	2.50	2.00
X	A8V5837912C	(A) (SK) SEAL Less 020%	1.00	139.00	111.20
X	A8V0668243	(A) (SK) CLIP Less 020%	10.00	9.70	5.60
X	A4B0637491B	(V) (SK) DOOR Less 020%	1.00	3.50	2.80
X	A8T0637947	(A) (SK) CAP Less 020%	6.00	2.20	10.56
X	A8V0637206A GRU	(A) (SK) HANDLE Less 020%	2.00	207.00	331.20
X	A8V5839267	(A) (GER) COVER Less 020%	1.00	13.80	11.04
X	A8V5807682M 989	(A) (SK) GRILL Less 020%	1.00	164.00	131.20
X	A500959651B	(A) (SK) SENSOR (TECH) Less 020%	1.00	238.50	190.80
X	A444955647	PLUG Less 020%	1.00	5.25	4.20
X	A8V0010502KE	(A) (GER) LABEL Less 020%	1.00	24.70	19.76
X	A5G0010029J	(A) (SK) STICKER Less 020%	1.00	22.20	17.76
X	AD 437540A1	(A) (SK) TAPE Less 020%	1.00	55.80	44.64
X	AD 355205A2	BONAGENT Less 020%	1.00	44.90	35.92
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
261 Alexandra Road
Singapore 119100
Main Telephone: 6386 2222
Main Telefax: 6471 3733

Alexandra Service Centre
261 Alexandra Road
Singapore 119100
Telephone: 6386 2221
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6386 2211
Telefax: 6471 1023

Customer Service
Service Appointment
Service Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2222
6471 1215

INSURANCE INVOICE

Company Reg. No. A09902271W

GST Reg. No. 199902271W

Page 8 17:39

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013687 Date: 11/04/2019 Order: SLW2909C Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: SLW2909C (V 36785)	Regn Date: 05/02/2018	Mileage: 501	WIP No.: 29409
Model: A3 SEDAN 1.0 TFSI 8VWANG	Chassis: WAUZZZ8V7J1035998	Engine: CHZ 417559	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details		Qty	Unit Price	Amount
X	AD 00920002	PRIMER (DG)	Less 020%	2.00	18.60	29.76
X	ABV5839912C	SEAL	Less 020%	1.00	146.00	116.80
X	ABV5831721A	(V) (GER) DOOR SEAL	Less 020%	1.00	139.00	111.20
X	AWHT003237	BOLT	Less 020%	4.00	1.00	3.20
X	AWHT001234	BOLT	Less 020%	2.00	2.10	3.36
X	AWHT001234	BOLT	Less 020%	4.00	2.10	6.72
X	AWHT001235	BOLT	Less 020%	2.00	2.10	3.36
X	AWHT001235	(A) (SK) BOLT	Less 020%	4.00	2.10	6.72
X	AN 01500210	NUT	Less 020%	4.00	1.00	3.20
X	AN 91109701	BOLT	Less 020%	4.00	1.50	4.80
X	ABV5853284B 222	WINDOW SLD	Less 020%	1.00	267.50	214.00
X	ABV5853764C 222	WINDOW SLD	Less 020%	1.00	255.50	204.40

Parts 28,846.28	Sub-Total	56,610.28
Labour 0.00	7% GST	3,962.72
Sublet 31,464.00	Grand Total	60,573.00
Menus 0.00		
Lubricant 0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLW 2909 C

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1213/2018/JW
5TH December 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sedan 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V7J1035998
Vehicle Regn No. : **SLW 2909 C**
Vehicle Mileage : **581** km
Vehicle Owner : Ms Tin Pei Ling
Certificate No : 1800007839
Own Damage Excess : S\$ 3,959.00 (inclusive of 7% GST)
Accident Date : 22/10/2018
Place : Outside Carribean @ Keppel Bay
Repair Cost : **\$ 60,573.00**
WIP No. : 29409
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 1pm
Date : 7/12/18

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of a woman.

License Number: S8340417E

Name: TIN PEI LING

Birth Date: 23 Dec 1983

Issue Date: 16 Jan 2018

Barcode: 002764456J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

	EFFECTIVE DATE
Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq$ 2500kg	16 Jan 2018

NP 428A





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TIN PEI LING
Period of Insurance : 05 Feb 2018 To 04 Feb 2019
Engine No. : CHZ417559
Chassis No. : WAUZZZ8V7J1035998

Vehicle No. : SLW2909C
Policy No. : 1800007839
Endorsement No. :
Issued Date : 07 Feb 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 30 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TIN PEI LING - \$1400 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408899 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125220

PREMIUM LEASING - MH
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

1000602879/AC4/Docaf

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2018 15:22		25 Oct 2018 15:09 Edit Adj Rpt	S\$60,310.28 Edit Estimates	S\$60,310.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TIN PEI LING, ID: S8340417E, Tel: +6597324904, Email: TINPEILING@GMAIL.COM								
Vehicle Reg. No.:	SLW2909C	Date of Loss:	22/10/2018 21:00 - :59 [8 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 5937930288SG	Policy/Cover Note No.:	1800007839 (Comprehensive)						
		Excess:	S\$3,700.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/11/2018]								
Driver/Custodian:	TIN PEI LING (34 / Female), NRIC: S8340417E, Tel: +6597324904 Email: TINPEILING@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (29/10/2018): Alert - Adj Mandate Approved (S\$73338.00) - SLW2909C - Claim Handler: Loo, Tong ... - AIG_SG (26/10/2018): SLW2909C / OD / 22/10/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW2909C (5937930288SG)
 OD
 Oct 22 2018 9:40PM
 [TIN PEI LING]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Assessment Reports															1 per page		☒	
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print	
1	25/10/18 16:39		Adjuster Immediate Advice												1 Load HTM			
Photos/Images															3 per page		☒	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print	
1	25/10/18 15:22		General View												1 Load JPG		☒	
2	25/10/18 15:22		General View												1 Load JPG		☒	
3	25/10/18 15:22		General View												1 Load JPG		☒	
4	25/10/18 15:22		General View												1 Load JPG		☒	
5	25/10/18 15:22		General View												1 Load JPG		☒	
6	25/10/18 15:22		General View												1 Load JPG		☒	
7	25/10/18 15:22		General View												1 Load JPG		☒	
8	25/10/18 15:22		General View												1 Load JPG		☒	
9	25/10/18 15:22		General View												1 Load JPG		☒	
10	25/10/18 15:22		General View												1 Load JPG		☒	
11	25/10/18 15:22		General View												1 Load JPG		☒	
12	25/10/18 15:22		General View												1 Load JPG		☒	
13	25/10/18 15:22		General View												1 Load JPG		☒	
14	25/10/18 15:22		General View												1 Load JPG		☒	
15	25/10/18 15:22		General View												1 Load JPG		☒	
16	25/10/18 15:22		General View												1 Load JPG		☒	
17	25/10/18 15:22		General View												1 Load JPG		☒	
18	25/10/18 15:22		General View												1 Load JPG		☒	
19	25/10/18 15:22		General View												1 Load JPG		☒	
20	25/10/18 15:22		General View												1 Load JPG		☒	
21	25/10/18 15:22		General View												1 Load JPG		☒	
22	25/10/18 15:22		General View												1 Load JPG		☒	
23	25/10/18 15:22		General View												1 Load JPG		☒	
24	25/10/18 15:22		General View												1 Load JPG		☒	
25	25/10/18 15:22		General View												1 Load JPG		☒	
26	25/10/18 15:22		General View												1 Load JPG		☒	
27	25/10/18 15:22		General View												1 Load JPG		☒	
28	25/10/18 15:22		General View												1 Load JPG		☒	
29	25/10/18 15:22		General View												1 Load JPG		☒	
30	25/10/18 15:22		General View												1 Load JPG		☒	
31	25/10/18 15:22		General View												1 Load JPG		☒	
32	25/10/18 15:22		General View												1 Load JPG		☒	
33	25/10/18 15:22		General View												1 Load JPG		☒	
34	25/10/18 15:22		General View												1 Load JPG		☒	
35	25/10/18 15:22		General View												1 Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	25/10/18 15:22	General View	 Load JPG	☒
37	25/10/18 15:22	General View	 Load JPG	☒
38	25/10/18 15:22	General View	 Load JPG	☒
39	25/10/18 15:22	General View	 Load JPG	☒
40	25/10/18 15:22	General View	 Load JPG	☒
41	25/10/18 15:22	General View	 Load JPG	☒
42	25/10/18 15:22	General View	 Load JPG	☒
43	25/10/18 15:22	General View	 Load JPG	☒
44	25/10/18 15:22	General View	 Load JPG	☒
45	25/10/18 15:22	General View	 Load JPG	☒
46	25/10/18 15:22	General View	 Load JPG	☒
47	25/10/18 15:22	General View	 Load JPG	☒
48	25/10/18 15:22	General View	 Load JPG	☒
49	25/10/18 15:22	General View	 Load JPG	☒
50	25/10/18 15:22	General View	 Load JPG	☒
51	25/10/18 15:22	General View	 Load JPG	☒
52	25/10/18 15:22	General View	 Load JPG	☒
53	25/10/18 15:22	General View	 Load JPG	☒
54	25/10/18 15:22	General View	 Load JPG	☒
55	25/10/18 15:22	General View	 Load JPG	☒
56	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
57	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
58	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
59	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
60	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
61	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
62	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
63	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
64	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
65	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
66	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
67	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
68	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
69	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
70	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
71	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
72	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
73	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
74	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
75	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
76	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
77	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
78	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
79	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
80	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
81	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
82	25/03/19 17:35	Reinspection Photo	Load JPG	☒
83	25/03/19 17:35	Reinspection Photo	Load JPG	☒
84	25/03/19 17:35	Reinspection Photo	Load JPG	☒
85	25/03/19 17:35	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
87	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
88	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
89	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
90	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
91	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
92	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
93	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
94	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
95	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
96	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
97	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
98	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
99	25/03/19 17:35	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 15:59	Singapore Accident Statement	 Load PDF	
2	25/10/18 15:59	MARK ESTIMATE	 Load PDF	
3	25/10/18 15:59	NEW CAR PRICE	 Load PDF	
4	25/10/18 16:17	Certificate of Insurance	 Load PDF	
5	25/10/18 16:17	Driver's Driving License	 Load PDF	
6	25/10/18 16:49	AMEND GIA REPORT	 Load PDF	
7	30/04/19 09:46	Workshop Invoice	 Load PDF	
8	30/04/19 09:46	Discharge Voucher	 Load PDF	
9	30/04/19 10:46	Supplementary	 Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	25/10/18 16:25	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/10/18 14:11	Accident Statement	 Load HTM	
2	25/10/18 16:29	Addendum Sheet	 Load JPG	☒
3	25/10/18 16:30	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/10/18 14:00	Accident Photo	 Load JPG	☒
2	23/10/18 14:00	Accident Photo	 Load JPG	☒
3	23/10/18 14:00	Accident Photo	 Load JPG	☒
4	23/10/18 14:00	Accident Photo	 Load JPG	☒
5	23/10/18 14:00	Accident Photo	 Load JPG	☒
6	23/10/18 14:00	Accident Photo	 Load JPG	☒
7	23/10/18 14:00	Accident Photo	 Load JPG	☒
8	23/10/18 14:00	Accident Photo	 Load JPG	☒
9	23/10/18 14:00	Accident Photo	 Load JPG	☒
10	23/10/18 14:00	Accident Photo	 Load JPG	☒
11	23/10/18 14:00	Accident Photo	 Load JPG	☒
12	23/10/18 14:00	Accident Photo	 Load JPG	

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				☒
13	23/10/18 14:00	Accident Photo	Load JPG	☒
14	23/10/18 14:00	Accident Photo	Load JPG	☒
15	23/10/18 14:00	Accident Photo	Load JPG	☒
16	23/10/18 14:00	Accident Photo	Load JPG	☒
17	23/10/18 14:00	Accident Photo	Load JPG	☒
18	23/10/18 14:00	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	23/10/18 13:13	Sketch Plan	Load JPG	☒
2	23/10/18 13:13	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18019417/AVBE2

Date: 30/04/2019

REFERENCE

Insured/Claimant: TIN PEI LING Policy No: 1800007839
Date of Loss: 22/10/2018 Nature of Claim: OD Claim No: 5937930288SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW2909C
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ417559
Reg. Date: 05/02/2018 (Man. Year: 2017) Chassis No: WAUZZZ8V7J1035998
Colour: Black Odometer: 3589 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$120,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	51,882.76	30,246.28	21,636.48	41.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	39,516.00	30,064.00	9,452.00	23.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	91,398.76	60,310.28	31,088.48	34.01
- Excess (S\$)	3,700.00	3,700.00	0.00	0.00
(S\$)	87,698.76	56,610.28	31,088.48	35.45
+ GST 7.00/7.00% (S\$)	6,138.91	3,962.72	2,176.19	35.45
Nett Amount (S\$)	93,837.67	60,573.00	33,264.67	35.45

INSPECTION

Date of Assignment: 25/10/2018
Date Inspected: 25/10/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 29.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - RH	Repair	746.00 FS	*- FS
2	1		*BRACKET FOR FENDER - RH	Not Necessary	34.00 FS	*- FS
3	1		*BRACKET FOR FENDER - RH	Not Necessary	24.00 FS	*- FS
4	1		*CLOSING ELEMENT WING - RH	Not Necessary	29.00 FS	*- FS
5	1		*INSULATION FOR FRONT FENDER - RH	Not Necessary	36.00 FS	*- FS
6	1		*WHEEL HOUSING LINER - RH	Not Necessary	151.00 FS	*- FS
7	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	77.00 FS	*- FS
8	1		*FRONT DOOR - RH	Distorted	2,190.00 FS	*1,823.20 FS
9	1		*OUTER DOOR SEAL - FRONT RH	Necessary	139.00 FS	*116.80 FS
10	1		*BONDING AGENT	Necessary	43.00 FS	*35.92 FS
11	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
12	1		*ATTACHMENT PARTS FOR DOOR	Not Necessary	206.00 FS	*- FS
13	1		*DOOR HINGE HALF - UPPER PART - RH UPPER	Bent	72.00 FS	*56.88 FS
14	1		*DOOR HINGE HALF - LOWER PART - RH UPPER	Bent	44.00 FS	*34.48 FS
15	1		*DOOR HINGE HALF - UPPER PART - RH LOWER	Bent	108.00 FS	*86.00 FS
16	1		*DOOR HINGE HALF - LOWER PART	Bent	44.00 FS	*34.48 FS
17	1		*DOOR CATCH	Not Necessary	92.00 FS	*- FS
18	1		*COVER FOR DOOR CATCH	Not Necessary	13.00 FS	*- FS
19	1		*DOOR SEAL, INNER	Bent	139.00 FS	*111.20 FS
20	1		*SECURING BRACKET DOOR PANEL	Not Necessary	11.00 FS	*- FS
21	1		*DOOR HANDLE, EXTERIOR PRIMED	Cut	207.00 FS	*165.60 FS
22	1		*DOOR HANDLE CAP - RH	Not Necessary	26.00 FS	*- FS
23	1		*SENSOR FOR DOOR HANDLE	Not Necessary	200.00 FS	*- FS
24	1		*FRONT DOOR LOCK CYLINDER - RH	Not Necessary	457.00 FS	*- FS
25	1		*MOUNTING BAR	Not Necessary	143.00 FS	*- FS
26	1		*BOWDEN CABLE	Not Necessary	48.00 FS	*- FS
27	1		*FRONT DOOR LOCK - RH	Not Necessary	466.00 FS	*- FS
28	1		*DOOR LOCK COVER	Not Necessary	13.00 FS	*- FS
29	1		*STRIKER	Bent	57.00 FS	*45.28 FS
30	1		*UNDERLAY	Not Necessary	30.00 FS	*- FS
31	1		*BOWDEN CABLE	Not Necessary	34.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*COVER FOR DOOR INNER PANEL - RH	Not Necessary	22.00 FS	*- FS
33	1		*WINDOW GUIDE - RH	Not Necessary	365.00 FS	*- FS
34	1		*TRIM STRIP FOR WINDOW GUIDE HIGH CHROME	Not Necessary	222.00 FS	*- FS
35	1		*WINDOW APERTURE SEAL - RH INNER	Not Necessary	113.00 FS	*- FS
36	1		*TRIM FOR B PILLAR BLACK GLOSSY - RH	Not Necessary	85.00 FS	*- FS
37	1		*WINDOW SLOT SEAL WITH TRIM STRIP CHROME	Cut	268.00 FS	*214.00 FS
38	1		*WINDOW LIFTER W/O MOTOR	Damaged	232.00 FS	*185.20 FS
39	1		*WINDOW MOTOR	Not Necessary	212.00 FS	*- FS
40	1		*FRONT DOOR CONTROL UNIT - RH	Not Necessary	438.00 FS	*- FS
41	1		*COVER - SATIN BLACK - RH	Necessary	15.00 FS	*12.32 FS
42	1		*COVER	Necessary	11.00 FS	*8.72 FS
43	1		*ADHESIVE TAPE	Necessary	55.00 FS	*44.64 FS
44	1		*DOOR PANEL SOUL (BLACK) - RH	Deformed	1,577.00 FS	*1,261.60 FS
45	1		*SWITCH MOUNTING - RH	Not Necessary	80.00 FS	*- FS
46	1		*ARM REST RH PLASTIC	Not Necessary	443.00 FS	*- FS
47	1		*TRIM FOR DOOR WINDOW FRAME - RH	Not Necessary	97.00 FS	*- FS
48	1		*WIRING HARDNESS FOR DOOR TRIM PANEL	Not Necessary	550.00 FS	*- FS
49	1		*DOOR WINDOW - FRONT RH	Not Necessary	204.00 FS	*- FS
50	1		*REAR DOOR - LH	Distorted	2,190.00 FS	*1,752.00 FS
51	1		*REAR DOOR OUTER SEAL - RH	Necessary	139.00 FS	*111.20 FS
52	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
53	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
54	1		*DOOR HINGE HALF - UPPER PART - RH UPPER	Bent	72.00 FS	*56.88 FS
55	1		*DOOR HINGE HALF - LOWER PART - RH UPPER	Bent	86.00 FS	*86.00 FS
56	1		*DOOR HINGE HALF - UPPER PART - RH LOWER	Bent	108.00 FS	*86.00 FS
57	1		*DOOR HINGE HALF - LOWER PART - RH LOWER	Bent	72.00 FS	*56.88 FS
58	4		*SOUND ABSORBER	Necessary	432.00 FS	*345.60 FS
59	1		*DOOR CATCH	Bent	82.00 FS	*67.92 FS
60	1		*COVER FOR DOOR CATCH	Damaged	14.00 FS	*11.04 FS
61	1		*DOOR SEAL, INNER	Cut	165.00 FS	*138.80 FS
62	1		*SLIDE VALVE	Not Necessary	11.00 FS	*- FS
63	1		*HOUSING PRIMED - RH	Not Necessary	26.00 FS	*- FS
64	1		*MOUNTING BAR	Damaged	143.00 FS	*114.00 FS
65	1		*BOWDEN CABLE	Not Necessary	48.00 FS	*- FS
66	1		*DOOR LOCK - RH REAR	Not Necessary	473.00 FS	*- FS
67	1		*STRIKER	Not Necessary	57.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
68	1		*UNDERLAY	Not Necessary	30.00 FS	*- FS
69	1		*BOWDEN CABLE	Not Necessary	34.00 FS	*- FS
70	1		*COVER FOR DOOR INNER PANEL - RH	Not Necessary	22.00 FS	*- FS
71	1		*WINDOW LIFTER W/O MOTOR - REAR RH	Not Necessary	220.00 FS	*- FS
72	1		*WINDOW MOTOR - REAR RH	Not Necessary	230.00 FS	*- FS
73	1		*DOOR CONTROL UNIT	Not Necessary	363.00 FS	*- FS
74	1		*GUIDE RAIL - REAR RH	Not Necessary	45.00 FS	*- FS
75	1		*WINDOW GUIDE - REAR RH	Not Necessary	365.00 FS	*- FS
76	1		*TRIM STRIP FOR WINDOW GUIDE HIGH CHROME - LH	Not Necessary	193.00 FS	*- FS
77	1		*TRIM STRIP FOR WINDOW GUIDE - HIGH CHROME	Not Necessary	193.00 FS	*- FS
78	1		*WINDOW APERTURE SEAL - RH INNER	Not Necessary	97.00 FS	*- FS
79	1		*B PILLAR TRIM COVER - RH REAR	Not Necessary	101.00 FS	*- FS
80	1		*C PILLAR TRIM COVER - RH	Not Necessary	101.00 FS	*- FS
81	1		*WINDOW SLOT SEAL WITH TRIM STRIP CHROME - REAR RH	Cut	256.00 FS	*204.40 FS
82	1		*DOOR PANEL SOUL (BLACK) / MAROON BROWN	Deformed	1,430.00 FS	*1,144.00 FS
83	1		*ARM REST - RH PLASTIC	Not Necessary	443.00 FS	*- FS
84	1		*SWITCH MOUNTING SOUL (BLACK)	Not Necessary	80.00 FS	*- FS
85	1		*SOUND ABSORBER FOR DOOR TRIM PANEL	Not Necessary	92.00 FS	*- FS
86	1		*LOUD SPEAKER TRIM CHESTNUT BROWN - RH	Not Necessary	40.00 FS	*- FS
87	1		*TRIM INSERT SILVER FLEX METALLIC - RH	Not Necessary	135.00 FS	*- FS
88	1		*TRIM FOR DOOR WINDOW FRAME SOUL (BLACK) - RH	Not Necessary	97.00 FS	*- FS
89	1		*REAR LIGHT REFLECTOR - RED REAR	Not Necessary	18.00 FS	*- FS
90	1		*INNER ACTUATOR - RH	Not Necessary	145.00 FS	*- FS
91	1		*FIBRE OPTIC CONDUCTOR - RH	Not Necessary	52.00 FS	*- FS
92	1		*STICKER WITH FOR AIR BAG / CHILDS SEAT	Necessary	21.00 FS	*17.76 FS
93	1		*DATE PLATE FOR TYRE PRESSURE	Necessary	25.00 FS	*19.76 FS
94	1		*DATA TAG (SILVER)	Not Necessary	406.00 FS	*- FS
95	1		*DOOR WINDOW - REAR RH	Not Necessary	204.00 FS	*- FS
96	1		*SIDE PART - RH	Distorted	3,190.00 FS	*2,552.00 FS
97	1		*B PILLAR, INNER FRAME - RH	Bent	831.00 FS	*664.40 FS
98	1		*CLOSING ELEMENT - RH		461.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
99	1		*B PILLAR PLATE - RH	Necessary	13.00 FS	*9.68 FS
100	1		*SIDE MEMBER - RH	Not Necessary	353.00 FS	*- FS
101	2		*SOUND ABSORBER FOR SIDE MEMBER - RH	Not Necessary	22.00 FS	*- FS
102	2		*GUIDE SECTION - LH/RH	Not Necessary	28.00 FS	*- FS
103	2		*LOCKING MECHANISM	Not Necessary	50.00 FS	*- FS
104	1		*RH REAR 1/4 GLASS	Necessary	502.00 FS	*401.20 FS
105	1		*REAR WINDSCREEN	Necessary	704.00 FS	*563.20 FS
106	2		*PRIMER	Necessary	38.00 FS	*29.76 FS
107	1		*FRONT BUMPER	Deformed	1,739.00 FS	*1,391.20 FS
108	1		*GUIDE SECTION - RH	Not Necessary	33.00 FS	*- FS
109	1		*AIR GUIDE GRILLE - SATIN BLACK	Cut	164.00 FS	*131.20 FS
110	1		*LED HEADLIGHT - RH	Cut	4,888.00 FS	*3,910.40 FS
111	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
112	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
113	1		*ARCYLIC SEALANT	Necessary	360.00 FS	*360.00 FS
114	1		*CAVITY WAX	Necessary	280.00 FS	*280.00 FS
115	1		*STONE CHIP TREATMENT	Necessary	180.00 FS	*180.00 FS
116	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
117	1		*HEAD AIR BAG UNIT - LH	Activated	1,692.00 FS	*1,353.60 FS
118	1		*HEAD AIR BAG UNIT - RH	Activated	1,692.00 FS	*1,353.60 FS
119	1		*SIDE AIR BAG UNIT - FRONT RH	Activated	1,378.00 FS	*1,102.40 FS
120	1		*CRASH SENSOR FOR AIR BAG	Activated	239.00 FS	*190.80 FS
121	1		*PRESSURE SENSOR	Activated	145.00 FS	*116.00 FS
122	1		*CONTROL UNIT FOR AIR BAG	Activated	1,538.00 FS	*1,230.40 FS
123	1		*BACKREST COVER (LEATHER) CHESTNUT BROWN - RH	Torn	1,933.00 FS	*1,546.40 FS
124	1		*SEAT BELT - LH	Activated	956.00 FS	*764.80 FS
125	1		*SEAT BELT - RH	Activated	956.00 FS	*764.80 FS
126	2		*SEAT BELT HEIGHT ADJUSTER	Damaged	343.00 FS	*137.20 FS
127	2		*A PILLAR TRIM ROCK GREY - LH/RH	Not Necessary	282.00 FS	*- FS
128	1		*SILL TRIM STRIP - RH INNER	Not Necessary	183.00 FS	*146.40 FS
129	1		*B-PILLAR TRIM SOUL (BLACK)	Not Necessary	102.00 FS	*- FS
130	1		*B-PILLAR TRIM ROCK GREY - RH UPPER	Not Necessary	190.00 FS	*- FS
131	1		*WHEEL HOUSING TRIM SOUL (BLACK)	Not Necessary	93.00 FS	*- FS
132	1		*MOULDED HEADLINER	Crumpled	1,551.00 FS	*1,240.80 FS
133	2		*GRAB HANDLE, FOLDING - FRONT	Not Necessary	248.00 FS	*- FS
134	2		*GRAB HANDLE, FOLDING - REAR LH/RH	Not Necessary	248.00 FS	*- FS
135	1		*ALUMINIUM RIM - LH FRONT	Cut	659.00 FS	*527.20 FS
136	1		*SEAT FRAME TRIM SOUL (BLACK)	Not Necessary	142.00 FS	*- FS
137	1		*SUNDRIES	Necessary	2,000.00 FS	*84.92 FS
138	1		*BOWDEN CABLE HOLDER	Damaged	5.12 FS	*5.12 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
139	1		*DOOR LOCK COVER	Damaged	10.16 FS	*10.16 FS
140	1		*DOOR COVER	Not Necessary	39.00 FS	*- FS
141	1		*DOOR END COVER	Necessary	4.48 FS	*4.48 FS
142	1		*NO PLATE - FRONT	Not Necessary	25.00 FS	*- FS
143	1		*SLIDE VALVE - RH	Not Necessary	11.00 FS	*- FS
144	1		*DOOR HANDLE, PRIMED - RH REAR	Cut	207.00 FS	*165.60 FS
Total Parts (S\$)					51,882.76	30,246.28

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
2	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	800.00
3	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN	New	600.00	600.00
4	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
5	TO REMOVE AND TRANSFER FRONT AND REAR DOORS MULTI-LOCK SYSTEMS AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	720.00	720.00
6	TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY, ABCD PILLAR TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,400.00	1,400.00
7	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
8	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, REAR SEAT BELTS	New	1,400.00	1,400.00
9	TO REMOVE AND REINSTALL CENTRE CONSOLE, RENEW AIRBAG CONTROL UNIT, ROOF LINER, BOTH CURTAIN AIRBAGS, AND BOTH FRONT SEAT BELTS	New	2,800.00	2,800.00
10	TO RENEW DRIVER SEAT AIR BAG AND LEATHER COVER	New	800.00	800.00
11	TO REMOVE AND REINSTALL FRONT SUSPENSION FOR CAR-O-LINER REPAIRS	New	2,400.00	2,400.00
12	TO REMOVE AND REINSTALL REAR EXHAUST SILENCER ASSY, REAR SUSPENSION ASSY AND FUEL TANK, FOR CAR-O-LINER REPAIRS	New	2,800.00	2,800.00
13	TO PLACE VEHICLE ON CAR-O-LINER	New	1,800.00	1,800.00
14	TO DISMANTLE FRONT AND REAR BUMPERS, RHS FRONT FENDER, RHS FRONT AND REAR DOORS AND REAR LID. INSPECT RHS FLOOR PAN FOR DAMAGES. CUT OUT AND WELD RHS B-PILLAR, INNER REINFORCEMENTS, SILL PANEL AND RHS REAR	New	12,600.00	7,500.00
15	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND REAR DOORS, DOOR HANDLES, RHS B PILLAR, SILL PANEL, DOOR ENTRANCES, INNER REINFORCEMENTS, RHS REAR FENDER, DRAIN PANEL, ROOF CHANNEL AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	8,500.00	4,340.00
16	TO RENEW LHS FRONT RIM AND TYRE AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
17	TO CARRY OUT DIAGNOSTIC CHECK	New	576.00	384.00
Gross Labour Cost (S\$)			39,516.00	30,064.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >