

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SLN1976L

TP/AXA

**M/S :** AXA INSURANCE (S) PTE LTD  
 8 SHENTON WAY  
 #27-02 AXA TOWER  
 SINGAPORE 068811

**Estimate No:** ES1891222/YISHUN  
**Date:** 24 Oct 2018  
**Policy No:** MT101628  
**Veh Reg No:** SLN1976L  
**Make/Model:** KIA FORTE K3 1.6A  
**Chassis No:** KNAFJ411MH57144264  
**Engine No:** G4FGGH647529  
**Reg. Date:** 26/04/2017

**TEL:** 63387288 **FAX:** 68804739  
**ATTN:** Motor Claim Department  
**WS Ref:** TP/AXA/YS  
**Claim Type:** Third Party  
**Accident Date:** 23/10/2018  
**TP Veh Reg No:** SLX6687K

*Not Authorized*

*Repair By paint*

### Estimate Repair Cost to Vehicle No :SLN1976L

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>Net Price</b>				
1 REAR BUMPER	688.00	1 PC	688.00	✓
2 REAR BUMPER LOWER SKIRT	344.00	1 PC	344.00	✓
3 REAR BUMPER REINFORCEMENT	313.00	1 PC	313.00	✓
4 REAR BUMPER REFLECTORS	65.00	2 PCS	130.00	✓
5 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
6 REAR PANEL	315.00	1 PC	315.00	✓
7 REAR PANEL INNER TOP GARNISH	58.00	1 PC	58.00	✓
8 REAR BOOT	1,297.00	1 PC	1,297.00	✓
9 REAR BOOT LOGO	42.00	1 PC	42.00	✓
10 REAR BOOT EMBLEM (CERATO K3)	60.00	1 PC	60.00	✓
11 REAR BOOT INNER LOCK	110.00	1 PC	110.00	X
12 REAR BOOT INNER RUBBER	98.00	1 PC	98.00	?
13 REAR SPARE TYRE COMPARTMENT	372.00	1 PC	372.00	✓
14 REAR SPARE TYRE HOLDER	18.00	1 PC	18.00	✓
15 REAR EXHAUST PIPE	480.00	1 PC	480.00	✓
16 FRONT BUMPER	735.00	1 PC	735.00	✓
17 FRONT BUMPER REINFORCEMENT	496.00	1 PC	496.00	✓
18 FRONT BUMPER SPONGE	85.00	1 PC	85.00	✓
19 FRONT BUMPER RH SIDE RETAINER	16.00	1 PC	16.00	✓
20 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
21 FRONT GRILLE	221.00	1 PC	221.00	✓
22 FRONT GRILLE LOGO BUMPER LOGO	35.00	1 PC	35.00	✓
23 FRONT GRILLE CLIPS	3.50	4 PCS	14.00	✓
24 HEADLAMPS	810.00	2 PCS	1,620.00	✓
25 BONNET	835.00	1 PC	835.00	✓
26 BONNET INNER LOCK	65.00	1 PC	65.00	✓
27 BONNET INNER LOCK CABLE	68.00	1 PC	68.00	✓
28 BONNET HINGES	42.00	2 PCS	84.00	✓
29 FRONT RH FENDER	325.00	1 PC	325.00	✓
30 FRONT RH FENDER TRIANGLE GLASS	233.00	1 PC	233.00	✓
31 FRONT RH DOOR	893.00	1 PC	893.00	✓
32 FRONT RH DOOR SIDE MIRROR	511.00	1 PC	511.00	✓
33 FRONT RH DOOR FRAME STICKER	40.00	1 SET	40.00	✓
34 FRONT WINDSCREEN GLASS	821.00	1 PC	821.00	✓

*o/s Brn n/s m/j/m*

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

**M/S :** AXA INSURANCE (S) PTE LTD  
 8 SHENTON WAY  
 #27-02 AXA TOWER  
 SINGAPORE 068811  
**TEL:** 63387288 **FAX:** 68804739  
**ATTN:** Motor Claim Department  
**WS Ref:** TP/AXA/YS  
**Claim Type:** Third Party  
**Accident Date:** 23/10/2018  
**TP Veh Reg No:** SLX6687K

**Estimate No:** ES1891222/YISHUN  
**Date:** 24 Oct 2018  
**Policy No:** MT101628  
**Veh Reg No:** SLN1976L  
**Make/Model:** KIA FORTE K3 1.6A  
**Chassis No:** KNAFJ411MH57144264  
**Engine No:** G4FGGH647529  
**Reg. Date:** 26/04/2017

## Estimate Repair Cost to Vehicle No :SLN1976L

Description	U/Price	Quantity	List Price	Amount
				S\$
35 FRONT WINDSCREEN GLASS MOULDING	60.00	1 PC	60.00	✓
36 FRONT WIPER ARMS	108.00	2 PCS	216.00	✓
37 FRONT WIPER BLADES	75.00	2 PCS	150.00	✓
38 FRONT WIPER GARNISH (CENTRE)	80.00	1 PC	80.00	✓
39 FRONT WIPER GARNISHS (SIDES)	25.00	2 PCS	50.00	✓
40 FRONT WIPER NOZZLES	22.00	2 PCS	44.00	✓
41 TOP ROOF RUBBERS	48.00	2 PCS	96.00	✓
42 AIR-CON CONDENSER	687.00	1 PC	687.00	✓
43 RADIATOR	493.00	1 PC	493.00	✓
44 RADIATOR FAN ASSY	567.00	1 PC	567.00	?
45 AIR-CON GAS DISCHARGE HOSE	617.00	1 PC	617.00	✓
46 AIR-FILTER DUCTING	94.00	1 PC	94.00	✓
47 AIR FILTER HOUSING	140.00	1 PC	140.00	✓
48 RADIATOR EXT PIPE	48.00	1 PC	48.00	?
49 VACCUM PUMP	149.00	1 PC	149.00	?
50 INLET MANIFOLD	906.00	1 PC	906.00	✓
51 FRT SUPPORT PANEL	662.00	1 PC	662.00	✓
52 AIRCON CONDENSER SIDE GARNISHS	28.00	2 PCS	56.00	✓
			16,579.00	
			Less 10%	1,657.90
				14,921.10
<b>Special Net</b>				
53 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
54 REVERSE SENSOR	200.00	1 PC	200.00	✓
55 FRONT WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
56 ERP BRACKET	20.00	1 PC	20.00	✓
57 COOLANT (2 LTRS)	40.00	1 UNIT	40.00	✓
			335.00	335.00
<b>Labour</b>				
58 TOWING	50.00	1 LA	50.00	✓
59 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	✓
60 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

**M/S :** AXA INSURANCE (S) PTE LTD  
 8 SHENTON WAY  
 #27-02 AXA TOWER  
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739  
 ATTN: Motor Claim Department  
 WS Ref: TP/AXA/YS  
 Claim Type: Third Party  
 Accident Date: 23/10/2018  
 TP Veh Reg No: SLX6687K

**Estimate No:** ES1891222/YISHUN  
**Date:** 24 Oct 2018  
**Policy No:** MT101628  
**Veh Reg No:** SLN1976L  
**Make/Model:** KIA FORTE K3 1.6A  
**Chassis No:** KNAFJ411MH57144264  
**Engine No:** G4FGGH647529  
**Reg. Date:** 26/04/2017

### Estimate Repair Cost to Vehicle No :SLN1976L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
61 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,BONNET & ATTACHMENT,RADIATOR,FRT FENDERS,MOTOR,TO CUT,WELD & RENEW FRT SUPPORT PANEL,KNOCK & REPAIR FRT LH FENDER, TOP ROOF PANEL,FRT FENDER INNER PANEL,PILLARS & REALIGN THE SAME	1,200.00	1 LA	1,200.00	1000
62 REMOVE & REFIX VACCUM PUMP,INLET MANIFOLD & CHECK ENGINE	100.00	1 LA	100.00	✓
63 PUTTY & RESPRAY ON TOP ROOF PANEL,FRT RH DOOR,FRT FENDERS,FRT BUMPER,SUPPORT PANEL,FRT FENDER INNER PANELS,BONNET & ALL AFFECTED AREAS	1,300.00	1 LA	1,300.00	1200
64 REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
65 REMOVE & REFIX TOP ROOF LINING,SEAT,CARPET & WASH CUSHION	120.00	1 LA	120.00	✓
66 REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,REAR BOOT & ATTACHMENT,CUT,WELD & RENEW REAR PANEL,REAR SPARE TYE COMPARTMENT,KNOCK & REPAIR REAR FENDERS,REAR CHASSISS & REALIGN THE SAME	1,500.00	1 LA	1,500.00	1400
67 PUTTY & RESPRAY REAR PANEL,REAR SPARE TYRE COMPARTMENT,REAR CHASSISS,REAR PANEL,BUMPER,BOOT	1,300.00	1 LA	1,300.00	1200
68 REMOVE & REFIX REAR UNDER CARRIAGE,REAR EXHAUST	250.00	1 LA	250.00	220
69 TO MOUNT ON CAR-O-LINER & REALIGN REAR CHASSIS	250.00	1 LA	250.00	✓
70 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
71 RUSTPROOFING	120.00	1 LA	120.00	✓
			6,700.00	6,700.00

Total S\$ 21,956.10  
 Add GST @ 7% 1,536.93  
**Total Amount Payable S\$ 23,493.03**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

**For Cheng Hoe Motor Pte Ltd**

  
 \_\_\_\_\_  
 AUTHORISED SIGNATURE