

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 434R**AAD1810-246**

Not Notified
Resony B4 part

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 434R
 VF1ABL15AUC283203
 RENAULT
 LATITUDE
 23.10.18
CHINA TAIPING

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Buland</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77 ✓
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>N</i> 914.08 X
1	HEADLAMP RH	\$	<i>SL</i> 1,184.43 X
1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>SL</i> 278.84 X
1	FENDER BRACKET LOWER RH	\$	<i>SL</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84 X
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	<i>N</i> 261.28
1	DOOR HINGE LOWER RH	\$	<i>N</i> 300.55
1	DOOR CHECK FRT RH	\$	<i>SL</i> 194.77
1	DOOR LOCK FRT RH	\$	<i>N</i> 908.75
1	DOOR CATCH FRT RH	\$	<i>SL</i> 131.23
1	DOOR HANDLE OUTER FRT RH	\$	<i>R</i> 477.76
1	DOOR HANDLE COVER FRT RH	\$	<i>SL</i> 13.22
1	DOOR HANDLE MODULE FRT RH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR FRT RH	\$	<i>SL</i> 505.19
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>SL</i> 796.46
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>SL</i> 120.97
1	DOOR MIRROR ASSY RH	\$	<i>SL</i> 1,483.40
1	LOWER ARM RH L70Y	\$	<i>SL</i> 685.76
1	KNUCKLE ARM RH L70Y	\$	<i>SL</i> 846.98

X

Trans-cab Auto Services Pte Ltd**AAD1810-246**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 434R

1	ABSORBER FRT RH L70Y	\$	<i>Sn</i> 360.54	} X
1	DRIVESHAFT RH	\$	<i>Sn</i> 1,747.45	
1	STABILIZER BAR FRT	\$	<i>Sn</i> 604.65	
1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 270.06	
1	WIPER RESERVOIR	\$	<i>Sn</i> 348.25	
1	WIPER RESERVOIR NECK	\$	<i>Sn</i> 136.11	
TOTAL		\$	19,688.96	
10%		\$	1,968.90	
		\$	17,720.06	

Special Nett

1SET	BUMPER CLIP FRT	\$	<i>Nec</i> 66.00	} X
1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i> 12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i> 10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i> 69.00	
1SET	WHEELARCH CLIP FRT RH	\$	<i>na</i> 30.50	
1SET	Front licence plate with holder	\$	<i>Sn</i> 80.00	
1	FRONT RIGHT TYRE	\$	<i>Sn</i> 330.00	
1	FRONT RIGHT TYRE RIM	\$	<i>Sn</i> 380.00	
1	WINDSCREEN SEALANT	\$	<i>na</i> 253.80	
1	FRONT WINDSCREEN MOULDING	\$	<i>na</i> 120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00	
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69	
1	DOOR GUIDE SCREW	\$	<i>Sn</i> 10.85	
1	DOOR HINGE BOLT	\$	<i>Sn</i> 10.85	
1	DOOR HINGE NUT RH	\$	<i>Sn</i> 14.60	
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69	
1	DOOR CHECK NUT	\$	<i>Sn</i> 3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>Sn</i> 6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>Sn</i> 10.06	
1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>na</i> 80.00 <i>60SN</i>	
1	FRONT DOOR STICKER 'Classic'	\$	<i>na</i> 50.00 <i>15SN</i>	
TOTAL		\$	1,683.43	

TOTAL PARTS \$ 19,403.49**LABOUR**

Trans-cab Auto Services Pte Ltd

AAD1810-246

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 434R

Putty and spray painting of the affected portion.	\$	3,000.00	6601
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts,	\$	3,000.00	5001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of front windscreen fittings and conduct water seepage test	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To rust-proofing of the affected areas.	\$	170.00	601
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	601
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00	X

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification to be allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

As acknowledged by Repairer

TOTAL \$ 8,970.00

Over All Total \$ 28,373.49

PART BY PART (REPAIR DAY)

10 DAYS

3 days