

## FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /2018	80908/0743	LOCATION OF FIRE:	
FIRE REPORTED ON: 08 September 2018		Along Sims Way towards Mountbatten Road before junction with Lorong 6 Geylang Singapore	
TIME OF CALL: 14:49:36 hrs			
STATION COVERAGE : Paya L	ebar Fire Station		
2. INCIDENT INFORMATION			
FIRE INVOLVED: The rear tyres of a bus (CB6956G).			
METHOD OF EXTINGUISHMENT: By SCDF crew using a 38mm hose line jet from fire appliance.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating due to friction)			
DAMAGE SUSTAINED: As a result of the fire, the rear tyres, window panels and the exterior of the bus sustained heat and smoke damage. The interior of the bus sustained smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
BASIR BIN MD YUSOF for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.