LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16 Singapore 079120 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Mohd Zawaye, Norsazani Date: 16 Nov 2018

Preliminary Advice

Vehicle No : SLX9643S **Accident Date** : 22/10/2018 Make : AUDI A3 Policy No. : 1800035271 **Assignment Date** : 25/10/2018 **Excess** : S\$300.00 Date of Inspection : 25/10/2018 Est. Duration of Repair : 13 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	79,271.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	54,987.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	·S\$	6 445 00

Check Items (Estimated) :S\$ 6,445.00
Total :S\$ 61,432.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$ 122,000.00

 COE / PARF Rebate
 :S\$ 49,547.00

Salvage Value :S\$

Margin for Repair :S\$ 72,453.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy co	overage.
	Kindly let us have your authorisation.	

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT IS \$ 2,084.00