

REF:

CC3 / AUH18019435 / Asber

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____


\$ 300/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

20 R/S

days

Res: Yes or No

Lump Sum: _____

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLX96435** Yr Regn: **2018 April**
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Trailer or _____

Make: _____

Audi A3 Sedan.C.C: **999.**

Colour: _____

Black Silver

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

3587 3946

T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: _____

WAU2228V3J1057092Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / ☒ STD A/Rim or

Tyre Size

F: **205/55R16.**R: **205/55R16**

☒ PS / ☒ DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / ☒ OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front

Rear

R/Bal: _____

06

mm

R/Bal: _____

06

mm

L/Bal: _____

06

mm

L/Bal: _____

06

mm

D.O.A: _____

D.O.I: _____

25/10/18.

Survey held at _____

Premium.Des. of Damages: ☒ Frt /☒ Rear /☐ O/S /☐ N/S /☐ U/C /☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD Allg.**New Car Price: 136k.****23/03/19**

Confirmed r/p \$ 52,561.64 @ 20 days With Admin
(\$ 28,915.06 Reb 34%)

MV: 122K.**PV: 49.5K****Nett: 72.5K.****SLX 96435 - X****RECEIVED 17 APR 2019**

Date/Time, File Pass to:



Prel. Report

17/04/19
Typist



Final Report

Date/Time, File Return to:

3

Days Of Repair: **20**Resurvey No. of Trip: **2**

Survey Fee: _____

Transporter: _____

Add Fee: ☐

Site Insp: (\$



Interview: (\$



Tech. Insp: (\$



Work and: (\$

Report Format: _____

Lump Sum / I.B: (\$ **52,561.64 r/p**)**200****10****210**

26/10/18 @ 12:57 p.m. revised IA to Norsazani via merimer.

26/10/18 @ 12:58 p.m. mandate ~~approved by~~ requested authorize repair to Norsazani via merimer.

28/10/18 @ 11:57 a.m. mandate approved by Andy Fong via merimer.

29/10/18 @ 14:05 p.m. revert authorize repair to Tony Crepner via email.

RETAIL PRICE LIST

Effective as of 6 Oct 2018



MODEL	Power (hp)	Torque (Nm)	Combined Fuel Consumption L/100km	VES (Band)	Retail Price	VES (rebate / surcharge)	Nett Price after VES
AUDI A3 Sportback							
A3 1.0 TFSI S tronic	118	200	4.8	C1	\$124,240	\$10,000	\$134,240
A3 1.4 TFSI S tronic	150	250	5.0	B	\$140,280	\$0	\$140,280
S3 2.0 TFSI qu S tronic	290	380	6.6	C2	\$219,580	\$20,000	\$239,580
RS 3 2.5 TFSI qu S tronic	400	480	8.4	C2	\$278,680	\$20,000	\$298,680
AUDI A3 Sedan							
A3 1.0 TFSI S tronic	118	200	4.7	C1	\$126,440	\$10,000	\$136,440
A3 1.4 TFSI S tronic	150	250	4.9	B	\$142,480	\$0	\$142,480
S3 2.0 TFSI qu S tronic	290	380	6.3	C2	\$221,780	\$20,000	\$241,780
RS 3 2.5 TFSI qu S tronic	400	480	8.4	C2	\$286,380	\$20,000	\$306,380
AUDI A3 Cabriolet							
A3 1.4 TFSI S tronic	150	250	5.1	B	\$178,719	\$0	\$178,719
AUDI A4 Sedan							
A4 2.0 TFSI S tronic	190	320	5.2	B	\$166,980	\$0	\$166,980
A4 2.0 TFSI qu S tronic (Design)	252	370	6.2	C2	\$223,080	\$20,000	\$243,080
S4 3.0 TFSI qu tiptronic	354	500	7.7	C1	\$284,680	\$10,000	\$294,680
AUDI A4 Avant							
A4 2.0 TFSI S tronic	190	320	5.4	B	\$176,480	\$0	\$176,480
A4 2.0 TFSI qu S tronic (Design)	252	370	6.5	C2	\$232,680	\$20,000	\$252,680
S4 3.0 TFSI qu tiptronic	354	500	7.8	C1	\$294,180	\$10,000	\$304,180
RS 4 2.9 TFSI qu tiptronic	450	600	8.9	C2	\$362,280	\$20,000	\$382,280
AUDI A5 Sportback							
A5 2.0 TFSI S tronic (Design)	190	320	5.6	B	\$191,980	\$0	\$191,980
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.4	C2	\$236,930	\$20,000	\$256,930
S5 3.0 TFSI qu tiptronic	354	500	7.9	C1	\$289,580	\$10,000	\$299,580
AUDI A5 Coupe							
A5 2.0 TFSI S tronic (Design)	190	320	5.5	B	\$196,580	\$0	\$196,580
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.4	C2	\$242,030	\$10,000	\$252,030
S5 3.0 TFSI qu tiptronic	354	500	7.9	C1	\$296,880	\$10,000	\$306,880
RS 5 2.9 TFSI qu tiptronic	450	600	8.6	C2	\$359,080	\$20,000	\$379,080
AUDI A5 Cabriolet							
A5 2.0 TFSI S tronic (Design)	190	320	5.9	B	\$235,701	\$0	\$235,701
A5 2.0 TFSI qu S tronic (Sport)	252	370	6.7	B	\$274,280	\$0	\$274,280
S5 3.0 TFSI qu tiptronic	354	500	8.1	C1	\$334,780	\$10,000	\$344,780
AUDI A7 Sportback							
A7 2.0 TFSI S tronic	252	370	5.9	C1	\$290,080	\$10,000	\$300,080
A7 3.0 TFSI qu S tronic (New)	340	500	7.3	C1	\$360,500	\$10,000	\$370,500
AUDI A8							
A8 L 3.0 TFSI qu tip	310	440	7.9	C1	\$402,380	\$10,000	\$412,380
A8 L 3.0 TFSI qu tip (New)	340	500	8.2	C2	\$417,479	\$20,000	\$437,479
AUDI Q2							
Q2 1.0 TFSI S tronic	116	200	5.2	C1	\$130,906	\$10,000	\$140,906
Q2 1.4 TFSI CDD S tronic	150	250	5.3	B	\$150,406	\$0	\$150,406
Q2 1.4 TFSI CDD S tronic (Sport)	150	250	5.3	B	\$160,360	\$0	\$160,360
AUDI Q3							
Q3 1.4 TFSI S tronic	150	250	6.0	C1	\$158,395	\$10,000	\$168,395
AUDI Q5							
Q5 2.0 TFSI qu S tronic (Sport)	252	370	7.4	C1	\$219,080	\$10,000	\$229,080
Q5S 3.0 TFSI qu tiptronic	354	500	8.7	C2	\$286,080	\$20,000	\$306,080
AUDI Q7							
Q7 2.0 TFSI qu tip	252	370	7.4	C1	\$283,780	\$10,000	\$293,780
Q7 3.0 TFSI qu tip	333	440	7.9	C2	\$343,402	\$20,000	\$363,402
AUDI Q8							
Q8 3.0 TFSI qu tip	340	500	8.9	C2	\$349,300	\$20,000	\$369,300
AUDI TT Roadster							
TT 1.8 TFSI S tronic	180	250	6.1	B	\$209,980	\$0	\$209,980
AUDI R8 Coupe							
R8 5.2 FSI qu S tronic	540	540	11.4	C2	\$763,380	\$20,000	\$783,380
AUDI R8 Spyder							
R8 5.2 FSI qu S tronic	540	540	11.7	C2	\$837,080	\$20,000	\$857,080

Terms and Conditions :

- ✓ Retail price is subject to in-house financing and insurance. Price includes 12 months road tax, registration fee and GST but without insurance.
- ✓ COE is non-guaranteed and subject to 6-bids, failing which new terms and conditions shall apply.
- ✓ Booking deposit for all models is \$520,000/-. Minimum booking deposit for instant order is \$525,000/-. with the exception of RS/R8 is \$75,000/-.
- ✓ All deposits are non-refundable upon cancellation.
- ✓ In-house utilization of PARF/COE Rebates for new car registration is within Premium Automobile's discretion.

All prices and promotions are subject to change without any prior notice.

Premium Automobiles

Audi Centre Singapore
281 Alexandra Road Singapore 159938



MAXIMISE YOUR COMFORT
WITH 7 SEATS & 2,500L STOWAGE

ALL-NEW
MAXUS G10
EXECUTIVE

[FIND OUT MORE](#)

[SEARCH](#) to

[Search](#) [View All](#) [Advanced Search](#)

Home > New Cars > Audi A3 Sedan Search Results

[Audi A3 Sedan Search Results \(1 vehicles\)](#)

Sort by 15 results/page

Car Model	Price	Dealer	Built in	User Rating
Audi A3 Sedan		Premium Automobiles	Hungary	★★★★☆ 14 User Reviews
 ☐ 1.0 TFSI S tronic (A) FACELIFT → Read facelift article	\$136,440 \$12,400 /yr	• 21.3km/l 114bhp 7-speed (A) S tronic		Promoted Editor's Review
☐ 1.4 TFSI S tronic (A)	\$142,480	• 20.4km/l 148bhp 7-speed (A) S tronic		

Car Model	Price	Dealer	Built in	User Rating
				15 results/page

SHORTLISTED

COMPARE

[Compare](#) 

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7159F
Vehicle Details	
Vehicle No.:	SLX96435
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Oct 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	CHZ907364
Chassis No.:	WAUZZZ8V3J1057092
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,712.00
Original Registration Date:	18 Apr 2018
First Registration Date:	18 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$26,597.00
PARF Eligibility and Amount	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Apr 2028
PARF Rebate Amount:	\$19,947.00
COE Expiry Date and Amount	
COE Expiry Date:	17 Apr 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,000.00
COE Rebate Amount:	\$29,600.00
Total Rebate Amount:	\$49,547.00

The information contained herein is correct as at 25 Oct 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 28 March 2019 10:42 AM
To: 'Boo seng yak'
Cc: Adrian Ling (LKKAuto); SUR; 'Carrine Leong'; jiyee.yap@premiumauto.com.sg;
'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLX9643S - OD AIG - SURVEYED 25 OCT 18

Dear Mr Boo,

Confirmed final fig \$52,561.64 @ 20 days of repairs before excess \$300/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Thursday, 24 January 2019 7:04 PM
To: Adrian Ling <adrianling@lkkauto.com>; shirleyHiew@lkkauto.com; sur@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiyee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLX9643S - OD AIG - SURVEYED 25 OCT 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$52,561.64 @ 20 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 29 October 2018 2:05 PM
To: 'Claims'
Cc: SUR
Subject: RE: OD claim for SLX 9643 S
Attachments: RE: SLX9643S OD / 3918351706SG -activation of courtesy (84.2 KB)

Hi Tony,

As instructed by our client, please proceed to repair the insured vehicle **SLX 9643S**. According to our surveyor's estimate marking (Excess \$ 300/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Please refer to the attachment above.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Saturday, 27 October 2018 11:03 AM

To: SUR <sur@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: RE: OD claim for SLX 9643 S

Dear all,

Please advise repair approval status and we can repair this case within \$90k (part by part basic) including supplementary.

Thank you.

Best Regards,

Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]
Sent: Thursday, 25 October, 2018 9:23 AM
To: 'SUR' <sur@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE : OD claim for SLX 9643 S

Good morning all ,

Here is the GIA and estimate for your kind reference .

Note : There is a survey today for Adrian. Is it possible if he can survey this car too .

Thank you.

Best Regards,
Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Shirley Hiew (LKK Auto)

From: Zawaye, Norsazani <Norsazani.Zawaye@aig.com>
Sent: Monday, 29 October 2018 1:20 PM
To: Claims; 'Shirley Hiew (LKK Auto)'
Subject: RE: SLX9643S OD / 3918351706SG -activation of courtesy

Hi Shirley LKK,

Believed that Andy already approve.

30	26 Oct 2018 13:34	Label Added	(20226):Coverage Confirmed.
31	28 Oct 2018 11:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/05. Mandate Remarks: To c
32	28 Oct 2018 11:57	Adj Mandate Set	Approved:50000.00:To commence repairs. Clear damage photogri

Please update the status.

Aside Tony,

Noted with thanks.

Thanks & Regards,

Norsazani Zawaye
AIG
Claims Adjuster | Express Auto Claims
Singapore Claims | AIG Shared Services

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Monday, October 29, 2018 1:17 PM
To: Zawaye, Norsazani
Cc: 'Shirley Hiew (LKK Auto)'; claims@premiumauto.com.sg
Subject: RE: SLX9643S OD / 3918351706SG -activation of courtesy

Dear Zawaye,

We haven receive repair approval. That's why we can't activate the replacement car.

We will assist activate the replacement car to owner.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Zawaye, Norsazani [<mailto:Norsazani.Zawaye@aig.com>]

Sent: Monday, 29 October, 2018 1:11 PM

To: 'Claims' <claims@premiumauto.com.sg>

Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: RE: SLX9643S OD / 3918351706SG -activation of courtesy

Hi Premium Automobiles,

Oi called in and ask on the activation of courtesy car and repair status.

Please be inform that AIG already confirm coverage on 26/10/2018.

Kindly assist to contact Oi and advise accordingly.

LAKSHMI NARAYANAN, ID: S2657159F, Tel: +6590402645, Email: LAKSHMI@WSPC.COM

Thanks & Regards,

Norsazani Zawaye

AIG

Claims Adjuster | Express Auto Claims

Singapore Claims | AIG Shared Services

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International

Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

View Received Message

This mail is associated with :

***SLX9643S (3918351706SG)**

OD

Oct 22 2018 8:00AM

[LAKSHMI NARAYANAN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 21/11/2018 18:24 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$61432.00) - SLX9643S - Claim Handler: Mohd Zawaye, Norsazani

Approved:61432.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLX9643S (3918351706SG)**

OD

Oct 22 2018 8:00AM

[LAKSHMI NARAYANAN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 13/11/2018 13:59 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$59348.00) - SLX9643S - Claim Handler: Mohd Zawaye, Norsazani

Approved:59348.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLX9643S (3918351706SG)**

OD

Oct 22 2018 8:00AM

[LAKSHMI NARAYANAN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/10/2018 11:57 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$50000.00) - SLX9643S - Claim Handler: Mohd Zawaye, Norsazani

Approved:50000.00:To commence repairs. Clear damage photographs reflecting damage must be provided for all awarded items.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 16 Nov 2018

Preliminary Advice

Vehicle No	: SLX9643S	Accident Date	: 22/10/2018
Make	: AUDI A3	Policy No.	: 1800035271
Assignment Date	: 25/10/2018	Excess	: S\$300.00
Date of Inspection	: 25/10/2018	Est. Duration of Repair	: 13 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	79,271.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	54,987.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	6,445.00
Total	:S\$	61,432.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	122,000.00
COE / PARF Rebate	:S\$	49,547.00
Salvage Value	:S\$	
Margin for Repair	:S\$	72,453.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT IS \$ 2,084.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 12 Nov 2018

Preliminary Advice

Vehicle No	: SLX9643S	Accident Date	: 22/10/2018
Make	: AUDI A3	Policy No.	: 1800035271
Assignment Date	: 25/10/2018	Excess	: S\$300.00
Date of Inspection	: 25/10/2018	Est. Duration of Repair	: 13 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	77,187.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	52,903.00 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	6,445.00
Total	:S\$	59,348.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	122,000.00
COE / PARF Rebate	:S\$	49,547.00
Salvage Value	:S\$	
Margin for Repair	:S\$	72,453.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 302.00.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 26 Oct 2018

Preliminary Advice

Vehicle No	: SLX9643S	Accident Date	: 22/10/2018
Make	: AUDI A3	Policy No.	: 1800035271
Assignment Date	: 25/10/2018	Excess	: S\$0.00
Date of Inspection	: 25/10/2018	Est. Duration of Repair	: 13 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	76,885.00
Revised Amount	:S\$	52,601.00
Check Items (Estimated)	:S\$	6,445.00
Total	:S\$	59,046.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	122,000.00
COE / PARF Rebate	:S\$	49,547.00
Salvage Value	:S\$	
Margin for Repair	:S\$	72,453.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We are pending repair cost from repairer.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/10/2018 16:51
Date Of Accident	22/10/2018 08:55
Exact Location Of Accident	BEF JALAN BAHAR EXIT ON PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX9643S
Insured/Policyholder	
Name Of Registered Owner	LAKSHMI NARAYANAN
NRIC No	S2657159F
Email Address	LAKSHMI@WSPC.COM
Mobile Phone No	(LOCAL) +65-90402645
Alternative Phone No	OTHERS-90402645

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI 8V
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800035271
Cover Note Number	

Driver

Name of Driver	LAKSHMI NARAYANAN
NRIC No	S2657159F
Date Of Birth	01/09/1962
Occupation	INDOOR
Date Of Driving Pass	27/08/1997
Driving Experience	21 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-90402645
Fax Number	
Contact Number	OTHERS-90402645
Email Address	LAKSHMI@WSPC.COM

Address	25 LEONIE HILL, #15-01, LEONIE GARDENS,
Postcode	239225
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WAS TRAVELLING ON PIE TOWARDS NTU. BEFORE JALAN BAHAR EXIT, THERE WAS A JAM AND CARS WERE MOVING AT VARIOUS SPEEDS. I WAS MOVING ALONG BUT SUDDENLY THE CAR IN FRONT OF ME STOPPED. SO I HIT IT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SU39D
Vehicle Make/Model/Colour	BMW / 520I/ DARK BLUE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HAN JUN SIEW
NRIC/Passport Number	S8110488C
Contact Number	86876767
Address	
Postcode	
Insurance Company Name	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/tan be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: JIM FAIR
NRIC/FIN No.: 630401472

Sketch Plan #2

SKETCH PLAN



A: SLX 9043 S

B: SU 3AD

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was travelling on PIE towards NTU. Before
Talan Bahad exit there was a jam and
cars were moving at various speeds.
I was moving along but suddenly the
car in front of me stopped so I hit
it.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: T. J. K. S.
NRIC/FIN No: 62401476

Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2657159F



Name:

LAKSHMI NARAYANAN

Race:

INDIAN

Date of birth:

01-09-1962

Country/Place of birth:

INDIA



Sex:
F

S2657159F

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S2657159F

Name:

LAKSHMI NARAYANAN

Birth Date: 01 Sep 1962

Issue Date: 12 Jul 2004



001256336A

5889764



NRIC No: S2657159F

Date of issue:

13-03-2018

Address:

25 LEONIE HILL
#15-01
SINGAPORE 239225

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg

27 Aug 1997



Licence No: S2657159F

NP 426A

CERTIFICATE OF INSURANCE

PROTECTOR PRIVATE VEHICLE

Policyholder : LAKSHMI NARAYANAN
Insurance : 18 Apr 2018 To 17 Apr 2019
No. : CHZ 907364
Chassis No. : WAUZZZ8V3J1057092

Vehicle No. : SLX9643S
Policy No. : 1800035271
Endorsement No. :
Issued Date : 26 Apr 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LAKSHMI NARAYANAN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia).

0504125207

PREMIUM LEASING - SLEE

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159038

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9643 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	FRONT W/S SEALANT <i>new</i>	S/N \$ 200.00 ✓	
82	AIR BAG UNIT FOR STEERING WHEEL	\$ 3,111.00 ✓	
83	AIR BAG UNIT	\$ 4,060.00 ✓	
84	HEAD AIR BAG UNIT	\$ 1,692.00 ✓	
85	HEAD AIR BAG GUIDE-LH/RH	2 \$ 44.00 ✓	
86	KNEE AIR BAG UNIT	\$ 1,692.00 ✓	
87	DASHBOARD LOWER BOTTOM TRIM <i>new</i>	\$ 397.00 ✓	
88	AIR BAG CONTROL UNIT	\$ 1,538.00 ✓	
89	CRASH SENSOR FOR AIR BAG	\$ 716.00 ✓	
90	AIR DUCT DASHBOARD <i>torn</i>	\$ 3,792.00 ✓	
91	MOULDED HEADLINER <i>cracked</i>	\$ 1,551.00 ✓	
92	GRAB HANDLE, FOLDING-FRONT <i>new</i>	2 \$ 248.00 ✓	
93	GRAB HANDLR, FOLDING-REAR LH/RH <i>new</i>	2 \$ 248.00 ✓	
94	THREE POINT AUTOMATIC SEAT BELT-LH/RH <i>Activated</i>	2 \$ 1,912.00 ✓	
95	SEAT BELT HEIGHT ADJUSTER <i>new</i>	2 \$ 343.00 ✓	
96	A-PILLAR TRIM-LH/RH <i>new</i>	2 \$ 282.00 ✓	
97	SUNDRIES	\$ 800.00 ?	
TOTAL SPARE PARTS		:	\$ 57,621.00
TOTAL LABOUR CHARGES		:	\$ 19,264.00
GRAND TOTAL		:	\$ 76,885.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1214/2018/GW
Date	:	24-Oct-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mrs Lakshmi Narayan
Address	:	25 Leonie Hill #15-01 Singapore 239225
Telephone	:	HP +65 90402645
Type of Claim	:	Own Damage claims
Policy No.	:	1800035271
Vehicle No	:	SLX 9643 S
Model Code	:	Audi A3 Sedan 1.0 TFSI
Model / Year	:	Apr-18
Engine No	:	CHZ 907364
Chassis No	:	WAUZZZ8V3J1057092
Mileage	:	3945 KM
Date In	:	22-Oct-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Oct-18
Place of Accident	:	Bef Jalan Bahar Exit On PIE

to supp mirror removal
labour. itw 25/10
12pm.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 9643 S

S/N	Nature of Jobs	Estimated Charges
1	To tow and recover vehicle from scene of accident.	S/N AIG ✓
2	To carry out measurement test on Car-O-Liner.	S/N \$ 800.00 ✗
3	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlihgt washer assy.	S/N \$ 360.00 ✓
4	To remove and renew aircon condenser, radiator, additional radiator, elctrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,000.00 ✓
5	To remove and reinstall center console, instrument panels and clusters. Renew dashboard, both frontal air bags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and kneew air bag.	S/N \$ 3,600.00 ✓
6	To renew front windscreen.	S/N \$ 480.00 ✓
SUB-TOTAL LABOUR CHARGES		: \$ 6,240.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 9643 S

S/N	Nature of Jobs	Estimated Charges
7	To dismantle and renew front bumper, bonnet and both front fenders, both headlights and rhs front door. Repair rhs fender top support. Renew front locl carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 6,900.00 3500.
8	To respray front bumper, both front fenders, bonnet, bonnet hinges, rhs fender top support and rhs front door.	S/N \$ 5,500.00 3170 5 x 550 = 2750 2 Hinge = 170 Fender top support : 250
9	To carry out wheel alignment.	S/N \$ 240.00 X
10	To carry out diagnostic check.	S/N \$ 384.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>19,264.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9643 S

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted.</i>	S 1,739.00 ✓	1391.20
2	FRONT BUMPER FIXING PARTS <i>new</i>	S 161.00 *	
3	FROTN BUMPER GUIDE SECTION-LH/RH <i>new 2</i>	S 66.00 ✓	51.68
4	FRONT BUMPER GRILLE-CENTER <i>new 2</i>	S 140.00 ✓	112.00
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>could</i>	S 460.00 ✓	368.00
6	FRONT BUMPER CLOSING ELEMENT-LH/RH <i>could 2</i>	S 508.00 ✓	406.40
7	FRONT BUMPER COVER TRIM-LH/RH <i>new 2</i>	S 280.00 ✓	
8	CLOSING ELEMENT	S 167.00 ✓	
9	FRONT ADAPTER WHEEL HOUSING LINER-LH/RH <i>2nd 2</i>	S 64.00 ✓	50.72
10	RADIATOR GRILLE <i>could</i>	S 1,239.00 ✓	991.20
11	RADIATOR CLOSING ELEMENT <i>2nd</i>	S 167.00 ✓	133.20
12	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>new 2</i>	S 328.00 *	
13	FOAM FILL PIECE <i>could</i>	S 162.00 ✓	129.60
14	SIDE REINFORCEMENT <i>Best</i>	S 633.00 ✓	506.20
15	FRONT BUMPER COVER <i>could</i>	S 105.00 ✓	83.60
16	AIR CONDITIONER STICKER <i>new</i>	S 7.00 ✓	4.82
17	SIGN 'CAUTION'	S 12.00 ✓	9.23
18	SIGNAL HORN-LOW TONE <i>Not New</i>	S 177.00 ✓	
19	SIGNAL HORN-HIGH TONE <i>Not New</i>	S 177.00 ✓	
20	FRONT FENDER-LH <i>Repair</i>	S 746.00 *	
SUB- TOTAL SPARE PARTS		\$ 7,338.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9643 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER-RH <i>Buckled.</i>	\$ 746.00 ✓	596.80
22	FENDER ATTACHEMENT PARTS -LH/RH <i>new</i>	2 \$ 123.00 ✓	
23	FRONT FENDER BRACKET-LH/RH <i>214 Bent</i>	2 \$ 68.00 ✓	34. 26.64
24	FRONT FENDER BRACE-LH/RH <i>211 Bent.</i>	2 \$ 168.00 ? ✓	67.04
25	BONNET <i>Distorted</i>	\$ 2,755.00 ✓	22.04
26	BONNET ATTACHEMENT PARTS <i>the new new</i>	\$ 141.00 ✓	X
27	BONNET LID HINGE-LH/RH <i>Bent</i>	2 \$ 106.00 ✓	84.64
28	BONNET STOP BUFFER <i>new new</i>	2 \$ 9.00 ✓	7.20
29	GAS FILLED STRUT <i>new</i>	\$ 105.00 ✓	
30	BONNET CATCH HOOK <i>new Bent</i>	\$ 78.00 ✓	62.24
31	BONNET TRIKER-LH/RH <i>new Bent</i>	2 \$ 192.00 ✓	152.96
32	BONNET EDGE PROTECTION <i>new</i>	\$ 24.00 ✓	17.32
33	BONNET CATCH HOOK <i>Bent</i>	\$ 55.00 ✓	43.34
34	BONNET LID LOCK WITH MIRCRO <i>Bent</i>	2 \$ 353.00 ? ✓	232.40
35	BONNET BOWDEN CABLE-CENTER <i>Bent</i>	\$ 50.00 ? ✓	40
36	BONNET SOUND ABS <i>new coupled.</i>	\$ 192.00 ✓	153.20
37	LENUM CHAMBER COVER <i>new</i>	\$ 156.00 ✓	124.80
38	FRONT COWL TRIM <i>new</i>	\$ 14.00 ✓	
39	WATER BOX SEAL <i>new</i>	\$ 50.00 ✓	
40	FRONT WHEEL HOUSING LINER-RH <i>new</i>	\$ 151.00 ✓	
SUB- TOTAL SPARE PARTS		\$ 5,536.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9643 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	WHEEL HOUSING LINER ATTACHEMENT PARTS <i>new</i>	S 77.00	X
42	LED HEADLIGHT-RH/LH <i>cracked</i>	2 S 9,776.00	✓ 7820.80
43	LED HEADLIGHT POWER MODULE <i>3 me new</i>	S 665.00	X
44	LED HEADLIGHT CONTROL UNIT	S 486.00	X
45	LED WITH HEAT SINK-RH <i>new</i>	S 625.00	X
46	LED HEADLIGHT LIFT CYLINDER-RH <i>Not new</i>	S 123.00	? X
47	WASH WATER RESERVOIR <i>new</i>	S 177.00	X
48	LOCK CARRIER WITH MOUNTING COOLANT RADIATOR <i>Replaced</i>	S 638.00	✓ 510.40
49	A/C CONDENSER WITH FLUID RESERVOIR <i>Best</i>	S 468.00	? ✓ 374.00
50	A/C CONDENSER VALVE <i>Not new</i>	S 46.00	? X
51	PRESSURE SENDER <i>Not new</i>	S 165.00	? X
52	COOLER FOR COOLANT <i>new Best</i>	S 828.00	✓ ? 662.40
53	ADDITIONAL COOLER FOR COOLANT <i>Best</i>	S 797.00	? ✓ 639.20
54	COOLANT CONDENSATE <i>new</i>	S 133.00	✓ 65.28
55	FRONT BUMPER AIR GUIDE-RH/LH <i>Not new</i>	2 S 40.00	? X
56	FRONT BUMPER AIR GUIDE-UPPER CENTRE <i>Replaced</i>	S 10.00	✓ 7.68
57	FAN RING <i>Not new</i>	S 172.00	? X
58	RADIATOR FAN WITH FAN RING <i>Not new</i>	S 1,425.00	? X
59	FLAT CONNECTOR HOUSING <i>Not new</i>	S 15.00	? X
60	FRONT BUMPER AIR GUIDE <i>Replaced</i>	S 59.00	? 46.80
TOTAL SPARE PARTS		\$ 16,725.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9643 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
61	SPRING BAND CLAMP <i>new</i>	\$ 18.00	X
62	INTAKE MANIFOLD <i>new</i>	\$ 124.00	X
63	AIR FILTER <i>new</i>	\$ 242.00	X
64	WINDSCREEN <i>cracked</i>	\$ 953.00	✓ 762.00
65	GEL FOIL FOR RAIN SENSOR <i>new</i>	\$ 127.00	✓ 101.20
66	SPRING CLIP <i>Abel New</i>	\$ 19.00	✓ X
67	PRIMER <i>new</i>	\$ 37.00	✓ 29.12
68	FRONT DOOR-RH <i>Regis</i>	\$ 2,190.00	X
69	FRONT OUTER DOOR SEAL-RH <i>new</i>	\$ 139.00	+
70	BONDING AGENT <i>2</i>	\$ 43.00	✓
71	CLEANING SOLUTION <i>new</i>	\$ 64.00	+
72	APPLICATOR	\$ 7.00	+
73	FRONT DOOR ATTACHMENT PARTS-RH <i>2</i>	\$ 206.00	+
74	FRONT DOOR CATCH-RH <i>new</i>	\$ 92.00	X
75	FRONT DOOR CATCH COVER-RH	\$ 13.00	+
76	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-RH <i>new</i>	\$ 268.00	+
77	WINDOW GUIDE TRIM STIP-RH <i>new</i>	\$ 222.00	+
78	DATE PLATE FOR TYRE PRESSURE <i>new</i>	\$ 25.00	+
79	REFRIGERANT LINE FOR A/C CONDENSER <i>new</i>	\$ 582.00	? X
80	FRONT NO. PLATE <i>3rd</i>	S/N \$ 25.00	✓
TOTAL SPARE PARTS		\$ 5,396.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9643 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
81	FRONT W/S SEALANT <i>neu</i>	S/N S 200.00 ✓	
82	AIR BAG UNIT FOR STEERING WHEEL	S 3,111.00 ✓	2488.80
83	AIR BAG UNIT	S 4,060.00 ✓	3248.00
84	HEAD AIR BAG UNIT	S 1,692.00 ✓	1353.60
85	HEAD AIR BAG GUIDE-LH/RH	2 S 44.00 ✓	X
86	KNEE AIR BAG UNIT	S 1,692.00 ✓	1353.60
87	DASHBOARD LOWER BOTTOM TRIM <i>neu</i>	S 397.00 ✓	
88	AIR BAG CONTROL UNIT	S 1,538.00 ✓	1230.40
89	CRASH SENSOR FOR AIR BAG	S 716.00 ✓	572.40
90	AIR DUCT DASHBOARD <i>torn</i>	S 3,792.00 ✓	2983.20
91	MOULDED HEADLINER <i>compd</i>	S 1,551.00 ✓	1240.80
92	GRAB HANDLE, FOLDING-FRONT <i>neu and</i>	2 S 248.00 ✓	198.40
93	GRAB HANDLR, FOLDING-REAR LH/RH <i>neu and</i>	2 S 248.00 ✓	198.40
94	THREE POINT AUTOMATIC SEAT BELT-LH/RH <i>Activated</i>	2 S 1,912.00 ✓	1529.60
95	SEAT BELT HEIGHT ADJUSTER <i>neu and</i>	2 S 343.00 ✓	274.40
96	A-PILLAR TRIM-LH/RH <i>neu deformed</i>	2 S 282.00 ✓	224.80
97	SUNDRIES <i>neu</i>	S 800.00 ✓	97.08
TOTAL SPARE PARTS		:	\$ 57,621.00
TOTAL LABOUR CHARGES		:	\$ 19,264.00
GRAND TOTAL		:	\$ 76,885.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

81476.70

20617.82

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L
Surveyed Date : 25/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 Days.

LIK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1214/2018/GW

14-Nov-18

Kee Siang

1 of 1

SLX 9643 S

Audi A3 Sedan 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Steering Wheel <i>ct</i>	\$ 2,084.00	<i>1617.30</i>
TOTAL		\$ 2,084.00	

For Premium Automobiles Pte Ltd



14/11/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1214/2018/GW 2-Nov-18 Kee Siang 1 of 1 SLX 9643 S Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	BONNET COVER	\$ 9.00	6.72
	HOOD PLUG	\$ 36.00	28.32
	FENDER TOP SIDE SEAL	\$ 36.00	28.16
	AIR DUCT	\$ 18.00	13.76
	AIR DUCT COVER	\$ 26.00	20.32
	AIR INLET	\$ 50.00	39.76
	RADIATOR MOUNT	\$ 75.00	59.36
	RADIATOR BUSH	\$ 17.00	13.44
	HEADLIGHT VENT HOSE	\$ 35.00	26.72
TOTAL		\$ 302.00	

For Premium Automobiles Pte Ltd



Authorised Signature

206 32

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1214/2018/GW 14-Nov-18 Kee Siang 1 of 1 SLX 9643 S Audi A3 Sedan 1.0 TFSI	
Quantity	Description		Unit Price	Amount
Labour				
1	To remove/reinstall RHS front door mirror assy to facilitate respray	S/N	\$ 300.00	\$ A 300.00 ✓
Parts				
1	Steering Wheel		\$ 2,084.00	\$ 1,667.20
2	Cover for speaker - dashboard		\$ 81.70	\$ A 65.36
3	Air vent - dashboard		\$ 132.00	\$ A 105.60
4	Curtain air bag RHS		\$ 1,692.00	\$ A 1,353.00
Materials			\$ 3,989.70	\$ 3,191.16
Labour			\$ 300.00	\$ 300.00
Total			\$ 4,289.70	\$ 3,491.16

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1214/2018/GW
Date	:	24-Oct-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

We took 20 days - parts order Ger

jb 24 Jan 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mrs Lakshmi Narayan
Address	:	25 Leonie Hill #15-01 Singapore 239225
Telephone	:	HP +65 90402645
Type of Claim	:	Own Damage claims
Policy No.	:	1800035271
Vehicle No	:	SLX 9643 S
Model Code	:	Audi A3 Sedan 1.0 TFSI
Model / Year	:	Apr-18
Engine No	:	CHZ 907364
Chassis No	:	WAUZZZ8V3J1057092
Mileage	:	3945 KM
Date In	:	22-Oct-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Oct-18
Place of Accident	:	Bef Jalan Bahar Exit On PIE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 9643 S

S/N	Nature of Jobs	Estimated Charges	
1	To tow and recover vehicle from scene of accident.	S/N	AIG
2	To carry out measurement test on Car-O-Liner.	S/N	\$ 800.00
3	To remove, check and reinstall front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00 \$ 360.00
4	To remove and renew aircon condenser, radiator, additional radiator, electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,000.00 \$ 1,000.00
5	To remove and reinstall center console, instrument panels and clusters. Renew dashboard, both frontal air bags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain air bags and kneew air bag.	S/N	\$ 3,600.00 \$ 3,600.00
6	To renew front windscreen.	S/N	\$ 480.00 \$ 480.00
SUB-TOTAL LABOUR CHARGES		:	\$ 6,240.00 \$ 5,440.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLX 9643 S

S/N	Nature of Jobs		Estimated Charges
		<i>c/f</i>	\$ 6,240.00
7	To dismantle and renew front bumper, bonnet and both front fenders, both headlights and rhs front door. Repair rhs fender top support. Renew front locl carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.		\$ 6,900.00
8	To respray front bumper, both front fenders, bonnet, bonnet hinges, rhs fender top support and rhs front door.	S/N	\$ 5,500.00
9	To carry out wheel alignment.	S/N	\$ 240.00
9a	<i>Added labour charges - see attached</i>	S/N	\$ 300.00
10	To carry out diagnostic check.	S/N	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 19,564.00

\$ 5,440.00

\$ 3,500.00

\$ 3,170.00

\$ 300.00

\$ 384.00

\$ 12,794.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9643 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,739.00	\$ 1,391.20
2	FRONT BUMPER FIXING PARTS	\$ 161.00	
3	FROTN BUMPER GUIDE SECTION-LH/RH	2 \$ 66.00	\$ 51.68
4	FRONT BUMPER GRILLE-CENTER	\$ 140.00	\$ 112.00
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 460.00	\$ 368.00
6	FRONT BUMPER CLOSING ELEMENT-LH/RH	2 \$ 508.00	\$ 406.40
7	FRONT BUMPER COVER TRIM-LH/RH	2 \$ 280.00	
8	CLOSING ELEMENT	\$ 167.00	
9	FRONT ADAPTER WHEEL HOUSING LINER-LH/RH	2 \$ 64.00	\$ 50.72
10	RADIATOR GRILLE	\$ 1,239.00	\$ 991.20
11	RADIATOR CLOSING ELEMENT	\$ 167.00	\$ 133.20
12	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$ 328.00	
13	FOAM FILLE PIECE	\$ 162.00	\$ 129.60
14	SIDE REINFORCEMENT	\$ 633.00	\$ 506.00
15	FRONT BUMPER COVER	\$ 105.00	\$ 83.60
16	AIR CONDITIONER STICKER	\$ 7.00	\$ 4.88
17	SIGN ' CAUTION'	\$ 12.00	\$ 9.28
18	SIGNAL HORN-LOW TONE	\$ 177.00	
19	SIGNAL HORN-HIGH TONE	\$ 177.00	
20	FRONT FENDER-LH	\$ 746.00	
SUB- TOTAL SPARE PARTS		\$ 7,338.00	\$ 4,237.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9643 S

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	4,237.76
21	FRONT FENDER-RH	\$	746.00	\$ 596.80
22	FENDER ATTACHEMENT PARTS -LH/RH	2 \$	123.00	
23	FRONT FENDER BRACKET-LH/RH	2 \$	68.00	\$ 26.64
24	FRONT FENDER BRACE-LH/RH	2 \$	168.00	\$ 67.04
25	BONNET	\$	2,755.00	\$ 2,204.00
26	BONNET ATTACHEMENT PARTS	\$	141.00	
27	BONNET LID HINGE-LH/RH	2 \$	106.00	\$ 84.64
28	BONNET STOP BUFFER	2 \$	9.00	\$ 7.20
29	GAS FILLED STRUT	\$	105.00	
30	BONNET CATCH HOOK	\$	78.00	\$ 62.24
31	BONNET TRIKER-LH/RH	2 \$	192.00	\$ 152.96
32	BONNET EDGE PROTECTION	\$	24.00	\$ 18.88
33	BONNET CATCH HOOK	\$	55.00	\$ 43.84
34	BONNET LID LOCK WITH MIRCRO	2 \$	353.00	\$ 282.40
35	BONNET BOWDEN CABLE-CENTER	\$	50.00	\$ 40.00
36	BONNET SOUND ABS	\$	192.00	\$ 153.20
37	LENUM CHAMBER COVER	\$	156.00	\$ 124.80
38	FRONT COWL TRIM	\$	14.00	
39	WATER BOX SEAL	\$	50.00	
40	FRONT WHEEL HOUSING LINER-RH	\$	151.00	
SUB- TOTAL SPARE PARTS			\$ 5,536.00	\$ 8,102.40

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9643 S

S/N	Parts Description	c/f	<u>Damage Parts & Prices</u>	
			S/NETT	REMARKS
			\$	8,102.40
41	WHEEL HOUSING LINER ATTACHEMENT PARTS		\$ 77.00	
42	LED HEADLIGHT-RH/LH	2	\$ 9,776.00	\$ 7,820.80
43	LED HEADLIGHT POWER MODULE		\$ 665.00	
44	LED HEADLIGHT CONTROL UNIT		\$ 486.00	
45	LED WITH HEAT SINK-RH		\$ 625.00	
46	LED HEADLIGHT LIFT CYLINDER-RH		\$ 123.00	
47	WASH WATER RESERVOIR		\$ 177.00	
48	LOCK CARRIER WITH MOUNTING COOLANT RADIATOR		\$ 638.00	\$ 510.40
49	A/C CONDENSER WITH FLUID RESERVOIR		\$ 468.00	\$ 374.00
50	A/C CONDENSER VALVE		\$ 46.00	
51	PRESSURE SENDER		\$ 165.00	
52	COOLER FOR COOLANT		\$ 828.00	\$ 662.40
53	ADDITIONAL COOLER FOR COOLANT		\$ 797.00	\$ 639.20
54	COOLANT CONDENSATE		\$ 133.00	\$ 65.28
55	FRONT BUMPER AIR GUIDE-RH/LH	2	\$ 40.00	
56	FRONTBUMPER AIR GUIDE-UPPER CENTRE		\$ 10.00	\$ 7.68
57	FAN RING		\$ 172.00	
58	RADIATOR FAN WITH FAN RING		\$ 1,425.00	
59	FLAT CONNECTOR HOUSING		\$ 15.00	
60	FRONT BUMPER AIR GUIDE		\$ 59.00	\$ 46.80
TOTAL SPARE PARTS			\$ 16,725.00	\$ 18,228.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 9643 S

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	18,228.96
61	SPRING BAND CLAMP	\$	18.00	
62	INTAKE MANIFOLD	\$	124.00	
63	AIR FILTER	\$	242.00	
64	WINDSCREEN	\$	953.00	\$ 762.00
65	GEL FOIL FOR RAIN SENSOR	\$	127.00	\$ 101.20
66	SPRING CLIP	\$	19.00	
67	PRIMER	\$	37.00	\$ 29.12
68	FRONT DOOR-RH	\$	2,190.00	
69	FRONT OUTER DOOR SEAL-RH	\$	139.00	
70	BONDING AGENT	\$	43.00	
71	CLEANING SOLUTION	\$	64.00	
72	APPLICATOR	\$	7.00	
73	FRONT DOOR ATTACHMENT PARTS-RH	\$	206.00	
74	FRONT DOOR CATCH-RH	\$	92.00	
75	FRONT DOOR CATCH COVER-RH	\$	13.00	
76	FRONT WINDOW SLOT SEAL WITH TRIM STRIP-RH	\$	268.00	
77	WINDOW GUIDE TRIM STIP-RH	\$	222.00	
78	DATE PLATE FOR TYRE PRESSURE	\$	25.00	
79	REFRIGERANT LINE FOR A/C CONDENSER	\$	582.00	
80	FRONT NO. PLATE	S/N	\$ 25.00	\$ 25.00
TOTAL SPARE PARTS		:	\$ 5,396.00	\$ 19,146.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SLX 9643 S

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1214/2018/GW 2-Nov-18 Kee Siang 1 of 1 SLX 9643 S Audi A3 Sedan 1.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	BONNET COVER	\$ 9.00	\$ 6.88
	HOOD PLUG	\$ 36.00	\$ 28.32
	FENDER TOP SIDE SEAL	\$ 36.00	\$ 28.16
	AIR DUCT	\$ 18.00	\$ 13.76
	AIR DUCT COVER	\$ 26.00	\$ 20.32
	AIR INLET	\$ 50.00	\$ 39.76
	RADIATOR MOUNT	\$ 75.00	\$ 59.36
	RADIATOR BUSH	\$ 17.00	\$ 13.44
	HEADLIGHT VENT HOSE	\$ 35.00	\$ 26.72
TOTAL		\$ 302.00	\$ 236.72

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLX 9643 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1214/2018/MAS

16 April 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLX 9643 S, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SLX 9643 S**, claimant, **Ms. Lakshmi Narayanan**, please find the related document per attached.

1. A copy of the Original invoice no. 85013685 – S\$55,919.95
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLX 9643 S

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Copy Copy Copy Copy Copy Copy
Audi Centre Singapore
281 Alexandra Road
Singapore 159958
Main Telephone 6388 2222
Main Telefax 6471 2733

Alexandra Service Centre
281 Alexandra Road
Singapore 159958
Telephone 6388 2222
Telefax 6475 1023

Uti Service Centre
55 Uti Road 1
Singapore 1588 2222
Telephone 6388 2222

Customer Service
Service Appointment
Your Breakdown Service
Email customer.care@premiumauto.com.sg

6366 2222
9628 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 1 17:24

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoices: 85013685
Date : 10/04/2019
Order : SLX9643S
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLX9643S (V 37465)

Regn Dates: 18/04/2018

Mileage: 3945

WIP No.: 29296

Model: A3 SEDAN 1.0 TFSI 8WMBG

Chassis: WAUZZZ8V3J1057092

Engine: CHZ 907364

Dept: U

VS8 No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-300.00	1.00	-300.00
S	BODYWORK	M: TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT, PRESSURISE COOLING SYSTEM, TO VARRY OUT VACUUM AND REGAS	1000.00	1.00	1,000.00
S	BODYWORK	M: TO REMOVE AND REINSTALL CENTRE CONSOLE, INSTRUMENT PANEL AND CLUSTERS, RENEW DASHBOARD, BOTH FRONTAL AIRBAG, SLIP RING, TRANSFER OLD FITTINGS, RENEW SEAT BELTS AND CONTROL UNIT,	3600.00	1.00	3,600.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

COPY COPY COPY COPY COPY

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6471 1021

UBi Service Centre
55 Ubi Road 1
Singapore 408722

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
6628 1233

INSURANCE TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 17:24

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013685 Date : 10/04/2019 Order : SLX96435 Term : 30	Account: A0006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLX96435 (V 37465)	Regn Date: 10/04/2018	Mileage: 3945	WIP No.: 29296
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V3J1057092	Engine: CHZ 907364	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIRBAGS AND KNEE AIRBAG M:	480.00	1.00	480.00
S	BODYWORK	TO RENEW FRONT WINDSCREEN M:	3500.00	1.00	3,500.00
S	BODYWORK	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND BOTH HEADLIGHT. REPAIR RHS FENDER TOP SUPPORT, RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION, REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. M:	3170.00	1.00	3,170.00
S	BODYWORK	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, BONNET, BONNET HINGES, RHS FENDER TOP SUPPORT AND RHS FRONT DOOR M:	384.00	1.00	384.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	200.00	1.00	200.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

COPY COPY COPY COPY COPY

Head Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6396 2223
Main Telefax: 6471 3333

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6396 2223
Telefax: 6471 3333

UBI Service Centre
55 Ubi Road 1
Singapore 408622
Telephone: 6388 2223

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6396 2223
6471 3333

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 3 17:24

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013685 Date : 10/04/2019 Order : SLX9643S Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLX9643S (V 37465) Regn Date: 10/04/2018 Mileage: 3945 WIP No.: 29296
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V3J1057092 Engine: CHZ 907364 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO SUPPLY FRONT WINDSCREEN SEALANT M: TO REMOVE AND REINSTALL RHS FRONT DOOR MIRROR ASSY TO FACILITATE RESPRAY	300.00	1.00	300.00
X	ABV0880201DNGPS	(A) (Ger) AIRBAG Less 020%	1.00	3111.00	2,468.00
X	ABV5880741D	(A) (Ger) AIRBAG Less 020%	1.00	1692.00	1,353.60
X	ABV5880742D	(A) (Ger) AIRBAG Less 020%	1.00	1692.00	1,353.60
X	ABV2880841D	(A) (SK) AIRBAG Less 020%	1.00	1692.00	1,353.60
X	A500959655BJ	(A) (SK) MODULE Less 020%	1.00	1538.00	1,230.40
X	ABV5867505S YX7	(A) (Ger) ROOFLINING Less 020%	1.00	1551.00	1,240.80
X	ABV0857607 MG6	(V) (Ger) HANDLE Less 020%	2.00	124.00	198.40
X	ABV0857607A MG6	(A) (Ger) HANDLE(01/11) Less 020%	1.00	124.00	99.20
X	ABV0857608 MG6	(A) (Ger) HANDLE(01/11) Less 020%	1.00	124.00	99.20
X	ABV5857705E V04	(A) (SK) SEAT BELT Less 020%	1.00	956.00	764.80
X	ABV5857706E V04	(A) (SK) SEAT BELT Less 020%	1.00	956.00	764.80
X	ABV5867233A VU6	(V) (Ger) LINING Less 020%	1.00	140.50	112.40
X	ABV5867234A VU6	(V) (Ger) LINING Less 020%	1.00	140.50	112.40
X	ABV2819635D 6PS	(V) (G) AIR VENT Less 020%	1.00	132.00	105.60
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

COPY COPY COPY COPY COPY
 Audi Centre Singapore
 281 Alexandra Road
 Singapore 159938
 Main Telephone: 6386 2223
 Main Telefax: 6471 3733

Alexandra Service Centre
 281 Alexandra Road
 Singapore 159938
 Telephone: 6386 2223
 Telefax: 6475 1023

Ubi Service Centre
 55 Ubi Road 1
 Singapore 408722
 Telephone: 6386 2223
 Telefax: 6475 1023

Customer Service
 Service Appointment
 4366 2323
 9628 1233
 Email: customers.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 4 17:24

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoices: 85013685 Date: 10/04/2019 Order: SLX9643S Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLX9643S (V. 37465) Regn Date: 18/04/2018 Mileage: 3945 WIP No.: 29296
 Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V3J1057092 Engine: CHZ 907364 Dept: U
 VSB No.:
 You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABV2857367B 6PS	(V) (G) COVER	Less 020%	1.00	81.70	65.36
X	ABV0941718B	(V) (SK) HOSE (05/11/18	Less 020%	1.00	33.40	26.72
X	ABV0419091CHINU	(V) (GER) STEERING MH	Less 020%	1.00	2084.00	1,667.20
X	ABV3853651AA3FZ	GRILLE	Less 020%	1.00	1239.00	991.20
X	A500016411AS	(A) (Ger) CONDENSER (29	Less 020%	1.00	467.50	374.00
X	ABV0800204G	(A) (SK) AIRBAG	Less 020%	1.00	4060.00	3,248.00
X	ABV0941773D	(A) (SK) HEADLIGHT (29/	Less 020%	1.00	4888.00	3,910.40
X	ABV0941774D	HEADLIGHT	Less 020%	1.00	4888.00	3,910.40
X	ABV0863825	(V) (SK) SILENCER (05/1	Less 020%	1.00	191.50	153.20
X	ABV5821106A	(A) (SK) FENDER (29/10/	Less 020%	1.00	746.00	596.80
X	A500121251GD	RADIATOR	Less 020%	1.00	828.00	662.40
X	A500121251GB	RADIATOR	Less 020%	1.00	799.00	639.20
X	ABV5807233B	PLATE	Less 020%	1.00	460.00	368.00
X	ABV5819401A 989	(A) (SK) COVER (29/10/1	Less 020%	1.00	156.00	124.80
X	ABV0805588A	CARRIER	Less 020%	1.00	637.50	510.00
X	ABV0807550A	FORM INSER	Less 020%	1.00	162.00	129.60
X	ABV4007109E	BEAM	Less 020%	1.00	632.50	506.00
X	AG A13040M2	PREMIX-COOLANT	Less 020%	4.00	20.40	65.28

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

COPY COPY COPY COPY COPY
Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6346 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6346 2223
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408722

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6346 2323
9628 1238

INS TAX INVOICE

Company Reg. No. 199902271M

GST Reg. No. 199902271M

Page 5 17:24

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013685 Date : 18/04/2019 Order : SLY9643S Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLY9643S (V 37465) Regn Date: 18/04/2018 Mileage: 3945 WIP No.: 29296

Model: A3 SEDAN 1.0 TFSI BVMRG Chassis: WAUZZZ8V3J1057092 Engine: CHZ 907364 Dept: U

VS8 No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABV58450996 NVB	(A) (SK) GLASS(29/10/1	Less 020%	1.00	952.50	762.00
X	ABV5823029A	HOOD	Less 020%	1.00	2755.00	2,204.00
X	ABV5807065R BRU	COVER	Less 020%	1.00	1739.00	1,391.20
X	ABV2857001J 24R	(A) (SK-Last) DASHBOARD	Less 020%	1.00	3729.00	2,983.20
X	AWHT001300	NUT	Less 020%	6.00	1.20	5.76
X	A4G0063511L	UTR ADHESIVE PADS	Less 020%	1.00	26.00	20.80
X	A500121367F	BRACKET	Less 020%	2.00	37.10	59.36
X	ABV0121285A	AIR DUCT	Less 020%	1.00	9.60	7.68
X	ABV0023126B	EDGING	Less 020%	1.00	23.60	18.88
X	ABV0007217A	COVER	Less 020%	1.00	104.50	83.60
X	ABV5807183	GUIDE	Less 020%	1.00	32.30	25.84
X	ABV5807184	GUIDE	Less 020%	1.00	32.30	25.84
X	ABV5807319	(A) (SK) PLATE	Less 020%	1.00	254.00	203.20
X	ABV5821468B	(A) (SK) BRACKET(29/10	Less 020%	1.00	33.30	26.64
X	ABV5807320	(A) (SK) PLATE	Less 020%	1.00	254.00	203.20
X	ABV0023301G	HINGE	Less 020%	1.00	52.90	42.32
X	ABV0023302G	HINGE	Less 020%	1.00	52.90	42.32
X	ABV0021136C	SUPPORT	Less 020%	1.00	67.00	53.60

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

COPY COPY COPY COPY COPY

Audi Centre Singapore
281 Alexandra Road
Singapore 159908
Admin Telephone: 6386 2222
Main Telephone: 6471 5793

Alexandra Service Centre
281 Alexandra Road
Singapore 159908
Telephone: 6386 2222
Telefax: 6475 1025

Uti Service Centre
55 Uti Road 1
Singapore 4386 5333
Telephone: 6386 2222

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2222
9628 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 6 17:24

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013685 Date : 18/04/2019 Order : SLX9643S Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLX9643S (V 37465)	Regn Date: 18/04/2010	Mileage: 3945	WIP No.: 29296
Model: A3 SEDAN 1.8 TFSI 8VWANG	Chassis: WAUZZZ8V3J1057092	Engine: CHZ 907364	Dept: U
USB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details		Qty	Unit Price	Amount
X	A500129621B	AIR DUCT	Less 020%	1.00	17.20	13.76
X	A8V0121230	SEAL	Less 020%	1.00	6.80	5.44
X	A500129618J	(A) (SK) AIR DUCT	Less 020%	1.00	58.50	46.80
X	A1K0121367F	(V) (SK) MOUNTING (05/1	Less 020%	2.00	8.40	13.44
X	A8V0823185C	CATCH	Less 020%	1.00	95.60	76.48
X	A8V0857819	(A) (SK) ADJUSTER	Less 020%	2.00	171.50	274.40
X	A8V0823186C	CATCH	Less 020%	1.00	95.60	76.48
X	A8V5807409B	ADAPTER	Less 020%	1.00	31.70	25.36
X	A4H0823543	COVER	Less 020%	1.00	8.60	6.88
X	A8V4823485C	HOOK	Less 020%	1.00	54.80	43.84
X	A4D0260749B	WASHER	Less 020%	1.00	2.90	2.32
X	A3D0260749C	WASHER	Less 020%	1.00	3.80	3.04
X	A8V5807410B	ADAPTER	Less 020%	1.00	31.70	25.36
X	A8P4803593A	PLUG	Less 020%	2.00	17.70	28.32
X	A4B0823481	BUMPER	Less 020%	2.00	4.50	7.20
X	A8V0823480A	HOOK	Less 020%	1.00	77.80	62.24
X	A8V0823509A	LOCK	Less 020%	2.00	176.50	282.40
X	A8V0823531A	BOND CABLE	Less 020%	1.00	50.00	40.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159956
Main Telephone: 6386 2222
Main Telefax: 6471 3737

Alexandra Service Centre
281 Alexandra Road
Singapore 159956
Telephone: 6386 2222
Telefax: 6471 3737

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6386 1222
Telefax: 6471 3737

Customer Service
Service Appointment
Your Breakdown Service
(Email)
customer.care@premiumauto.com.sg

6386 2222
9828 1235

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 7 17:24

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013685 Date : 10/04/2019 Order : SLX9643S Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLX9643S (V 37465) Regn Date: 10/04/2018 Mileage: 3945 WTP No.: 29296

Model: A3 SEDAN 1.0 TFSI 80WANG Chassis: WAUZZZ8V3J1057092 Engine: CHZ 907364 Dept: U

VS8 No.:

You have been assisted by :- UD-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABV58076478 989	GRILLE	Less 020%	1.00	140.00	112.00
X	ABV0821170E	(V) (SK) COVER (05/11/1	Less 020%	1.00	35.20	28.16
X	ABU0955609	FILM	Less 020%	1.00	126.50	101.20
X	AS009596518	(A) (SK) SENSOR	Less 020%	3.00	238.50	572.40
X	ABX0010520A	PLATE	Less 020%	1.00	11.60	9.28
X	ABV0010515A	STICKER	Less 020%	1.00	6.10	4.88
X	AD 00920002	PRIMER (DG)	Less 020%	2.00	18.20	29.12
X	AS00129254B	AIR DUCT	Less 020%	1.00	49.70	39.76
X	ABV0121284K	AIR DUCT	Less 020%	1.00	19.90	15.92
X	ABV0121283K	AIR DUCT	Less 020%	1.00	19.90	15.92
X	ABV3853949	PLATE	Less 020%	1.00	166.50	133.20
X	AN 0161857	POP-RIVET	Less 020%	10.00	2.90	23.20
X	AN 91022001	NUT	Less 020%	4.00	1.40	4.48
X	AS00129354	COVER	Less 020%	1.00	25.40	20.32

Parts 39,542.64
Labour 0.00
Sublet 13,019.00
Menus 0.00
Lubricant 0.00

Sub-Total 52,261.64

7% GST 3,658.31

Grand Total 55,919.95



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLX9643S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1214/2018/TF
22 November 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V3J1057092
Vehicle Regn No. : SLX9643S
Vehicle Mileage : 3945km
Vehicle Owner : Ms. Lakshmi Narayanan
Certificate No : 1800035271
Own Damage Excess : S\$ 321.00 (inclusive of 7% GST)
Accident Date : 22/10/2018
Place : Before Jalan Bahar Exit on PIE
Repair Cost : \$ 55,919.95
WIP No. : 29296
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

23/11

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2657159F



LAKSHMI NARAYANAN



Race
INDIAN
Date of birth
01-09-1962
Country/Place of birth
INDIA

Sex
F

S2657159F

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S2657159F

Name:

LAKSHMI NARAYANAN

Birth Date: 01 Sep 1962

Issue Date: 12 Jul 2004



001256336A

5889764



NRIC No: S2657159F

Date of issue:
13-03-2018

Address
25 LEONIE HILL
#15-01
SINGAPORE 239225

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg

27 Aug 1997

NP 426A



License No: S2657159F

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LAKSHMI NARAYANAN
Period of Insurance : 18 Apr 2018 To 17 Apr 2019
Engine No. : CHZ 907364
Chassis No. : WAUZZZ8V3J1057092

Vehicle No. : SLX9643S
Policy No. : 1800035271
Endorsement No. :
Issued Date : 26 Apr 2018

ABOUT THE COVER

Make/Model	AUDI A3 Sedan 1.0 TFSI S tronic		
Engine Capacity/Tonnage	999.00 CC	Sum Insured	: Market Value
Driver Restriction	NA	Off Peak Car	: No
		First Year of Registration	: 2018
		Insuring with COE/PARF	: Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, place-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade business or use for any purpose in connection with motor trade

Loss of Use 1800cc - 2000cc Optional

¹ Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LAKSHMI NARAYANAN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center: Add: 55 Ubi Road 1 Singapore 408699 63963323

For other Approved Reporting Centres/AIG Authorized Repairs, please contact our 24-hour accident emergency hotline at +65 8336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

C504125207

PREMIUM LEASING - SLEE
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Therapy Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2018		25 Oct 2018 16:29 Edit Adj Rpt	\$552,561.64 Edit Estimates	\$552,561.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LAKSHMI NARAYANAN , ID: S2657159F, Tel: +6590402645, Email: LAKSHMI@WSPC.COM									
Vehicle Reg. No.: SLX9643S		Date of Loss: 22/10/2018 08:00 - :59 [6 Months and 4 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 3918351706SG		Policy/Cover Note No.: 1800035271 (Comprehensive) Coverage: 18/04/2018 - 17/04/2019							
		Excess: S\$300.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/11/2018]									
Driver/Custodian: LAKSHMI NARAYANAN (56 / Female) , NRIC: S2657159F, Tel: +6590402645 Email: LAKSHMI@WSPC.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (21/11/2018): Alert - Adj Mandate Approved (S\$61432.00) - SLX9643S - Claim Handler: Mohd Zaway... - AIG_SG (13/11/2018): Alert - Adj Mandate Approved (S\$59348.00) - SLX9643S - Claim Handler: Mohd Zaway... - AIG_SG (28/10/2018): Alert - Adj Mandate Approved (S\$50000.00) - SLX9643S - Claim Handler: Mohd Zaway... - AIG_SG (26/10/2018): SLX9643S / OD / 22/10/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLX9643S (3918351706SG)
OD
Oct 22 2018 8:00AM
[LAKSHMI NARAYANAN]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		v	☒		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)														Thumbnail	Print			
1	22/10/18 17:04	Video - Accident [Linked Accident Report Documents]														Load MP4				
Assessment Reports															1 per page		v	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	26/10/18 12:57	Adjuster Immediate Advice														Load HTM				
2	12/11/18 16:45	Adjuster Immediate Advice														Load HTM				
3	16/11/18 09:51	Adjuster Immediate Advice														Load HTM				
Photos/Images															3 per page		v	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	26/10/18 12:55	General View														Load JPG	☒			
2	26/10/18 12:55	Chassis Number														Load JPG	☒			
3	26/10/18 12:55	General View														Load JPG	☒			
4	26/10/18 12:55	General View														Load JPG	☒			
5	26/10/18 12:55	General View														Load JPG	☒			
6	26/10/18 12:55	General View														Load JPG	☒			
7	26/10/18 12:55	General View														Load JPG	☒			
8	26/10/18 12:55	General View														Load JPG	☒			
9	26/10/18 12:55	General View														Load JPG	☒			
10	26/10/18 12:55	General View														Load JPG	☒			
11	26/10/18 12:55	General View														Load JPG	☒			
12	26/10/18 12:55	General View														Load JPG	☒			
13	26/10/18 12:55	General View														Load JPG	☒			
14	26/10/18 12:55	General View														Load JPG	☒			
15	26/10/18 12:55	General View														Load JPG	☒			
16	26/10/18 12:55	General View														Load JPG	☒			
17	26/10/18 12:55	General View														Load JPG	☒			
18	26/10/18 12:55	General View														Load JPG	☒			
19	26/10/18 12:55	General View														Load JPG	☒			
20	26/10/18 12:55	General View														Load JPG	☒			
21	26/10/18 12:55	General View														Load JPG	☒			
22	26/10/18 12:55	General View														Load JPG	☒			
23	26/10/18 12:55	General View														Load JPG	☒			
24	26/10/18 12:55	General View														Load JPG	☒			
25	26/10/18 12:55	General View														Load JPG	☒			
26	26/10/18 12:55	General View														Load JPG	☒			
27	26/10/18 12:55	General View														Load JPG	☒			
28	26/10/18 12:55	General View														Load JPG	☒			
29	26/10/18 12:55	General View														Load JPG	☒			
30	26/10/18 12:55	General View														Load JPG				

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				☒
31	26/10/18 12:55	General View	 Load JPG	☒
32	26/10/18 12:55	General View	 Load JPG	☒
33	26/10/18 12:55	General View	 Load JPG	☒
34	26/10/18 12:55	General View	 Load JPG	☒
35	26/10/18 12:55	General View	 Load JPG	☒
36	26/10/18 12:55	General View	 Load JPG	☒
37	26/10/18 12:55	General View	 Load JPG	☒
38	26/10/18 12:55	General View	 Load JPG	☒
39	26/10/18 12:55	General View	 Load JPG	☒
40	26/10/18 12:55	General View	 Load JPG	☒
41	26/10/18 12:55	General View	 Load JPG	☒
42	26/10/18 12:55	General View	 Load JPG	☒
43	26/10/18 12:55	General View	 Load JPG	☒
44	26/10/18 12:55	General View	 Load JPG	☒
45	26/10/18 12:55	General View	 Load JPG	☒
46	26/10/18 12:55	General View	 Load JPG	☒
47	26/10/18 12:55	General View	 Load JPG	☒
48	26/10/18 12:55	General View	 Load JPG	☒
49	26/10/18 12:55	General View	 Load JPG	☒
50	26/10/18 12:55	General View	 Load JPG	☒
51	26/10/18 12:55	General View	 Load JPG	☒
52	26/10/18 12:55	General View	 Load JPG	☒
53	26/10/18 12:55	General View	 Load JPG	☒
54	26/10/18 12:55	General View	 Load JPG	☒
55	26/10/18 12:55	General View	 Load JPG	☒
56	26/10/18 12:55	General View	 Load JPG	☒
57	26/10/18 12:55	General View	 Load JPG	☒
58	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
59	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
60	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
61	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
62	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
63	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
64	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
65	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
66	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
67	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
68	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
69	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
70	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
71	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
72	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
73	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
74	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
75	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
76	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
77	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
78	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
79	08/11/18 10:25	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UB1)	Thumbnail	Print
80	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
81	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
82	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
83	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
84	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
85	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
86	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
87	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
88	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
89	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
90	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
91	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
92	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
93	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
94	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
95	08/11/18 10:25	Reinspection Photo	 Load JPG	☒
96	08/11/18 10:26	Reinspection Photo	 Load JPG	☒
97	08/11/18 10:26	Reinspection Photo	 Load JPG	☒
98	08/11/18 10:26	Reinspection Photo	 Load JPG	☒
99	08/11/18 10:26	Reinspection Photo	 Load JPG	☒
100	08/11/18 10:26	Reinspection Photo	 Load JPG	☒
101	08/11/18 10:26	Reinspection Photo	 Load JPG	☒
102	08/11/18 10:26	Reinspection Photo	 Load JPG	☒
103	08/11/18 10:26	Reinspection Photo	 Load JPG	☒
104	08/11/18 10:26	Reinspection Photo	 Load JPG	☒
105	08/11/18 10:26	Reinspection Photo	 Load JPG	☒
106	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
107	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
108	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
109	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
110	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
111	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
112	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
113	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
114	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
115	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
116	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
117	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
118	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
119	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
120	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
121	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
122	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
123	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
124	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
125	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
126	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
127	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
128	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
129	16/11/18 10:09	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
130	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
131	16/11/18 10:09	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/10/18 11:56	DRIVING & INS. CERT.pdf	 Load PDF	
2	26/10/18 12:53	ESTIMATE.pdf	 Load PDF	
3	12/11/18 16:38	SUPPLEMENTARY.pdf	 Load PDF	
4	16/11/18 10:17	SUPPLEMENTARY 2.pdf	 Load PDF	
5	28/03/19 09:42	ESTIMATE & SUPPLEMENTARY MARKED.pdf	 Load PDF	
6	30/04/19 16:08	Workshop Invoice	 Load PDF	
7	30/04/19 16:08	Discharge Voucher	 Load PDF	
8	30/04/19 16:50	Supplementary	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/10/18 17:04	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/10/18 17:29	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/10/18 17:19	Accident Photo	 Load JPG	☒
2	22/10/18 17:19	Accident Photo	 Load JPG	☒
3	22/10/18 17:19	Accident Photo	 Load JPG	☒
4	22/10/18 17:19	Accident Photo	 Load JPG	☒
5	22/10/18 17:19	Accident Photo	 Load JPG	☒
6	22/10/18 17:19	Accident Photo	 Load JPG	☒
7	22/10/18 17:19	Accident Photo	 Load JPG	☒
8	22/10/18 17:19	Accident Photo	 Load JPG	☒
9	22/10/18 17:19	Accident Photo	 Load JPG	☒
10	22/10/18 17:19	Accident Photo	 Load JPG	☒
11	22/10/18 17:19	Accident Photo	 Load JPG	☒
12	22/10/18 17:19	Accident Photo	 Load JPG	☒
13	22/10/18 17:19	Accident Photo	 Load JPG	☒
14	22/10/18 17:19	Accident Photo	 Load JPG	☒
15	22/10/18 17:19	Accident Photo	 Load JPG	☒
16	22/10/18 17:19	Accident Photo	 Load JPG	☒
17	22/10/18 17:19	Accident Photo	 Load JPG	☒
18	22/10/18 17:19	Accident Photo	 Load JPG	☒
19	22/10/18 17:19	Accident Photo	 Load JPG	☒
20	22/10/18 17:19	Accident Photo	 Load JPG	☒
21	22/10/18 17:19	Accident Photo	 Load JPG	☒
22	22/10/18 17:19	Accident Photo	 Load JPG	☒
23	22/10/18 17:19	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/10/18 17:20	Sketch Plan	 Load JPG	

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				☒
2	22/10/18 17:20	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18019435/ASBE2

Date: 30/04/2019

REFERENCE

Insured/Claimant: LAKSHMI NARAYANAN Policy No: 1800035271
Date of Loss: 22/10/2018 Nature of Claim: OD Claim No: 3918351706SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX9643S**
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ907364
Reg. Date: 18/04/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V3J1057092
Colour: Silver Odometer: 3946 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$122,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	61,048.88	39,767.64	21,281.24	34.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,564.00	12,794.00	6,770.00	34.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	80,612.88	52,561.64	28,051.24	34.80
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	80,312.88	52,261.64	28,051.24	34.93
+ GST 7.00/7.00% (S\$)	5,621.90	3,658.31	1,963.59	34.93
Nett Amount (S\$)	85,934.78	55,919.95	30,014.83	34.93

INSPECTION

Date of Assignment: 25/10/2018
Date Inspected: 25/10/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 20.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,739.00 FS	*1,391.20 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	161.00 FS	*- FS
3	2	*FRONT BUMPER GUIDE SECTION - LH/RH	Damaged	66.00 FS	*51.68 FS
4	1	*FRONT BUMPER GRILLE - CENTER	Damaged	140.00 FS	*112.00 FS
5	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	460.00 FS	*368.00 FS
6	2	*FRONT BUMPER CLOSING ELEMENT - LH/RH	Cracked	508.00 FS	*406.40 FS
7	2	*FRONT BUMPER COVER TRIM - LH/RH	Not Necessary	280.00 FS	*- FS
8	1	*CLOSING ELEMENT	Not Necessary	167.00 FS	*- FS
9	2	*FRONT ADAPTER WHEEL HOUSING LINER - LH / RH	Damaged	64.00 FS	*50.72 FS
10	1	*RADIATOR GRILLE	Cracked	1,239.00 FS	*991.20 FS
11	1	*RADIATOR CLOSING ELEMENT	Damaged	167.00 FS	*133.20 FS
12	2	*FRONT BUMPER AIR GUIDE GRILLE - LH/RH	Not Necessary	328.00 FS	*- FS
13	1	*FOAM FILLER PIECE	Cracked	162.00 FS	*129.60 FS
14	1	*SIDE REINFORCEMENT	Bent	633.00 FS	*506.00 FS
15	1	*FRONT BUMPER COVER	Deformed	105.00 FS	*83.60 FS
16	1	*AIR CONDITIONER STICKER	Necessary	7.00 FS	*4.88 FS
17	1	*SIGN CAUTION	Necessary	12.00 FS	*9.28 FS
18	1	*SIGNAL HORN - LOW TONE	Not Necessary	177.00 FS	*- FS
19	1	*SIGNAL HORN - HIGH TONE	Not Necessary	177.00 FS	*- FS
20	1	*FRONT FENDER - LH	Repair	746.00 FS	*- FS
21	1	*FRONT FENDER - RH	Buckled	746.00 FS	*596.80 FS
22	2	*FENDER ATTACHMENT PARTS - LH/RH	Not Necessary	123.00 FS	*- FS
23	1	*FRONT FENDER BRACKET - LH/RH	O/S Bent	68.00 FS	*26.64 FS
24	1	*FRONT FENDER BRACE - LH/RH	O/S Bent	168.00 FS	*67.04 FS
25	1	*BONNET	Distorted	2,755.00 FS	*2,204.00 FS
26	1	*BONNET ATTACHMENT PARTS	Not Necessary	141.00 FS	*- FS
27	2	*BONNET LID HINGE - LH/RH	Bent	106.00 FS	*84.64 FS
28	2	*BONNET STOP BUFFER	Necessary	9.00 FS	*7.20 FS
29	1	*GAS FILLED STRUT	Not Necessary	105.00 FS	*- FS
30	1	*BONNET CATCH HOOK	Bent	78.00 FS	*62.24 FS
31	2	*BONNET TRIKER - LH/RH	Bent	192.00 FS	*152.96 FS
32	1	*BONNET EDGE PROTECTION	Necessary	24.00 FS	*18.88 FS
33	1	*BONNET CATCH HOOK	Bent	55.00 FS	*43.84 FS
34	2	*BONNET LID LOCK WITH MICRO	Damaged	353.00 FS	*282.40 FS
35	1	*BONNET BOWDEN CABLE - CENTER	Damaged	50.00 FS	*40.00 FS
36	1	*BONNET SOUND ABS	Crumpled	192.00 FS	*153.20 FS
37	1	*LENUM CHAMBER COVER	Cut	156.00 FS	*124.80 FS
38	1	*FRONT COWL TRIM	Not Necessary	14.00 FS	*- FS
39	1	*WATER BOX SEAL	Not Necessary	50.00 FS	*- FS
40	1	*FRONT WHEEL HOUSING LINER - RH	Not Necessary	151.00 FS	*- FS
41	1	*WHEEL HOUSING LINER ATTACHEMENT PARTS	Not Necessary	77.00 FS	*- FS
42	2	*LED HEADLIGHT - RH/LH	Cracked	9,776.00 FS	*7,820.80 FS
43	1	*LED HEADLIGHT POWER MODULE	Not Necessary	665.00 FS	*- FS
44	1	*LED HEADLIGHT CONTROL UNIT	Not Necessary	486.00 FS	*- FS
45	1	*LED WITH HEAT SINK - RH	Not Necessary	625.00 FS	*- FS
46	1	*LED HEADLIGHT LIFT CYLINDER - RH	Not Necessary	123.00 FS	*- FS
47	1	*WASH WATER RESERVOIR	Not Necessary	177.00 FS	*- FS
48	1	*LOCK CARRIER WITH MOUNTING COOLANT RADIATOR	Distorted	638.00 FS	*510.40 FS
49	1	*A/C CONDENSER WITH FLUID RESERVOIR	Bent	468.00 FS	*374.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
50	1	*A/C CONDENSER VALVE	Not Necessary	46.00 FS	*- FS
51	1	*PRESSURE SENDER	Not Necessary	165.00 FS	*- FS
52	1	*COOLER FOR COOLANT	Bent	828.00 FS	*662.40 FS
53	1	*ADDITIONAL COOLER FOR COOLANT	Bent	797.00 FS	*639.20 FS
54	1	*COOLANT CONDENSATE	Necessary	133.00 FS	*65.28 FS
55	2	*FRONT BUMPER AIR GUIDE - RH / LH	Not Necessary	40.00 FS	*- FS
56	1	*FRONT BUMPER AIR GUIDE - UPPER CENTRE	Deformed	10.00 FS	*7.68 FS
57	1	*FAN RING	Not Necessary	172.00 FS	*- FS
58	1	*RADIATOR FAN WITH FAN RING	Not Necessary	1,425.00 FS	*- FS
59	1	*FLAT CONNECTOR HOUSING	Not Necessary	15.00 FS	*- FS
60	1	*FRONT BUMPER AIR GUIDE	Deformed	59.00 FS	*46.80 FS
61	1	*SPRING BAND CLAMP	Not Necessary	18.00 FS	*- FS
62	1	*INTAKE MANIFOLD	Not Necessary	124.00 FS	*- FS
63	1	*AIR FILTER	Not Necessary	242.00 FS	*- FS
64	1	*WINDSCREEN	Cracked	953.00 FS	*762.00 FS
65	1	*GEL FOIL FOR RAIL SENSOR	Necessary	127.00 FS	*101.20 FS
66	1	*SPRING CLIP	Not Necessary	19.00 FS	*- FS
67	1	*PRIMER	Necessary	37.00 FS	*29.12 FS
68	1	*FRONT DOOR - RH	Repair	2,190.00 FS	*- FS
69	1	*FRONT OUTER DOOR SEAL - RH	Not Necessary	139.00 FS	*- FS
70	1	*BONDING AGENT	Not Necessary	43.00 FS	*- FS
71	1	*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
72	1	*APPLICATOR	Not Necessary	7.00 FS	*- FS
73	1	*FRONT DOOR ATTACHMENT PARTS - RH	Not Necessary	206.00 FS	*- FS
74	1	*FRONT DOOR CATCH - RH	Not Necessary	92.00 FS	*- FS
75	1	*FRONT DOOR CATCH COVER - RH	Not Necessary	13.00 FS	*- FS
76	1	*FRONT WINDOW SLOT SEAL WITH TRIM STRIP - RH	Not Necessary	268.00 FS	*- FS
77	1	*DATE PLATE FOR TYRE PRESSURE	Not Necessary	25.00 FS	*- FS
78	1	*REFRIGERANT LINE FOR A/C CONDENSER	Not Necessary	582.00 FS	*- FS
79	1	*FRONT NO. PLATE	Bent	25.00 FS	*25.00 FS
80	1	*FRONT W/S SEALANT	Necessary	200.00 FS	*200.00 FS
81	1	*AIR BAG UNIT FOR STEERING WHEEL	Activated	3,111.00 FS	*2,488.80 FS
82	1	*AIR BAG UNIT	Activated	4,060.00 FS	*3,248.00 FS
83	1	*HEAD AIR BAG UNIT	Activated	1,692.00 FS	*1,353.60 FS
84	2	*HEAD AIR BAG GUIDE - LH/RH	Not Necessary	44.00 FS	*- FS
85	1	*KNEE AIR BAG UNIT	Activated	1,692.00 FS	*1,353.60 FS
86	1	*DASHBOARD LOWER BOTTOM TRIM	Not Necessary	397.00 FS	*- FS
87	1	*AIR BAG CONTROL UNIT	Activated	1,538.00 FS	*1,230.40 FS
88	1	*CRASH SENSOR FOR AIR BAG	Activated	716.00 FS	*572.40 FS
89	1	*AIR DUCT DASHBOARD	Torn	3,792.00 FS	*2,983.20 FS
90	1	*MOULDED HEADLINER	Crumpled	1,551.00 FS	*1,240.80 FS
91	2	*GRAB HANDLE, FOLDING - FRONT	Damaged	248.00 FS	*198.40 FS
92	2	*GRAB HANDLR, FOLDING - REAR LH/RH	Damaged	248.00 FS	*198.40 FS
93	2	*THREE POINT AUTOMATIC SEAT BELT - LH/RH	Activated	1,912.00 FS	*1,529.60 FS
94	2	*SEAT BELT HEIGHT ADJUSTER	Damaged	343.00 FS	*274.40 FS
95	2	*A-PILLAR TRIM - LH/RH	Deformed	282.00 FS	*224.80 FS
96	1	*SUNDRIES	Necessary	800.00 FS	*97.08 FS
97	1	*STEERING WHEEL	Cut	1,667.20 FS	*1,667.20 FS
98	1	*BONNET COVER	Cut	6.88 FS	*6.88 FS
99	1	*HOOD PLUG	Missing	28.32 FS	*28.32 FS
100	1	*FENDER TOP SIDE SEAL	Torn	28.16 FS	*28.16 FS
101	1	*AIR DUCT	Cracked	13.76 FS	*13.76 FS
102	1	*AIR DUCT COVER	Cracked	20.32 FS	*20.32 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
103	1		*AIR INLET	Cracked	39.76 FS	*39.76 FS
104	1		*RADIATOR MOUNT	Necessary	59.36 FS	*59.36 FS
105	1		*RADIATOR BUSH	Necessary	13.44 FS	*13.44 FS
106	1		*HEADLIGHT VENT HOSE	Cut	26.72 FS	*26.72 FS
107	1		*COVER FOR SPEAKER - DASHBOARD	Damaged	65.36 FS	*65.36 FS
108	1		*AIR VENT - DASHBOARD	Damaged	105.60 FS	*105.60 FS
109	1		*CURTAIN AIR BAG RHS	Activated	1,353.00 FS	*1,353.00 FS
110	1		*WINDOW GUIDE TRIM STIP - RH	Not Necessary	222.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	61,048.88	39,767.64
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CARRY OUT MEASUREMENT TEST ON CAR-O-LINER	New	800.00	0.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,000.00	1,000.00
4	TO REMOVE AND REINSTALL CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIR BAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAG AND KNEEW AIR BAG	New	3,600.00	3,600.00
5	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH FRONT FENDERS, BOTH HEADLIGHTS, AND RHS FRONT DOOR. REPAIR RHS FENDER TOP SUPPORT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,900.00	3,500.00
7	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, BONNET HINGES, RHS FENDER TOP SUPPORT AND RHS FRONT DOOR	New	5,500.00	3,170.00
8	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
10	TO REMOVE / REINSTALL RHS FRONT DOOR MIRROR ASSY TO FACILITATE RESPRAY	New	300.00	300.00
Gross Labour Cost (S\$)			19,564.00	12,794.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >