

/SS. REG. BY:

REF: CS/ICS1819437 / Tltb n2 Special Instruction:

Surrey

Merriman

ASSIGNMENT (Office)

From (Person): Desmond Lee of ICS Date/Time: 25/10/2018 2:16pm

Estimated Cost: Bill to:

OD / ~~ED~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKL 581X Insured: SJG 3353G

at Workshop m/s Cycle & Carriage. Tel: 9186 5113

of 188 Pandan Loop

Policy No: Claim No: DMP C1800252H

Sum Insured: Excess:

Make of Veh: D.O.A. 30062018

(Client's Record) 'DS'

CA / REV / REP. / REV 24 HRS 29.10.2018 @ after 10am H.O.D. Endorsement:

Date/Time: 25-10-2018 2:49pm Person Contacted: Keryn Vehicle IN / ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate
	SKL 581X - X
	SJG 3353G - X
	Part by part \$7871.58.
	(Red: 2174.29, 21%)

Taufikh

REF:

108

SALES

From

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.

at Workshop n/s

of

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh:

After 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lump Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Kerlyn

Date / Time

Action / Instruction

Veh No.

SKL581X

Yr Regn:

2013 Sp.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Mercedes Benz E200

1991

Make

Colour

Black

A/C

Insured / Std / NI / NA

Sp. Reading

9/4/18

T. Radio

Insured / Std / NI / NA

Eng/No:

91418

C/No:

W1D21203424868209

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A:

D.O.I.

29/10/18

Survey held at

CSC Pander Loop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 14 DEC 2018

Date/Time File Pass to:

14/12 Typist

Date/Time File Return to:



: Preli. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



Site Insp. \$



Interview \$



Tech. Insp. \$



Weekend \$

Survey Fee

Transportation

1. 50-80 \$

2. 80-100 \$

3. 100-150 \$

4. 150-200 \$

5. 200-250 \$

350
10

360

Report Format:

Lump Sum / 10 \$

TP

7371.50

Catherine Chong (LKK Auto)

From: motorsurvey <motorsurvey@ecics.com.sg>
Sent: Thursday, 25 October, 2018 2:18 PM
To: Kerlyn Ong; Janice Goh Siew Geok (ECICS, Claims); motorsurvey; assignments
Cc: ECICS Claims
Subject: RE: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018 / OREF: DMPC1800252H

Hi LKK

Kindly assist with the tppd survey.

Thank you.

Best regards,
Desmond Lee
Claims Division
DID: +65 6303 0167
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Center
Singapore 408600

-----Original Message-----

From: Kerlyn Ong [mailto:kerlyn.ong@cyclecarriage.com.sg]
Sent: Thursday, 25 October, 2018 1:24 PM
To: Janice Goh Siew Geok (ECICS, Claims); motorsurvey
Cc: ECICS Claims
Subject: RE: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018

Dear Officer,

Please arrange to survey on 29/10/2018 after 10am.

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

-----Original Message-----

From: Kerlyn Ong
Sent: Thursday, 25 October, 2018 1:22 PM
To: 'Janice Goh Siew Geok (ECICS, Claims)'
Cc: ECICS Claims

Subject: RE: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018

Dear Janice,

Please arrange to survey on 29/10/2018 after 10am.

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

-----Original Message-----

From: Janice Goh Siew Geok (ECICS, Claims) [mailto:Janice_Goh@ecics.com.sg]

Sent: Wednesday, 10 October, 2018 3:45 PM

To: Kerlyn Ong

Cc: ECICS Claims

Subject: RE: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018

Without Prejudice

Sorry for my late reply.

Liability is clear.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

-----Original Message-----

From: ECICS Claims

Sent: Friday, 3 August, 2018 10:20 AM

To: 'Kerlyn Ong Kai Li'

Subject: RE: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018

Without Prejudice

Dear Kerlyn

We are looking into it and will revert to you next week.
Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Pls note that we're moving our office to new location:
Our new address wef 6 August 2018:
ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

**Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.
Thank you for your kind patience and understanding.**

-----Original Message-----

From: Kerlyn Ong Kai Li [<mailto:kerlyn.ong@cyclecarriage.com.sg>]
Sent: Friday, 3 August, 2018 10:06 AM
To: ECICS Claims
Subject: RE: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018

Dear Officer,

We been sending email in regard to the liability and nobody had revert or update us on the liability?

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

-----Original Message-----

From: Kerlyn Ong Kai Li
Sent: Tuesday, 31 July, 2018 1:05 PM
To: ECICS Claims
Subject: RE: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018

Dear Officer,

We been sending email in regard to the liability and nobody had revert or update us on the liability?

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

-----Original Message-----

From: Kerlyn Ong Kai Li
Sent: Wednesday, 25 July, 2018 2:25 PM
To: 'ECICS Claims'
Subject: RE: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018

Dear Officer,

Any update on the liability?

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

-----Original Message-----

From: Kerlyn Ong Kai Li
Sent: Tuesday, 17 July, 2018 9:37 AM
To: 'ECICS Claims'
Subject: RE: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018

Dear Officer,

Any update on the liability?

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center

Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

-----Original Message-----

From: Kerlyn Ong Kai Li

Sent: Friday, 6 July, 2018 2:04 PM

To: 'ECICS Claims'

Subject: RE: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018

Dear Officer,

Any update on the liability?

Your Sincerely,

Kerlyn Ong

Service Advisor - Body Care & Repair

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

188 Pandan Loop Service Center

Mobile: 91865113 | DID: 67714420 | Fax: 68721272

Website: www.mercedes-benz.com.sg

-----Original Message-----

From: Kerlyn Ong Kai Li

Sent: Monday, 2 July, 2018 3:55 PM

To: ECICS Claims

Subject: Accident involving motor vehicle nos. SKL581X & SJG3353G along NO.12 WEST COAST DR, Accident date: 30/06/2018

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SKL581X), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SJG3353G) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at kerlyn.ong@cyclecarriage.com.sg.

Your Sincerely,

Kerlyn Ong

Service Advisor - Body Care & Repair

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

188 Pandan Loop Service Center

Mobile: 91865113 | DID: 67714420 | Fax: 68721272

Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

[ECICS Facebook] [ECICS Twitter] [ECICS Limited]

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/07/2018 14:52
Date Of Accident	30/06/2018 13:00
Exact Location Of Accident	NO 12 WEST COAST DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL581X
Insured/Policyholder	
Name Of Registered Owner	HIGH-TECH ENGINEERING PTE LTD
Co Reg No	200602944W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94892834

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA126129/1
Cover Note Number	

Driver

Name of Driver	TIAN HONG
NRIC No	S2686090C
Date Of Birth	03/04/1964
Occupation	INDOOR
Date Of Driving Pass	30/11/2001
Driving Experience	16 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94892834
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	7 PIONEER WALK
Postcode	627774
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : HUANG LI
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING MY CAR ALONG WEST COAST DRIVE. AS I WAS APPROACHING NO 12 WEST COAST DR. CAR B (SJG3353G) REVERSED HIS VEHICLE FROM HIS CAR WITHOUT NOTICING MY CAR AND COLLIDED ONTO MY LEFT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG3353G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN WEE HOCK
NRIC/Passport Number	S1562638J
Contact Number	
Address	
Postcode	
Insurance Company Name	ECICS LIMITED
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Policyholder's Signature

Date & Time



Driver's Signature

(If driver is not the policyholder)


Date & Time 02/07/2018 1407

Reporting Centre Personnel's

Name: KERLYN

NRIC/FIN No.:

SKETCH PLAN



A: SKL581X

B: SJG3353G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING MY CAR (SKL581X) ALONG WEST COAST DRIVE. AS I WAS APPROACHING NO.12 WEST COAST DR, VEHICLE B (SJG3353G) REVERSED HIS VEHICLE FROM HIS CAR WITHOUT NOTICING MY CAR AND COLLIDED ONTO MY LEFT PORTION.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time 02/07/2018 1407

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarrriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop
Name: KERLYN
NRIC/FIN No.:



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKL581X

High-Tech Engineering Pte Ltd

7 Pioneer Walk
Singapore 627774
(attn : Mr Tian Hong)

Mobile: 94892834

Vehicle & Document Information

WIP No 24866
Reg No/Reg Date SKL581X / 26/09/2013
Date In/Mileage / 0
Chassis No WDD2120342A868109
Engine No 27492030096152
Make/Model MB/E 200 2.0 CGI SEDAN (W212)
Colour/Trim 021 197 Obsidian B1/ 042 274 Leather Jav

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	02/07/2018/ 15:11	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : GA126129/1 // 30/06/2018 DRIVE IN/EXCESS : 02/07/2018 // SJG3353G - ECICS DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				11920 2880.00
A BPIRES RESPRAY LH/ FRONT FENDER, LH/ FRONT DOOR & LH/ RUNNING BOARD				1500 1300 1800.00
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	✓✓ 380.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT			0.19	✓✓ 400.00
M LH/ FRONT DOOR	1.00	2069.88	00.00	2069.88
M LH/ FRONT DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
M LH/ FRONT DOOR TOP INSULATION	1.00	32.68	00.00	32.68
M LH/ FRONT DOOR BOTTOM INSULATION	1.00	26.48	00.00	26.48
M LH/ FRONT DOOR INSULATION	1.00	138.31	00.00	138.31
M LH/ FRONT DOOR ORNAMENTAL COVER	1.00	85.80	00.00	85.80
M LH/ FRONT DOOR SEALING RAIL	1.00	106.27	00.00	106.27
M LH/ FRONT DOOR WINDOW GUIDE RAIL	1.00	108.17	00.00	108.17
M LH/ WING MIRROR FRAME	1.00	949.95	00.00	949.95
M LH/ WING MIRROR HOUSING	1.00	419.98	00.00	419.98
M LH/ WING MIRROR LOWER TRIM	1.00	174.33	00.00	174.33
M LH/ FRONT DOOR CHROME MOULDING	1.00	120.99	00.00	120.99
M LH/ FRONT FENDER CHROME MOULDING	1.00	43.10	00.00	43.10

Signature
21/10/18

Tan Jiah 9749549
-wp-
29/10/18 @ 130 pm
04-05 days
sure (11/10/18 to 10/11/18)

LKK Auto Consultants hence notify
the Repairer of the following:

Confirmed & accepted by

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp
is subject to final approval from Insurance Company

Kerlyn Ong Kai Li

DID 36771 4420 HP: 9186 5113

Email: kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Nett 10,016.66
7% GST on 10016.66 701.17

Total Payable 10,717.83

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKL581X

High-Tech Engineering Pte Ltd

7 Pioneer Walk
Singapore 627774
(attn : Mr Tian Hong)

Mobile: 94892834

Vehicle & Document Information

WIP No 24866
Reg No/Reg Date SKL581X / 26/09/2013
Date In/Mileage 29/10/2018/ 91418
Chassis No WDP2120342A868109
Engine No 27492030096152
Make/Model MB/E 200 2.0 CGI SEDAN (W212)
Colour/Trim 021 197 Obsidian Bl/ 042 274 Leather Jav

Account No	Terms	Date/Time Printed	CSE	Operator
CTP00001	Cash	02/11/2018/ 16:36	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M. BPNSUN

POLICY NO/ACC DATE : GA126129/ // 30/06/2018
DRIVE IN/EXCESS : 02/07/2018 // SJ933536 - 501CS
DATE IN/DATE SURVEY: 29/10/2018 1330 // LKK - TAUFIKH
DIRECT SETTLEMENT : 10/10/2018 // ECICS - JANICE

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESpray LH/ FRONT FENDER, LH/ FRONT DOOR & LH/ RUNNING BOARD

A BPILAB

USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR.NETT

X LH/ FRONT DOOR	1.00	2069.88	00.00	2069.88
X LH/ FRONT DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
X LH/ FRONT DOOR TOP INSULATION	1.00	32.68	00.00	32.68
X LH/ FRONT DOOR BOTTOM INSULATION	1.00	26.48	00.00	26.48
X LH/ FRONT DOOR INSULATION	1.00	138.31	00.00	138.31
X LH/ FRONT DOOR ORNAMENTAL COVER	1.00	85.80	00.00	85.80
X LH/ FRONT DOOR SEALING RAIL	1.00	106.27	00.00	106.27
X WINDOW GUIDE RAIL	1.00	133.83	00.00	133.83
X LH/ WING MIRROR HOUSING	1.00	419.98	00.00	419.98
X LH/ WING MIRROR LOWER TRIM	1.00	174.33	00.00	174.33
X LH/ FRONT DOOR CHROME MOULDING	1.00	120.99	00.00	120.99
X LH/ FRONT FENDER CHROME MOULDING	1.00	43.10	00.00	43.10
X RIVET	10.00	3.12	00.00	31.20
X TREENAIL	3.00	2.67	00.00	8.01

Finalization

Confirmed & accepted by

Nett 7,371.58
7% GST on 7871.58 551.01
Total Payable 8,422.59

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKL581X

High-Tech Engineering Pte Ltd

7 Pioneer Walk
Singapore 627774
(attn : Mr Tian Hong)

Mobile: 94892834

Vehicle & Document Information
WIP No **24866**
Reg No/Reg Date **SKL581X / 26/09/2013**
Date In/Mileage **29/10/2018/ 91418**
Chassis No **WDP2120342A868109**
Engine No **27492030096152**
Make/Model **MB/E 200 2.0 CGI SEDAN (W212)**
Colour/Trim **021 197 Obsidian Bl/ 042 274 Leather Jav**

Account No	Terms	Date/Time Printed	CSE	Operator
CTP00001	Cash	02/11/2018/ 16:34	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RIVET	10.00	3.12	00.00	31.20
X TREENAIL	3.00	2.67	00.00	8.01

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **39.21** **2.74**
Nett 39.21
Total Payable 41.95

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18019437/T1TBN2

Date: 20/12/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC18A00141800
Claimant Vehicle No :	SKL581X	Insured Vehicle No :	SJG3353G
Date of Loss:	30/06/2018	Nature of Claim:	TP
		Claim No:	DMPC1800252H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL581X	Engine No:	27492030096152
Make & Model:	MERCEDES-BENZ E200, 2.0 CGI SEDAN (A)	Chassis No:	WDD2120342A868109
Reg. Date:	26/09/2013 (Man. Year: 2013)	Odometer:	91418 km
Colour:	Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R17	Rear Tyre Size:	245/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,621.53	3,671.58	949.95	20.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,460.00	4,200.00	1,260.00	23.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,081.53	7,871.58	2,209.95	21.92
+ GST 7.00/7.00% (S\$)	705.71	551.01	154.70	21.92
Nett Amount (S\$)	10,787.24	8,422.59	2,364.65	21.92

INSPECTION

Date of Assignment:	25/10/2018	
Date Inspected:	29/10/2018	Inspected At:
		Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2018)
Parts:	143	MERCEDES-BENZ E200 2.0 CGI SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL581X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH/FRONT DOOR	Dented	2,069.88 FS	*2,069.88 FS
2	1		*LH/FRONT DOOR WEATHERSTRIP	Necessary	280.72 FS	*280.72 FS
3	1		*LH/FRONT DOOR TOP INSULATION	Necessary	32.68 FS	*32.68 FS
4	1		*LH/FRONT DOOR BOTTOM INSULATION	Necessary	26.48 FS	*26.48 FS
5	1		*LH/FRONT DOOR INSULATION	Necessary	138.31 FS	*138.31 FS
6	1		*LH/FRONT DOOR ORNAMENTAL COVER	Necessary	85.80 FS	*85.80 FS
7	1		*LH/FRONT DOOR SEALING RAIL	Necessary	106.27 FS	*106.27 FS
8	1		*LH/FRONT DOOR WINDOW GUIDE RAIL	Necessary	133.83 FS	*133.83 FS
9	1		*LH/WING MIRROR FRAME	Not Necessary	949.95 FS	*- FS
10	1		*LH/WING MIRROR HOUSING	Cut	419.98 FS	*419.98 FS
11	1		*LH/WING MIRROR LOWER TRIM	Cut	174.33 FS	*174.33 FS
12	1		*LH/FRONT DOOR CHROME MOULDING	Necessary	120.99 FS	*120.99 FS
13	1		*LH/FRONT FENDER CHROME MOULDING	Necessary	43.10 FS	*43.10 FS
14	10		*RIVET	Necessary	31.20 FS	*31.20 FS
15	3		*REENAIL	Necessary	8.01 FS	*8.01 FS
Total Parts (\$\$)					4,621.53	3,671.58

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	2,880.00	1,920.00
2	RESPRAY LH/FRONT FENDER,LH/FRONT DOOR & LH/RUNNING BOARD	New	1,800.00	1,500.00
3	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
4	REMOVE & TRANSFER DOOR MECHANICAL & ELECTRICAL INSTALL TO NEW DOOR	New	400.00	400.00
Gross Labour Cost (S\$)			5,460.00	4,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >