

ASS. REC. BY:

REF: CS/CTI18019440/ 71ad3n2 Special Instruction:

Surveyor: Tauitch ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 25/10/18 @ 4:05 pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLE 4446C Insured: PA 8701M

at Workshop m/s Vermogen Ace Tel: 6358 3031

of G Benof see for

Policy No: OMBISN1745021802 Claim No: SNM18D05064C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23/10/18
(Client's Record)

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement: 26/10/18

Date/Time: 4:44pm @ 25/10/18 Person Contacted: pila Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE 4446C - NBA / CTI 18019306 / Y DOA: 23/10/18
12/11/18	PA 8701M - NBA / CTI 18019306 / Y DOA: 23/10/18 Tan Ahn finalised vs \$10900, 12 days. Cred \$ 20832.68, 66%.

Supervisor: Taylor

REF: CTI

ASSIGNMENT

From: Date: 26/10/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 4446C

at Workshop m/s Vermogen
of G Beroi Sector

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: \$ 67K.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{cup}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLE 4446C Yr Regn: 20/6 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: Honda Vezel 1.5 c.c. 1996

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 44396 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RU1111715.1

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modf: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 29/10/18

Survey held at Vermogen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair cost \$ 16K. Note: 50,852
RECEIVED 19 MAR 2019	

Date/Time, File Pass to? 1) 19/3 2019
Preli. Report
Final Report

Days Of Repair: 12
Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
\$ + RS, SI	
Photos	
Others	
220	
TOTAL	

Date/Time, File Return to? 2)
Report Format: WEP-TP
Lump Sum / L.B.F. (\$): 10900

Add Fee:
 Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2018		25 Oct 2018 16:05 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S LONGLIM PTE LTD, Co. Reg. No.: 201109995N		
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SLE4446C	Date of Loss:	23/10/2018 19:00 - :59
Claim Type:	TP / SNM18D05064C02	Policy/Cover Note No.:	DMB15N1745021802 (Comprehensive)
Vehicle Reg. No. (Insured):	PA8701M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector, 629904 Jurong West - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/11/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Minoko Chan <minoko@vermogen-group.com>
Sent: Thursday, 17 January 2019 11:05 AM
To: Shiau Chan (LKKAuto)
Cc: Taufikh (LKKAuto); SUR; Pila Ng; Tejano Exequiel Dawal; Baldoz Juan Paulo Bongon; desmond; Vmg admin; Vermogen Ace
Subject: Re: SLE4446C finalise

Dear Taufik,

As spoken just now, we agreed to accept your revise COR @ lump sum \$10,900.00 & 12 repair days (excluding PRS/RS/Weekend & PH).

Thank you.

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

On Thu, Nov 29, 2018 at 5:35 PM Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Minoko,

Please refer to the attachment.

Best Regards,

Shiau Chan (Ms) | Case Handler

Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	SLE4446C		
Vehicle Type:	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	HONDA		
Vehicle Model:	VEZEL 1.5X CVT		
Chassis No.:	RU11117151		
Propellant:	Petrol		
Engine No.:	L15B4037164		
Engine Capacity:	1496 cc		
Maximum Power Output:	96.0 kW (128 bhp)		
Maximum Laden Weight:	1465 kg		
Unladen Weight:	1190 kg		
Year Of Manufacture:	2016		
Original Registration Date:	22 Jul 2016		
Lifespan Expiry Date:	-		
COE Category:	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium:	\$55,200.00		
COE Expiry Date:	21 Jul 2026		
Road Tax Expiry Date:	21 Jan 2019		
PARF Eligibility Expiry Date:	21 Jul 2026		
Inspection Due Date:	21 Jul 2019		
Intended Transfer Date:	12 Dec 2018		
CO2 Emission:	117.00 (g/km)		
CEV/VES Rebate Utilised Amount:	\$10,000.00		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
<p>The current road tax expiry is 21 Jan 2019. You may renew the road tax from 22 Oct 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 21 Jan 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.</p> <p>Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.</p>			
Amount Payable (From 22 Jan 2019 to 21 Jul 2019)			
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	341.00	-	341.00
Total Amount Payable:			366.00
Amount Payable (From 22 Jan 2019 to 21 Jan 2020)			
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	682.00	-	682.00
Total Amount Payable:			707.00

You may print this page for reference.

OK

Print

Denise Tay (LKKAuto)

From: minoko@vermogen-group.com
Sent: Wednesday, 31 October 2018 11:25 AM
To: Taufikh (LKKAuto)
Cc: SUR; 'Pila Ng'; 'Tejano Exequiel Dawal'; 'juan paulo baldoz'; 'Desmond Kor'; 'vmg.vermogenace'; 'Vermogen Ace'
Subject: *SLE4446C* ~~SLE430Z~~ CHECK ITEM PHOTO
Attachments: 0b1f4e2f-0b3c-4d78-b47b-66253c8b87bb.jpg; 8f0f14d2-f284-4354-9c21-6e9d2c82fed4.jpg; 9ca8615b-c8f1-416d-8c6d-fdb412a7a7aea.jpg; 9320bc0d-882c-4f27-a37e-4b15e217cb42.jpg; de047ff3-ba90-4304-be00-3de2959d0214.jpg

Dear Taufik,

Attach here check item as your request.

Kindly check & revert.

Thank you

Best Regards,

Minoko
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929



SLE4446C

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 23/10/2018

Vehicle Reg. No. : SLE4446C
Vehicle Reg. Date: 22-Jul-2016
Make / Model : VEZEL 1.5X CVT
Engine No. : L15B4037164
Chassis No. : RU11117151

COST OF CLAIMS

Parts Cost / List Items : \$ 25,507.10
Plus/Less 20% \$ 5,101.42
Total Cost / List : \$ 20,405.68
Special Nett Items : \$ 1,015.00
Total Parts Amount : \$ 21,420.68
Total Labour Amount : \$ 9,180.00
Gross Total : \$ 30,600.68
GST % : 7% \$ 2,142.05
Nett Amount : \$ 32,742.73

Surveyor Name and Company :

Tanfah 92495749

Date of survey : 24/10/18 6:50

Part by Part / Lump Sum : 12 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : s10e/klampun

Fax No :

HP No :

Handwritten signature and date 21/10/18

Handwritten number 31732.65

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a 'Without Prejudice' basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company
Acknowledged by Repairer
Signature:
Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLE4446C
 Vehicle Reg. Date: 22/7/2016
 Make / Model : VEZEL 1.5X CVT
 Engine No. : L15B4037164
 Chassis No. : RU11117151

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	TAILGATE WINDSCREEN	wa	\$ 1,150.10	0950	
2	1	TAILGATE WINDSCREEN MLDG SET	wa	\$ 140.00		
3	1	TAILGATE	bt	\$ 1,100.90	"	
4	2	TAILGATE HINGE	bt	\$ 100.00		
5	1	TAILGATE SPOILER	wa	\$ 430.20		
6	1	THIRD BRAKE LIGHT	x	\$ 280.00		
7	1	TAILGATE OUTER GARNISH	wa	\$ 285.00		
8	1SET	TAILGATE OUTER GARNISH CLIPS	wa	\$ 40.00		
9	1	TAILGATE LOGO	wa	\$ 52.00		
10	1	TAILGATE EMBLEM "VEZEL"	wa	\$ 56.20		
11	2	TAILGATE LAMP LH/RH	wa	\$ 920.20		
12	1SET	TAILGATE CLIPS	wa	\$ 40.00		
13	1	TAILGATE OUTER HANDLE SWITCH	dis	\$ 180.00		
14	2	TAILGATE DAMPER LH/RH	bt	\$ 424.00	360	
15	1	TAILGATE INNER TRIM LOWER	de	\$ 153.40		
16	1SET	TAILGATE INNER TRIM LOWER CLIPS	wa	\$ 45.00		
17	2	TAILGATE INNER TRIM UPPER LH/RH	de	\$ 100.60		
18	1	TAILGATE WEATHERSTRIP	wa	\$ 96.80		
19	1	TAILGATE LOCK SENSOR	wa	\$ 157.10		
20	1	TAILGATE BUZZER	wa	\$ 85.00		
21	1	REAR ANTENNA SENSOR	x	\$ 58.70		
22	1	TAILGATE WIPER NOZZEL	x	\$ 28.00		
23	1	TAILGATE WIPER BLADE	wa	\$ 48.60		
24	1	TAILGATE WIPER MOTOR	bt	\$ 205.00		
25	1	TAILGATE INNER HANDLE	de	\$ 74.00		
26	1	TAILGATE INNER LOCK	wa	\$ 245.00		
27	1	TAILGATE STRIKER	bt	\$ 55.00		
28	1	TAILGATE RUBBER STOPPER	wa	\$ 96.00		
29	1SET	REAR NUMBER PLATE LAMP	dis	\$ 165.20		
30	1	REAR BUMPER	de	\$ 508.50		
31	1SET	REAR BUMPER CLIPS	wa	\$ 50.00		
32	2	REAR BUMPER RETAINER LH/RH	wa	\$ 144.00		
33	2	REAR BUMPER SIDE COVER LH/RH	LH-de, RH-RP	\$ 390.00		
34	2	REAR BUMPER REFLECTOR LH/RH	x	\$ 296.60		
35	1	REAR END PANEL INNER	RP	\$ 415.60		
36	1	REAR END PANEL OUTER	bt	\$ 415.60		
37	1	REAR END PANEL TOP GARNISH	de	\$ 185.00		
38	1	REAR END PANEL TOP GARNISH CLIPS	wa	\$ 25.00		
39	1	SPARETYRE PANEL	RP	\$ 662.20		
40	1	SPARETYRE INSULATOR	x	\$ 186.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLE4446C
 Vehicle Reg. Date: 22/7/2016
 Make / Model : VEZEL 1.5X CVT
 Engine No. : L15B4037164
 Chassis No. : RU11117151

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	SPARETYRE TOOL TRAY	9 Can	\$ 225.00		
42	1	SPARETYRE TOP BOARD	9 de	\$ 186.00		
43	1	EXHAUST MUFFLER	X nn	\$ 528.00		
44	1	EXHAUST MUFFLER RUBBER MOUNTING	X nn	\$ 36.00		
45	1	EXHAUST MUFFLER HEAT SHIELD	X nn	\$ 165.00		
46	2	TAIL LAMP LH/RH	LH Can, RH Can	\$ 857.40		
47	1set	TAIL LAMP CLIPS	nn	\$ 36.00		
48	2	TAIL LAMP PANEL LH/RH	LH-Can, RH-X	\$ 270.00		
49	2	REAR FENDER LH/RH	LH-Can, RH-X	\$ 1,809.40	904.70	
50	2	REAR FENDER QTR GARNISH LH/RH	LH-Can, RH-Can	\$ 76.00		
51	2	REAR FENDER ARC GARNISH LH/RH	LH-Can, RH-Can	\$ 195.40		
52	2	REAR FENDER INNER TRIM UPPER LH/RH	LH-Can, RH-Can	\$ 73.00	de	
53	2	REAR FENDER INNER TRIM LOWER LH/RH	LH-Can, RH-Can	\$ 590.00	de	
54	2	REAR WHEEL HOUSE LH/RH	RY	\$ 1,457.20		
55	2	REAR FENDER UNDERSHIELD LH/RH	X nn	\$ 180.40		
56	1set	REAR FENDER UNDERSHIELD CLIPS	X nn	\$ 80.00		
57	1	FUEL LID COVER	RY	\$ 65.00		
58	2	REAR FENDER AIR DUCT LH/RH - 7 nn	de	\$ 150.00		
59	2	REAR CHASSIC MEMBER LH/RH	LH-Can, RH-Can	\$ 1,440.00	nn	
60	1	REAR NUMBER PLATE WITH FRAME	bt	\$ 55.00		45
61	1	TAILGATE WINDSCREEN SEALANT	neg	\$ 80.00		
62	1	TAILGATE WINDSCREEN INNER SEAL	neg	\$ 80.00		
63	1	REAR END PANEL SEALANT	wcd	40	\$ 80.00	
64	1	SPARETYRE PANEL SEALANT	X nn	\$ 80.00		
65	1	SPARETYRE PANEL PADDING	X nn	\$ 80.00		
66	1	REAR FENDER SEALANT	nn	50	\$ 80.00	
67	1	REVERSE SENSOR	nn	\$ 80.00		
68	1	REVERSE CAMERA	X nn	\$ 300.00		
69	1	REAR DOOR sticker	X nn	\$ 80.00		
70	2	REAR DOOR STICKER	LH-Can, RH-Can	\$ 1,861.20	R	
71	2	REAR DOOR HINGE TOP	X	\$ 40.00		
72	2	REAR DOOR HINGE BOTTOM	X	\$ 96.00		
73	2	REAR DOOR CHECKER	X	\$ 96.00		
74	2	REAR DOOR WEATHERSTRIP	X	\$ 110.00		
75	2	REAR DOOR STRIKER	X	\$ 190.40		
76	2	REAR DOOR RUBBER TOP	X	\$ 220.00		
77	2	REAR DOOR RUBBER LOWER	X	\$ 29.80		
78	2	REAR DOOR RUBBER FRT	X	\$ 58.40		
79	2	REAR DOOR POWER WINDOW MOTOR	X	\$ 780.00		
80	2	REAR DOOR POWER WINDOW MECHANISM	X	\$ 420.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLE4446C
 Vehicle Reg. Date: 22/7/2016
 Make / Model : VEZEL 1.5X CVT
 Engine No. : L15B4037164
 Chassis No. : RU11117151

PAGE 3

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
81	2	REAR DOOR TRIM	X	\$ 1,270.00		
82	2	REAR DOOR TRIM CLIPS	X	\$ 50.00		
83	2	REAR DOOR SPEAKER	X	\$ 191.00		
84	2	REAR DOOR OUTER HANDLE	X	\$ 196.00		
85	2	REAR DOOR INNER HANDLE	X	\$ 130.00		
86	2	REAR DOOR WINDOW SWITCH	X	\$ 96.00		
87	2	REAR DOOR GLASS	X	\$ 856.00		
88	2	REAR OUTER MOULDING	X	\$ 130.00		
89	2	REAR DOOR RUN CHANNEL	X	\$ 176.00		
90	1	REAR WINDSCREEN GLASS DECAL	new		\$ 20.00	
91	0	0 <i>Roof lining</i>				
92	0	0 <i>Spring type handles top door lock bracket X2.</i>				
93	0	0 <i>tailgate inner trim upper center</i>				
94	0	0				
95	0	0				
96	0	0				
97	0	0				
98	0	0				
99	0	0				
100	0	0				
101	0	0				
102	0	0				
103	0	0				
104	0	0				
105	0	0				
106	0	0				
107	0	0				
108	0	0				
109	0	0				
110	0	0				
111	0	0				
112	0	0				
113	0	0				
114	0	0				
115	0	0				
116	0	0				
117	0	0				
118	0	0				
119	0	0				
120	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLE4446C
 Vehicle Reg. Date: 22/7/2016
 Make / Model : VEZEL 1.5X CVT
 Engine No. : L15B4037164
 Chassis No. : RU11117151

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To straighten and panel beating accident area. Rear Portion.	\$ 3,000.00	1600 / 1600
2	To putty, respray painting and polish accident area. Rear Portion.	\$ 3,500.00	1800 / 1600
3	To check and rectify wiring after disconnect and connect.	\$ 180.00	650.
4	To remove and refit interior trims and upholstery.	\$ 280.00	100.
5	To remove and transfer tailgate components.	\$ 180.00	60.
6	To remove and refit tailgate windscreen.	\$ 180.00	120.
7	To remove and refit exhaust pipe and align	\$ 250.00	x nm
8	To remove and refit reverse sensor.	\$ 180.00	30.
9	To rust proof affected areas.	\$ 200.00	100.
10	To remove & refit reverse camera	\$ 180.00	x nm
11	To remove & install rear both door components	\$ 350.00	x nm
12	^{Repair} To mount vehicle chassis alignment	\$ 350.00	200 / 150
13	To reset fault code light on	\$ 350.00	100 / 150

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

44 Benoi Road, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLE4446C
 Vehicle Reg. Date: 22/7/2016
 Make / Model : VEZEL 1.5X CVT
 Engine No. : L15B4037164
 Chassis No. : RU11117151

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	ROOF LINING <i>board lock</i>		\$ 1,250.00		\$ 1,250.00
2	2	SPARE TYRE TOP BAR LOCK BRACKET		\$ 90.00		\$ 90.00
3	1	TAILGATE INNER TRIM UPPER CENTER		\$ 75.00		\$ 75.00
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

*750. de ✓
 cm ✓
 de ✓*

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO: LKK-TAUFIK
Surveyor Name and Company

Date of Accident : 23/10/2018

BILL TO: CHINA TAIPING
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SLE4446C

Make / Model : VEZEL 1.5X CVT

COST OF CLAIMS

Parts Cost / List : \$ 10,889.00

Supp. Parts : \$ 1,415.00

Special Nett : \$ 395.00

Total Parts : \$ 10,238.20

Total Labour : \$ 4,210.00

TOTAL REPAIR COST : \$ 14,448.20

Total Parts Cost/List :	<u>\$</u>	<u>12,304.00</u>
Plus / Less : <u>20%</u>	<u>\$</u>	<u>2,460.80</u>
Total :	<u>\$</u>	<u>9,843.20</u>

Lump Sum Discount : <u>20%</u>	<u>\$</u>	<u>2,889.64</u>
Lump Sum Amount:	<u>\$</u>	<u>11,558.56</u>

Final Lump Sum Amount : \$ 11,550.00

Submitted by / Date : MINOKO

No. of Repair Days: 12

Confirmed by / Date : _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE4446C**
 Vehicle Reg. Date: 22/7/2016
 Make / Model : VEZEL 1.5X CVT
 Engine No. : L15B4037164
 Chassis No. : RU11117151

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	TAILGATE WINDSCREEN		\$ 1,150.10		\$ 1,150.10
2	1	TAILGATE WINDSCREEN MLDG SET		\$ 140.00		\$ 140.00
3	1	TAILGATE		\$ 1,100.90		\$ 1,100.90
4	2	TAILGATE HINGE		\$ 100.00		\$ 100.00
5	1	TAILGATE SPOILER		\$ 430.20		
6	1	THIRD BRAKE LIGHT		\$ 280.00		
7	1	TAILGATE OUTER GARNISH		\$ 285.00		\$ 285.00
8	1SET	TAILGATE OUTER GARNISH CLIPS		\$ 40.00		\$ 40.00
9	1	TAILGATE LOGO		\$ 52.00		\$ 52.00
10	1	TAILGATE EMBLEM "VEZEL"		\$ 56.20		\$ 56.20
11	2	TAILGATE LAMP LH/RH		\$ 920.20		\$ 920.20
12	1SET	TAILGATE CLIPS		\$ 40.00		\$ 40.00
13	1	TAILGATE OUTER HANDLE SWITCH		\$ 180.00		\$ 180.00
14	2	TAILGATE DAMPER LH/RH		\$ 424.00		\$ 424.00
15	2	TAILGATE INNER TRIM LOWER		\$ 153.40		\$ 153.40
16	1SET	TAILGATE INNER TRIM LOWER CLIPS		\$ 45.00		\$ 45.00
17	2	TAILGATE INNER TRIM UPPER LH/RH		\$ 100.60		\$ 100.60
18	1	TAILGATE WEATHERSTRIP		\$ 96.80		\$ 96.80
19	1	TAILGATE LOCK SENSOR		\$ 157.10		\$ 157.10
20	1	TAILGATE BUZZER		\$ 85.00		\$ 85.00
21	1	REAR ANTENNA SENSOR		\$ 58.70		
22	1	TAILGATE WIPER NOZZEL		\$ 28.00		
23	1	TAILGATE WIPER BLADE		\$ 48.60		\$ 48.60
24	1	TAILGATE WIPER MOTOR		\$ 205.00		\$ 205.00
25	1	TAILGATE INNER HANDLE		\$ 74.00		\$ 74.00
26	1	TAILGATE INNER LOCK		\$ 245.00		\$ 245.00
27	1	TAILGATE STRIKER		\$ 55.00		\$ 55.00
28	1	TAILGATE RUBBER STOPPER		\$ 96.00		\$ 96.00
29	1SET	REAR NUMBER PLATE LAMP		\$ 165.20		\$ 165.20
30	1	REAR BUMPER		\$ 508.50		\$ 508.50
31	1SET	REAR BUMPER CLIPS		\$ 50.00		\$ 50.00
32	2	REAR BUMPER RETAINER LH/RH		\$ 144.00		\$ 144.00
33	2	REAR BUMPER SIDE COVER LH/RH		\$ 390.00		\$ 180.00
34	2	REAR BUMPER REFLECTOR LH/RH		\$ 296.60		
35	1	REAR END PANEL INNER		\$ 415.60		
36	1	REAR END PANEL OUTER		\$ 415.60		\$ 415.60
37	1	REAR END PANEL TOP GARNISH		\$ 185.00		\$ 185.00
38	1	REAR END PANEL TOP GARNISH CLIPS		\$ 25.00		\$ 25.00
39	1	SPARETYRE PANEL		\$ 662.20		
40	1	SPARETYRE INSULATOR		\$ 186.00		\$ 186.00

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLE4446C
 Vehicle Reg. Date: 22/7/2016
 Make / Model : VEZEL 1.5X CVT
 Engine No. : L15B4037164
 Chassis No. : RU11117151

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	SPARETYRE TOOL TRAY		\$ 225.00		\$ 225.00
42	1	SPARETYRE TOP BOARD		\$ 186.00		\$ 186.00
43	1	EXHAUST MUFFLER		\$ 528.00		
44	1	EXHAUST MUFFLER RUBBER MOUNTING		\$ 36.00		
45	1	EXHAUST MUFFLER HEAT SHIELD		\$ 165.00		
46	2	TAIL LAMP LH/RH		\$ 857.40		\$ 857.40
47	1set	TAIL LAMP CLIPS		\$ 36.00		\$ 36.00
48	2	TAIL LAMP PANEL LH/RH		\$ 270.00		\$ 135.00
49	2	REAR FENDER LH/RH		\$ 1,809.40		\$ 904.70
50	2	REAR FENDER QTR GARNISH LH/RH		\$ 76.00		
51	2	REAR FENDER ARC GARNISH LH/RH		\$ 195.40		\$ 97.70
52	2	REAR FENDER INNER TRIM UPPER LH/RH		\$ 73.00		\$ 73.00
53	2	REAR FENDER INNER TRIM LOWER LH/RH		\$ 590.00		\$ 590.00
54	2	REAR WHEEL HOUSE LH/RH		\$ 1,457.20		
55	2	REAR FENDER UNDERSHIELD LH/RH		\$ 180.40		
56	1set	REAR FENDER UNDERSHIELD CLIPS		\$ 80.00		
57	1	FUEL LID COVER		\$ 65.00		
58	2	REAR FENDER AIR DUCT LH/RH		\$ 150.00		\$ 75.00
59	2	REAR CHASSIC MEMBER LH/RH		\$ 1,440.00		
60	1	REAR NUMBER PLATE WITH FRAME			\$ 45.00	
61	1	TAILGATE WINDSCREEN SEALANT			\$ 80.00	
62	1	TAILGATE WINDSCREEN INNER SEAL			\$ 80.00	
63	1	REAR END PANEL SEALANT			\$ 40.00	
64	1	SPARETYRE PANEL SEALANT			\$ -	
65	1	SPARETYRE PANEL PADDING			\$ -	
66	1	REAR FENDER SEALANT			\$ 50.00	
67	1	REVERSE SENSOR			\$ 80.00	
68	1	REVERSE CAMERA			\$ -	
69	2	REAR DOOR			\$ -	
70	2	REAR DOOR STICKER		\$ 1,861.20		
71	2	REAR DOOR HINGE TOP		\$ 40.00		
72	2	REAR DOOR HINGE BOTTOM		\$ 96.00		
73	2	REAR DOOR CHECKER		\$ 96.00		
74	2	REAR DOOR WEATHERSTRIP		\$ 110.00		
75	2	REAR DOOR STRIKER		\$ 190.40		
76	2	REAR DOOR RUBBER TOP		\$ 220.00		
77	2	REAR DOOR RUBBER LOWER		\$ 29.80		
78	2	REAR DOOR RUBBER FRT		\$ 58.40		
79	2	REAR DOOR POWER WINDOW MOTOR		\$ 780.00		
80	2	REAR DOOR POWER WINDOW MECHANISM		\$ 420.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLE4446C
 Vehicle Reg. Date: 22/7/2016
 Make / Model : VEZEL 1.5X CVT
 Engine No. : L1584037164
 Chassis No. : RU11117151

PAGE 3

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
81	2	REAR DOOR TRIM		\$ 1,270.00		
82	2	REAR DOOR TRIM CLIPS		\$ 50.00		
83	2	REAR DOOR SPEAKER		\$ 191.00		
84	2	REAR DOOR OUTER HANDLE		\$ 196.00		
85	2	REAR DOOR INNER HANDLE		\$ 130.00		
86	2	REAR DOOR WINDOW SWITCH		\$ 96.00		
87	2	REAR DOOR GLASS		\$ 856.00		
88	2	REAR OUTER MOULDING		\$ 130.00		
89	2	REAR DOOR RUN CHANNEL		\$ 176.00		
90	1	REAR WINDSCREEN GLASS DECAL			\$ 20.00	
91	0	0				
92	0	0				
93	0	0				
94	0	0				
95	0	0				
96	0	0				
97	0	0				
98	0	0				
99	0	0				
100	0	0				
101	0	0				
102	0	0				
103	0	0				
104	0	0				
105	0	0				
106	0	0				
107	0	0				
108	0	0				
109	0	0				
110	0	0				
111	0	0				
112	0	0				
113	0	0				
114	0	0				
115	0	0				
116	0	0				
117	0	0				
118	0	0				
119	0	0				
120	0	0				

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : SLE4446C
 Vehicle Reg. Date: 22/7/2016
 Make / Model : VEZEL 1.5X CVT
 Engine No. : L15B4037164
 Chassis No. : RU11117151

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To straighten and panel beating accident area. Rear Portion.	\$ 3,000.00	\$ 1,700.00 /600
2	To putty, respray painting and polish accident area. Rear Portion.	\$ 3,500.00	\$ 1,700.00 /600
3	To check and rectify wiring after disconnect and connect.	\$ 180.00	\$ 50.00
4	To remove and refit interior trims and upholstery.	\$ 280.00	\$ 100.00
5	To remove and transfer tailgate components.	\$ 180.00	\$ 60.00
6	To remove and refit tailgate windscreen.	\$ 180.00	\$ 120.00
7	To remove and refit exhaust pipe and align	\$ 250.00	
8	To remove and refit reverse sensor.	\$ 180.00	\$ 30.00
9	To rust proof affected areas.	\$ 200.00	\$ 100.00
10	To remove & refit reverse camera	\$ 180.00	
11	To remove & install rear both door components	\$ 350.00	
12	To mount vehicle chassis alignment	\$ 350.00	\$ 200.00
13	To reset fault code light on	\$ 350.00	\$ 150.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019440/T1QD3N2

Date: 19/03/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN1745021802		
Claimant Vehicle No :	SLE4446C	Insured Vehicle No :	PA8701M		
Date of Loss:	23/10/2018	Nature of Claim:	TP	Claim No:	SNM18D05064C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE4446C	Engine No:	L15B4037164
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11117151
Reg. Date:	22/07/2016 (Man. Year: 2016)	Odometer:	144396 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	22,552.68	9,638.92	12,913.76	57.26	
Miscellaneous Items	0.00	0.00	0.00		
Labour	9,180.00	4,010.00	5,170.00	56.32	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	31,732.68	13,648.92	18,083.76	56.99	
Approved Total (Overridden) (S\$)		10,900.00			
	(S\$)	31,732.68	10,900.00	20,832.68	65.65
+ GST 7.00/7.00% (S\$)	2,221.29	763.00	1,458.29	65.65	
Nett Amount (S\$)	33,953.97	11,663.00	22,290.97	65.65	

INSPECTION

Date of Assignment:	25/10/2018		
Date Inspected:	29/10/2018	Inspected At:	Vermogen Ace Pte Ltd (benoi) (HQ) 6 Benoi Sector Singapore 629904
Estimated Period of Repair:	12.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2019)	
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLE4446C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE WINDSCREEN	Cracked	1,150.10 FL	*950.00 FL
2	1		*SET TAILGATE WINDSCREEN MLDG	Necessary	140.00 FL	*140.00 FL
3	1		*TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
4	2		*TAILGATE HINGE	Bent	100.00 FL	*100.00 FL
5	1		*TAILGATE SPOILER	Not Necessary	430.20 FL	*- FL
6	1		*THIRD BRAKE LIGHT	Not Necessary	280.00 FL	*- FL
7	1		*TAILGATE OUTER GARNISH	Cracked	285.00 FL	*285.00 FL
8	1		*SET TAILGATE OUTER GARNISH CLIPS	Necessary	40.00 FL	*40.00 FL
9	1		*TAILGATE LOGO	Necessary	52.00 FL	*52.00 FL
10	1		*TAILGATE EMBLEM VEZEL	Necessary	56.20 FL	*56.20 FL
11	2		*TAILGATE LAMP LH/RH	Cracked	920.20 FL	*920.20 FL
12	1		*SET TAILGATE CLIPS	Necessary	40.00 FL	*40.00 FL
13	1		*TAILGATE OUTER HANDLE SWITCH	Distorted	180.00 FL	*180.00 FL
14	2		*TAILGATE DAMPER LH/RH	Bent	424.00 FL	*360.00 FL
15	1		*TAILGATE INNER TRIM LOWER	Deformed	153.40 FL	*153.40 FL
16	1		*SET TAILGATE INNER TRIM LOWER CLIPS	Necessary	45.00 FL	*45.00 FL
17	2		*TAILGATE INNER TRIM UPPER LH/RH	Deformed	100.60 FL	*100.60 FL
18	1		*TAILGATE WEATHERSTRIP	Twisted	96.80 FL	*96.80 FL
19	1		*TAILGATE LOCK SENSOR	Cracked	157.10 FL	*157.10 FL
20	1		*TAILGATE BUZZER	Cracked	85.00 FL	*85.00 FL
21	1		*REAR ANTENNA SENSOR	Not Necessary	58.70 FL	*- FL
22	1		*TAILGATE WIPER NOZZLE	Not Necessary	28.00 FL	*- FL
23	1		*TAILGATE WIPER BLADE	Cut	48.60 FL	*48.60 FL
24	1		*TAILGATE WIPER MOTOR	Bent	205.00 FL	*205.00 FL
25	1		*TAILGATE INNER HANDLE	Deformed	74.00 FL	*74.00 FL
26	1		*TAILGATE INNER LOCK	Jammed	245.00 FL	*245.00 FL
27	1		*TAILGATE STRIKER	Bent	55.00 FL	*55.00 FL
28	1		*TAILGATE RUBBER STOPPER	Necessary	96.00 FL	*96.00 FL
29	1		*SET REAR NUMBER PLATE LAMP	Distorted	165.20 FL	*165.20 FL
30	1		*REAR BUMPER	Deformed	508.50 FL	*508.50 FL
31	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
32	2		*REAR BUMPER RETAINER LH/RH	Necessary	144.00 FL	*144.00 FL
33	1		*REAR BUMPER SIDE COVER LH/RH	N/s Deformed/O/s Repair	390.00 FL	*195.00 FL
34	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	296.60 FL	*- FL
35	1		*REAR END PANEL INNER	Repair	415.60 FL	*- FL
36	1		*REAR END PANEL OUTER	Bent	415.60 FL	*415.60 FL
37	1		*REAR END PANEL TOP GARNISH	Deformed	185.00 FL	*185.00 FL
38	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	25.00 FL	*25.00 FL
39	1		*SPARETYRE PANEL	Repair	662.20 FL	*- FL
40	1		*SPARETYRE INSULATOR	Deformed	186.00 FL	*186.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*SPARETYRE TOOL TRAY	Cracked	225.00 FL	*225.00 FL
42	1		*SPARETYRE TOP BOARD	Deformed	186.00 FL	*186.00 FL
43	1		*EXHAUST MUFFLER	Not Necessary	528.00 FL	*- FL
44	1		*EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	36.00 FL	*- FL
45	1		*EXHAUST MUFFLER HEAT SHIELD	Not Necessary	165.00 FL	*- FL
46	2		*TAIL LAMP LH/RH	N/s Cracked/O/s Cut	857.40 FL	*857.40 FL
47	1		*SET TAIL LAMP CLIPS	Necessary	36.00 FL	*36.00 FL
48	1		*TAIL LAMP PANEL LH/RH	N/s Bent/O/s Not Necessary	270.00 FL	*135.00 FL
49	1		*REAR FENDER LH/RH	N/s Buckled/O/s Not Necessary	1,809.40 FL	*904.70 FL
50	2		*REAR FENDER QTR GARNISH LH/RH	Not Necessary	76.00 FL	*- FL
51	1		*REAR FENDER ARC GARNISH LH/RH	N/s Deformed/O/s Not Necessary	195.40 FL	*97.70 FL
52	2		*REAR FENDER INNER TRIM UPPER LH/RH	Deformed	73.00 FL	*73.00 FL
53	2		*REAR FENDER INNER TRIM LOWER LH/RH	Deformed	590.00 FL	*590.00 FL
54	2		*REAR WHEEL HOUSE LH/RH	Repair	1,457.20 FL	*- FL
55	2		*REAR FENDER UNDERSHIELD LH/RH	Not Necessary	180.40 FL	*- FL
56	1		*SET REAR FENDER UNDERSHIELD CLIPS	Not Necessary	80.00 FL	*- FL
57	1		*FUEL LID COVER	Repair	65.00 FL	*- FL
58	1		*REAR FENDER AIR DUCT-LH/RH	N/s Deformed/O/s Not Necessary	150.00 FL	*75.00 FL
59	2		*REAR CHASSIC MEMBER-LH/RH	Not Necessary	1,440.00 FL	*- FL
60	2		*REAR DOOR HINGE TOP	Not Necessary	40.00 FL	*- FL
61	2		*REAR DOOR HINGE BOTTOM	Not Necessary	96.00 FL	*- FL
62	2		*REAR DOOR CHECKER	Not Necessary	96.00 FL	*- FL
63	2		*REAR DOOR WEATHERSTRIP	Not Necessary	110.00 FL	*- FL
64	2		*REAR DOOR STRIKER	Not Necessary	190.40 FL	*- FL
65	2		*REAR DOOR RUBBER TOP	Not Necessary	220.00 FL	*- FL
66	2		*REAR DOOR RUBBER LOWER	Not Necessary	29.80 FL	*- FL
67	2		*REAR DOOR RUBBER FRT	Not Necessary	58.40 FL	*- FL
68	2		*REAR DOOR POWER WINDOW MOTOR	Not Necessary	780.00 FL	*- FL
69	2		*REAR DOOR POWER WINDOW MECHANISM	Not Necessary	420.00 FL	*- FL
70	2		*REAR DOOR TRIM	Not Necessary	1,270.00 FL	*- FL
71	2		*REAR DOOR TRIM CLIPS	Not Necessary	50.00 FL	*- FL
72	2		*REAR DOOR SPEAKER	Not Necessary	191.00 FL	*- FL
73	2		*REAR DOOR OUTER HANDLE	Not Necessary	196.00 FL	*- FL
74	2		*REAR DOOR INNER HANDLE	Not Necessary	130.00 FL	*- FL
75	2		*REAR DOOR WINDOW SWITCH	Not Necessary	96.00 FL	*- FL
76	2		*REAR DOOR GLASS	Not Necessary	856.00 FL	*- FL
77	2		*REAR OUTER MOULDING	Not Necessary	130.00 FL	*- FL
78	2		*REAR DOOR RUN CHANNEL	Not Necessary	176.00 FL	*- FL
79	1		*ROOF LINING	Deformed	1,250.00 FL	*750.00 FL
80	1		*TAILGATE INNER TRIM UPPER CENTER	Deformed	75.00 FL	*75.00 FL
81	2		*SPARE TYRE TOP BOARD LOCK BRACKET	Cracked	90.00 FL	*90.00 FL
82	1		*REAR NUMBER PLATE WITH FRAME	Bent	55.00 FS	*45.00 FS
83	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS
84	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*80.00 FS
85	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
86	1		*SPARETYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
87	1		*SPARETYRE PANEL PADDING	Not Necessary	80.00 FS	*- FS
88	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
89	1		*REVERSE SENSOR	Not Working	80.00 FS	*80.00 FS
90	1		*REVERSE CAMERA	Not Necessary	300.00 FS	*- FS
91	1		*REAR DOOR STICKER	Not Necessary	80.00 FS	*- FS
92	2		*REAR DOOR	Repair	1,861.20 FL	*- FL
93	1		*REAR WINDSCREEN GLASS DECAL	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	27,937.10	11,949.90
- List Item Discount on L Items 20.00/20.00% (S\$)	5,384.42	2,310.98
Total Parts (S\$)	22,552.68	9,638.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA.REAR PORTION	New	3,000.00	1,600.00
2	TO PUTTY,RESPRAY PAINTING AND POLISH ACCIDENT AREA.REAR PORTION	New	3,500.00	1,600.00
3	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	180.00	50.00
4	TO REMOVE AND REFIT INTERIOR TRIMS AND UPHOLSTERY	New	280.00	100.00
5	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	New	180.00	60.00
6	TO REMOVE AND REFIT TAILGATE WINDSCREEN	New	180.00	120.00
7	TO REMOVE AND REFIT EXHAUST PIPE AND ALIGN	New	250.00	0.00
8	TO REMOVE AND REFIT REVERSE SENSOR	New	180.00	30.00
9	TO RUST PROOF AFFECTED AREAS	New	200.00	100.00
10	TO REMOVE AND REFIT REVERSE CAMERA	New	180.00	0.00
11	TO REMOVE & INSTALL REAR BOTH DOOR COMPONENTS	New	350.00	0.00
12	TO REPAIR CHASSIS ALIGNMENT	New	350.00	200.00
13	TO RESET FAULT CODE LIGHT ON	New	350.00	150.00
Gross Labour Cost (S\$)			9,180.00	4,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >