

ASS. REC. BY:

Lau Hieh

REF:

CS/CT18019447/119d302

Special Instruction:

Surveyor

Menman

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

CTI

Date/Time:

25/10/18 @ 4:15pm

Estimated Cost:

Bill to:

☒ OD

TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 9292M

Insured:

at Workshop m/s

cycle & Carriage Automotive

Tel:

6568 4601

of

209 Pandan Gardens

Policy No:

DMPCSN1745141801

Claim No:

SNM18D05059C01

Sum Insured:

Excess:

\$500.00

NIL

Make of Veh:

(Client's Record)

D.O.A.

24/10/2018

CA / ☒ REV

/ REP. / REV 24 HRS

26/10/2018

H.O.D. Endorsement:

Date/Time:

4:17pm @ 25/10/18

Person Contacted:

Don bang

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

29/10-

SLP 9292M-CS/CT118019388/Drd3

Drd: 24/10/18

01/11/18

Revert via menman (Total loss)

02/11/18 @ 7:55pm

revert to Catherine Thia via Menman. (Vehicle how to Chang Hoe)

08/11/18 @ 12:45pm

Advised Toh informed C/A via Menman.

08/11/18 @ 2:57pm

informed Dorren CA & EX-NIL by email.

Tamplin

REF:

CT1

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No:

Claims No:

Sum Insured:

Excess:

to be advise

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$66K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

10 days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLP9292M

Yr Regn:

2017 June

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Lancer Ex 1.6 cc 1590

Colour:

Maroon

A/G

Insured / Std / NI / NA

Sp. Reading

27273

T/Radio

Insured / Std / NI / NA

Eng/No:

C/No:

JMYSKCYIA64006743

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A.

D.O.I.

05/11/18 26/10/18

Survey held at

Cheng Hoe

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/12/18 @ 4.30pm Repair Unit \$17K. confirmed with Dorlyn final Ag \$14789.24, 10 days (Ref B 1727.08 + 10%)

RECEIVED 27 DEC 2018

Date/Time. File Pass to?

☐

: Preli. Report

11/12/18 Tamplin

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

10

Resurvey No. of Trip:

2

Survey Fee:

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

WEEK-01

Lump Sum / I.B.I. (\$

14789.24

220

2217

ASSIGNMENT

From: Date: 26/10/18

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLP9292M
at Workshop m/s: cycle & Carriage Automotive
of: 209 Panchan Gardens

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$500.00

(Client's Record)

Make of Veh: Don bong

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

X	X
N/S	O/S

Bal. or Market Value: 966k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP9292M Yr Regn: 2017 June

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or:

Make: Mits-bishi Lancer Exl. 1.6 cc 1590

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 27273 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYSRCY14G4006 743

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16
R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or:

Front

R/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 26/10/18 2:15pm

Survey held at: C&P Panchan Garden

Des. of Damages: ☒ F/R / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

White: 948, 564

Date / Time Action / Instruction

5522 - 230

Repair limit 4/7K

RECEIVED 01 NOV 2018

Date/Time. File Pass to?

1) 01/11 11:15 AM

Date/Time. File Return to?

2)

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee

Transportation

1 \$ + RE \$

Photos

Others

TOTAL

Report Format: NER-TL-4

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2018		25 Oct 2018 16:15 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	LIM LI YI		
Vehicle Reg. No.:	SLP9292M	Date of Loss:	24/10/2018 08:00 - :59
Claim Type:	OD / SNM18D05059C01	Policy/Cover Note No.:	DMPCSN1745141801 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel: 65684501/65684518		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 24 December 2018 4:36 PM
To: 'Cheng Hoe Motor Pte Ltd (AMK)'; SUR
Subject: RE: FINALISATION FOR SLP9292M (DOA:24/10/2018) - OD/CHINA

Dear Dorlyn,

WITHOUT PREJUDICE

Confirm final fig \$14,789.24 before excess \$0.00 & GST and 10 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

11k 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheng Hoe Motor Pte Ltd (AMK) <chmamk@singnet.com.sg>
Sent: Thursday, 6 December 2018 2:17 PM
To: SUR <sur@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: FINALISATION FOR SLP9292M (DOA:24/10/2018) - OD/CHINA

Hi,

After paint photos, revised audatex estimate and supplier invoice as per attach, please assist to advise on finalise amount.

Thank you.

Rgds

Dorlyn Li

Cheng Hoe Motor Pte Ltd (AMK)

Tel : 64812001

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 8 November 2018 2:51 PM
To: chmamk@singnet.com
Cc: SUR
Subject: VEHICLE SLP 9292M (DOA: 24/10/2018)

Dear Doreen,

As instructed by our client, please proceed to repair the **insured vehicle SLP 9292M (Excess NIL)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	01 Nov 2018 16:51	Cim Veh Model Changed	(204291) MITSUBISHI LANCER 1.6 (A).		[R] DORLYN LI YAZHU
2	01 Nov 2018 16:51	Cim Created	Reg No: SLP9292M, Policy No: DMPCSN1745141801. Acct Date: 2018/10/24. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Cheng Hoe Motor Pte Ltd (Yishun)		[R] DORLYN LI YAZHU
3	01 Nov 2018 16:51	Cim Existing Check Notice			[R] DORLYN LI YAZHU
4	01 Nov 2018 16:57	Cim Submitted	16516.32.		[R] DORLYN LI YAZHU
5	01 Nov 2018 17:21	Cim Registration Modified	Excess: -> 500.00.		[I] Catherine Thia
6	01 Nov 2018 17:24	Cim Registration Modified	Excess: 500.00 -> 0.00.		[I] Catherine Thia
7	01 Nov 2018 17:24	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):you have previously surveyed the vehicle at cycl e and carriage. As its repair cost is too high, vehicle was towed to chenghoe motor instead, please assist to finalise repair cost with chenghoe motor		[I] Catherine Thia
8	01 Nov 2018 17:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/13		[I] Catherine Thia
9	01 Nov 2018 17:24	Adj Mandate Set	Approved:0.00.		[I] Catherine Thia
10	01 Nov 2018 17:52	Assignment 1st Accessed			[A] Nivitha Govindasamy
11	02 Nov 2018 07:51	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID		[A] Nivitha Govindasamy
12	07 Nov 2018 15:50	Adj Rpt Initiated			[A] SHIAU CHAN
13	07 Nov 2018 15:52	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/11/13		[A] SHIAU CHAN
14	07 Nov 2018 15:53	Adj Mandate Request	Cur.Req:16466.32:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
15	08 Nov 2018 12:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/13. Mandate Remarks: Proceed to authorize repairs at \$16,076.43. RE-INSPECTION OF VEHICLE REQUIRED.		[I] Alfred Toh
16	08 Nov 2018 12:24	Adj Mandate Set	Approved:16076.43:Proceed to authorize repairs at \$16,076.43. RE-INSPECTION OF VEHICLE REQUIRED.Reinsp:Adj decides.		[I] Alfred Toh

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1963855	01/11/2018 16:51	Motor	Cheng Hoe Motor Pte Ltd	Cheng Hoe Motor Pte Ltd (Yishun)	SLP9292M		XX.XX
1967594	07/11/2018 15:50	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLP9292M		10.70

Denise Tay (LKKAUTO)

From: Don Bong Kiong Hua <kionghua.bong@cyclecarriage.com.sg>
Sent: Monday, 29 October 2018 5:11 PM
To: Denise Tay (LKKAUTO)
Cc: Shiau Chan (LKKAUTO); Loi Ai Ting
Subject: RE: SLP 9292M / CHINA TAI PING / DOA: 24/10/2018 / OWN DAMAGE

Importance: High

Hi Denise,

We unable to undertake amount of the repair limit of \$17,000/-.

Thanks

Don Bong
Claim Division Operations
209 Pandan Gardens
Singapore 609339



Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4501 • F: +65 6565 1240 • www.cyclecarriage.com.sg

 A member of the Jardine Cycle & Carriage Group

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, 29 October, 2018 5:01 PM
To: Don Bong Kiong Hua
Cc: Shiau Chan (LKKAUTO); Loi Ai Ting
Subject: SLP 9292M / CHINA TAI PING / DOA: 24/10/2018 / OWN DAMAGE

Dear Don,

Please check on the limit repair at \$17,000/-.

Please let us know if you are able to repair within this amount

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia

Date: 07 Nov 2018

Preliminary Advice

Vehicle No	: SLP9292M	Accident Date	: 24/10/2018
Make	: MITSUBISHI LANCER	Policy No.	: DMPCSN1745141801
Assignment Date	: 01/11/2018	Excess	: S\$0.00
Date of Inspection	: 05/11/2018	Est. Duration of Repair	: 10.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,516.32
Revised Amount	:S\$	13,161.32
Check Items (Estimated)	:S\$	3,305.00
Total	:S\$	16,466.32
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	48,552.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,448.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia

Date: 29 Oct 2018

Preliminary Advice

Vehicle No	: SLP9292M	Accident Date	: 24/10/2018
Make	: MITSUBISHI LANCER	Policy No.	: DMPCSN1745141801
Assignment Date	: 25/10/2018	Excess	: S\$500.00
Date of Inspection	: 26/10/2018	Est. Duration of Repair	: 15.00
Inspection At	: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,391.00
Revised Amount	:S\$	24,924.00
Check Items (Estimated)	:S\$	8,812.00
Total	:S\$	33,736.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	48,552.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,448.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please be inform according to the repairer, starting from 30/10/2018 one week storage fee is free subsequently there will be fee at \$30 per day.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia

Date: 29 Oct 2018

Preliminary Advice

Vehicle No	: SLP9292M	Accident Date	: 24/10/2018
Make	: MITSUBISHI LANCER	Policy No.	: DMPCSN1745141801
Assignment Date	: 25/10/2018	Excess	: S\$500.00
Date of Inspection	: 26/10/2018	Est. Duration of Repair	: 15.00
Inspection At	: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	35,391.00
Revised Amount	:S\$	24,924.00
Check Items (Estimated)	:S\$	8,812.00
Total	:S\$	33,736.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	48,552.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,448.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Pending repair cost from repairer

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9870B
Vehicle Details	
Vehicle No.:	SLP9292M
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Oct 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	4A92CP4092
Chassis No.:	JMYSRCY1AGU006743
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$12,523.00
Original Registration Date:	28 Jun 2017
First Registration Date:	28 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$12,523.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2027
PARF Rebate Amount:	\$9,392.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,201.00
COE Rebate Amount:	\$39,160.00
Total Rebate Amount:	\$48,552.00

The information contained herein is correct as at 29 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/10/2018 12:04
Date Of Accident	24/10/2018 08:50
Exact Location Of Accident	ALONG AYE TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP9292M
Insured/Policyholder	
Name Of Registered Owner	LIM LI YI
NRIC No	S8319870B
Email Address	JASMINELIM73@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98007737
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1745141801
Cover Note Number	

Driver

Name of Driver	LIM LI YI
NRIC No	S8319870B
Date Of Birth	03/07/1983
Occupation	INDOOR
Date Of Driving Pass	19/08/2002
Driving Experience	16 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98007737
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	JASMINELIM73@HOTMAIL.COM

Address	BLK 443B FAJAR RD #06-90
Postcode	672443
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 24/10/2018 AT ABOUT 0850 HRS. WHILE I WAS TRAVELLING ALONG AYE TOWARDS CITY. VEHICLE B IN FRONT OF ME SUDDENLY APPLY EMERGENCY BRAKE. I COULDN'T STOP IN TIME AND COLLIDED ONTO REAR VEHICLE B. VEHICLE B MOVE IN FRONT AND COLLIDED ONTO VEHICLE C.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4767D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TANG BOON HIN
NRIC/Passport Number	S7525011H
Contact Number	96547952
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: :

GENDER: :

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHB4139C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

TOH SENG LAN

NRIC/Passport Number

S1214625F

Contact Number

91063383

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN

A - SLP9292M
B - SHD4767D
C - SHB4139C

AYE Towards City

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to circumstances

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

☐ Claim own policy
☐ Claim third party
☒ Claim TP at other works hop Mitsubishi
☐ For record purpose
Policy No. DMPCSN17CS141801
Insurer China Veh. No. SLP9292M

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Co. Reg. No. 300208384E

MX1F
R SN
DR0477A
Cov. Type: C

MOTOR PRIVATE CAR R

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE No.

DMPCSN1745141801

Engine No : 4A92CP4092

Chano: JMYSRCYLAGU006743

1. Index Mark and Registration

Number of Vehicle

SLP9292M

2. Name of Policy Holder

LIM LI YI (LIN LIYI)

3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment

28 June 2018

Named Drivers Ex Sect. I S\$500.00

Additional Ex Other than Named Drivers:

4. Date of Expiry of Insurance

27 June 2019

Ex Sect. I - Age <= 25..... S\$3,000.00

Ex Sect. I - Age >= 26..... S\$500.00

* Age as at date of accident

5. Persons or Classes of Persons entitled to drive*

EX ON WINDSCREEN S\$100.00

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use for social, domestic and pleasure purposes and for the Policyholder's business.
The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time waiver of Excess for the first S\$500 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised Workshops for each Policy Year.

HIRE PURCHASE CO. - UNITED OVERSEAS BANK LIMITED AS HP OWNER

Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: 15msn
Authorised Officer

Authorised Signatory

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S8319870B**

Name: **LIM LI YI (LIN LIYI)**

Birth Date: **03 Jul 1983**

Issue Date: **16 Jun 2003**

Barcode: 1000571811J

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S8319870B**



Name

LIM LI YI (LIN LIYI)

林 丽 仪

Race

CHINESE

Date of birth

03-07-1983

Country/Place of birth

SINGAPORE

Sex

F



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which includes does not exceed 3500 kilograms

PASS DATE: **19 Aug 2003**

License No: **S8319870B**

NP-428A

FOR C&C USE ONLY

5256248

Barcode

APRIC No: **S8319870B**

Date of issue: **14-01-2014**

APT BLK 443B FAJAR ROAD #08-80
SINGAPORE 672443

NRIC No: **S8319870B** Date: **15/04/2016**

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





中国太平保險(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Co. Reg. No. 200208384E

MX1F
R SN
DR0477A
Cov. Type: C

MOTOR PRIVATE CAR R

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1950 (Malaysia)

ORIGINAL

CERTIFICATE No.

DMPCSN1745141801

Engine No : 4A92CP4092

ChasNo: 3MYSRCY1AGU006743

1. Index Mark and Registration

Number of Vehicle

SLP9292M

2. Name of Policy Holder

LIM LI YI (LIN LIYI)

3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment

28 June 2018

Named Drivers Ex Sect. I \$5500.00

Additional Ex Other than Named Drivers:

4. Date of Expiry of Insurance

27 June 2019

Ex Sect. I - Age <= 25..... \$3,000.00

Ex Sect. I - Age >= 26..... \$5500.00

* Age as at date of accident

5. Persons or Classes of Persons entitled to drive*

EX ON WINDSCREEN \$100.00

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use.*

Use for social, domestic and pleasure purposes and for the policyholder's business.
The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time waiver of Excess for the first \$5500 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised workshops for each Policy Year.

HIRE PURCHASE CO. - UNITED OVERSEAS BANK LIMITED AS HP OWNER

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: _____
Issued By: _____
Authorised Officer

Authorised Signatory

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S8319870B**

Name: **LIM LI YI (LIN LIYI)**

Birth Date: **03 Jul 1983**

Issue Date: **16 Jun 2003**

Barcode: 980571911J

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8319870B**

Name: **LIM LI YI (LIN LIYI)**
林麗儀

Race: **CHINESE**

Date of Birth: **03-07-1983**

Country/Place of Birth: **SINGAPORE**

Sex: **F**

Barcode: 980571911J

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Valid Until
Class 2	Motor Cars and Motor Tractors the weight of which together does not exceed 3500 kilograms	19 Aug 2007

License No: **S8319870B**

NP 428A

FOR C&C USE ONLY

5256248

Barcode: 980571911J

NRIC No: **S8319870B**

Date of issue: **14-01-2014**

APT BLK 443B FAJAR ROAD #08-80
SINGAPORE 672443

NRIC No: **S8319870B** Date: **15/04/2016**

FOR C&C USE ONLY



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms LIM LI YI (LIN LIYI)	Cust No/Name	/Ms LIM LI YI (LIN LIYI)
443b Fajar Road	Reg No/Reg Date	SLP9292M / 28/06/201
#06-90	Date In/Mileage	/ 27273
Singapore 672443	Chassis No	JMYSRCY1AGU006743
Contact No Mobile: 98007737	Engine No	4A92CP4092
	Make/Model	MIT/16MY LANCER EX 1.6 4AT (E21)
	Colour/Trim	P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	26/10/2018/ 16:15	QUD	247 / DonBong	32354
Description of Goods / Services					Qty Unit Price Disc% Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT REINFORCEMENT, FRONT BONNET, RH FRONT FENDER, LH FRONT FENDER, FRONT BUMPER, REPAIR RH FRONT DOOR, LH FRONT DOOR, REPAIR FRONT CHASSIS MEMBER					3025 3300.00
E PNT88000 REMOVE AND INSTALL A/CON CONDENSER AND RADAITOR TO FACILITATE REPAIR WORK					100.00
A 55900099 TOP UP AIR CON GAS AND CHECK A/CON SYSTEM					80.00
E PNT98000 PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT REINFORCEMENT, FRONT BONNET, RH FRONT FENDER, LH FRONT FENDER, FRONT BUMPER, RH FRONT DOOR, LH FRONT DOOR, FRONT CHASSIS MEMBER AND AFFECTED PORTION					2740 4200.00
E PNT88000 REMOVE AND INSTALL FRONT WINDSCREEN GLASS					240.00
M SUNDRY SUPPLY WINDSCREEN SEALANT					80.00
A PNT88100 TO MOUNT VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS ALIGNMENT					1000.00
A 52900099 REMOVE AND REPLACE INSTRUMENT PANEL INCLUDING REPLACE PASSENGER AIR BAG AND DRIVER AIR BAG (DEPLOY)					550.00
A 52900099 REMOVE AND INSTALL FRONT BOTH SAFERY BELT AND BUCKLE					225 275.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					200.00
M SUNDRY SUPPLY BODY SEALANT					140-140 160.00
M SUNDRY INSTALL FRONT WINDSCREEN RIKE COOL SOLAR FILM					220.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms LIM LI YI (LIN LIYI)	Cust No/Name /Ms LIM LI YI (LIN LIYI)
443b Fajar Road	Reg No/Reg Date SLP9292M / 28/06/201
#06-90	Date In/Mileage / 27273
Singapore 672443	Chassis No JMYSRCYIAGU006743
Contact No Mobile: 98007737	Engine No 4A92CP4092
	Make/Model MIT/16MY LANCER EX 1.6 4AT (E21)
	Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	26/10/2018/ 16:15	QUD	247 / DonBong	32354
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SUNDRY	PERFORM RUST PREVENTION				100 120.00
M SUNDRY	SUPPLY FRONT NUMBER PLATE WITH FRAME				bt 50.00
M SUNDRY	TOW IN FEE				✓ 90.00
M SUNDRY	SUNDRIES				20 50.00
S SPECIALISTJOB	WO: 200215380 ACCIDENT TOWED FROM ALEXANDRA HEAVY VEH. PARK TO PG CNC				
M PNL,HEADLAMP SUPT,UPR RH		1.00	86.00	00.00	bt 86.00
M PANEL,HEADLAMP SUPPORT,UPR		1.00	293.00	00.00	bt 293.00
M PNL,HEADLAMP SUPT,UPR LH		1.00	86.00	00.00	bt 86.00
M PANEL,HEADLAMP SUPPORT,LWR		1.00	504.00	00.00	? 504.00
M EXTENSION,FR SIDEMEMBER,RH		1.00	41.00	00.00	? 41.00
M EXTENSION,FR SIDEMEMBER,LH		1.00	41.00	00.00	? 41.00
M CONDENSER ASSY,A/C REFRIGE		1.00	1123.00	00.00	? 1123.00
M PIPE,A/C CONDENSER OUTLET		1.00	114.00	00.00	? 114.00
M PIPE,RR A/C DISCHARGE		1.00	130.00	00.00	? 130.00
M HOSE,A/C COMPR DISCHARGE		1.00	195.00	00.00	? 195.00
M PANEL,HEADLAMP SUPPORT,LH		1.00	56.00	00.00	bt 56.00
M PANEL,HEADLAMP SUPPORT,RH		1.00	56.00	00.00	bt 56.00
M HORN		1.00	88.00	00.00	? 88.00
M HORN		1.00	81.00	00.00	? 81.00
M SENSOR,AIR BAG,LH		1.00	292.00	00.00	act 292.00
M SENSOR,AIR BAG,RH		1.00	292.00	00.00	act 292.00
M COVER,AIR BAG SENSOR,LH		1.00	5.00	00.00	act 5.00
M COVER,AIR BAG SENSOR,RH		1.00	5.00	00.00	act 5.00
M SPRING,AIR BAG SENSOR		1.00	312.00	00.00	act 312.00
M PANEL,INSTRUMENT		1.00	1094.00	00.00	act 1094.00
M MODULE,PASSENGER AIR BAG		1.00	2269.00	00.00	act 2269.00
M MODULE,AIR BAG(PYRO TYPE)		1.00	1365.00	00.00	act 1365.00
M CONT UNIT,SRS DIAGNOSIS		1.00	1008.00	00.00	act 1008.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms LIM LI YI (LIN LIYI)	Cust No/Name /Ms LIM LI YI (LIN LIYI)
443b Fajar Road	Reg No/Reg Date SLP9292M / 28/06/201
#06-90	Date In/Mileage / 27273
Singapore 672443	Chassis No JMYSRCY1AGU006743
Contact No Mobile: 98007737	Engine No 4A92CP4092
	Make/Model MIT/16MY LANCER EX 1.6 4AT (E21)
	Colour/Trim PO2 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	26/10/2018/ 16:15	QUD	247 / DonBong	32354
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
M HARNESS,AIR BAG	1.00	46.00	00.00	46.00	46.00
M HARNESS,FOG LAMP	1.00	105.00	00.00	105.00	105.00
M S/BELT,FR PRE-TENSIO,OTR L	1.00	693.00	00.00	693.00	693.00
M S/BELT,FR PRE-TENSIO,OTR R	1.00	660.00	00.00	660.00	660.00
M SEAT BELT,FR SEAT,INR LH	1.00	100.00	00.00	100.00	100.00
M SEAT BELT,FR SEAT,INR RH	1.00	100.00	00.00	100.00	100.00
M GLASS,WINDSHIELD	1.00	1278.00	00.00	1278.00	1278.00
M STOPPER,WINDSHIELD GLASS	2.00	3.00	00.00	6.00	6.00
M SPACER,QTR WINDOW	5.00	8.00	00.00	40.00	40.00
M MOULDING,WINDSHILD,LWR	1.00	79.00	00.00	79.00	79.00
M BRACKET, IU ADHESIVE	1.00	26.00	00.00	26.00	26.00
M HOOD	1.00	888.00	00.00	888.00	888.00
M HINGE,HOOD,LH	1.00	63.00	00.00	63.00	63.00
M HINGE,HOOD,RH	1.00	63.00	00.00	63.00	63.00
M INSULATOR,HOOD	1.00	94.00	00.00	94.00	94.00
M WEATHERSTRIP,HOOD	1.00	17.00	00.00	17.00	17.00
M WEATHERSTRIP,HOOD,FR	1.00	30.00	00.00	30.00	30.00
M LATCH,HOOD	1.00	57.00	00.00	57.00	57.00
M CLIP,HOOD LOCKING	1.00	3.00	00.00	3.00	3.00
M FENDER,FR LH	1.00	645.00	00.00	645.00	645.00
M FENDER,FR RH	1.00	645.00	00.00	645.00	645.00
M BRACKET,FR FENDER,RH	1.00	15.00	00.00	15.00	15.00
M BRACKET,FR FENDER,LH	1.00	15.00	00.00	15.00	15.00
M HEADLAMP ASSY,LH	1.00	838.00	00.00	838.00	838.00
M HEADLAMP ASSY,RH	1.00	838.00	00.00	838.00	838.00
M LAMP ASSY,SIDE MARKER,LH	1.00	601.00	00.00	601.00	601.00
M LAMP ASSY,SIDE MARKER,RH	1.00	601.00	00.00	601.00	601.00
M LAMP ASSY,FOG,FR LH	1.00	300.00	00.00	300.00	300.00
P LAMP ASSY,FOG,FR RH	1.00	300.00	00.00	300.00	300.00
M COVER,HEADLAMP SUPT PANEL	1.00	69.00	00.00	69.00	69.00
M BRACKET,FR BUMPER SIDE,LH	1.00	17.00	00.00	17.00	17.00
M BRACKET,FR BUMPER SIDE,RH	1.00	12.00	00.00	12.00	12.00
M SUPPORT,FR BUMPER,LH	1.00	13.00	00.00	13.00	13.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms LIM LI YI (LIN LIYI)	Cust No/Name /Ms LIM LI YI (LIN LIYI)
443b Fajar Road	Reg No/Reg Date SLP9292M / 28/06/201
#06-90	Date In/Mileage / 27273
Singapore 672443	Chassis No JMYSRCY1AGU006743
Contact No Mobile: 98007737	Engine No 4A92CP4092
	Make/Model MIT/16MY LANCER EX 1.6 4AT (E21)
	Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	26/10/2018/ 16:15	QUD	247 / DonBong	32354
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SUPPORT,FR BUMPER,RH		1.00	13.00	00.00	13.00
M GRILLE,FR BUMPER		1.00	77.00	00.00	77.00
M GARNISH,FR BUMPER,CTR		1.00	231.00	00.00	231.00
M GARNISH,FR BUMPER,CTR		1.00	231.00	00.00	231.00
M REINFORCEMENT,FR BUMPER		1.00	92.00	00.00	92.00
M FACE,FR BUMPER		1.00	1030.00	00.00	1030.00
M COVER,FR BUMPER		1.00	37.00	00.00	37.00
M GARNISH,FR BUMPER,LH		1.00	36.00	00.00	36.00
M GARNISH,FR BUMPER,RH		1.00	36.00	00.00	36.00
M MARK,THREE-DIA		1.00	51.00	00.00	51.00
M BRKT,F/BMPR AIR INLET GARN		1.00	2.00	00.00	2.00
M BRKT,F/BMPR AIR INLET GARN		1.00	2.00	00.00	2.00
M BRKT,F/BMPR AIR INLET GARN		1.00	2.00	00.00	2.00
M BRKT,F/BMPR AIR INLET GARN		1.00	2.00	00.00	2.00
M BRKT,F/BMPR AIR INLET GARN		1.00	2.00	00.00	2.00
M BRKT,F/BMPR AIR INLET GARN		1.00	2.00	00.00	2.00
M REINFORCEMENT,FR BUMPER		1.00	428.00	00.00	428.00
M GARNISH,FR FENDER RH		1.00	65.00	00.00	65.00
M GARNISH,FR FENDER LH		1.00	65.00	00.00	65.00
M GARNISH,FR PILLAR,LH		1.00	28.00	00.00	28.00
M GARNISH,FR PILLAR,RH		1.00	25.00	00.00	25.00
M DUCT,A/CLNR INTAKE		1.00	161.00	00.00	161.00
M RADIATOR ASSY		1.00	1113.00	00.00	1113.00
M FAN,COOLING		1.00	74.00	00.00	74.00
M SHROUD,COOLING FAN		1.00	254.00	00.00	254.00
M MOTOR,COOLING FAN(*)		1.00	463.00	00.00	463.00
M HARNESS,COOLING FAN		1.00	57.00	00.00	57.00
M HOSE,RADIATOR,UPR RH		1.00	14.00	00.00	14.00
M CAP ASSY,RADIATOR		1.00	93.00	00.00	93.00
M HOSE,RADIATOR,UPR LH		1.00	50.00	00.00	50.00
M HOSE,RADIATOR,LWR		1.00	73.00	00.00	73.00
M TANK ASSY,RADIATOR COND		1.00	60.00	00.00	60.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms LIM LI YI (LIN LIYI)	Cust No/Name /Ms LIM LI YI (LIN LIYI)
443b Fajar Road	Reg No/Reg Date SLP9292M / 28/06/201
#06-90	Date In/Mileage / 27273
Singapore 672443	Chassis No JMYSRCY1AGU006743
Contact No Mobile: 98007737	Engine No 4A92CP4092
	Make/Model MIT/16MY LANCER EX 1.6 4AT (E21)
	Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	26/10/2018/ 16:15	QUD	247 / DonBong	32354		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	TANK,WINDSHIELD WASHER			1.00	89.00	00.00	89.00
M	LLC 4L			1.00	26.00	00.00	26.00
M	MANIFOLD,INLET,UPR			1.00	762.00	00.00	762.00
M	COVER ASSY,ENG,UPR			1.00	135.00	00.00	135.00

Estimate

SURVEYOR NAME: Tanpin 971957289SURVEYOR SIGNATURE: [Signature]DATE: 26/10/18REMARKS: Resurvey before paint
sure (LKK Auto Consultants)15 daysEx \$500.Resurvey
check repair limit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

Nett 35,391.00
7% GST on 35391.00 2477.37

Total Payable 37,868.37

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

清河

Repairer Estimates

CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/CHINA
Policy No:	DMPCSN1745141801	Date of Loss:	24/10/2018
Vehicle Reg. No.:	SLP9292M	Driveable?	
Driver Age/Info:	35 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LIM LI YI	Contact No:	+6598007737
Driver:	LIM LI YI		

Make/Model:	MITSUBISHI LANCER, 1.6 (A)	Vehicle Reg. Date:	28/06/2017
Vehicle Colour:	RED	Chassis No:	JMYSRCY1AGU006743
Engine No:	4A92CP4092		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	0

Tan Jiah 97495749
Revert, Not Authorise
5/11/18
Resurvey before paint.
sur @ huan to work.
Ex: to be advise.
10 days.

Description of Accident/Loss	REFER TO GIA REPORT
Remarks:	VEHICLE TOW IN FROM CYCLE & CARRIAGE ON 30/10/2018
Present Location:	CHENG HOE MOTOR PTE LTD (AMK)

COST OF CLAIMS

	Amount
Parts	13,328.00
Miscellaneous Items	425.00
Labour	2,763.32
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	16,516.32
+ GST 7.00% (\$\$)	1,156.14
Nett Amount (\$\$)	17,672.46

This claim is the property of LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Parts: 143

Labour: Repairer's

Print Code:

Validity:

Version: 1.0 (Last Synchronised: 01 Nov 2018)

MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List)

Cheng Hoe Motor Pte Ltd/SLP9292M/01/11/2018 16:57

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA				
2	1	NA	*AIR INTAKE HOSE	0.00	0.00	bt / ? *180.00 F
3	1	NA	*AIR INTAKE MANIFOLD	0.00	0.00	de / ? *85.00 F
4	1	NA	*AIRBAG CONTROL UNIT	0.00	0.00	act / ✓ *550.00 F
5	1	NA	*AIRBAG SPRING	0.00	0.00	act / ✓ *180.00 F
6	1	NA	*AIRBAG UNIT	0.00	0.00	act / ✓ *1,050.00 F
7	1	NA	*ALTERNATOR	0.00	0.00	act / ✓ *880.00 F
8	1	NA	*BATTERY TRAY	0.00	0.00	act / ✓ *28.00 F
9	1	NA	*BONDING KIT	0.00	0.00	act / ✓ *F
10	1	NA	*BONNET	0.00	0.00	bt / ✓ *410.00 F
11	1	NA	*BONNET FRONT SEAL	0.00	0.00	ne / ✓ *19.00 F
12	1	NA	*BONNET INSULATION	0.00	0.00	de / ✓ *65.00 F
13	1	NA	*BONNET LOCK	0.00	0.00	bt / ✓ *45.00 F
14	1	NA	*CONDENSER - photo	0.00	0.00	bt / ✓ 600.00 F
15	1	NA	*CONNECTION TUBE	0.00	0.00	de / ? *85.00 F
16	1	NA	*CONTROL CABLE	0.00	0.00	de / ? *26.00 F
17	1	NA	*COOLING FAN - photo	0.00	0.00	de / ? *38.00 F
18	1	NA	*CTR PROTECT MOULDING	0.00	0.00	cur / ✓ *130.00 F
19	1	NA	*FILLER NECK	0.00	0.00	de / ? *20.00 F
20	1	NA	*FRONT BUMPER COVER	0.00	0.00	de / ✓ *460.00 F
21	1	NA	*FRONT NUMBER PLATE	0.00	0.00	de / ✓ *35.00 F
22	1	NA	*FRT BUMPER REINF	0.00	0.00	bt / ✓ *50.00 F
23	1	NA	*FRT BUMPER SUPPORT	0.00	0.00	bt / ✓ *240.00 F
24	1	NA	*FRT LWR CROSSMEMBER	0.00	0.00	bt / ✓ *260.00 F
25	1	NA	*FRT SCREEN MNTG KIT	0.00	0.00	ne / ✓ *F
26	1	NA	*FRT TOWING EYE COVER	0.00	0.00	de / ✓ *26.00 F
27	1	NA	*FRT UPP LOCK CARRIER	0.00	0.00	bt / ✓ *140.00 F
28	1	NA	*GRILLE	0.00	0.00	an / ✓ *145.00 F
29	1	NA	*HEADLAMP BRACKET X2	0.00	0.00	ne / ✓ *20.00 F
30	1	NA	*HIGH TONE HORN	0.00	0.00	bt / ✓ *55.00 F
31	1	NA	*INLET HOSE	0.00	0.00	bt / ✓ *125.00 F
32	1	NA	*INN UPP FR PANELLING	0.00	0.00	de / ✓ *45.00 F
33	1	NA	*INSTRUMENT PANEL	0.00	0.00	de / ✓ *720.00 F
34	1	NA	*L/F AIRBAG SENSOR	0.00	0.00	act / ✓ *180.00 F
35	1	NA	*L/F BUMPER BRACKET	0.00	0.00	ne / ✓ *10.00 F
36	1	NA	*L/F OUT S-MEMBER PNL	0.00	0.00	ne / ✓ *6.00 F
37	1	NA	*L/F PANEL	0.00	0.00	ne / ✓ *50.00 F
38	1	NA	*L/F REPEATER LAMP	0.00	0.00	ne / ✓ *2.00 F
39	1	NA	*L/F SEAT BELT	0.00	0.00	ne / ✓ *4.00 F
40	1	NA	*L/F WING	0.00	0.00	ne / ✓ *29.00 F
41	1	NA	*L/LOWER AIR GRILLE	0.00	0.00	ne / ✓ *28.00 F
42	1	NA	*L/LWR B-PILLAR TRIM	0.00	0.00	ne / ✓ *55.00 F
43	1	NA	*LEFT BONNET HINGE	0.00	0.00	ne / ✓ *38.00 F
44	1	NA	*LEFT HEADLAMP ASSY	0.00	0.00	ne / ✓ *410.00 F
45	1	NA	*LOW TONE HORN	0.00	0.00	ne / ✓ *55.00 F
46	1	NA	*LWR RADIATOR GRILLE	0.00	0.00	ne / ✓ *55.00 F

Cheng Hoe Motor Pte Ltd/SLP9292M/01/11/2018 16:57. No valid without Reference section.
Generated using Merimen e-Claims IEAS

Qty	Part No.	Particulars	Repairer Estimates	%Disc	%Depr	Amount
46	1	NA				
47	1	NA				
48	1	NA				
49	1	NA				
50	1	NA				
51	1	NA				
52	1	NA				
53	1	NA				
54	1	NA				
55	1	NA				
56	1	NA				
57	1	NA				
58	1	NA				
59	1	NA				
60	1	NA				
61	1	NA				
62	1	NA				
63	1	NA				
64	1	NA				
65	1	NA				
66	1	NA				
67	1	NA				
		*PASSENGER AIRBAG		0.00	0.00	act ✓ 1,550.00 F
		*R/F AIRBAG SENSOR		0.00	0.00	act ✓ 180.00 F
		*R/F BUMPER BRACKET		0.00	0.00	act ✓ 10.00 F
		*R/F OUT S-MEMBER PNL		0.00	0.00	act ✓ 36.00 F
		*R/F PANEL		0.00	0.00	act ✓ 50.00 F
		*R/F REPEATER LAMP		0.00	0.00	act ✓ 32.00 F
		*R/F SEAT BELT		0.00	0.00	act ✓ 440.00 F
		*R/F WING		0.00	0.00	act ✓ 290.00 F
		*R/LOWER AIR GRILLE		0.00	0.00	act ✓ 28.00 F
		*RAD BY PASS TUBE		0.00	0.00	act ✓ 26.00 F
		*RADIATOR - photo		0.00	0.00	act ✓ 630.00 F
		*RADIATOR FAN MOTOR - photo		0.00	0.00	act ✓ 240.00 F
		*RADIATOR SHROUD - photo		0.00	0.00	act ✓ 145.00 F
		*RIGHT BONNET HINGE		0.00	0.00	act ✓ 38.00 F
		*RIGHT HEADLAMP ASSY		0.00	0.00	act ✓ 410.00 F
		*SPACER		0.00	0.00	act ✓ 0.00 F
		*SPACER PART		0.00	0.00	act ✓ 0.00 F
		*UPP WINDSCREEN MLDG		0.00	0.00	act ✓ 60.00 F
		*UPPER RADIATOR HOSE		0.00	0.00	act ✓ 32.00 F
		*VALVE COVER		0.00	0.00	act ✓ 95.00 F
		*WASHER RESERVOIR		0.00	0.00	act ✓ 55.00 F
		*WINDSCREEN		0.00	0.00	act ✓ 550.00 F
Total Parts (S\$)						13,328.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SLP9292M/01/11/2018 16:57, Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Y1912

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	SPECIALIST AIRCON GAS	nec / 50.00
2	1	SPECIALIST COOLANT	nec / 20.00
3	1	SPECIALIST IU BRACKET	nec / 15.00
4	1	SPECIALIST RESET N PROGRAME.	/ 200.00
5	1	SPECIALIST WS SEALANT	nec / 40.00
6	1	SUNDRY PARTS	/ 100.00
Sub Total (S\$)			425.00 ✓

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Total Paint Labour	New	635.20 672.00
2	Total Paint Materials	New	293.44 297.92
3	Total Panel/Mechanical Labour	New	1503.60 1,793.40
Gross Labour Cost (S\$)			2,763.32 ✓

Cheng Hoe Motor Pte Ltd/SLP9292M/01/11/2018 16:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tlgd3

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 01 Nov 2018)

Parts: 143

MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SLP9292M/01/11/2018 16:57

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*AIR INTAKE HOSE	0.00	0.00	180.00 F
2	1	NA	*AIR INTAKE MANIFOLD	0.00	0.00	85.00 F
3	1	NA	*AIRBAG CONTROL UNIT	0.00	0.00	550.00 F
4	1	NA	*AIRBAG SPRING	0.00	0.00	180.00 F
5	1	NA	*AIRBAG UNIT	0.00	0.00	1,050.00 F
6	1	NA	*ALTERNATOR	0.00	0.00	880.00 F
7	1	NA	*BATTERY TRAY	0.00	0.00	28.00 F
8	1	NA	*BONDING KIT	0.00	0.00	-F
9	1	NA	*BONNET	0.00	0.00	410.00 F
10	1	NA	*BONNET FRONT SEAL	0.00	0.00	19.00 F
11	1	NA	*BONNET INSULATION	0.00	0.00	65.00 F
12	1	NA	*BONNET LOCK	0.00	0.00	45.00 F
13	1	NA	*CONDENSER	0.00	0.00	600.00 F
14	1	NA	*CONNECTION TUBE	0.00	0.00	85.00 F
15	1	NA	*CONTROL CABLE	0.00	0.00	26.00 F
16	1	NA	*COOLING FAN	0.00	0.00	38.00 F
17	1	NA	*CTR PROTECT MOULDING	0.00	0.00	130.00 F
18	1	NA	*FILLER NECK	0.00	0.00	20.00 F
19	1	NA	*FRONT BUMPER COVER	0.00	0.00	460.00 F
20	1	NA	*FRONT NUMBER PLATE	0.00	0.00	35.00 F
21	1	NA	*FRT BUMPER REINF	0.00	0.00	50.00 F
22	1	NA	*FRT BUMPER SUPPORT	0.00	0.00	240.00 F
23	1	NA	*FRT LWR CROSSMEMBER	0.00	0.00	260.00 F
24	1	NA	*FRT SCREEN MNTG KIT	0.00	0.00	-F
25	1	NA	*FRT TOWING EYE COVER	0.00	0.00	26.00 F
26	1	NA	*FRT UPP LOCK CARRIER	0.00	0.00	140.00 F
27	1	NA	*GRILLE	0.00	0.00	145.00 F
28	1	NA	*HEADLAMP BRACKET X2	0.00	0.00	20.00 F
29	1	NA	*HIGH TONE HORN	0.00	0.00	55.00 F
30	1	NA	*INLET HOSE	0.00	0.00	125.00 F
31	1	NA	*INN UPP FR PANELLING	0.00	0.00	45.00 F
32	1	NA	*INSTRUMENT PANEL	0.00	0.00	720.00 F
33	1	NA	*L/F AIRBAG SENSOR	0.00	0.00	180.00 F
34	1	NA	*L/F BUMPER BRACKET	0.00	0.00	10.00 F
35	1	NA	*L/F OUT S-MEMBER PNL	0.00	0.00	6.00 F
36	1	NA	*L/F PANEL	0.00	0.00	60.00 F
37	1	NA	*L/F REPEATER LAMP	0.00	0.00	2.00 F
38	1	NA	*L/F SEAT BELT	0.00	0.00	4.00 F
39	1	NA	*L/F WING	0.00	0.00	290.00 F
40	1	NA	*L/LOWER AIR GRILLE	0.00	0.00	28.00 F
41	1	NA	*L/LWR B-PILLAR TRIM	0.00	0.00	55.00 F
42	1	NA	*LEFT BONNET HINGE	0.00	0.00	38.00 F
43	1	NA	*LEFT HEADLAMP ASSY	0.00	0.00	400.00 F
44	1	NA	*LOW TONE HORN	0.00	0.00	55.00 F
45	1	NA	*LWR RADIATOR GRILLE	0.00	0.00	55.00 F

Cheng Hoe Motor Pte Ltd/SLP9292M/01/11/2018 16:57. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

11/7/2018

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1	NA	*PASSENGER AIRBAG	0.00	0.00	act / 1,550.00 F
47	1	NA	*R/F AIRBAG SENSOR	0.00	0.00	act / 180.00 F
48	1	NA	*R/F BUMPER BRACKET	0.00	0.00	act / 10.00 F
49	1	NA	*R/F OUT S-MEMBER PNL SIDE PANEL X	0.00	0.00	? 36.00 F
50	1	NA	*R/F PANEL HIL PANEL	0.00	0.00	? 50.00 F
51	1	NA	*R/F REPEATER LAMP	0.00	0.00	? 32.00 F
52	1	NA	*R/F SEAT BELT	0.00	0.00	act / 440.00 F
53	1	NA	*R/F WING	0.00	0.00	bt / 290.00 F
54	1	NA	*R/LOWER AIR GRILLE FICOVER	0.00	0.00	? 28.00 F
55	1	NA	*RAD BY PASS TUBE TUBE 4	0.00	0.00	? 26.00 F
56	1	NA	*RADIATOR - photo	0.00	0.00	? 630.00 F
57	1	NA	*RADIATOR FAN MOTOR - photo	0.00	0.00	? 240.00 F
58	1	NA	*RADIATOR SHROUD - photo	0.00	0.00	? 145.00 F
59	1	NA	*RIGHT BONNET HINGE	0.00	0.00	bt / 38.00 F
60	1	NA	*RIGHT HEADLAMP ASSY	0.00	0.00	act / 410.00 F
61	1	NA	*SPACER X	0.00	0.00	? .F
62	1	NA	*SPACER PART X	0.00	0.00	? .F
63	1	NA	*UPP WINDSCREEN MLDG	0.00	0.00	act / 60.00 F
64	1	NA	*UPPER RADIATOR HOSE	0.00	0.00	twi / 32.00 F
65	1	NA	*VALVE COVER ENGINE T/COVER	0.00	0.00	? 95.00 F
66	1	NA	*WASHER RESERVOIR WASHER TANK X	0.00	0.00	? 55.00 F
67	1	NA	*WINDSCREEN	0.00	0.00	act / 550.00 F

F=Franchise part.

Total Parts (\$\$)

13,328.00

Cheng Hoe Motor Pte Ltd/SLP9292M/01/11/2018 16:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

**CHENG HOE MOTOR PTE
LTD
BLK 1019, YISHUN
INDUSTRIAL PARK A
#01-374/382
SINGAPORE 768761**

Claim Reference:
Assessment Number: CSLP9292
Version: CHENGHOE/2
Date Calculated: 04/12/2018 03:27

Full Report - V1
Registration: SLP9292M
Printed: 04/12/2018 11:28

Summary Information



Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	CHENG HOE MOTOR PTE LTD	Date of Incident:	24/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	21 day(s)
Policy Number:	DMPCSN1745141801	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	MITSUBISHI	FROM 09/2016	AIR CONDITIONING
Model:	Lancer	PRIVACY GLAZING	ELECT FOLDING MIRROR
Sub Model:	EX	MIRROR W/INDICATOR	RADIO CD
Model Sheet Number:	G39 57	FOG LAMPS	INDICATORS
Registration:	SLP9292M	DAYTIME RUNNING LIGHT	AUTO DIPPING MIRROR
Registration Month:	June	RAD GRILLE CHROME	RAIN SENSOR
Registration Year:	2017	ANTI-THEFT ALARM	DETACHABLE TOW BAR
VIN Number:	JMYSRCY1AGU006743	PAINTED DOOR HANDLES	KEYLESS ENTRY
Manufacture Year:	2017	REARVIEW CAMERA	KEYLESS GO
Odometer:	Not Known	1.6 LTR 85/86/91KW	4 SPEED AUTOMATIC
Colour:	Red	SPLIT GRILLE	STABILITY PROGRAM
Engine Number:		PASSENGER AIRBAG	ANTI LOCK BRAKES
Fuel Level:	%	DRIVER AIRBAG	CRUISE CONTROL
		TYRES 205/60 HR 16	WHEEL 6.5 JJ X 16
		4-DOOR SALOON	PREPARE OFF VEHICLE
		TWO COAT PEARL/MICA	

Vehicle Condition

Vehicle Status		
Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	01/11/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:		
Tread Depth LHF:	Tread Depth RHF:	

CHENG HOE MOTOR PTE LTD**Claim Reference:****Assessment Number: CSLP9292****Version: CHENGHOE/2****Date Calculated: 04/12/2018 03:27****Full Report - V1****Registration: SLP9292M****Printed: 04/12/2018 11:28**Tread Depth LHR:
Damage Areas:Tread Depth RHR:
Direction of Impact:**Addresses****Repairer**

Name : CHENG HOE MOTOR PTE LTD

Address :

NO 10, AMK IND PK 2A

01-04

Post Code : 568047

Cost Summary

Total Labour	\$2,158.80
Total Paint/Material	\$293.44
Total Parts	\$12,012.00
Total of Additional Costs	\$325.00
Excess:	TBA
Grand Total Exc GST:	\$14,789.24
7 % GST:	\$1,035.25
Grand Total Inc GST:	\$15,824.49

Repair Information**LABOUR**Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR**Repair /**

Guide Number	Repair Details	WU	Cost Price (\$)
GROUP42B	PREPARATION TIME PER JOB	2.0	8.40
NO NUMBER	ADD/TIME VEHICLE WITH AIR CONDITIONING	2.0	8.40
514121 10)	R + R ATTACHED PARTS OF THE BUMPER (BUMPER WITH FRONT FOG LAMPS)	12.0	50.40
528311 10	R + R L/F AIRBAG SENSOR	3.0	12.60
528311 10	R + R R/F AIRBAG SENSOR	3.0	12.60
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT (BUMPER REMOVED)	3.0	12.60
425111 10)	RENEW BONNET (REMOVED)	2.0	8.40
	INCLUDES: R + R ATTACHED PARTS, ALIGN BONNET		
425113 10)	R + R LEFT BONNET HINGE (BONNET REMOVED)	1.0	4.20
425113 10)	R + R RIGHT BONNET HINGE (BONNET REMOVED)	1.0	4.20
NO NUMBER	ADJUST HEADLAMPS	2.0	8.40
421020 YE	RENEW FRONT PANEL CPL INCLUDES: R + R BUMPER, FRONT WINGS, SPLASH SHIELD, BONNET, HEADLAMPS,	99.0	415.80

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSLP9292

Version: CHENGHOE/2

Date Calculated: 04/12/2018 03:27

Full Report - V1

Registration: SLP9292M

Printed: 04/12/2018 11:28

	RADIATOR AND ATTACHED PARTS IN THE REPAIR SECTION		
423121 10	R + R WINDSCREEN	33.0	138.60
522010 10ZAX	R + R L/F SEAT BELT	2.0	8.40
	INCLUDES: R + R B-PILLAR TRIM		
522020 10ZAX	R + R R/F SEAT BELT	2.0	8.40
	INCLUDES: R + R B-PILLAR TRIM		
NO NUMBER	R + R L/F SIDE TRIM	3.0	12.60
NO NUMBER	R + R R/F SIDE TRIM	3.0	12.60
528511 10	R + R AIRBAG CONTROL UNIT	9.0	37.80
523312 10ZAX	R + R REAR CENTRE CONSOLE	3.0	12.60
523111 10)	RENEW INSTRUMENT PANEL CPL	14.0	58.80
	(INSTRUMENT PANEL REMOVED)		
	INCLUDES: R + R INSTRUMENT PANEL PAD		
NO NUMBER	R + R INSTRUMENT PANEL CPL	14.0	58.80
NO NUMBER	DRAIN + REFILL COOLANT	4.0	16.80
NO NUMBER	R + R AIR INLET NECK	2.0	8.40
547015 10	RENEW AIRBAG WINDING	6.0	25.20
	INCLUDES: R + R STEERING WHEEL AND TRIM		
553210 10)	R + R CONDENSER	6.0	25.20
	INCLUDES: REFILL AIR CONDITIONING		
555511 10)	R + R AIR CONDITIONING INTAKE HOSE	5.0	21.00
555512 10)	R + R AIR CONDITIONING PRESSURE HOSE	4.0	16.80
NO NUMBER	R + R AIR CONDITIONING CONNECTION PIPE	2.0	8.40
0245	ADDITIONAL WORK PULLING FRONT PANELS	30.0*	126.00
1167	REPAIR L/F UP W-HOUSE REINF	15.0*	63.00
1168	REPAIR R/F UP W-HOUSE REINF	15.0*	63.00
1201	REPAIR L/F SIDE MEMBER CPL	20.0*	84.00
1202	REPAIR R/F SIDE MEMBER CPL	20.0*	84.00
1481	REPAIR LEFT FRONT DOOR	8.0*	33.60
1482	REPAIR RIGHT FRONT DOOR	8.0*	33.60
LABOUR COST			
	Total Work Units	358.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	35.8HRS	\$1,503.60
	Paint Labour	15.6HRS	\$655.20
	Total Labour	51.4HRS	\$2,158.80

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PREPARE OFF VEHICLE		
	- TWO COAT PEARL/MICA		
340	FRT BUMPER REINF SURFACE PAINT	4.0	
341	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
471	BONNET NEW PART PAINTING	24.0	
741	L/F WING NEW PART PAINTING	10.0	
742	R/F WING NEW PART PAINTING	10.0	
1017	FRT UPP LOCK CARRIERSURFACE PAINT	4.0	
1019	L/F PANEL SURFACE PAINT	4.0	
1020	R/F PANEL SURFACE PAINT	4.0	

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSLP9292

Version: CHENGHOE/2

Date Calculated: 04/12/2018 03:27

Full Report - V1

Registration: SLP9292M

Printed: 04/12/2018 11:28

283	FRONT BUMPER COVER NEW PART PAINT K1R	13.0	
345	CTR BUMPER BRACKET SURFACE PAINT	4.0	
1010	FRT LWR CROSSMEMBER SURFACE PAINT	5.0	
1167	L/F UP W-HOUSE REINFSURFACE PAINT	4.0	
1168	R/F UP W-HOUSE REINFSURFACE PAINT	4.0	
1187	L/F OUT S-MEMBER PNLSURFACE PAINT	4.0	
1188	R/F OUT S-MEMBER PNLSURFACE PAINT	4.0	
1201	L/F SIDE MEMBER CPL SURFACE PAINT	4.0	
1202	R/F SIDE MEMBER CPL SURFACE PAINT	4.0	
1481	LEFT FRONT DOOR SURFACE PAINT	8.0	
1482	RIGHT FRONT DOOR SURFACE PAINT	8.0	
LABOUR COST - PAINT			
	TIME(PAINT)	126.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	156.0	
	Total Paintwork Labour	15.6HRS	\$655.20
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$119.20
	New Part Painting - Plastic K1R		\$64.94
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$71.70
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$293.44
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$293.44

PARTS

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
4481	1	AIR INTAKE HOSE	7815A459		0%	180.00*
8388	1	AIR INTAKE MANIFOLD	1505A955		0%	85.00*
7443	1	AIRBAG CONTROL UNIT	8635A073		0%	550.00*
7440	1	AIRBAG SPRING	8651A086		0%	180.00*
7444	1	AIRBAG UNIT	7030A332XA		0%	1,050.00*
1411	1	BONDING KIT	Z2156737		0%	0.00F
471	1	BONNET	5900A209		0%	410.00*
524	1	BONNET FRONT SEAL	5902A021		0%	19.00*
481	1	BONNET INSULATION	5915A014		0%	65.00*
493	1	BONNET LOCK	5908A010		0%	45.00*
4465	1	CONDENSER	7812A204		0%	600.00*
4490	1	CONNECTION TUBE	7815A068		0%	85.00*
500	1	CONTROL CABLE	5910A064		0%	26.00*
7791	1	COOLING FAN	1355A132		0%	38.00*
354	1	CTR PROTECT MOULDING	6400B398		0%	130.00*
1439	1	FILLER NECK	8260A118		0%	20.00*
283	1	FRONT BUMPER COVER	6400H438		0%	460.00*
257	1	FRONT NUMBER PLATE	KNPL3		0%	35.00*
340	1	FRT BUMPER REINF	6400A832		0%	50.00*
341	1	FRT BUMPER SUPPORT	6400C639		0%	240.00*
1413	1	FRT SCREEN MNTG KIT	USE SINGLE PARTS		0%	0.00
293	1	FRT TOWING EYE COVER	6400G805XA		0%	26.00*

CHENG HOE MOTOR PTE LTD

Claim Reference:

Assessment Number: CSLP9292

Version: CHENGHOE/2

Date Calculated: 04/12/2018 03:27

Full Report - V1

Registration: SLP9292M

Printed: 04/12/2018 11:28

1017	1	FRT UPP LOCK CARRIER	5256A607	0%	140.00*
410	1	GRILLE	7450B019	0%	145.00*
1000	1	HEADLAMP BRACKET X2	Renew	0%	20.00*
9646	1	HIGH TONE HORN	8211A212	0%	55.00*
4482	1	INLET HOSE	7815A775	0%	125.00*
8777	1	INN UPP FR PANELLING	5230A813	0%	45.00*
4331	1	INSTRUMENT PANEL	8000A100XA	0%	720.00*
539	1	L/F AIRBAG SENSOR	8651A178	0%	180.00*
355	1	L/F BUMPER BRACKET	6400F549	0%	10.00*
1019	1	L/F PANEL	5256A599	0%	50.00*
707	1	L/F REPEATER LAMP	8351A001	0%	32.00*
4661	1	L/F SEAT BELT	7000B600	0%	440.00*
741	1	L/F WING	5220G043	0%	290.00*
351	1	L/LOWER AIR GRILLE	8321A089	0%	28.00*
475	1	LEFT BONNET HINGE	5905A089	0%	38.00*
575	1	LEFT HEADLAMP ASSY	8301C373	0%	410.00*
9645	1	LOW TONE HORN	8211A213	0%	55.00*
313	1	LWR RADIATOR GRILLE	6402A399	0%	55.00*
4325	1	PASSENGER AIRBAG	7030A060	0%	1,550.00*
540	1	R/F AIRBAG SENSOR	8651A178	0%	180.00*
356	1	R/F BUMPER BRACKET	6400F550	0%	10.00*
1020	1	R/F PANEL	5256A600	0%	50.00*
708	1	R/F REPEATER LAMP	8351A001	0%	32.00*
4662	1	R/F SEAT BELT	7000B624	0%	440.00*
742	1	R/F WING	5220G044	0%	290.00*
352	1	R/LOWER AIR GRILLE	8321A690	0%	28.00*
7761	1	RADIATOR	1350A298	0%	630.00*
7800	1	RADIATOR FAN MOTOR	1355A141	0%	240.00*
7767	1	RADIATOR SHROUD	1355A146	0%	145.00*
476	1	RIGHT BONNET HINGE	5905A090	0%	38.00*
576	1	RIGHT HEADLAMP ASSY	8301C374	0%	410.00*
1228	5	SPACER	MR957780	0%	0.00F
1227	1	SPACER PART	MR520530	0%	0.00F
1423	1	UPP WINDSCREEN MLDG	6107A013	0%	60.00*
7776	1	UPPER RADIATOR HOSE	1370A121	0%	32.00*
7943	1	VALVE COVER	1003A243	0%	95.00*
1401	1	WINDSCREEN	6102A482	0%	550.00*
f: OEM Parts				Saving	\$24.04
g: Original				Sub Total	\$11,912.00
h: Secondhand				Sundry Parts	\$100.00
p: Parallel				(Fixed)	
x: Exchange				Total Parts	\$12,012.00

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
COOLANT SPECIALIST	0%	\$20.00
AIRCON GAS SPECIALIST		\$50.00
WS SEALANT SPECIALIST	0%	\$40.00
IU BRACKET SPECIALIST		\$15.00
RESET N PROGRAME SPECIALIST	0%	\$200.00

CHENG HOE MOTOR PTE LTD

Claim Reference:
Assessment Number: CSLP9292
Version: CHENGHOE/2
Date Calculated: 04/12/2018 03:27

Full Report - V1
Registration: SLP9292M
Printed: 04/12/2018 11:28

	Total Extras	\$325.00
Final Calculation		
Total Parts		\$12,012.00
Labour		
Total Panel/Mechanical	\$1,503.60	
Total Paintwork	\$655.20	
Total Labour		\$2,158.80
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$325.00	
Total of Additional Costs		\$325.00
Total Paint/Material Costs		\$293.44
Grand Total Excludes GST		\$14,789.24
GST @ 7 %		\$1,035.25
Grand Total Includes GST		\$15,824.49

Assessment Notes



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9191 / 6745 8806



Dept Direct: 6306 9810

Dept Direct: 6306 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9796

Dept Direct: 6417 9798

Dept Direct: 6417 9799

Wiper blade: NWB (Nippon Wiper blades), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

CHENG HOE MOTOR PTE LTD
BLK 10 #01-04
ANG MO KIO AUTO POINT

TEL : 64812001 FAX : 64821296
ATTN : DORLYN

TAX INVOICE AR201811-04968
DATE 12/11/2018
CUSTOMER ID CHE002
VEH REG. NO. SLP9292M
TERMS 30 days
PO NO.
PAGE NO. Page 1 of 1
CURR. SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
✓	WMB/6102A304 (NIP)	FRT W/S GLASS	MO	1	550.00	550.00
	EVO X "08/CY1/CZ4		1D42			
✓	MLD.MIT CY2/4 TOP CMC 6107A013	FRT W/S MLD TOP (OEM)	MO	1	60.00	60.00
	CY2/4 LANCER 07"		1A77E			

SUB-TOTAL : 610.00
ADD GST 7.00% 42.70

E & OR TOTAL AMOUNT SGD : 652.70

[P] 12/11/2018 10:57:43AM

[E] 12/11/2018 10:49:50AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : YIP



AR201811-04968

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date




豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Feng Tat Building Singapore 347493 Tel: 67493586/67499958 Fax: 67495866/67495007
25 Kall Buit Road 4, #01-23 Synergy @ Kall Singapore 417900 Tel: 6396 5369 / 6394 2235 Fax: 6394 2245
Blk 685 #01-324 Race Course Road Singapore 210885 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M

GST Reg. No.: M2-00252314

INVOICE TO: CHENG HOE MOTOR PTE LTD-ANG MO KIO
10, #01-04 Amk Autoport
SINGAPORE 458047
SLP 9292 H



TAX INVOICE NO.: TL126899
INVOICE DATE: 12/11/2018
CREDIT TERMS: 30 DAYS
SALES ORDER NO.: TBS
SALESMAN: TBS
PAGE(S): 1

TAX INVOICE

PARTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
J8260A118	HOSE, W/SHLD WSHR TANK FLR		1 PCS	(SIN) 20.000	(SIN) 20.00
				GST Excl Amount : Special Discount : GST @ 7 % :	20.00 1.40

FONG EE INDUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

PRINT BY :

TBS 12/11/2018 14:23:46

AUTHORISED SIGNATURE

SIGNATURE

TOTAL

21.40



豐裕工業 (私營) 有限公司

FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347403 Tel: 67495388/67495389 Fax: 67495666/67495607
25 Kallang Road 4, #01-02 Synergy @ Kallang Singapore 347603 Tel: 6396 0369 / 6394 2235 Fax: 6394 2245
Bk 645 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197602013M

GST Reg. No.: M2-00252314

INVOICE TO:

CHENG HOE MOTOR PTE LTD-ANG MO KIO
10 ANG MO KIO IND PK 2A
#01-04 ANK AUTOPOINT
VEH:SLP 9292 H

TAX INVOICE

PARTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
J1003A243	COVER ASSY, ENG, UPR		1	(SIN) 95.000	(SIN) 95.00
				GST Excl Amount : Special Discount : GST @ 7 % :	95.00 6.65

FONG EE INDUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

101.65

TOTAL

PRINT BY :

TBS 09/11/2018 10:52:11

AUTHORISED SIGNATURE

SIGNATURE

11:55





豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED
 (AUTOMOTIVE DIVISION)

No. 3 Mallang Way 2A Fong Tat Building Singapore 341493 Tel: 67493553/67496958 Fax: 67493866/67495007
 25 Kaki Bukit Road 4, #01-23 Synergy @ K3 Singapore 417900 Tel: 6384 6363 / 6384 2235 Fax: 6384 2245
 Bldg 685 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
 Co. Reg. No.: 197602013M

GST Reg. No.: M2-00252314

INVOICE TO:

CHENG HOE MOTOR PTE LTD-ANG HO KIO

10 ANG HO KIO IND PK 2A

#01-04 ANK AUTOPOINT

VEH:SLP 9292 M

TAX INVOICE NO.: TL126882

INVOICE DATE : 09/11/2018

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : TBS

PAGE(S) : 1

TAX INVOICE

PARTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
				(SIN)	(SIN)
J6400H438	FACE, FR BUMPER		1	450.000	450.00
J6400A832	REINFORCEMENT, FR BUMPER		1	50.000	50.00
J6400C639	REINFORCEMENT, FR BUMPER		1	240.000	240.00
J5902A021	WEATHERSTRIP, HOOD, FR		1	19.000	19.00
J8321A689	GARNISH, FR BUMPER, LH		1	28.000	28.00
J8321A690	GARNISH, FR BUMPER, RH		1	28.000	28.00
J6400F549	BRACKET, FR BUMPER SIDE, LH		1	10.000	10.00
J6400F550	BRACKET, FR BUMPER SIDE, RH		1	10.000	10.00
J6402A399	GRILLE, FR BUMPER		1	55.000	55.00
J6402A402	GARNISH, FR BUMPER, CTR		1	130.000	130.00
J6400G805WA	COVER, FR BUMPER		1	26.000	26.00

FONG EE INDUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

AUTHORISED SIGNATURE

SIGNATURE





豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED
 (AUTOMOTIVE DIVISION)

No. 3 Kai Kang Way 2A Fong Tat Building Singapore 347433 Tel: 67493588/67498558 Fax: 67498666/67495007
 25 Kallang Road 4, #01-23 Syntex @ KB Singapore 417800 Tel: 6386 6389 / 6384 2235 Fax: 6384 2245
 SIA 885 #01-324 Race Course Road Singapore 210665 Tel: 62954551 Fax: 62970774
 Co. Reg. No. 197603013M

GST Reg. No.: M2-00252314

INVOICE TO: CHENG HOE MOTOR PTE LTD-ANG MO KIO

10 ANG MO KIO IND PK 2A

#01-04 ANK AUTOPOINT

VEH: SLP 9292 H

TAX INVOICE

PARTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
J7450B019	GRILLE, RADIATOR		1	145.000	145.00
J5900A209	HOOD		1	410.000	410.00
J5908A056	LATCH, HOOD/5908A080		1	45.000	45.00
J5905A089-R	HINGE, HOOD, LH		1	38.000	38.00
J5905A090-R	HINGE, HOOD, RH		1	38.000	38.00
J5915A014	INSULATOR, HOOD		1	65.000	65.00
J5910A064	CABLE, HOOD LOCK RELEASE		1	26.000	26.00
J5220G041	FENDER, FR LH		1 PCS	290.000	290.00
J5220G042	FENDER, FR RH		1 PCS	290.000	290.00
J7405A646	GARNISH, FR FENDER		2	32.000	64.00
J8301C379	BODY, HEADLAMP, LH		1	410.000	410.00

FONG EE INDUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

AUTHORISED SIGNATURE

SIGNATURE



TAX INVOICE NO.: TL126882

INVOICE DATE: 09/11/2018

CREDIT TERMS: 30 DAYS

SALES ORDER NO.: TBS

SALESMAN: TBS

PAGE(S): 2



豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A Fong Tat Building Singapore 347493 Tel: 67493566/67493558 Fax: 67493566/67493507
25 Kallang Road 4, #01-23 Synergy @ KB Singapore 417802 Tel: 6396 6269/6264 2235 Fax: 6394 2245
Bik 655 #01-324 Race Course Road Singapore 210685 Tel: 62954551 Fax: 62970774
Co. Reg. No.: 197402013M


GST Reg. No.: M2-00252314

INVOICE TO: CHENG HOE MOTOR PTE LTD-ANG MO KIO

10 ANG MO KIO IND PK 2A

#01-04 ANK AUTOPOINT

VEH:SLP 9292 M



TAX INVOICE NO.: TL126882

INVOICE DATE: 09/11/2018

CREDIT TERMS: 30 DAYS

SALES ORDER NO.:

SALESMAN: TBS

PAGE(S): 3

TAX INVOICE

PARTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE (SIN)	AMOUNT (SIN)
J8301C380	BODY, HEADLAMP, RH		1	410.000	410.00
J6400A851	SUPPORT, FR BUMPER, LH		1	10.000	10.00
J6400A852	SUPPORT, FR BUMPER, RH		1	10.000	10.00
J5256A599	PNL, HEADLAMP SUPT, UPR, LH		1	50.000	50.00
J5256A600	PNL, HEADLAMP SUPT, UPR, RH		1	50.000	50.00
J8211A212	HORN		1 PCS	55.000	55.00
J8211A213	HORN		1 PCS	55.000	55.00
J5256A607	PANEL, HEADLAMP SUPPORT, UPR		1	140.000	140.00
J6400A831	COVER, HEADLAMP SUPT PANEL		1	45.000	45.00
J7812A204	CONDENSER ASSY, A/C		1 PCS	600.000	600.00
J7815B035	PIPE, A/C CONDENSER OUTLET		1	85.000	85.00

FONG EE INDUSTRIAL (PTE) LIMITED

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

AUTHORISED SIGNATURE

SIGNATURE



豐裕工業 (私營) 有限公司
FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)
No. 3 Kallang Way 2A Fong Tai Building Singapore 347403 Tel: 67493586/67499958 Fax: 67495866/67496007
25 Kallang Road 4, #01-23 Syntex @ KB Singapore 417800 Tel: 6396 6369 / 6384 2235 Fax: 6394 2245
Bld 685 #01-324 Race Course Road Singapore 210665 Tel: 62954551 Fax: 62970774
Co. Reg No.: 197602013M

GST Reg. No.: M2-00252314

INVOICE TO:

CHENG HOE MOTOR PTE LTD-ANG MO KIO
10 ANG MO KIO IND PK 2A
#01-04 ANK AUTOPOINT
VEH: SLP 9292 M

TAX INVOICE

PARTS NO	DESCRIPTION	LOC	QUANTITY	UNIT PRICE	AMOUNT
JJ7815A775	HOSE, A/C COMPRESSOR SUCTION		1	180.000	180.00
J7815A459	HOSE, A/C COMPRESSOR DISCHARGE		1	125.000	125.00
J1350A298	RADIATOR ASSY		1 PCS	630.000	630.00
J1355A146	SHROUD, COOLING FAN		1	145.000	145.00
J1355A141	MOTOR, COOLING FAN (*)		1	240.000	240.00
J1355A132	FAN, COOLING		1	38.000	38.00
J1370A426	HOSE, RADIATOR, UPR LH		1	32.000	32.00
J1505A955	DUCT, AIR CLEANER INTAKE		1	85.000	85.00
J8651A143 / 8651 A002	SENSOR, AIR BAG, LH/RH		2 PCS	180.000	360.00
* J8635A073	CONTROL UNIT, SRS DIAGNOSIS		1 PCS	550.000	550.00
® J7030A060	MODULE, PASSENGER AIR BAG		1	1550.000	1550.00

FONG EE INDUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH GOODS RECEIVED

TOTAL

AUTHORISED SIGNATURE

SIGNATURE



TAX INVOICE NO.: TL126882
INVOICE DATE : 09/11/2018
CREDIT TERMS : 30 DAYS
SALES ORDER NO.: TBS
SALESMAN : TBS
PAGE(S) : 4



豐裕工業 (私營) 有限公司

FONG EE INDUSTRIAL (PTE) LIMITED

(AUTOMOTIVE DIVISION)

No. 3 Kallang Way 2A, Fong Tat Building Singapore 347403 Tel: 67483588/67483586 Fax: 67495666/67495007
25 Kall Bukit Road 4, #01-02 Singapore 417600 Tel: 6396 0389 / 6384 2235 Fax: 6384 2245
Bla 685 #01-324 Race Course Road Singapore 210645 Tel: 62954551 Fax: 62970774
Co. Reg No: 197602813M

GST Reg. No.: M2-00252314

INVOICE TO:

CHENG HOE MOTOR PTE LTD-ANG HO KIO
10 ANG HO KIO IND PK 2A
#01-04 ANG AUTOPOINT
VEH:SLP 9292 H

TAX INVOICE

TAX INVOICE NO.: TL126882
INVOICE DATE: 09/11/2018
CREDIT TERMS: 30 DAYS
SALES ORDER NO.:
SALESMAN: TBS
PAGE(S): 5



PARTS NO.	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	AMOUNT
J7030A332XA	MODULE, AIR BAG		1 PCS	(SIN) 1050.000	1050.00
J8619A018	SPRING, AIR BAG SENSOR		1	(SIN) 180.000	180.00
J7000B599	S/BELT, FR PRE-TENSIONER, OTR LH		1	(SIN) 440.000	440.00
J7000B602	S/BELT, FR PRE-TENSIONER, OTR RH		1	(SIN) 440.000	440.00
J8000A062XA	PANEL, INSTRUMENT		1	(SIN) 720.000	720.00
				GST Excl Amount :	11152.00
				Special Discount :	
				GST @ 7 %	780.64

FONG EE INDUSTRIAL (PTE) LIMITED GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :

TBS 09/11/2018 09:35:55

AUTHORISED SIGNATURE

SIGNATURE

TOTAL

11932.64

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2018 16:55 Sendback Est	01 Nov 2018 16:57 S\$16,516.32	01 Nov 2018 17:24 Edit Adj Rpt	S\$14,789.24 Edit Estimates	S\$14,789.24 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: LIM LI YI , ID: 583198708, Tel: +6598007737									
Vehicle Reg. No.: SLP9292M		Date of Loss: 24/10/2018 08:00 - :59 [15 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D05059C01		Policy/Cover Note No.: DMPCSN1745141801 (Comprehensive) Coverage: 28/06/2018 - 27/06/2019							
		Excess: S\$0.00							
Reparer: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 13/11/2018]									
Driver/Custodian: LIM LI YI (35 / Female) , NRIC: 583198708, Tel: +6598007737									
Adj Asg. Remarks: you have previously surveyed the vehicle at cycle and carriage. As its repair cost is too high, vehicle was towed to chenghoe motor instead. please assist to finalise repair cost with chenghoe motor									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (08/11/2018): Alert - Adj Mandate Approved (S\$16076.43) - SLP9292M - Claim Handler: Catherine ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLP9292M (SNM18D05059C01)

OD

Oct 24 2018 8:00AM

[LIM LI YI]

Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	01/11/18 16:57	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/11/18 15:52	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/11/18 15:34	Odometer Reading	Load JPG	☒
2	07/11/18 15:34	General View	Load JPG	☒
3	07/11/18 15:34	General View	Load JPG	☒
4	07/11/18 15:34	General View	Load JPG	☒
5	07/11/18 15:34	General View	Load JPG	☒
6	07/11/18 15:34	General View	Load JPG	☒
7	07/11/18 15:34	General View	Load JPG	☒
8	07/11/18 15:34	General View	Load JPG	☒
9	07/11/18 15:34	General View	Load JPG	☒
10	07/11/18 15:34	General View	Load JPG	☒
11	07/11/18 15:34	General View	Load JPG	☒
12	07/11/18 15:34	General View	Load JPG	☒
13	07/11/18 15:34	General View	Load JPG	☒
14	07/11/18 15:34	General View	Load JPG	☒
15	07/11/18 15:34	General View	Load JPG	☒
16	07/11/18 15:34	General View	Load JPG	☒
17	07/11/18 15:34	General View	Load JPG	☒
18	07/11/18 15:34	General View	Load JPG	☒
19	07/11/18 15:34	General View	Load JPG	☒
20	07/11/18 15:34	General View	Load JPG	☒
21	07/11/18 15:34	General View	Load JPG	☒
22	07/11/18 15:34	General View	Load JPG	☒
23	07/11/18 15:34	General View	Load JPG	☒
24	07/11/18 15:34	General View	Load JPG	☒
25	07/11/18 15:34	General View	Load JPG	☒
26	07/11/18 15:34	General View	Load JPG	☒
27	07/11/18 15:34	General View	Load JPG	☒
28	07/11/18 15:34	General View	Load JPG	☒
29	07/11/18 15:34	General View	Load JPG	☒
30	07/11/18 15:34	General View	Load JPG	☒
31	07/11/18 15:34	General View	Load JPG	☒
32	07/11/18 15:34	General View	Load JPG	☒
33	07/11/18 15:34	General View	Load JPG	☒
34	07/11/18 15:34	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
				☒
35	07/11/18 15:34	General View	 Load JPG	☒
36	07/11/18 15:34	General View	 Load JPG	☒
37	07/11/18 15:34	General View	 Load JPG	☒
38	07/11/18 15:34	General View	 Load JPG	☒
39	07/11/18 15:34	General View	 Load JPG	☒
40	07/11/18 15:34	General View	 Load JPG	☒
41	07/11/18 15:34	General View	 Load JPG	☒
42	07/11/18 15:34	General View	 Load JPG	☒
43	07/11/18 15:34	General View	 Load JPG	☒
44	07/11/18 15:34	General View	 Load JPG	☒
45	07/11/18 15:35	General View	 Load JPG	☒
46	07/11/18 15:35	General View	 Load JPG	☒
47	07/11/18 15:35	General View	 Load JPG	☒
48	07/11/18 15:35	General View	 Load JPG	☒
49	07/11/18 15:35	General View	 Load JPG	☒
50	07/11/18 15:35	General View	 Load JPG	☒
51	07/11/18 15:35	General View	 Load JPG	☒
52	07/11/18 15:35	General View	 Load JPG	☒
53	07/11/18 15:35	General View	 Load JPG	☒
54	07/11/18 15:35	General View	 Load JPG	☒
55	07/11/18 15:35	General View	 Load JPG	☒
56	07/11/18 15:35	General View	 Load JPG	☒
57	07/11/18 15:35	General View	 Load JPG	☒
58	07/11/18 15:35	General View	 Load JPG	☒
59	07/11/18 15:35	General View	 Load JPG	☒
60	07/11/18 15:35	General View	 Load JPG	☒
61	07/11/18 15:35	General View	 Load JPG	☒
62	07/11/18 15:35	General View	 Load JPG	☒
63	07/11/18 15:35	General View	 Load JPG	☒
64	07/11/18 15:35	General View	 Load JPG	☒
65	07/11/18 15:35	General View	 Load JPG	☒
66	07/11/18 15:35	General View	 Load JPG	☒
67	07/11/18 15:35	General View	 Load JPG	☒
68	07/11/18 15:35	General View	 Load JPG	☒
69	07/11/18 15:35	General View	 Load JPG	☒
70	07/11/18 15:35	General View	 Load JPG	☒
71	07/11/18 15:35	General View	 Load JPG	☒
72	07/11/18 15:35	General View	 Load JPG	☒
73	07/11/18 15:35	General View	 Load JPG	☒
74	07/11/18 15:35	General View	 Load JPG	☒
75	07/11/18 15:35	General View	 Load JPG	☒
76	07/11/18 15:35	General View	 Load JPG	☒
77	07/11/18 15:35	General View	 Load JPG	☒
78	07/11/18 15:35	General View	 Load JPG	☒
79	07/11/18 15:35	General View	 Load JPG	☒
80	07/11/18 15:35	General View	 Load JPG	☒
81	07/11/18 15:35	General View	 Load JPG	☒
82	07/11/18 15:35	General View	 Load JPG	☒
83	26/12/18 15:51	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
84	26/12/18 15:51	Reinspection Photo		☒
85	26/12/18 15:51	Reinspection Photo		☒
86	26/12/18 15:51	Reinspection Photo		☒
87	26/12/18 15:51	Reinspection Photo		☒
88	26/12/18 15:51	Reinspection Photo		☒
89	26/12/18 15:51	Reinspection Photo		☒
90	26/12/18 15:51	Reinspection Photo		☒
91	26/12/18 15:51	Reinspection Photo		☒
92	26/12/18 15:51	Reinspection Photo		☒
93	26/12/18 15:51	Reinspection Photo		☒
94	26/12/18 15:51	Reinspection Photo		☒
95	26/12/18 15:51	Reinspection Photo		☒
96	26/12/18 15:51	Reinspection Photo		☒
97	26/12/18 15:51	Reinspection Photo		☒
98	26/12/18 15:51	Reinspection Photo		☒
99	26/12/18 15:51	Reinspection Photo		☒
100	26/12/18 15:51	Reinspection Photo		☒
101	26/12/18 15:51	Reinspection Photo		☒
102	26/12/18 15:51	Reinspection Photo		☒
103	26/12/18 15:51	Reinspection Photo		☒
104	26/12/18 15:51	Reinspection Photo		☒
105	26/12/18 15:51	Reinspection Photo		☒
106	26/12/18 15:51	Reinspection Photo		☒
107	26/12/18 15:51	Reinspection Photo		☒
108	26/12/18 15:51	Reinspection Photo		☒
109	26/12/18 15:51	Reinspection Photo		☒
110	26/12/18 15:51	Reinspection Photo		☒
111	26/12/18 15:51	Reinspection Photo		☒
112	26/12/18 15:51	Reinspection Photo		☒
113	26/12/18 15:51	Reinspection Photo		☒
114	26/12/18 15:51	Reinspection Photo		☒
115	26/12/18 15:51	Reinspection Photo		☒
116	26/12/18 15:51	Reinspection Photo		☒
117	26/12/18 15:51	Reinspection Photo		☒
118	26/12/18 15:51	Reinspection Photo		☒
119	26/12/18 15:51	Reinspection Photo		☒
120	26/12/18 15:51	Reinspection Photo		☒
121	26/12/18 15:51	Reinspection Photo		☒
122	26/12/18 15:51	Reinspection Photo		☒
123	26/12/18 15:51	Reinspection Photo		☒
124	26/12/18 15:51	Reinspection Photo		☒
125	26/12/18 15:51	Reinspection Photo		☒
126	26/12/18 15:51	Reinspection Photo		☒
127	26/12/18 15:51	Reinspection Photo		☒
128	26/12/18 15:51	Reinspection Photo		☒
129	26/12/18 15:51	Reinspection Photo		☒
130	26/12/18 15:51	Reinspection Photo		☒
131	26/12/18 15:51	Reinspection Photo		☒
132	26/12/18 15:51	Reinspection Photo		☒
133	26/12/18 15:51	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
		Cheng Hoe Motor Pte Ltd (Yishun)		
Documentation			1 per page	☒
No	Finalized On		Thumbnail	Print
1	01/11/18 16:57	GIA REPORT		Load PDF
		China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		
1	03/12/18 11:14	Revised Estimate		Load PDF
		LKK Auto Consultants Pte Ltd (HQ)		
1	07/11/18 15:39	ESTIMATE		Load PDF
2	07/11/18 15:39	AUDATEX		Load PDF
3	03/01/19 11:27	Parts Invoice		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18019447/T1QD3E2

Date: 03/01/2019

REFERENCE

Insured/Claimant: LIM LI YI Policy No: DMPCSN1745141801
Date of Loss: 24/10/2018 Nature of Claim: OD Claim No: SNM18D05059C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP9292M**
Make & Model: MITSUBISHI LANCER, 1.6 (A) Engine No: 4A92CP4092
Reg. Date: 28/06/2017 (Man. Year: 2017) Chassis No: JMYSRCY1AGU006743
Colour: Maroon Odometer: 27273 km
Engine Capacity: 1590 cc
Market Value/New Car Price: S\$66,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,328.00	11,912.00	1,416.00	10.62
Miscellaneous Items	425.00	425.00	0.00	0.00
Labour	2,763.32	2,452.24	311.08	11.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,516.32	14,789.24	1,727.08	10.46
+ GST 7.00/7.00% (S\$)	1,156.14	1,035.25	120.89	10.46
Nett Amount (S\$)	17,672.46	15,824.49	1,847.97	10.46

INSPECTION

Date of Assignment: 01/11/2018 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 26/10/2018 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2019)
Parts: 143	mitsubishi LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP9292M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIR INTAKE HOSE	Bent	180.00 F	*180.00 F
2	1	NA	*AIR INTAKE MANIFOLD	Deformed	85.00 F	*85.00 F
3	1	NA	*AIRBAG CONTROL UNIT	Activated	550.00 F	*550.00 F
4	1	NA	*AIRBAG SPRING	Activated	180.00 F	*180.00 F
5	1	NA	*AIRBAG UNIT	Activated	1,050.00 F	*1,050.00 F
6	1	NA	*ALTERNATOR	Not Necessary	880.00 F	*- F
7	1	NA	*BATTERY TRAY	Not Necessary	28.00 F	*- F
8	1	NA	*BONDING KIT	Not Necessary	0.00 F	*- F
9	1	NA	*BONNET	Bent	410.00 F	*410.00 F
10	1	NA	*BONNET FRONT SEAL	Necessary	19.00 F	*19.00 F
11	1	NA	*BONNET INSULATION	Deformed	65.00 F	*65.00 F
12	1	NA	*BONNET LOCK	Bent	45.00 F	*45.00 F
13	1	NA	*CONDENSER	Bent	600.00 F	*600.00 F
14	1	NA	*CONNECTION TUBE	Deformed	85.00 F	*85.00 F
15	1	NA	*CONTROL CABLE	Distorted	26.00 F	*26.00 F
16	1	NA	*COOLING FAN	Cracked	38.00 F	*38.00 F
17	1	NA	*CTR PROTECT MOULDING	Cracked	130.00 F	*130.00 F
18	1	NA	*FILLER NECK	Deformed	20.00 F	*20.00 F
19	1	NA	*FRONT BUMPER COVER	Deformed	460.00 F	*460.00 F
20	1	NA	*FRONT NUMBER PLATE	Deformed	35.00 F	*35.00 F
21	1	NA	*FRT BUMPER REINF	Bent	50.00 F	*50.00 F
22	1	NA	*FRT BUMPER SUPPORT	Bent	240.00 F	*240.00 F
23	1	NA	*FRT LWR CROSSMEMBER	Not Necessary	260.00 F	*- F
24	1	NA	*FRT SCREEN MNTG KIT	Not Necessary	0.00 F	*- F
25	1	NA	*FRT TOWING EYE COVER	Deformed	26.00 F	*26.00 F
26	1	NA	*FRT UPP LOCK CARRIER	Bent	140.00 F	*140.00 F
27	1	NA	*GRILLE	Cracked	145.00 F	*145.00 F
28	1	NA	*HEADLAMP BRACKET X2	Necessary	20.00 F	*20.00 F
29	1	NA	*HIGH TONE HORN	Bent	55.00 F	*55.00 F
30	1	NA	*INLET HOSE	Bent	125.00 F	*125.00 F
31	1	NA	*INN UPP FR PANELLING	Deformed	45.00 F	*45.00 F
32	1	NA	*INSTRUMENT PANEL	Deformed	720.00 F	*720.00 F
33	1	NA	*L/F AIRBAG SENSOR	Activated	180.00 F	*180.00 F
34	1	NA	*L/F BUMPER BRACKET	Necessary	10.00 F	*10.00 F
35	1	NA	*L/F OUT S-MEMBER PNL	Not Necessary	36.00 F	*- F
36	1	NA	*L/F PANEL	Bent	50.00 F	*50.00 F
37	1	NA	*L/F REPEATER LAMP	Distorted	32.00 F	*32.00 F
38	1	NA	*L/F SEAT BELT	Cut	440.00 F	*440.00 F
39	1	NA	*L/F WING	Bent	290.00 F	*290.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1	NA	*L/LOWER AIR GRILLE	Deformed	28.00 F	*28.00 F
41	1	NA	*L/LWR B-PILLAR TRIM	Not Necessary	95.00 F	*- F
42	1	NA	*LEFT BONNET HINGE	Bent	38.00 F	*38.00 F
43	1	NA	*LEFT HEADLAMP ASSY	Cracked	410.00 F	*410.00 F
44	1	NA	*LOW TONE HORN	Bent	55.00 F	*55.00 F
45	1	NA	*LWR RADIATOR GRILLE	Cracked	55.00 F	*55.00 F
46	1	NA	*PASSENGER AIRBAG	Activated	1,550.00 F	*1,550.00 F
47	1	NA	*R/F AIRBAG SENSOR	Activated	180.00 F	*180.00 F
48	1	NA	*R/F BUMPER BRACKET	Necessary	10.00 F	*10.00 F
49	1	NA	*R/F OUT S-MEMBER PNL	Not Necessary	36.00 F	*- F
50	1	NA	*R/F PANEL	Bent	50.00 F	*50.00 F
51	1	NA	*R/F REPEATER LAMP	Distorted	32.00 F	*32.00 F
52	1	NA	*R/F SEAT BELT	Activated	440.00 F	*440.00 F
53	1	NA	*R/F WING	Bent	290.00 F	*290.00 F
54	1	NA	*R/LOWER AIR GRILLE	Deformed	28.00 F	*28.00 F
55	1	NA	*RAD BY PASS TUBE	Not Necessary	26.00 F	*- F
56	1	NA	*RADIATOR	Bent	630.00 F	*630.00 F
57	1	NA	*RADIATOR FAN MOTOR	Distorted	240.00 F	*240.00 F
58	1	NA	*RADIATOR SHROUD	Cracked	145.00 F	*145.00 F
59	1	NA	*RIGHT BONNET HINGE	Bent	38.00 F	*38.00 F
60	1	NA	*RIGHT HEADLAMP ASSY	Cracked	410.00 F	*410.00 F
61	1	NA	*SPACER	Not Necessary	0.00 F	*- F
62	1	NA	*SPACER PART	Not Necessary	0.00 F	*- F
63	1	NA	*UPP WINDSCREEN MLDG	Necessary	60.00 F	*60.00 F
64	1	NA	*UPPER RADIATOR HOSE	Twisted	32.00 F	*32.00 F
65	1	NA	*VALVE COVER	Cracked	95.00 F	*95.00 F
66	1	NA	*WASHER RESERVOIR	Not Necessary	55.00 F	*- F
67	1	NA	*WINDSCREEN	Cracked	550.00 F	*550.00 F

F=Franchise part.

Total Parts (\$\$)	13,328.00	11,912.00
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	SPECIALIST AIRCON GAS (NECESSARY)	50.00	50.00
2	1	SPECIALIST COOLANT (NECESSARY)	20.00	20.00
3	1	SPECIALIST IU BRACKET (NECESSARY)	15.00	15.00
4	1	SPECIALIST RESET N PROGRAME .	200.00	200.00
5	1	SPECIALIST WS SEALANT (NECESSARY)	40.00	40.00
6	1	SUNDRY PARTS (NECESSARY)	100.00	100.00
Sub Total (S\$)			425.00	425.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	672.00	655.20
2	Total Paint Materials	New	297.92	293.44
3	Total Panel/Mechanical Labour	New	1,793.40	1,503.60
Gross Labour Cost (S\$)			2,763.32	2,452.24

Report was unsubmitted during this print-out.

< END OF ESTIMATES >