

































PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701 Tel : 645 31173, Fax : 645 36131.

Report No: 0581-18-TCA

24 September 2018

ACCIDENT VEHICLE SURVEY REPORT

3H Transportation & Tradir
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	PC1145D	<i>Odometer:</i>	391015km
<i>Make & Model:</i>	Toyota Hiace Hiroof Auto	<i>Colour:</i>	Silver
<i>Chassis number:</i>	JTFST22PX00011472	<i>Date of accident:</i>	20/02/2018
<i>Year of Regn.:</i>	15/09/2011	<i>Date inspected:</i>	22/02/2018
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	10/03/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.



