



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
 100 BEACH ROAD
 #19-00 SHAW TOWERS
 SINGAPORE 189702

Registration No : SME4866L

Chassis No : MRHFC5650JT001643

Model : CIVIC 1.6 VTI YM2018

Owner's Name : HAO YANLIANG

Ins Policy No. :

Date of Accident : 24/10/2018

Document No. : SQT18004566

Date : 24. Oct 2018

Customer No. : WZL009

Svc Advisor :

Engine No : R16B25501907

Date | Time : 24. Oct 2018 6:02:41 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:HAO YANLIANG OWNER INSURER:TOKIO MARINE ACC DATE:24/10/2018 SURVEYED BY: DATE: REF NO: TP INSURER:LONPAC INSURANCE TP VEH:PG 7693 J						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20 <i>de</i>	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20 <i>de</i>	25	28.65	2.01	30.66
33505-TEA-T01	REFLECTOR ASSY,RR.	1	7.00 ?	25	5.25	0.37	5.62
33555-TEA-T01	REFLECTOR ASSYL,RR.	1	7.00 ?	25	5.25	0.37	5.62
71503-TEA-T00	GARNISH,RR.BUMPER SIDE	1	7.60 ?	25	5.70	0.40	6.10
71508-TEA-T00	GARNISH,RR.BUMPER SIDE	1	7.60 ?	25	5.70	0.40	6.10
71593-TEA-T01	SPACER,RR.BUMPER SIDE	1	11.50 <i>new</i>	25	8.62	0.60	9.22
71598-TEA-T01	SPACER,RR.BUMPER SIDE	1	11.50 <i>new</i>	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.00 <i>new</i>	25	10.50	0.74	11.24
75722-TBA-A00	EMBLEM SET,RR.	1	11.50 ?	25	8.62	0.60	9.22
75725-TEA-T01	EMBLEM,RR.	1	10.60 ?	25	7.95	0.56	8.51
75701-TBA-A10	EMBLEM,H-MARK	1	11.90 ?	25	8.92	0.62	9.54
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10 <i>Rx</i>	25	354.07	24.78	378.85
74865-TEA-T01	WEATHERSTRIP,TRUNK LID	1	70.00 ?	25	52.50	3.68	56.18
74890-TEA-T11ZB	GARNISH ASSY,RR.LICENSE	1	97.70 ?	25	73.27	5.13	78.40
NMRS-4P	4 PCS REAR SENSOR	1	149.20 ?	10	134.28	9.40	143.68
74940-TR0-003	BUZZER ASSY,SMART	1	58.90 ?	25	44.17	3.09	47.26
66501-TEA-T00ZZ	STIFFENERRR.SHELF FR.	1	41.20 X	25	30.90	2.16	33.06
65550-TEA-T00ZZ	PAN COMP,SPARE TIRE	1	210.40 X	25	157.80	11.05	168.85
66100-TEC-307ZZ	PANEL SET,RR. <i>photo</i>	1	236.00 ?	25	177.00	12.39	189.39
Sum Item					1590.67	111.35	1,702.02



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702
Registration No : SME4866L
Chassis No : MRHFC5650JT001643
Model : CIVIC 1.6 VTI YM2018
Owner's Name : HAO YANLIANG
Ins Policy No. :
Date of Accident : 24/10/2018

Document No. : SQT18004566
Date : 24. Oct 2018
Customer No. : WZL009
Svc Advisor :
Engine No : R16B25501907
Date | Time : 24. Oct 2018 6:02:41 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1	100.00	30.	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL	1	100.00	X	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00	✓	280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00	✓	280.00	19.60	299.60
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA(N)	1	380.00	✓	380.00	26.60	406.60
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM(N)	1	380.00	✓	380.00	26.60	406.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00	560.	800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	560.	800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.	1	5000.00	2520	5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00	1575.	3000.00	210.00	3210.00
Sum Labor					11320.00	792.40	12,112.40

Survey By

Date & Time

Excess

Status

Signature

Taufik 97495789.
19/11/18 @ 1030
WP

Total Amount 12,910.67 903.75 13,814.42

Total (Inclusive of GST) 13,814.42

Signature: 
surp like auto room
6-7 days
* Resurvey before paint

Printed on 24/10/2018 6:17:16 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: