



Case Details

Case Reference Number : BUS/10/18/1034
Type of Repair : Accident Repair
Vehicle Registration Number : SG5743U

Company Type : SMRT Buses Ltd
Estimation ID : EST-4262-ID
Assigned By : Audrey Woo Yee Shin

Insurance Company Name : EQ Insurance Company Ltd
Accident Date and Time : 19/10/2018 04:30 PM
Vehicle Age(In Months) : 30

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
Standard	Main	VE	6010298	LAMP,STOP:LED (MAN BUS)	1	1,141.70	1,141.70	10.00	1,027.53	Replace	1	1,027.53	Replace ✓ CLK
Standard	Main	BODY LH	6010005	PANEL,SIDE:L11,FOR MAN A22 BUS	1	1,092.50	1,092.50	10.00	983.25	Replace	1	983.25	Replace ✓ CLK
Standard	Main	BODY LH	6010315	PANEL,FRAME SIDE:L11,FOR MAN A22 BUS	1	1,610.00	1,610.00	10.00	1,449.00	Replace	1	1,449.00	Replace ✓ Bt
Standard	Main	Body	6010060	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1	974.70	974.70	10.00	877.23	Replace	1	877.23	Replace ✓ CLK
Total Spare Part Cost									4,337.01		Surveyor Total	4,337.01	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									4,337.01		Final Sur Total	4,337.01	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	2,120.00	1,325	
Total:		2,120.00	1,325.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	528	
Total:		616.00	528.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	CHASSIS ALIGNMENT	200.00	0	NN
Total:		200.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,337.01	4,337.01
Total Labour Cost	2,120.00	1,325.00
Total Spray Painting	616.00	528.00
Other	200.00	0.00
Overall Total	7,273.01	6,190.01
Lump Sum Repair Option		
Lump Sum Total	0.00	6,190.01
Surveyor Approved Amount		6,190.01
No of Repair Days*	5	4
Remarks		PART BY PART REPAIR. 4 DAYS. BEFORE PAINT PHOTOS.
Surveyor Name		Naz
Signature		

Save

Clear

Survey Date

24/10/2018

NAZ LKK

NH

24/10/18

P/E

4 DAYS

BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: