

TP Lot Pac
Xico Tmng.

SG6880G.

Subaru Forester

JF1SJ6K8SF6052323

Rear Bumper	Distorted	763	✓
Rear Bumper Clips	per	30	✓
Rear Bumper Side Holder	x02	34xL=68	✓
Rear Bumper Reflector	x02	48x2=96	48
Rear Bumper Reinforcement	Bent	512	✓
Rear Bumper Top Garnish	cauled	330	✓
Reverse Sensor	changed	280(SN)	200(SN)
Rear End Panel	Repair	553	+
Rear End Panel Top Garnish	cauled	192	✓
Rear End Panel Sealant	new	60(SN)	x
Taillamp	x02	562xL=1124	562
Tailgate	Repair	1073	x
Tailgate Lock		280	+
Tailgate Weatherstripe		131	+
Tailgate Glass Moulding	HP	132	+
Tailgate Glass Sealant	per	60(SN)	+

SGG8806.

Subaru Logo	HPM	89	+
Subaru Wording.	}	36	✓
Forester Wording		42	✓
XT Wording.		27	✓
4WD Wording		22	✓

Rees Exhaust Pipe	Rept	792	+
Rees Exhaust Chrome Pipe Bent		129	80(SW)

Inst. 2632
 Less 20% 210560.
 SN : 280

Labour 1820
 Total: 40560
 H/S: 33K 04 Days.

3.3K

Panel Beating	1400	750
Spray Painting.	1100	850
Wiring.	50	30
To underseal	150	X

To remove reverse sensor	100	50
To remove upholstery.	150	40.
To transfer tailgate fittings	150	X
To remove tailgate g/s	180	X
To remove exhaust pipe.	150	X.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party - if any is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: