

Signature:

KSC

DOI:

ASSIGNMENT

24.10.18

Date / Time:

24-10-18

Registered in Meritmen:

26-10-18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLP9194C

Name of Insured:

Leo Thai (Huen Jueky)

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

20/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Banyan Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SHO 664



INSRS:

WSP:

Tel:

Liability:

RMKS:

r/cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call CR:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

S\$

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia.:

Repair Cost:

S\$

OI REPR. BOARD TP.

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(5

x

days)

Loss of Income (LOI):

S\$

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+ 550.

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2. (Strike if N.A.)

S\$

Name 2:

Payee 3. (Strike if N.A.)

S\$

Name 3:

COPY SENT  
31.1.19

ASSIGNMENT

From: Date: 24/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHD 664

at Workshop min: Transcab  
of: No-2 AMK St-63

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lump Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHD 664 Yr Regn: 03 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude C.C. 1995

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 289275 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF1ABL15AUC 282726

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: ————

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

R/Bal: 2 mm

L/Bal: 2 mm

D.O.A: 20/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/10 File pass to Carhome

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech Invs (\$)  
☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS: \$

Phone:

Others:

TOTAL:

Report Format :

Lump Sum / L.B.I: (\$)

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 66U****AAD1810-236***Not Notified  
Presumy B4 pain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHD 66U**

VF1ABL15AUC282726

RENAULT

LATITUDE

20.10.18

**ECICS****PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>nd/w</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	} X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	
5	1 BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	} X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>n</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>n</i> 225.95	X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>Bu</i> 1,471.77	✓
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56	X
15	1 TAILLAMP RH	\$	<i>Sn</i> 552.55	X
16	1 TAILLAMP PANEL RH	\$	<i>n</i> 986.70	X
17	1 TAILLAMP LH	\$	<i>Sn</i> 552.55	X
18	1 TAILLAMP PANEL LH	\$	<i>n</i> 986.70	X
19	1 BOOT REAR	\$	<i>Bu</i> 2,872.68	✓
20	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	X
21	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	X
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	X
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	X
24	1 BOOT BADGE 'RENAULT'	\$	<i>n</i> 225.36	✓
25	1 BOOT BADGE	\$	<i>n</i> 225.36	✓
26	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	X
27	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	X
28	1 BOOT HINGE LH	\$	<i>n</i> 367.84	X
29	1 BOOT HINGE RH	\$	<i>n</i> 367.84	X

**Trans-cab Auto Services Pte Ltd**

AAD1810-236

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 66U**

30	1 BOOT INNER TRIM	\$	586.45	X
31	1 BOOT SWITCH	\$	168.13	X
32	1 BOOT LOCK	\$	202.67	X
33	1 BOOT LOCK CATCH	\$	74.40	X

<b>TOTAL</b>	<b>\$</b>	<b>16,046.87</b>
<b>10%</b>	<b>\$</b>	<b>1,604.69</b>
	<b>\$</b>	<b>14,442.19</b>

**Special Nett**

1	1SET PARKING AID	\$	700.00	X
2	1SET REAR BUMPER CLIP	\$	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1 BOOT STICKER "Trans-cab"	\$	80.00	✓
11	1 BOOT STICKER "6555-3333"	\$	80.00	✓
12	1 EXHAUST MOUNTING REAR	\$	17.82	X
13	2 REAR WINDSCREEN SEALANT	\$	80.00	X
14	1 WINDSCREEN MOULDING	\$	100.00	X
15	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	X

<b>TOTAL</b>	<b>\$</b>	<b>1,404.82</b>
--------------	-----------	-----------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>15,847.01</b>
--------------------	-----------	------------------

**LABOUR**

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00

Panel Beating, Knocking And Straightening The  
Necessary Portion, Remove And Renewal Of Parts,  
Adjust And Realign The Same \$ 3,000.00

**Trans-cab Auto Services Pte Ltd****AAD1810-236**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 66U**

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>601</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>601</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>m</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>

**TOTAL** \$ 7,960.00**Over All Total** \$ 23,807.01**PART BY PART ( REPAIR DAY)****10 DAYS***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3581 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 26 Oct 2018

## Preliminary Advice

Insured Vehicle No	: SLR9194C	Accident Date	: 20/10/2018
TP Vehicle No	: SHD66U	Assignment Date	: 26/10/2018
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 5 days
Date of Inspection	: 24/10/2018		
Inspection At	: Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages ....rear... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,807.01
Revised Amount	:S\$	8,529.99
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,529.99

Lump Sum Repair :S\$

### Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ☒ Other comments : We have not authorized repairs.

## Asher Sng (LKKAUTO)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Friday, 28 December 2018 5:58 PM  
**To:** 'Crystabelle Tan Gek Peng (ECICS, Claims)'  
**Subject:** RE: ARRANGE FOR SURVEY SHD66U - Our Ref : DMPC1800405H/02/CT  
**Attachments:** PRIVATE SETTLEMENT AGREEMENT.pdf

'WITHOUT PREJUDICE'  
SAVE AS TO COSTS

Hi Crystabelle,

We refer to the above matter.

We were informed by TP workshop that insured have private settled with repairer without our survey fee.

In view of the above, We will proceed to submit our w/p report.

Thank You.

Best Regards,  
Asher Sng | Case Handler  
LKK Auto Consultants Pte Ltd  
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Crystabelle Tan Gek Peng (ECICS, Claims) <Crystabelle\_Tan@ecics.com.sg>  
Sent: Monday, 5 November 2018 5:06 PM  
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>  
Subject: FW: ARRANGE FOR SURVEY SHD66U - Our Ref : DMPC1800405H/02/CT

Dear Asher

Insured has private settled with Third party.

Please confirm with Third party in order for us to close case at our end.

Best regards,  
Crystabelle Tan  
Claims Division  
DID: +65 6303 0190  
FAX: +65 6338 9267  
Email: crystabelle\_tan@ecics.com.sg

ECICS Limited  
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

-----Original Message-----

From: Crystabelle Tan Gek Peng (ECICS, Claims)  
Sent: Monday, 5 November, 2018 10:38 AM  
To: 'Admin-D (LKKAuto)'  
Cc: Admin A; assignments  
Subject: RE: ARRANGE FOR SURVEY SHD66U - Our Ref : DMPC1800405H/02/CT

Dear Asher

Please assist this matter urgently as Insured would like to settle this case by today.

Best regards,  
Crystabelle Tan  
Claims Division  
DID: +65 6303 0190  
FAX: +65 6338 9267  
Email: crystabelle\_tan@ecics.com.sg

ECICS Limited  
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

-----Original Message-----

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
Sent: Monday, 5 November, 2018 10:22 AM  
To: Crystabelle Tan Gek Peng (ECICS, Claims)  
Cc: Admin A; assignments  
Subject: RE: ARRANGE FOR SURVEY SHD66U - Our Ref : DMPC1800405H/02/CT

Dear Crystabelle,

Thank you for your email.

Dear Asher,

FYNA. Our Ref: CC4/ICS18019496/Kea3

Best Regards,  
Catherine Chong | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,  
#02-25 | S(408933)

-----Original Message-----

From: Crystabelle Tan Gek Peng (ECICS, Claims) [mailto:Crystabelle\_Tan@ecics.com.sg]



Sent: Monday, 5 November, 2018 10:20 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: ARRANGE FOR SURVEY SHD66U - Our Ref : DMPC1800405H/02/CT

Dear G.Nivitha

Our Insured would like to have private settlement with Third Party.

Can the surveyor assist to further negotiate the cost of repair since this is a cash payment directly from Insured.

Best regards,

Crystabelle Tan

Claims Division

DID: +65 6303 0190

FAX: +65 6338 9267

Email: crystabelle\_tan@ecics.com.sg

ECICS Limited

10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

-----Original Message-----

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Wednesday, 24 October, 2018 11:31 AM

To: Crystabelle Tan Gek Peng (ECICS, Claims); assignments

Cc: Admin A

Subject: RE: ARRANGE FOR SURVEY SHD66U - Our Ref : DMPC1800405H/02/CT

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Crystabelle Tan Gek Peng (ECICS, Claims) [mailto:Crystabelle\_Tan@ecics.com.sg]

Sent: Tuesday, 23 October 2018 6:10 PM

To: assignments <assignments@lkkauto.com>

Subject: ARRANGE FOR SURVEY SHD66U - Our Ref : DMPC1800405H/02/CT

Dear LKK

Refer to below email and assist to arrange survey.

NOTE : Our insured has yet to file accident report.

Best regards,  
Crystabelle Tan  
Claims Division  
DID: +65 6303 0190  
FAX: +65 6338 9267  
Email: crystabelle\_tan@ecics.com.sg

ECICS Limited  
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

-----Original Message-----

From: Zhe Wei [mailto:zhewei.kek@transcab.com.sg]  
Sent: Tuesday, 23 October, 2018 10:34 AM  
To: ECICS Claims  
Cc: Candy Kong <candy.kong@transcab.com.sg>  
Subject: RE: ARRANGE FOR SURVEY SHD66U

Dear all ,

PLS ARRANGE LKK AUTO CONSULTANTS PTE LTD TO SURVEY.

Please arrange for survey as below :

SLR9194C - 20.10.2018 at 1230Hrs - SHD66U

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Kindly quote our reference in your future replies to us.

Best Regards,  
Kek Zhewei  
Claims Officer

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

[ECICS Facebook] [ECICS Twitter] [ECICS Limited]

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone.

In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

---  
This email has been checked for viruses by AVG.  
<https://www.avg.com>

**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666 Fax: 6366 8862

GST Reg No. : 201019626G

Co. Reg No. : 201019626G

**MUTUAL SETTLEMENT**

TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63

We, Singapore 569111 (Owner/Driver) and Leo Thai Chuan, Jacky

(Owner/Driver) hereby agreed to settle mutually among ourselves in regards to an


accident involving SNO 664 and SLR 9194C along  
Balestier Road on 20.10.18 at 0030 hrs.

We have further agreed to settle this matter amicably as follows: \* delete "a" or "b" as applicable.

\*a. Neither party shall be liable to compensate the other party for any loss, damages or injury either directly or indirectly incurred or to be incurred as a result of the accident.

\*b. Without any admission of liability, Leo Thai Chuan, Jacky (party paying compensation) has paid a sum of S\$ 9645.10 which Transcab Services Pte Ltd (owner receiving compensation) hereby acknowledges receipt thereof in full and final settlement of all damages (ie. property damage, loss of use, rental expenses, bodily injury) and costs incurred and/or to be incurred as a result of the accident.

Dated in Singapore on 5 day of Nov 2018.

  
(Signature)

TRANS-CAB SERVICES PTE LTD


Name No. 2 Ang Mo Kio Street 63NRIC No. : Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

Address: \_\_\_\_\_

Vehicle no. : \_\_\_\_\_

Contact no. : \_\_\_\_\_

  
(Signature)

Name : Leo Thai Chuan, JackyNRIC No. : S 7838189BAddress: B165 G Hujung b+32

# 07-11 S(534039)

Vehicle no. : SLR 9194CContact no. : 8163 9255

TRANS-CAB AUTO SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

**OFFICIAL RECEIPT**

No.: 257-18

Date: 05 NOV 2018

茲收到

Received from SHD 664 & SLR 9194C Third party paid

支付大銀

the sum of Dollars \$ 9645.10

系还

in payment of \_\_\_\_\_

\$ 9645.10

Cash / Cheque No.:

**YVONNE**

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jan 2019 09:42 <a href="#">Edit Reg</a>		24 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$8,529.99</b> <a href="#">Edit Estimates</a>	<b>S\$8,529.99</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>TEO THAI CHUAN JACKY</b> , ID: 578381898, Email: www.abcd@com.sg									
Main Claimant: <b>TRANS-CAB SERVICES PTE LTD</b> , Co. Reg. No.: 200303878K									
Vehicle Reg. No.: <b>SHD66U</b>		Date of Loss: 20/10/2018 00:00 - :59 <b>[30 Months and 28 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>TP / DMPC1800405H/CT</b>		Policy/Cover Note No.: <b>MPC18A00287700</b>							
Vehicle Reg. No. (Insured): <b>SLR9194C</b>		Policy No. (Claimant): <b>VPX/P1680520</b>							
		Excess:							
Repairer: <b>Trans-cab Auto Services Pte Ltd ( )</b> No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:									
Handling Insurer: <b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178 ... [Handled by <b>Crystabelle Tan</b> - 6303 0190]									
Claimant's Insurer: <b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 07/11/2018]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SHD66U (DMPC1800405H/CT)  
[SLR9194C]  
TP  
TRANS-CAB SERVICES PTE LTD  
Oct 20 2018 12:00AM  
[TEO THAI CHUAN JACKY]  
Trans-cab Auto Services Pte Ltd

[Upload Documents](#) | 
 [Upload Photos](#) | 
 [Compose New Letter](#)

**View** [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/10/18 11:26	Adjuster Immediate Advice		Load HTML	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
2	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
3	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
4	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
5	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
6	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
7	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
8	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
9	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
10	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
11	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
12	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
13	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
14	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
15	05/11/18 16:44	General View		Load JPG	<input checked="" type="checkbox"/>
16	05/11/18 16:44	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
17	05/11/18 16:44	Chassis Number		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/10/18 11:23	TP ESTIMATE + TP GIA REPORT		Load PDF	
2	26/10/18 11:23	ACKNOWLEDGEMENT EMAIL TO ICS DD 24.10.2018		Load PDF	
3	27/10/18 22:42	TP ESTIMATE-MARKED		Load PDF	
No	Finalized On	ECICS Limited (HQ)		Thumbnail	Print
1	05/11/18 10:20	Singapore Accident Statement		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/ICS18019496/KEA3Q2

Date: 18/01/2019

## REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC18A00287700

Claimant Vehicle No : SHD66U Insured Vehicle No : SLR9194C

Date of Loss: 20/10/2018 Nature of Claim: TP Claim No: DMPC1800405H/CT

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SHD66U**  
 Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C003033  
 Reg. Date: 22/03/2016 (Man. Year: 2015) Chassis No: VF1ABL15AUC282726  
 Colour: White Odometer: 289275 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Giti 8 mm Rear Left Side: Giti 7 mm  
 Front Right Side: Giti 8 mm Rear Right Side: Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,846.99	7,029.99	8,817.00	55.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,960.00	1,500.00	6,460.00	81.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>23,806.99</b>	<b>8,529.99</b>	<b>15,277.00</b>	<b>64.17</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,666.49</b>	<b>597.10</b>	<b>1,069.39</b>	<b>64.17</b>
<b>Nett Amount (S\$)</b>	<b>25,473.48</b>	<b>9,127.09</b>	<b>16,346.39</b>	<b>64.17</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

Date of Assignment: 24/10/2018

Date Inspected: 24/10/2018 Inspected At:

Trans-cab Auto Services Pte Ltd  
No 2 Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2019)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD66U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
18	1		*TAILLAMP PANL LH	Repair	986.70 FL	*- FL
19	1		*BOOT REAR	Buckled	2,872.68 FL	*2,872.68 FL
20	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
24	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
25	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
26	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
28	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
29	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
30	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
31	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
32	1		*BOOT LOCK	Repair	202.67 FL	*- FL
33	1		*BOOT LOCK CATCH	Serviceable	74.40 FL	*- FL
34	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
35	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
36	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
39	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
41	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
42	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
43	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*80.00 FS
44	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	*80.00 FS
45	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
46	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
47	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
48	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,451.68	7,774.99
- List Item Discount on L Items 10.00/10.00% (S\$)	1,804.69	745.00
Total Parts (S\$)	15,846.99	7,029.99

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	660.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	600.00
3	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
7	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
8	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
9	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
10	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
11	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
12	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>7,960.00</b>	<b>1,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >