

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 66U**AAD1810-236***Not Authored
Resurvey By paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 66U

VF1ABL15AUC282726

RENAULT

LATITUDE

20.10.18

ECICS**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>nd/w</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47	} X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	
5	1 BUMPER RETAINER RH REAR	\$	<i>SL</i> 44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	
8	1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99	}
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>Bu</i> 1,471.77	✓
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i> 404.56	X
15	1 TAILLAMP RH	\$	<i>SL</i> 552.55	X
16	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	X
17	1 TAILLAMP LH	\$	<i>SL</i> 552.55	X
18	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	X
19	1 BOOT REAR	\$	<i>Bu</i> 2,872.68	✓
20	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
21	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	X
22	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	X
23	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	X
24	1 BOOT BADGE 'RENAULT'	\$	<i>SL</i> 225.36	✓
25	1 BOOT BADGE	\$	<i>SL</i> 225.36	✓
26	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	X
27	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	X
28	1 BOOT HINGE LH	\$	<i>R</i> 367.84	X
29	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X

Trans-cab Auto Services Pte Ltd**AAD1810-236**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 66U

30	1 BOOT INNER TRIM	\$	586.45	X
31	1 BOOT SWITCH	\$	168.13	X
32	1 BOOT LOCK	\$	202.67	X
33	1 BOOT LOCK CATCH	\$	74.40	X

TOTAL	\$	16,046.87
10%	\$	1,604.69
	\$	14,442.19

Special Nett

1	1SET PARKING AID	\$	700.00	X
2	1SET REAR BUMPER CLIP	\$	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1 BOOT STICKER "Trans-cab"	\$	80.00	✓
11	1 BOOT STICKER "6555-3333"	\$	80.00	✓
12	1 EXHAUST MOUNTING REAR	\$	17.82	X
13	2 REAR WINDSCREEN SEALANT	\$	80.00	X
14	1 WINDSCREEN MOULDING	\$	100.00	X
15	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	X

TOTAL	\$	1,404.82
--------------	-----------	-----------------

TOTAL PARTS	\$	15,847.01
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same \$ 3,000.00

Trans-cab Auto Services Pte Ltd

AAD1810-236

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 66U

To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 601
To Rust-Proofing Of The Affected Areas.	\$	170.00 601
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 601
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
TOTAL	\$	7,960.00
Over All Total	\$	23,807.01

PART BY PART (REPAIR DAY)~~10 DAYS~~

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: