

ASS. REC. BY:

REF: CS/FCT18019497/Klsd3

Special Instruction: n2

Surveyor:
CWS

ASSIGNMENT (Office)

From (Person): Luene jaw

of FCT

Date/Time: 11:20am @ 26/10/18

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 1625A

Insured: SHC 7816G

at Workshop n/s: Premier Automotive

Tel: 65446689

of 23 Changi South Ave 2 # 01-02

Policy No:

Claim No: D18007725MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 24/10/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 11:30am @ 26/10/18

Person Contacted: Vincent

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 1625A - NA / AIG 16006962 / Y DoA: 12/04/2016
	SHC 7816G - X
30/10/18	@ 16:46 p.m. revised PA to Luene Jaw via email.

08/11/03
 Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHD1625A Yr Regn: 28 Sep 2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai 2.30 c.c. 1582
 Colour: Silver A/C: Ins / Std / NI / NA
 Sp. Reading: 163455 T/Radio: Ins / Std / NI / NA
 Eng/No: _____
 C/No: TM AD2814VHJ12521
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Maxxis
 Front: _____ Rear: _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 24/10/8 D.O.I. 29/10/8
 Survey held at Premise
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>7/11/8</u>	<u>Quoted L/S \$1700 / 3 days. FC2</u>
<u>07/11/8</u>	<u>Confirmed L/S \$ 1,700/- @ 3 days with Kalvin. (L \$ 2,517.01 Red 60%)</u>
RECEIVED 07 NOV 2018	

Date/Time, File Pass to? : Preli. Report

1) 7/11/8 : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	<u>135</u>
Transportation:	<u>50</u>
_____ S + RS, _____ SI	<u>50</u>
Photos	<u>30</u>
Others	
TOTAL	<u>265</u>

Report Format: _____

Lump Sum / I.B.I. (\$ 1,700/- HS)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007725MFSH

Date: 30 October 2018

Our Ref: CS/FCI18019497/K1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 1625A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/10/2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>SS 4,217.01</u> .
Revised Estimate Amount	: <u>SS 2,170.74</u> .
"Check" Items Amount	: <u>SS</u> .
Market Value	: <u>SS</u> .
LTA Reimbursement Value	: <u>SS</u> .
Nett Value	: <u>SS</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Kalvin Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date 25-10-2018 Our Ref No. D18007725MFSH
Accident Date 24-10-2018 Claim Type. Third Party
Insured Vehicle SHC7816G Third Party Vehicle. SHD1625A
Survey Location 23 CHANGI SOUTH AVENUE 2, #01-02
Contact Person. VINCENT CHUA
Contact No. 65446689/ 0 Fax No. 0
Survey Type WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:
Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD
Contact Person NA Fax No. 68416315
Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop PREMIER AUTOMOTIVE SERVICES PTE LTD Attention. NIL
Cc : TP Solicitor NA TP Solicitor Fax No. NA
Officer Incharge LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 30 October 2018 4:46 PM
To: 'Lurene Jaw'; 'CWS Motor Claims'
Cc: Admin-D (LKKAuto); SUR; assignments
Subject: RE: SURVEY ASSESSMENT - D18007725MFSH/1
Attachments: SHD 1625A - Preli Advise.pdf

Dear Lurene,

Enclosed preliminary revised of vehicle SHD 1625A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 26 October 2018 11:22 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007725MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 26 October 2018 11:11 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007725MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1625A
 Previous Vehicle No.: -
 Effective Date of Ownership: 28 Sep 2016
 Original Regn Date: 28 Sep 2016
 Registration Date: 28 Sep 2016
 Year of Manufacture: 2016
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ121521
 Engine No.: D4FBGZ105474
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$20,131.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 27 Sep 2024
 Minimum PARF Benefit: \$7,610.00
 No. of Transfers: 0
 IU Label No.: 1050681098
 COE No.: 2016092801004226K
 COE Expiry Date: 27 Sep 2024
 COE Category: A - Car (up to 1600cc & 97kW (130bhp))
 COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))
 Quota Premium (QP) / Prevailing Quota Premium: - / \$53,339.00
 PQP Paid: \$42,672.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

29-Oct-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1625 A

1 pc	Tailgate lower garnish	— <i>nc</i>	\$	362.61
1 pc	Emblem I30	— <i>nc</i>	\$	27.80
1 pc	Emblem CRDI	— <i>nc</i>	\$	29.40
1 pc	Emblem Hyundai	X <i>on photo</i>	\$	29.40
1 pc	Rear bumper	— <i>nc</i>	\$	811.11
1 pc	Rear bumper sponge	X <i>see</i>	\$	79.20
1 pc	Rear bumper reinforcement	X <i>see</i>	\$	815.64
1 pc	Rear bumper reinforcement centre	X <i>see</i>	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	X <i>see</i>	\$	104.40
			\$	<u>2,338.76</u>
			Less 20%	\$ 467.75
			\$	<u>1,871.01</u>

S/NETT

1 set	Rear bumper clips	— <i>nc</i>	\$	48.00	
1 set	Reverse sensor	— <i>shut</i>	\$	280.00 <i>200</i>	
1 set	Tailgate stickers	— <i>nc</i>	\$	100.00	
1 set	Tailgate lower garnish clips	— <i>nc</i>	\$	38.00	
Sundry				\$	50.00 <i>20 nec</i>
To dismantle and replace reverse sensor and test system				\$	80.00 <i>20</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs				\$	180.00 <i>X 11</i>
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, etc				\$	850.00 <i>400</i>
To putty and spray painting on the rear bumper, tailgate lower garnish, end panel				\$	600.00 <i>360</i>
To apply rustproofing on the repaired and replaced panels				\$	120.00 <i>X 11</i>
Total			\$	<u>4,217.01</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any repair work
- To display damaged parts during resurvey
- Parts prices are subject to market fluctuations
- No insurance claim to be made on the basis of third party insurance
- No insurance claim to be made on the basis of own insurance policy

Signature: _____
Date: _____

Katrina
29/10/18 1045L
3 days
Edue P/P photo



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18019497/K1sd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-11-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7816G	Veh. Inspected	SHD 1625A
Policy No.		Coverage (\$)	0.00
Claim No.	D18007725MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	26/10/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I30	c.c	1582
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	TMAD281UVHJ121521	Colour	SILVER
Odometer	163455	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXXIS	7 mm
L/H Front Tyre	195/65 R15	MAXXIS	7 mm
R/H Rear Tyre	195/65 R15	MAXXIS	7 mm
L/H Rear Tyre	195/65 R15	MAXXIS	7 mm

4. Description of Damages

<p>THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.</p>
--

5. General Information

Accident Date	24/10/2018	Inspection Date	29/10/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1625A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE LOWER GARNISH	CRACKED	362.61	362.61
1	EMBLEM I30	NECESSARY	27.80	27.80
1	EMBLEM CRDI	NECESSARY	29.40	29.40
1	EMBLEM HYUNDAI	NOT NECESSARY	29.40	-
1	REAR BUMPER	DEFORMED	811.11	811.11
1	REAR BUMPER SPONGE	SERVICEABLE	79.20	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	815.64	-
1	REAR BUMPER REINFORCEMENT CENTRE	SERVICEABLE	79.20	-
2	REAR BUMPER N/S & O/S SIDE BRACKET @\$52.20 LESS 20% DISCOUNT	SERVICEABLE	104.40 -467.75	- -246.18
			1,871.01	984.74
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET TAILGATE STICKERS (SN)	NECESSARY	100.00	100.00
1	SET TAILGATE LOWER GARNISH CLIPS (SN)	NECESSARY	38.00	38.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			516.00	406.00
LABOUR				
TO DISMANTLE AND REPLACE REVERSE SENSOR AND TEST SYSTEM.			80.00	20.00
TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		NOT NECESSARY	180.00	-
TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING TO KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE OF THE END PANEL, ETC.			850.00	400.00
TO PUTTY AND SPRAY PAINTING ON THE REAR BUMPER, TAILGATE LOWER GARNISH, END PANEL.			600.00	360.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,830.00	780.00
GRAND TOTAL			4,217.01	2,170.74

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00
---	--	--	--	-----------------

Report Ref No. CS/FCI18019497/K1sd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.