

ASS. REC. BY:

REF:

CS/FCI18019499/R/cd3ⁿ²

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

CWS

From (Person):

Karen Tan

of

FCI

Date/Time:

25/10/18 @ 5:54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SKH 8417G

Insured:

SHA 41264

at Workshop m/s:

Cycle 7 Cernage Ind.

Tel:

83320062

of

188 prinden loop

Policy No.:

Claim No.:

D18007716MFCH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/10/2018

CA / REV / REP. / REV 24 HRS 'Ds'

H.O.D. Endorsement:

Date/Time:

9:22am @ 26/10/18

Person Contacted:

Vincent

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SKH 8417G-X

SHA 41264-X

26/10/18-


VNI yet (vincent)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKH 84176
 at Workshop m/s CBC
 of 188, Lennon Way
 Insured: FCI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS O/S

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKH 84176 Yr Regn: 2013 / Jan
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mercedes Benz C180 c.c. 1595
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp. Reading: 85423 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD 204 031 2A 808 660
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/35R19
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 23/10/18 D.O.I. 30/10/18
 Survey held at CBC CPL
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
rear o/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Final big 23,659.19 (Red 2153.02, 372)</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: 50

S + RS _____ SI

Photos

Others

TOTAL

Report Format : TP
 Lump Sum / I.B.I. (\$) 23,659.19

140
50
19
209

Your Ref: D18007716MFSHDate: 2 November 2018Our Ref: CS/FCI18019499/R1rd3The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKH 8417G

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/10/2018 at the premises of M/s CYCLE & CARRIAGE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 5,812.21 .
Revised Estimate Amount	: S\$ 3,659.19 .
"Check" Items Amount	: S\$ 1,553.20 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the rear o/s portion.



Yours faithfully

RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	24-10-2018	Our Ref No. D18007716MFSH
Accident Date	23-10-2018	Claim Type. Third Party
Insured Vehicle	SHA4126U	Third Party Vehicle. SKH8417G
Survey Location	PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP	
Contact Person.	ALAN QUEK	
Contact No.	67714377/ 91865112	Fax No. 68721272
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE INDUSTRIES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Wednesday, November 07, 2018 3:59 PM
To: 'CWS Motor Claims'
Cc: 'Karen Tan'
Subject: RE: SURVEY ASSESSMENT - D18007716MFSH/1
Attachments: SKH 8417G.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for SKH 8417G.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, October 26, 2018 11:31 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007716MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 25 October 2018 5:54 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007716MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8188A
Vehicle Details	
Vehicle No.:	SKH8417G
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 BLUEEFFICIENCY
Primary Colour:	Black
Manufacturing Year:	2012
Engine No.:	27491030030226
Chassis No.:	WDD2040312A808160
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$31,873.00
Original Registration Date:	23 Jan 2013
First Registration Date:	23 Jan 2013
Transfer Count:	1
Actual ARF Paid:	\$26,873.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jan 2023
PARF Rebate Amount:	\$18,811.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$92,100.00
COE Rebate Amount:	\$37,384.00
Total Rebate Amount:	\$56,195.00

The information contained herein is correct as at 31 Dec 2018

OK



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKH8417G

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 27812
Reg No/Reg Date SKH8417G / 23/01/2013
Date In/Mileage / 0
Chassis No WDD2040312A808160
Engine No 27491030030226
Make/Model MB/C 180 CGI BlueEFFICIENCY
Colour/Trim 021 183 Magnetite B/ 042 221 Leather B1

Account No	Terms	Date/Time Printed	CSE	Operator				
WF001862	Credit	23/10/2018/ 13:12	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M BPN SUN POLICY NO/ACC DATE : S28988279 // 23-10-2018 DRIVE IN: 23-10-2018 // TP CAR NO: SHA4126U (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT							0.10	380.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.								960 1440.00
A BPIRES RESPRAY REAR BUMPER								600 220.00
S BPN SUB SUPPLY & INSTALL 1 SET OF REVERSE SENSORS.NETT								NN 680.00
M REAR BUMPER					1.00	1509.93	00.00	DE 1509.93
M RH/R BUMPER SIDE BRACKET					1.00	36.21	00.00	NN 36.21
M REAR BOTTOM PANEL					1.00	173.05	00.00	NN 173.05
M REAR CROSS MEMBER					1.00	670.31	00.00	NN 670.31
M CT/R BASIC MOUNTING FOR BUMPER					1.00	135.13	00.00	NN 135.13
M RH/R BASIC MOUNTING FOR BUMPER					1.00	67.58	00.00	NN 67.58

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4311 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Rasul
Hp 90010068
3 days

8/11/18

30/10/18 @ 1540

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

Nett 5,812.21
7% GST on 5812.21 406.85
Total Payable 6,219.06

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Finalization

ESTIMATE FOR SKH8417G

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-850011-X

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Rasul

Vehicle & Document Information
WIP No 27812
Reg No/Reg Date SKH8417G / 23/01/2013
Date In/Mileage 30/10/2018 / 89423
Chassis No S WDD2040312A808160 7G
Engine No 27491030030226
Make/Model MB/C 180 CGI BlueEFFICIENCY
Colour/Trim 021 183 Magnetite B/ 042 221 Leather 81

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	27/12/2018/ 13:45	AQ	305 / Alan Quek A1 Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : S28988279 // 23-10-2018 DRIVE IN-23-10-2018 // TP CAR NO: SHA4126U (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: 30-10-2018 // LKK RASUL BY/AUTHORIZED ON : KARENT // 25-10-2018				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				960.00
A BPIRES RESPRAY REAR BUMPER				600.00
X REAR BUMPER	1.00	1509.93	00.00	1509.93
X RH/R BUMPER SIDE BRACKET	1.00	36.21	00.00	36.21
X REAR BOTTOM PANEL	1.00	173.05	00.00	173.05

OFFICIAL TAX INVOICE
3 Days
ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 3,659.19
7% GST on 3659.19 256.14

Authorized signatory and company stamp

Total Payable 3,915.33

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18019499/R1cd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-01-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4126U	Veh. Inspected	SKH 8417G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007716MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	25/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD2040312A808160	Colour	BLACK	
Odometer	89423	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/35 R19	GOODYEAR	6 mm	
L/H Front Tyre	235/35 R19	GOODYEAR	6 mm	
R/H Rear Tyre	235/35 R19	GOODYEAR	6 mm	
L/H Rear Tyre	235/35 R19	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/10/2018	Inspection Date	30/10/2018	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 8417G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	1,509.93	1,509.93
1	RH/R BUMPER SIDE BRACKET (SN)	NECESSARY	36.21	36.21
1	REAR BOTTOM PANEL (SN)	SCRATCHED	173.05	173.05
1	REAR CROSS MEMBER (SN)	NOT NECESSARY	670.31	-
1	CT/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	135.13	-
1	RH/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	67.58	-
1	SET OF REVERSE SENSORS (SN)	NOT NECESSARY	680.00	-
			3,272.21	1,719.19
LABOUR				
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.		1,440.00	960.00
	RESPRAY REAR BUMPER.		720.00	600.00
			2,540.00	1,940.00
GRAND TOTAL			5,812.21	3,659.19
RECOMMENDED COST OF REPAIRS				3,659.19

Report Ref No. CS/FCI18019499/R1cd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.