



## PDI TUAS

PDI TUAS

V L TEST SYSTEMS (FAR EAST)  
PTE LTD  
2 BUKIT MERAH CENTRAL  
#21-01  
Singapore, 159835  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV039906  
Quote No. SER/QUO/1801776  
QuoteDate 24/10/18  
Salesperson TIMOTY TEO  
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make                 | Model Description             | Mileage              | Service Advisor |
|----------------------|-------------------------------|----------------------|-----------------|
| Light Commercial Veh | CADDY 4 MAXI VAN TDI 75(A)WGD | 9,444                | Tang Shu Shi    |
| License No.          | VIN                           | Initial Registration | Sales Advisor   |
| GBA8289C             | WV1ZZZ2KZHX164475             | 31/01/18             | TIMOTY TEO      |
| Engine Code          | Labor Type                    | Engine No.           | Model Code      |
|                      | 69                            | DFS 221284           | SAHA26          |

| No.               | Description                   | Qty. | UoM     | Unit Price | Amount                   |
|-------------------|-------------------------------|------|---------|------------|--------------------------|
| P B&P MACP LABOUR | LABOUR                        | 6    | UNIT    |            | <del>1680</del> 5,040.00 |
| P B&P MACP PAINT  | SPRAY PAINT                   | 5    | UNIT    |            | <del>800</del> 4,000.00  |
| P B&P DIAG        | PROGRAMMING & CALIBRATION     | 1    | Time Un |            | 480.00                   |
| P B&P MECH        | ELECTRICAL CHECK OR MECHA     | 1    | Time Un |            | 280.00                   |
|                   | <b>Sum Labor</b>              |      |         |            | <b>9,800.00</b>          |
| P 2K2945096AB     | RHR TAILLIGHT <i>car</i>      | 1    | Pieces  |            | <del>1680</del> 198.45   |
| P 2K3809604E      | RHR FENDER <i>repair</i>      | 1    | Pieces  |            | 2,994.29                 |
| P 2K5807393A      | LHR BUMPER BRACKET <i>X</i>   | 1    | Pieces  |            | 34.11                    |
| P 2K5807394A      | RHR BUMPER BRACKET <i>X</i>   | 1    | Pieces  |            | 34.11                    |
| P 2K5807417C 9B9  | REAR BUMPER <i>sc</i>         | 1    | Pieces  |            | 601.27                   |
| P 2K6857508T 9B9  | RH WING HOUSING <i>?</i>      | 1    | Pieces  |            | 295.49                   |
| P 2K6857522B      | RH WING MIRROR GLASS <i>?</i> | 1    | Pieces  |            | 238.38                   |
| P 7E2857528 9B9   | RH WING MIRROR COVER <i>?</i> | 1    | Pieces  |            | 47.08                    |
| P D 007600A1      | INOXSPRAY <i>X</i>            | 1    | Pieces  |            | 68.36                    |
| P D 180003M2      | 2KADHESIV <i>X</i>            | 1    | Pieces  |            | 286.20                   |
| P D 476KD1M2      | SEALANT <i>X</i>              | 1    | Pieces  |            | 77.38                    |
| P D 506KD1A3      | 2K FOAM <i>X</i>              | 1    | Pieces  |            | 157.96                   |
|                   | <b>Sum Item</b>               |      |         |            | <b>5,033.08</b>          |

Payments to:

- BBN: - Acc.-No.:



PDI TUAS

PDI TUAS

V L TEST SYSTEMS (FAR EAST)  
PTE LTD  
2 BUKIT MERAH CENTRAL  
#21-01  
Singapore, 159835  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV039906  
Quote No. SER/QUO/1801776  
QuoteDate 24/10/18  
Salesperson TIMOTY TEO  
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make                 | Model Description             | Mileage              | Service Advisor |
|----------------------|-------------------------------|----------------------|-----------------|
| Light Commercial Veh | CADDY 4 MAXI VAN TDI 75(A)WGD | 9,444                | Tang Shu Shi    |
| License No.          | VIN                           | Initial Registration | Sales Advisor   |
| GBA8289C             | WV1ZZZ2KZHX164475             | 31/01/18             | TIMOTY TEO      |
| Engine Code          | Labor Type                    | Engine No.           | Model Code      |
|                      | 69                            | DFS 221284           | SAHA26          |

|                     |           |
|---------------------|-----------|
| Sum Labor           | 9,800.00  |
| Sum Item            | 5,033.08  |
| Total SGD           | 14,833.08 |
| 7% GST              | 1,038.32  |
| Total SGD Incl. GST | 15,871.40 |

### Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Rasm*  
*HP 90010068*  
*4 days*  
*29/10/18 @ 1545*  
*Rey by paint*