

ASS. REC. BY:

REF: CS/CT118019505/ R1+d3⁵²

Special Instruction:

Surveyor:

Paul

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CT1

Date/Time: 26/10/18 @ 11:51am

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGU 6841G

Insured:

SGF 6064L

at Workshop m/s

cycle & Carriage Industries

Tel:

9186 5113

of

188 pandan loop

Policy No:

DMPCSN1622581802

Claim No:

8NM18D05075C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 24/10/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time: 12:04pm @ 26/10/18

Person Contacted:

Kerylyn

Vehicle IN

☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SGU 6841G - X
	SGF 6064L - NA / RS114012759 / e1
26/10/18	called kerylyn vni yet.
	Part by Part \$747.73, 3days (Red: 1110.30, 13%)

Surveys: Pam

REF:

5173H

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGU 68416at Workshop m/s: Cycle & carriageof 188, Pandan LoopInsured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGU 68416 Yr Regn: 2011 / DECType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MERCEDES Benz E 300 c.c. 2996Colour: Gold A/C: Insured / Std / NI / NASp. Reading: 92007 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2120542A 501710Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40R18R: 245/40R18BS / DUN / EXNOVA / GV / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____


Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 24/10/18 D.O.I. 27/11/18Survey held at C&C (PL)Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S FAT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

RECEIVED 28 DEC 2018



28/12/2018

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report

Date/Time, File Return to?

2)

Report Format : TPLump Sum / I.B.I. (\$) 7347.73Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 220

Transportation: _____

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Oct 2018		26 Oct 2018 11:51 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S YOMA STRATEGIC HOLDINGS LTD, Co. Reg. No.: 196200185E		
Main Claimant:	VAGHESE EDAPPARA PAPACHAN		
Vehicle Reg. No.:	SGU6841G	Date of Loss:	24/10/2018 13:00 - :59
Claim Type:	TP / SNM18D05075C02	Policy/Cover Note No.:	DMPCSN1622581802 (Comprehensive)
Vehicle Reg. No. (Insured):	SGF6064L	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairee:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/11/2018]		
Adj Asg. Remarks:	EST \$8569.60 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Kerlyn Ong <kerlyn.ong@cyclecarriage.com.sg>
Sent: Thursday, 25 October, 2018 4:54 PM
To: Claims Dept of CTI
Subject: Accident involving motor vehicle nos. SGU6841G & SGF6064L along 78 SHENTON WAY AIG BUILDING MSCP, Accident date: 24/10/2018
Attachments: img-X25164110-0001.pdf

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number SGU6841G), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number SGF6064L) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at kerlyn.ong@cyclecarriage.com.sg.

Your Sincerely,

Kerlyn Ong
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 91865113 | DID: 67714420 | Fax: 68721272
Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2018 15:21
Date Of Accident	24/10/2018 16:30
Exact Location Of Accident	78 SHENTON WAY AIG BUILDING MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGU6841G
Insured/Policyholder	
Name Of Registered Owner	VARGHESE EDAPPARA PAPACHAN
NRIC No	S6985173H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93837600
Alternative Phone No	OFFICE-93837600

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E300
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100281493-06
Cover Note Number	

Driver

Name of Driver	VARGHESE EDAPPARA PAPACHAN
NRIC No	S6985173H
Date Of Birth	10/05/1969
Occupation	INDOOR
Date Of Driving Pass	16/08/2003
Driving Experience	15 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93837600
Fax Number	
Contact Number	OFFICE-93837600
EMail Address	NOEMAIL

Address

60 TANAH MERAH KECHIL AVENUE #06-17 S 465529

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

-

-

-

Insurance Company of Driver's Own Vehicle

-

-

-

General Information of the Accident

Type Of Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGF6064L

Vehicle Make/Model/Colour

Details Of Properties JOYCELYN

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number 98182379

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time 25/10/2018 1423

Driver's Signature

(If driver is not the policyholder)

Date & Time

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarrriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop
Reporting Centre Personnel's
Name: KERLYN
NRIC/FIN No.:

SKETCH PLAN

A: SGU6841G

B: SGF6064L



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I PARKED MY CAR (SGU6841G) AT 78 SHENTON WAY AIG BUILDING MSCP. I HAD RECEIVED A CALL FROM THE MANAGEMENT OFFICE THAT VEHICLE B (SGF6064L) HAD COLLIDED ONTO MY CAR WHILE MAKING A LEFT TURN OUT FROM THE PARKING LOT, THE OWNER OF THE VEHICLE HAD WAITED FOR ME.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Policyholder's Signature

Date & Time 25/10/2018 1423

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's

Name: KERLYN

NRIC/FIN No.:



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGU6841G

Varghese Edappara Papachan

60 Tanah Merah Kechil Avenue
#06-17
Singapore 465529

Mobile: 93837600

Vehicle & Document Information

WIP No **27863**
Reg No/Reg Date **SGU6841G / 05/12/2011**
Date In/Mileage **/ 0**
Chassis No **WDD2120542A501790**
Engine No **27295231942270**
Make/Model **MB/E 300 SEDAN (W212)**
Colour/Trim **027 794 Pearl Beige/ 042 205 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	25/10/2018/ 15:01	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : 2100281493-06 // 24/10/2018				
DRIVE IN/EXCESS : 25/10/2018 //				
DATE IN/DATE SURVEY:				
BY/AUTHORIZED ON :				
A BPILAB				
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				
A BPIRES				
RESPRAY FRONT BUMPER				
A BPILAB				
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	
A BPILAB				
TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT				
M RH/ HEADLAMP	1.00	2622.51	00.00	2622.51
M FRONT BUMPER	1.00	1515.62	00.00	1515.62
M RH/ FRONT BUMPER RAIL	1.00	13.64	00.00	13.64
M RH/ FOG LAMP ORNAMENTAL MOULDING	1.00	128.33	00.00	128.33
M RH/ TOP BASIC MOUNTING	1.00	68.15	00.00	68.15
M PARKING SENDER UNIT	1.00	273.79	00.00	273.79
M PARKTRONIC SENSOR SPACER RING	1.00	6.93	00.00	6.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by
Acknowledged by Repairer
Signature:
Date:

Authorized signatory and company stamp

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

7% GST on **8008.97** **560.63**

Total Payable 8,569.60

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGU6841G

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 27863
Reg No/Reg Date SGU6841G / 05/12/2011
Date In/Mileage 27/11/2018 / 89464
Chassis No WDD2120542A501790
Engine No 27295231942270
Make/Model MB/E 300 SEDAN (W212)
Colour/Trim 027 794 Pearl Beige/ 042 205 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	30/11/2018/ 09:03	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST

Customer Request

M BPN50N

POLICY NO/ACC DATE : 2100281493-06 // 24/10/2018
DRIVE IN/EXCESS : 25/10/2018 // SGF6064L - CHINA
DATE IN/DATE SURVEY: 27/11/2018 1030 // LKK - RASUL
DIRECT SETTLEMENT : 01/11/2018 // CHINA - BOON SEN

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY FRONT BUMPER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

TO REMOVE, REPLACE HEADLAMP WITH FOCUS NETT

X RH/ HEADLAMP UNIT

1.00 3316.12 00.00 3316.12

X FRONT BUMPER

1.00 1515.62 00.00 1515.62

X PARKTRONIC SENSOR SPACER RING

1.00 6.93 00.00 6.93

X FRONT BUMPER COVERING

1.00 61.95 00.00 61.95

X FRONT BUMPER COVERING

1.00 61.95 00.00 61.95

X FRONT BUMPER FRAME

1.00 256.69 00.00 256.69

X BONNET CABLE

1.00 68.47 00.00 68.47

Finalization

Confirmed & accepted by

7% GST on **Nett** 7,347.73
514.34

Authorized signatory and company stamp

Total Payable 7,862.07

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGU6841G

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
6222366

Vehicle & Document Information

WIP No **27863**
Reg No/Reg Date **SGU6841G / 05/12/2011**
Date In/Mileage **27/11/2018/ 89464**
Chassis No **WDD2120542A501790**
Engine No **27295231942270**
Make/Model **MB/E 300 SEDAN (W212)**
Colour/Trim **027 794 Pearl Beige/ 042 205 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	30/11/2018/ 09:02	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X FRONT BUMPER COVERING	1.00	61.95	00.00	61.95
X FRONT BUMPER COVERING	1.00	61.95	00.00	61.95
X FRONT BUMPER FRAME	1.00	256.69	00.00	256.69
X BONNET CABLE	1.00	68.47	00.00	68.47

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

Nett **449.06**
7% GST on **449.06** **31.43**
Total Payable **480.49**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	26 Oct 2018		26 Oct 2018 11:51 Edit Adj Rpt	S\$7,347.73 Edit Estimates	S\$7,347.73 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	M/S YOMA STRATEGIC HOLDINGS LTD, Co. Reg. No.: 196200185E		
Main Claimant:	VAGHESE EDAPPARA PAPACHAN		
Vehicle Reg. No.:	SGU6841G	Date of Loss:	24/10/2018 13:00 - :59 [82 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05075C02	Policy/Cover Note No.:	DMPCSN1622581802 (Comprehensive)
Vehicle Reg. No. (Insured):	SGF6064L	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 07/11/2018]		
Adj. Asg. Remarks:	EST \$8569.60 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGU6841G (SNM18D05075C02)**
[SGF6064L]

TP

VAGHESE EDAPPARA PAPACHAN

Oct 24 2018 1:00PM

[M/S YOMA STRATEGIC HOLDINGS LTD]
Cycle & Carriage Industries Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)








Assessment Reports

1 per page ☒





























No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 14:23	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page ☒

No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 13:09	SCENE PHOTO [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	25/10/18 13:09	SCENE PHOTO [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	25/10/18 13:09	INSURED CHASSIS NO [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
12	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
13	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
14	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
15	25/10/18 13:09	INSURED VEH [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
2	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
3	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
4	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
5	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
6	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
7	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
8	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
9	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
10	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>
11	28/12/18 15:34	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	✓
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
12	28/12/18 15:34	General View	 Load JPG	✓
13	28/12/18 15:34	General View	 Load JPG	✓
14	28/12/18 15:34	General View	 Load JPG	✓
15	28/12/18 15:34	General View	 Load JPG	✓
16	28/12/18 15:34	General View	 Load JPG	✓
17	28/12/18 15:34	General View	 Load JPG	✓
18	28/12/18 15:34	General View	 Load JPG	✓
19	28/12/18 15:34	General View	 Load JPG	✓
20	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
21	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
22	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
23	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
24	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
25	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
26	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
27	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
28	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
29	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
30	28/12/18 15:34	Reinspection Photo	 Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/10/18 11:49	EMAIL FM C&C	 Load PDF	
2	26/10/18 11:49	REPAIR EST WITH TP GIA	 Load PDF	
3	26/10/18 11:50	OI GIA	 Load PDF	
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 13:06	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	25/10/18 13:06	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	25/10/18 13:07	INSURED CI [Linked Accident Report Documents]	 Load TIF	
4	25/10/18 13:07	DRIVER IC [Linked Accident Report Documents]	 Load TIF	
5	25/10/18 13:07	DRIVER DL [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/01/19 14:20	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 14:23	Accident Statement	 Load HTM	
Photos/Images			3 per page	✓
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 13:09	SCENE PHOTO	 Load JPG	✓
2	25/10/18 13:09	SCENE PHOTO	 Load JPG	✓
3	25/10/18 13:09	INSURED VEH	 Load JPG	✓
4	25/10/18 13:09	INSURED CHASSIS NO	 Load JPG	✓
5	25/10/18 13:09	INSURED VEH	 Load JPG	✓
6	25/10/18 13:09	INSURED VEH	 Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
7	25/10/18 13:09	INSURED VEH	Load JPG	✓
8	25/10/18 13:09	INSURED VEH	Load JPG	✓
9	25/10/18 13:09	INSURED VEH	Load JPG	✓
10	25/10/18 13:09	INSURED VEH	Load JPG	✓
11	25/10/18 13:09	INSURED VEH	Load JPG	✓
12	25/10/18 13:09	INSURED VEH	Load JPG	✓
13	25/10/18 13:09	INSURED VEH	Load JPG	✓
14	25/10/18 13:09	INSURED VEH	Load JPG	✓
15	25/10/18 13:09	INSURED VEH	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 13:06	Sketch Plan	Load TIF	
2	25/10/18 13:06	Sketch Plan #2	Load TIF	
3	25/10/18 13:07	INSURED CI	Load TIF	
4	25/10/18 13:07	DRIVER IC	Load TIF	
5	25/10/18 13:07	DRIVER DL	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118019505/R1TD3S2
Date: 02/01/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN1622581802
Claimant Vehicle No: SGU6841G Insured Vehicle No: SGF6064L
Date of Loss: 24/10/2018 Nature of Claim: TP Claim No: SNM18D05075C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGU6841G
Make & Model: MERCEDES-BENZ E300, 2.0 (A) Engine No: 27295231942270
Reg. Date: 05/12/2011 (Man. Year: 2011) Chassis No: WDD2120542A501790
Colour: Gold Odometer: 92007 km
Engine Capacity: 2996 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,771.64	5,287.73	483.91	8.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,060.00	1,320.00	39.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,151.64	7,347.73	1,803.91	19.71
+ GST 7.00/7.00% (S\$)	640.61	514.34	126.27	19.71
Nett Amount (S\$)	9,792.25	7,862.07	1,930.18	19.71

INSPECTION

Date of Assignment: 26/10/2018
Date Inspected: 27/11/2018 Inspected At: Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378
Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2019)
Parts:	M1-COUPE	MERCEDES-BENZ E300 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU6841G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH / HEADLAMP	Scratched	3,316.12 FS	*3,316.12 FS
2	1		*FRONT BUMPER	Scratched	1,515.62 FS	*1,515.62 FS
3	1		*RH / FRONT BUMPER RAIL	Serviceable	13.64 FS	*- FS
4	1		*RH / FOG LAMP ORNAMENTAL MOULDING	Serviceable	128.33 FS	*- FS
5	1		*RH / TOP BASIC MOUNTING	Serviceable	68.15 FS	*- FS
6	1		*PARKING SENDER UNIT	Serviceable	273.79 FS	*- FS
7	1		*PARKTRONIC SENSOR AFTER RING	Necessary	6.93 FS	*6.93 FS
8	1		*FRONT BUMPER COVERING	Cracked	61.95 FS	*61.95 FS
9	1		*FRONT BUMPER COVERING	Cracked	61.95 FS	*61.95 FS
10	1		*FRONT BUMPER FRAME	Bent	256.69 FS	*256.69 FS
11	1		*BONNET CABLE	Cut	68.47 FS	*68.47 FS
					Total Parts (S\$)	5,771.64 5,287.73

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.	New	1,920.00	960.00
2	RESPRAY FRONT BUMPER.	New	960.00	600.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.	New	380.00	380.00
4	TO REMOVE, REPLACE HEADLAMP WITH FOCUS.	New	120.00	120.00
Gross Labour Cost (S\$)			3,380.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >