

ASS. REC. BY:

REF:

CS/ICS18019509/As d3

Instructions:

Surveyor:

ASSIGNMENT (Office)

Merimer

From (Person):

Janice Goh

of

ICS

Date/Time: 26/10/18 @ 12:04pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 3193G

Insured:

at Workshop m/s

First Autowork

Tel:

9247 8842

of

23 Kaki Blk Ave 4 #04-01

Policy No:

MPC18A00048900

Claim No:

DMPC1800407H

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A. 23/10/2018

CA /

REV

/ REP. / REV 24 HRS

29/10/18 @ 2:30pm

Date/Time:

12:24pm @ 26/10/18

Person Contacted:

Vincent

Vehicle IN / ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLK 3193G-X
20/10/18	@ 13:25 p.m. revised IN to Janice Goh via merimer.
30/10/18	@ 13:26 p.m. mandate requested authorize repair to Janice Goh via merimer.
31/10/18	@ 17:29 p.m. mandate approved by Janice Goh via merimer.
01/11/18	@ 10:16 a.m. revert authorize repair to Vincent (Gopher) via email.

REF: ICS

ASSIGNMENT

From: Date: 29/10/2018

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SLK 3193G
at Workshop mis: First Autowork
of: 23 kaki Bkt Ave 4 #04-01

Insured:

Policy No:

Claims No:

Sum Insured: Excess: \$500.00

(Client's Record)

Make of Veh: 2:30pm @ owner waiting
vincent

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 78K

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 06 hrs. days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLK3193G Yr Regn: 2017 Jan.

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Astra Sports Tourer 999.

Colour: grey A/C: Insured / Std / NI / NA

Sp. Reading: 44592 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WOLBE8FA4H8.026414.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18 -

R: 225/40R18 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIRY SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I. 29/10/18.

Survey held at: First Autowork.

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

DEC 11 2018

MV: 78K

PV: 45.8K

Net: 32.4K

RECEIVED 20 DEC 2018

20/12/18 Confirmed P/P \$13,211.10 @ 6 days with Adrian.
(\$8,796.95 Red - 40%)

Date/Time, File Pass to?

20/12/18

1) Typist

Date/Time, File Return to?

2)

☐ Preli. Report☒ Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$ 13,211.10 P/P)

450

10

460

Return: 82925594

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

7642G

Vehicle Details

Vehicle No.:

SLK3193G

Vehicle to be Exported:

Yes

Intended Deregistration Date:

24 Oct 2018

Vehicle Make:

OPEL

Vehicle Model:

ASTRA ST 1.0 AT

Primary Colour:

Grey

Manufacturing Year:

2016

Engine No.:

B1162877GT2X0934

Chassis No.:

W0LBE8EA4H8026414

Maximum Power Output:

77.0 kW (103 bhp)

Open Market Value:

\$19,609.00

Original Registration Date:

12 Jan 2017

First Registration Date:

12 Jan 2017

Transfer Count:

0

Actual ARF Paid:

\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

11 Jan 2027

PARF Rebate Amount:

\$3,750.00

Intended COE Rebate Details

COE Expiry Date:

11 Jan 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$52,503.00

COE Rebate Amount:

\$42,002.00

Total Rebate Amount:

\$45,752.00

The information contained herein is correct as at 24 Oct 2018

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

(More 10 Years COE) **Peugeot Accord 4.30**



100% Quality Car, Low
Mileage for 10,000 Km
Only 10,000 Km
Sincere Motoring


[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

2 vehicles

Search Selection

opel astra

Any

Any

2017

Any

Any

Any

Available



Opel Astra 1.4A

\$85,900

\$9,050 /yr

08-Jun-2017

1,399 cc

42,000 km

Hatchback

Available

5 Years Full Car Warranty, Free Every 10K Km Servicing Till 100K Km Mileage, Schedule A Test Drive Today. Viewing Is Strictly By Appointment Only.
Carro

Posted: 19-Oct-2018 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel Astra, astra, Used Opel



Opel Astra Sports Tourer 1.0A

\$78,000

\$8,680 /yr

03-Jul-2017

999 cc

26,000 km

Stationwagon

Available

Single Owner Unit! Maintained By Agent With Warranty Till 2022 And 4 More Free Servicing By Agent. Deep Sky Blue Exterior With Black Interior.
Many Functions And Great Fuel Economy, Low Maintenance W...

Audax Auto Pte Ltd

Posted: 17-Oct-2018 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel Astra, astra, Used Opel

Save this search criteria, to get email alerts whenever a match is found.

Model

Price

Depreciation

Eng Cap

Mileage

Veh Type

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#)
[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Article](#)
[Forum](#)
[Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used opel astra, opel astra Singapore, used opel astra Singapore, used opel astra, used vehicles Singapore or even buy used opel astra Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)
©2004-2018 sgCarMart. All rights reserved.

Nivitha (LKK Auto)

From: motorsurvey <motorsurvey@ecics.com.sg>
Sent: Friday, 26 October 2018 12:04 PM
To: vincent.sim@alpinemotors.sg; 'assignments'
Cc: Kelvin Chew; suhaimi@alpinemotors.sg; motorsurvey
Subject: RE: SLK3193G ECICS OWN DAMAGE-DOA 23/10/2018
Attachments: SLK3193G_ESTIMATE PG 2.jpg; SLK3193G_ESTIMATE.JPG; SLK3193G OWN DAMAGE.PDF

Hi Vincent

Thank you for your email.
We will appoint LKK for the OD survey.

Aside to LKK

Please assist for the OD survey.
Policy excess is \$500.00.

Our claim no. DMPC1800407H.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: Vincent Sim [mailto:vincent.sim@alpinemotors.sg]
Sent: Friday, 26 October, 2018 11:38 AM
To: motorsurvey
Cc: Kelvin Chew; suhaimi@alpinemotors.sg
Subject: fw: SLK3193G ECICS OWN DAMAGE-DOA 23/10/2018

Dear Sir,
Have not received any confirmation , kindly get surveyor to call us to confirm the survey on Monday (29-10-2018) at 10.30am

Regards,
Vincent Sim- Claims Dept

vincent.sim@alpinemotors.sg

65113022 ext 343

H/P: 92478842

From: "Vincent Sim" <vincent.sim@alpinemotors.sg>
Sent: Thursday, October 25, 2018 3:01 PM
To: "ecics survey" <motorsurvey@ecics.com.sg>
Cc: "Janice Goh Siew Geok" <janice_goh@ecics.com.sg>, "Kelvin Chew" <Kelvin.chew@alpinemotors.sg>, "suhaimi@alpinemotors.sg" <suhaimi@alpinemotors.sg>
Subject: SLK3193G ECICS OWN DAMAGE-DOA 23/10/2018

Janice,
As attached the Own Damaged Claim of the above with estimate ,
kindly allocated surveyor, on Next Monday (29-10-2018) at 10.30am , kindly confirm and revert

Location :
Person in charge :-
Suhaimi , Kelvin – 82925595 H/P.
68441985 – office phone
E-mail ;
suhaimi@alpinemotors.sg
Kelvin.chew@alpinemotors.sg

Add;
First Autoworks Pte Ltd
23, Kaki Bukit Ave 4
#04-01 (South Wing)
singapore 415933
(Vicom Building)
tel; 6844-1985

Regards,
Vincent Sim- Claims Dept

vincent.sim@alpinemotors.sg

65113022 ext 343

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

follow us on  facebook follow us on  twitter visit our website ecics.com.sg 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 20 December 2018 9:46 AM
To: Kelvin.chew@alpinemotors.sg
Cc: suhaimi@firstautoworks.com.sg; SUR
Subject: RE: SLK 3193 G OPEL ASTRA ECICS OD DOA 23.10.2018

Dear Kelvin,

Confirmed final fig of \$ 13,211.10 (part by part) @ 6 days of repairs before excess \$500/- & GST.

Final invoice and all supporting documents sent over to ECICS LTD.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kelvin Chew [mailto:Kelvin.chew@alpinemotors.sg]
Sent: Saturday, 15 December 2018 1:15 PM
To: sur@lkkauto.com
Cc: suhaimi@firstautoworks.com.sg
Subject: SLK 3193 G OPEL ASTRA ECICS OD DOA 23.10.2018

Hi Lkk,

attach is finalize report.
part by part \$13,211.10 before excess \$500.00 @ 6 working days.
kindly please check & confirm with me.
thanks.

from,
kelvin chew
8292 5595

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

Shirley Hiew (LKK Auto)

8292 5595
Kelvin

From: Kelvin Chew <Kelvin.chew@alpinemotors.sg>
Sent: Thursday, 22 November 2018 5:18 PM
To: sur@lkkauto.com
Cc: suhaimi@firstautoworks.com.sg
Subject: SLK 3193 G OPEL ASTRA ECICS OD DOA 23.10.2018

Hi Lkk,

supplementary price.

1. FRT SUPORT PANEL TOP GARNISH RH \$152
2. FRT SUPORT PANEL TOP GARNISH LH \$152

thanks.

from,
kelvin chew
8292 5595

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 1 November 2018 10:16 AM
To: 'vincent.sim@alpinemotors.sg'
Cc: 'suhaimi@alpinemotors.sg'; 'kelvin.chew@alpinemotors.sg'
Subject: SLK 3193G OD (ECICS)

Dear Vincent,

As instructed by our client, please proceed to repair the insured vehicle **SLK 3193G (Excess \$ 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLK3193G (DMPC1800407H/JG)**

OD

Oct 23 2018 8:00AM

[TEO KWANG LOONG RANDALL]

1st Autoworks Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 26/11/2018 12:06 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$15645.10) - SLK3193G - Claim Handler: Janice Goh

Approved:15645.10.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLK3193G (DMPC1800407H/JG)**

OD

Oct 23 2018 8:00AM

[TEO KWANG LOONG RANDALL]

1st Autoworks Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 31/10/2018 17:29 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$15341.10) - SLK3193G - Claim Handler: Janice Goh

Approved:15341.10.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 23 Nov 2018

Preliminary Advice

Vehicle No	: SLK3193G	Accident Date	: 23/10/2018
Make	: OPEL ASTRA ST	Policy No.	: MPC18A00048900
Assignment Date	: 26/10/2018	Excess	: S\$500.00
Date of Inspection	: 29/10/2018	Est. Duration of Repair	: 6 days
Inspection At	: 1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,312.05 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	10,855.60 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	4,789.50
Total	:S\$	15,645.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	45,752.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,248.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SUPPLEMENTARY AMOUNT IS \$ 304.00

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Oct 2018

Preliminary Advice

Vehicle No	: SLK3193G	Accident Date	: 23/10/2018
Make	: OPEL ASTRA ST	Policy No.	: MPC18A00048900
Assignment Date	: 26/10/2018	Excess	: S\$0.00
Date of Inspection	: 29/10/2018	Est. Duration of Repair	: 6 days
Inspection At	: 1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01 Singapore 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,008.05
Revised Amount	:S\$	10,551.60
Check Items (Estimated)	:S\$	4,789.50
Total	:S\$	15,341.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	45,752.00
Salvage Value	:S\$	
Margin for Repair	:S\$	32,248.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/10/2018 14:46
 Date Of Accident 23/10/2018 08:25
 Exact Location Of Accident BARTLEY ROAD EAST
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLK3193G
Insured/Policyholder
 Name Of Registered Owner TEO KWANG LOONG RANDALL
 NRIC No S8027642G
 Email Address RANDALLTEO@YAHOO.COM
 Mobile Phone No (LOCAL) +65-88581980
 Alternative Phone No OFFICE-88581980

Vehicle Particulars

Manufacturer OPEL
 Model OPEL ATSRA TOURER 1.0
 Exact Purpose for which vehicle was being used at time of accident LEISURE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company ECICS LIMITED
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number MPC18A00048900

Cover Note Number

Driver

Name of Driver TEO KWANG LOONG RANDALL
 NRIC No S8027642G
 Date Of Birth 08/09/1980
 Occupation INDOOR
 Date Of Driving Pass 23/02/2010
 Driving Experience 8 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-88581980
 Fax Number
 Contact Number OFFICE-88581980
 Email Address RANDALLTEO@YAHOO.COM

Address	BLK 401 JURONG WEST ST 42 #03-531
Postcode	640401
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH186M
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any verbal misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 23/1/19
C44016

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/Pass No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling on the right most lane of Barley Rd East. I wasn't speeding and tail-gating. The Toyota Prius in front of me suddenly braked hard, and ~~released~~ I did not hit him initially but the driver applied another sudden hard brake and I ~~crashed~~ ~~crashed~~ into his car. The damage was minimal on car B as my car only touched his rear bumper.

DECLARATION

I/we declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time 23/1/18
09:00 Hrs

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
I.H.L./M.N. No

Identification Card

00000146120187

NAME: **CHEN, JIN**
 ADDRESS: **204 4TH JARROW WEST STREET 42**
 CITY: **CHENNAI**
 STATE: **INDIA**
 DATE OF BIRTH: **1980/01/01**
 SEX: **M**
 HEIGHT: **170 CM**
 WEIGHT: **65 KG**
 EYES: **BROWN**
 HAIR: **BLACK**
 SKIN: **Fair**
 SIGNATURE: **[Signature]**
 PASS DATE: **22 Feb 2018**



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

CLASS 1: Motor Cars up to 2000kg and 4-wheelers, excluding auto-rickshaws and other motor vehicles up to 2000kg



INS CERT

CERTIFICATE OF INSURANCE

THE STATE OF INSURANCE

OFFICE WORKSHOPS

• 1988年，中国开始实行“双轨制”。

[illegible]

Important Notes

10. The vehicle has been used in a way that would result in the use of the vehicle in a manner that is not in accordance with the terms of the lease agreement.

Driving License





Repair Estimate

Date :24/10/2018

Reference: OPEL
Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLK3193G
CHASSIS NO.: W0LBE8EA4H8026414
ENGINE NO.: B1162877GT2X0934

Name of insured : TEO KWANG LOONG RANDALL
Date of accident.: 23/10/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>cracked</i>	\$ 1,758.00
2	1	FRT BONNET LOCK <i>new</i>	\$ 312.00
3	4	FRT BONNET STOPED <i>new</i>	\$ 40.00
4	1	FRT BUMPER <i>cracked</i>	\$ 1,994.00
5	1	FRT BUMPER TOW COVER <i>new</i>	\$ 128.00
6	15	FRT BUMPER CLIP <i>new</i>	\$ 92.50
7	1	FRT BUMPER SIDE RETAINER LH - GUIDE <i>2 new</i>	\$ 136.00
8	1	FRT BUMPER SIDE RETAINER LH - UPP	\$ 106.00
9	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
10	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
11	1	FRT BUMPER BRACKET LH <i>new</i>	\$ 192.00
12	1	FRT BUMPER BRACKET RH <i>new</i>	\$ 192.00
13	1	FRT BUMPER BRACKET TOP CENTRE <i>new</i>	\$ 198.00
14	1	FRT BRACE BRACKET CENTRE <i>new</i>	\$ 229.00
15	1	FRT BRACE BRACKET RH <i>new</i>	\$ 118.00
16	1	FRT BRACE BRACKET LH <i>new</i>	\$ 118.00
17	1	FRT BUMPER SPONGE <i>new</i>	\$ 254.00
18	1	FRT BUMPER REINFORCEMENT UPP (metal) <i>new</i>	\$ 798.00
19	1	FRT BUMPER REINFORCEMENT LOW (firbe) <i>new</i>	\$ 374.00
20	1	FRT BUMPER PARKING SENSOR <i>2 new</i>	\$ 272.00
21	1	FRT BUMPER PARKING SENSOR SEAL <i>new</i>	\$ 12.00
22	1	FRT BUMPER PARKING SENSOR WIRE HARNESS	\$ 394.00
23	1	FRT GRILLE ASSY <i>new</i>	\$ 800.00
24	1	FRT GRILLE LOGO <i>new</i>	\$ 160.00
25	1	FRT LOW CENTRE GRILLE <i>new</i>	\$ 202.00
26	1	RH HEADLAMP <i>cracked</i>	\$ 820.00
27	1	LH HEADLAMP <i>cracked</i>	\$ 820.00
28	1	RADIATOR SUPORT PANEL TOP GARNISH RH <i>new</i>	\$ 152.00
29	1	RADIATOR SUPORT PANEL TOP GARNISH LH <i>new</i>	\$ 152.00
30	1	RADIATOR SUPORT PANEL TOP <i>new</i>	\$ 334.00
31	1	RADIATOR <i>new</i>	\$ 1,424.00
32	1	RADIATOR COOLANT <i>new</i>	\$ 164.00
33	1	RADIATOR TOP BRACKET LH <i>new</i>	\$ 124.00

34	1	RADIATOR TOP BRACKET RH		\$	124.00	+
35	1	RADIATOR TOP MOUNTING		\$	18.00	+
36	1	RADIATOR BRACKET LOWER LH		\$	162.00	+
37	1	RADIATOR BRACKET LOWER RH		\$	162.00	+
38	1	A/C CONDENSER		\$	730.00	x
39	1	A/C CONDENSER TOP SEAL		\$	112.00	x
40	1	A/C CONDENSOR AIR GUIDE TOP CENTRE		\$	158.00	x
41	1	A/C CONDENSOR AIR GUIDE RH UPP		\$	134.00	x
42	1	A/C CONDENSOR AIR GUIDE LH		\$	138.00	x
43	1	A/C CONDENSOR ELECTRONIC AIR GUIDE		\$	514.00	x
44	1	INTERCOOLER, TURBOCHARGER		\$	1,060.00	x
45	1	ENGINE AIR INTAKE DUCT		\$	166.00	x
46	1	ENGINE AIR INTAKE DUCT HOSE		\$	120.00	x

Parts Total: \$ 16,714.50
Less 10%: \$ 1,671.45
Total: \$ 15,043.05

Labour

No.	Labour Description	Price (SGD)	
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 3,900.00	1950
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT FENDER LH, FRT FENDER RH, FRT SUPPORT PANEL	\$ 2,000.00	1800
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00	120
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00	x
5	To remove and refit radiator and conduct pressure test	\$ 180.00	x

Labour Total: \$ 6,900.00

Others

No.	Other Description	Price (SGD)	
1	FRT NUMBER PLATE	\$ 65.00	x

Other Total: 65.00

TOTAL: 22,008.05
GST (7%): 1,540.56

GRAND TOTAL: 23,548.61

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

Yours faithfully

Service Advisor

PARTS PRICES ARE SUBJECT TO CHANGES.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim
P/P 29/10/18

obpys

Excess \$500 not authorized

VEHICLE NO: SLK 3193G

VEHICLE NO: SLK 3193G

[illegible]

Repair Estimate

Date :24/10/2018

Reference: OPEL
Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLK3193G
CHASSIS NO.: W0LBE8EA4H8026414
ENGINE NO.: B1162877GT2X0934

Name of insured : TEO KWANG LOONG RANDALL
Date of accident.: 23/10/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Cracked</i>	\$ 1,758.00
2	1	FRT BONNET LOCK <i>new</i>	\$ 312.00
3	4	FRT BONNET STOPED <i>new</i>	\$ 40.00
4	1	FRT BUMPER <i>Cracked</i>	\$ 1,994.00
5	1	FRT BUMPER TOW COVER <i>new</i>	\$ 128.00
6	15	FRT BUMPER CLIP <i>new</i>	\$ 92.50
7	1	FRT BUMPER SIDE RETAINER LH - GUIDE <i>2 new</i>	\$ 136.00
8	1	FRT BUMPER SIDE RETAINER LH - UPP	\$ 106.00
9	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
10	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
11	1	FRT BUMPER BRACKET LH <i>new</i>	\$ 192.00
12	1	FRT BUMPER BRACKET RH <i>new</i>	\$ 192.00
13	1	FRT BUMPER BRACKET TOP CENTRE <i>new</i>	\$ 198.00
14	1	FRT BRACE BRACKET CENTRE <i>new</i>	\$ 229.00
15	1	FRT BRACE BRACKET RH <i>new</i>	\$ 118.00
16	1	FRT BRACE BRACKET LH <i>new</i>	\$ 118.00
17	1	FRT BUMPER SPONGE <i>new</i>	\$ 254.00
18	1	FRT BUMPER REINFORCEMENT UPP (metal) <i>new</i>	\$ 798.00
19	1	FRT BUMPER REINFORCEMENT LOW (firbe) <i>new</i>	\$ 374.00
20	1	FRT BUMPER PARKING SENSOR <i>2 new</i>	\$ 272.00
21	1	FRT BUMPER PARKING SENSOR SEAL <i>new</i>	\$ 12.00
22	1	FRT BUMPER PARKING SENSOR WIRE HARNESS	\$ 394.00
23	1	FRT GRILLE ASSY <i>new</i>	\$ 800.00
24	1	FRT GRILLE LOGO <i>new</i>	\$ 160.00
25	1	FRT LOW CENTRE GRILLE <i>new</i>	\$ 202.00
26	1	RH HEADLAMP <i>Cracked</i>	\$ 820.00
27	1	LH HEADLAMP <i>Cracked</i>	\$ 820.00
28	1	RADIATOR SUPORT PANEL TOP GARNISH RH <i>new</i>	\$ 152.00
29	1	RADIATOR SUPORT PANEL TOP GARNISH LH <i>new</i>	\$ 152.00
30	1	RADIATOR SUPORT PANEL TOP <i>new</i>	\$ 334.00
31	1	RADIATOR <i>new</i>	\$ 1,424.00
32	1	RADIATOR COOLANT <i>new</i>	\$ 164.00
33	1	RADIATOR TOP BRACKET LH <i>new</i>	\$ 124.00

34	1	RADIATOR TOP BRACKET RH <i>new</i>	\$ 124.00	<i>✓</i>
35	1	RADIATOR TOP MOUNTING <i>new</i>	\$ 18.00	<i>✓</i>
36	1	RADIATOR BRACKET LOWER LH <i>new</i>	\$ 162.00	<i>✓</i>
37	1	RADIATOR BRACKET LOWER RH <i>new</i>	\$ 162.00	<i>✓</i>
38	1	A/C CONDENSER <i>260mm</i>	\$ 730.00	<i>✓</i>
39	1	A/C CONDENSER TOP SEAL	\$ 112.00	<i>✓</i>
40	1	A/C CONDENSER AIR GUIDE TOP CENTRE <i>260mm</i>	\$ 158.00	<i>✓</i>
41	1	A/C CONDENSER AIR GUIDE RH UPP <i>260mm</i>	\$ 134.00	<i>✓</i>
42	1	A/C CONDENSER AIR GUIDE LH	\$ 138.00	<i>✓</i>
43	1	A/C CONDENSER ELECTRONIC AIR GUIDE <i>260mm</i>	\$ 514.00	<i>✓</i>
44	1	INTERCOOLER, TURBOCHARGER <i>new</i>	\$ 1,060.00	<i>✓</i>
45	1	ENGINE AIR INTAKE DUCT <i>260mm</i>	\$ 166.00	<i>✓</i>
46	1	ENGINE AIR INTAKE DUCT HOSE <i>260mm</i>	\$ 120.00	<i>✓</i>

Parts Total: \$ 16,714.50

Less 10%: \$ 1,671.45

Total: \$ 15,043.05

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 3,900.00 <i>1950</i>
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT FENDER LH, FRT FENDER RH, FRT SUPPORT PANEL	\$ 2,000.00 <i>1800</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00 <i>120</i>
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00
5	To remove and refit radiator and conduct pressure test	\$ 180.00

Labour Total: \$ 6,900.00

Others

No.	Other Description	Price (SGD)
1	FRT NUMBER PLATE <i>new</i>	\$ 65.00

Other Total: 65.00

TOTAL: 22,008.05

GST (7%): 1,540.56

GRAND TOTAL: 23,548.61

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor

Adrian Lj
P/P 29/10/18
oblys
Excess \$500
Not Authorised


Wir lieben Autos.
FINALIZE
EGICS LIMITED
GST Ref. No: 20-0000274-Z

Vehicle No: SLK3193G
Chassis No: W0LBE8EA4H8026414
Engine No: B1162877GT2X0934
Date of accident :23/10/2018

Invoice No:
Invoice Date:
DESCRIPTION
AMOUNT SGD
Parts

No.	Qty.	Description	Price (SGD)
1	1	FRT BONNET	\$ 1,758.00
2	1	FRT BUMPER	\$ 1,994.00
3	5	FRT BUMPER CLIP	\$ 30.00
4	1	FRT BUMPER SIDE RETAINER LH - GUIDE	\$ 136.00
5	1	FRT BUMPER SIDE RETAINER LH - UPP	\$ 106.00
6	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
7	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
8	1	FRT BUMPER BRACKET LH	\$ 192.00
9	1	FRT BUMPER BRACKET RH	\$ 192.00
10	1	FRT BUMPER BRACKET TOP CENTRE	\$ 198.00
11	1	FRT BRACE BRACKET CENTRE	\$ 229.00
12	1	FRT BRACE BRACKET RH	\$ 118.00
13	1	FRT BRACE BRACKET LH	\$ 118.00
14	1	FRT BUMPER SPONGE	\$ 254.00
15	1	FRT BUMPER REINFORCEMENT UPP (metal)	\$ 798.00
16	1	FRT GRILLE ASSY	\$ 800.00
17	1	FRT GRILLE LOGO	\$ 160.00
18	1	RH HEADLAMP	\$ 820.00
19	1	LH HEADLAMP	\$ 820.00
20	1	RADIATOR SUPPORT PANEL TOP GARNISH RH	\$ 152.00
21	1	RADIATOR SUPPORT PANEL TOP GARNISH LH	\$ 152.00
22	1	A/C CONDENSER AIR GUIDE TOP CENTRE	\$ 158.00
23	1	A/C CONDENSER AIR GUIDE RH UPP	\$ 134.00
24	1	A/C CONDENSER AIR GUIDE LH	\$ 138.00
25	1	A/C CONDENSER ELECTRONIC AIR GUIDE	\$ 514.00
26	1	ENGINE AIR INTAKE DUCT	\$ 166.00

Supplementary

--	--	--	--

Total: \$ 10,379.00
 Less 10%: \$ 1,037.90
 Parts Total: \$ 9,341.10

Labour

No.		Price (SGD)
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	\$ 1,950.00
2	CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA.FRT BUMPER , FRT BONNET , FRT FENDER LH , FRT FENDER RH , FRT SUPPORT PANEL	\$ 1,800.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	\$ 120.00

Labour Total : \$ 3,870.00

Other

No.		Price (SGD)
1	1	

Other Total : \$ -

Total : \$ 13,211.10
 Excess: \$ 500.00
 GST (7%) : \$ 889.78
 Grand Total : \$ 13,600.88

Yours Faithfully,

 Kelvin Chew
 Service Advisor
 Tel: 68441985 Fax:68445185

Please check and finalize with me

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Dec 2018 10:57 Edit Reg		26 Oct 2018 00:00 Edit Adj Rpt	\$413,211.10 Edit Estimates	\$413,211.10 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TEO KWANG LOONG RANDALL , Co. Reg. No.: S8027642G, Email: EMAIL@EMAIL.COM									
Vehicle Reg. No.: SLK3193G		Date of Loss: 23/10/2018 08:00 - :59 [21 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / DMPC1800407H/JG		Policy/Cover Note No.: MPC18A00048900 (Comprehensive)							
		Excess: S\$500.00							
Repairer: 1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01, 415933 Kaki Bukit - Tel: 68441985									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/11/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- ECICS (26/11/2018): Alert - Adj Mandate Approved (\$\$15645.10) - SLK3193G - Claim Handler: Janice Goh - ECICS (31/10/2018): Alert - Adj Mandate Approved (\$\$15341.10) - SLK3193G - Claim Handler: Janice Goh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK3193G (DMPC1800407H/JG)
 OD
 Oct 23 2018 8:00AM
 [TEO KWANG LOONG RANDALL]
 1st Autoworks Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 13:25	Adjuster Immediate Advice	 Load HTM	☐
2	23/11/18 13:03	Adjuster Immediate Advice	 Load HTM	☐
3	23/11/18 16:31	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 13:24	General View	 Load JPG	☒
2	30/10/18 13:24	Chassis Number	 Load JPG	☒
3	30/10/18 13:24	General View	 Load JPG	☒
4	30/10/18 13:24	General View	 Load JPG	☒
5	30/10/18 13:24	General View	 Load JPG	☒
6	30/10/18 13:24	General View	 Load JPG	☒
7	30/10/18 13:24	General View	 Load JPG	☒
8	30/10/18 13:24	General View	 Load JPG	☒
9	30/10/18 13:24	General View	 Load JPG	☒
10	30/10/18 13:24	General View	 Load JPG	☒
11	30/10/18 13:24	General View	 Load JPG	☒
12	30/10/18 13:24	General View	 Load JPG	☒
13	30/10/18 13:24	General View	 Load JPG	☒
14	30/10/18 13:24	General View	 Load JPG	☒
15	30/10/18 13:24	General View	 Load JPG	☒
16	30/10/18 13:24	General View	 Load JPG	☒
17	30/10/18 13:24	General View	 Load JPG	☒
18	30/10/18 13:24	General View	 Load JPG	☒
19	30/10/18 13:24	General View	 Load JPG	☒
20	30/10/18 13:24	General View	 Load JPG	☒
21	30/10/18 13:24	General View	 Load JPG	☒
22	30/10/18 13:24	General View	 Load JPG	☒
23	30/10/18 13:24	General View	 Load JPG	☒
24	30/10/18 13:24	General View	 Load JPG	☒
25	30/10/18 13:24	General View	 Load JPG	☒
26	30/10/18 13:24	General View	 Load JPG	☒
27	30/10/18 13:24	General View	 Load JPG	☒
28	30/10/18 13:24	General View	 Load JPG	☒
29	30/10/18 13:24	General View	 Load JPG	☒
30	30/10/18 13:24	General View	 Load JPG	☒
31	30/10/18 13:24	General View	 Load JPG	☒
32	30/10/18 13:24	General View	 Load JPG	☒
33	30/10/18 13:24	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	30/10/18 13:24	General View	 Load JPG	☒
35	30/10/18 13:24	General View	 Load JPG	☒
36	30/10/18 13:24	General View	 Load JPG	☒
37	30/10/18 13:24	General View	 Load JPG	☒
38	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
39	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
40	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
41	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
42	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
43	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
44	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
45	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
46	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
47	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
48	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
49	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
50	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
51	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
52	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
53	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
54	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
55	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
56	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
57	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
58	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
59	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
60	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
61	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
62	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
63	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
64	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
65	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
66	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
67	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
68	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
69	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
70	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
71	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
72	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
73	18/12/18 18:37	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 13:23	ESTIMATE .pdf	 Load PDF	
2	23/11/18 13:07	SUPPLEMENTARY.pdf	 Load PDF	
3	20/12/18 09:38	ESTIMATE MARKED & SUPPLEMENTARY.pdf	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One
Singapore 038987

Our File No: CS/ICS18019509/ASD3E2

Date: 27/12/2018

REFERENCE

Insured/Claimant: TEO KWANG LOONG RANDALL Policy No: MPC18A00048900
Date of Loss: 23/10/2018 Nature of Claim: OD Claim No: DMPC1800407H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK3193G**
Make & Model: OPEL ASTRA ST, 999cc (A) Engine No: B1162877GT2X0934
Reg. Date: 12/01/2017 (Man. Year: 2016) Chassis No: W0LBE8EA4H8026414
Colour: Grey Odometer: 44592 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$78,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,108.05	9,341.10	5,766.95	38.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,900.00	3,870.00	3,030.00	43.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,008.05	13,211.10	8,796.95	39.97
- Excess (\$\$)	500.00	500.00	0.00	0.00
(\$\$)	21,508.05	12,711.10	8,796.95	40.90
+ GST 7.00/7.00% (\$\$)	1,505.56	889.78	615.78	40.90
Nett Amount (\$\$)	23,013.61	13,600.88	9,412.73	40.90

INSPECTION

Date of Assignment: 26/10/2018
Date Inspected: 29/10/2018 Inspected At: 1st Autoworks Pte Ltd (HQ)
23 Kaki Bukit Ave 4, #04-01
Singapore 415933
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2018)
Parts:	144	OPEL ASTRA ST 999cc (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK3193G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Buckled	1,758.00 FL	*1,758.00 FL
2	1		*FRT BONNET LOCK	Not Necessary	312.00 FL	*- FL
3	4		*FRT BONNET STOPPED	Not Necessary	40.00 FL	*- FL
4	1		*FRT BUMPER	Deformed	1,994.00 FL	*1,994.00 FL
5	1		*FRT BUMPER TOW COVER	Not Necessary	128.00 FL	*- FL
6	15		*FRT BUMPER CLIP	Necessary	97.50 FL	*30.00 FL
7	1		*FRT BUMPER SIDE RETAINER LH - GUIDE	Necessary	136.00 FL	*136.00 FL
8	1		*FRT BUMPER SIDE RETAINER LH - UPP	Necessary	106.00 FL	*106.00 FL
9	1		*FRT BUMPER SIDE RETAINER RH - GUIDE	Necessary	136.00 FL	*136.00 FL
10	1		*FRT BUMPER SIDE RETAINER RH - UPP	Necessary	106.00 FL	*106.00 FL
11	1		*FRT BUMPER BRACKET LH	Damaged	192.00 FL	*192.00 FL
12	1		*FRT BUMPER BRACKET RH	Damaged	192.00 FL	*192.00 FL
13	1		*FRT BUMPER BRACKET TOP CENTRE	Bent	198.00 FL	*198.00 FL
14	1		*FRT BRACE BRACKET CENTRE	Bent	229.00 FL	*229.00 FL
15	1		*FRT BRACE BRACKET RH	Bent	118.00 FL	*118.00 FL
16	1		*FRT BRACE BRACKET LH	Bent	118.00 FL	*118.00 FL
17	1		*FRT BUMPER SPONGE	Deformed	254.00 FL	*254.00 FL
18	1		*FRT BUMPER REINFORCEMENT UPP (METAL)	Bent	798.00 FL	*798.00 FL
19	1		*FRT BUMPER REINFORCEMENT LOW (FIRBE)	Not Necessary	374.00 FL	*- FL
20	1		*FRT BUMPER PARKING SENSOR	Not Necessary	272.00 FL	*- FL
21	1		*FRT BUMPER PARKING SENSOR SEAL	Not Necessary	12.00 FL	*- FL
22	1		*FRT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	394.00 FL	*- FL
23	1		*FRT GRILLE ASSY	Cracked	800.00 FL	*800.00 FL
24	1		*FRT GRILLE LOGO	Necessary	160.00 FL	*160.00 FL
25	1		*FRT LOW CENTRE GRILLE	Not Necessary	202.00 FL	*- FL
26	1		*RH HEADLAMP	Cracked	820.00 FL	*820.00 FL
27	1		*LH HEADLAMP	Cracked	820.00 FL	*820.00 FL
28	1		*RADIATOR SUPORT PANEL TOP GARNISH RH	Deformed	152.00 FL	*152.00 FL
29	1		*RADIATOR SUPORT PANEL TOP GARNISH LH	Deformed	152.00 FL	*152.00 FL
30	1		*RADIATOR SUPORT PANEL TOP	Repair	334.00 FL	*- FL
31	1		*RADIATOR	Not Necessary	1,424.00 FL	*- FL
32	1		*RADIATOR COOLANT	Not Necessary	164.00 FL	*- FL
33	1		*RADIATOR TOP BRACKET LH	Not Necessary	124.00 FL	*- FL
34	1		*RADIATOR TOP BRACKET RH	Not Necessary	124.00 FL	*- FL
35	1		*RADIATOR TOP MOUTING	Not Necessary	18.00 FL	*- FL
36	1		*RADIATOR BRACKET LOWER LH	Not Necessary	162.00 FL	*- FL
37	1		*RADIATOR BRACKET LOWER RH	Not Necessary	162.00 FL	*- FL
38	1		*A/C CONDENSER	Not Necessary	730.00 FL	*- FL
39	1		*A/C CONDENSER TOP SEAL	Not Necessary	112.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*A/C CONDENSOR AIR GUIDE TOP CENTRE	Cracked	158.00 FL	*158.00 FL
41	1		*A/C CONDENSOR AIR GUIDE RH UPP	Cracked	134.00 FL	*134.00 FL
42	1		*A/C CONDENSOR AIR GUIDE LH	Cracked	138.00 FL	*138.00 FL
43	1		*A/C CONDENSOR ELECTRONIC AIR GUIDE	Cracked	514.00 FL	*514.00 FL
44	1		*INTERCOOLER, TURBOCHARGER	Not Necessary	1,060.00 FL	*- FL
45	1		*ENGINE AIR INTAKE DUCT	Cracked	166.00 FL	*166.00 FL
46	1		*ENGINE AIR INTAKE DUCT HOSE	Not Necessary	120.00 FL	*- FL
47	1		*FRT NUMBER PLATE	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	16,779.50	10,379.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,671.45	1,037.90
Total Parts (S\$)	15,108.05	9,341.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	3,900.00	1,950.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT BONNET, FRT FENDER LH, FRT FENDER RH, FRT SUPORT PANEL	New	2,000.00	1,800.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	220.00	120.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM	New	600.00	0.00
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	180.00	0.00
Gross Labour Cost (S\$)			6,900.00	3,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >