

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

ATTN : MOTOR CLAIMS DEPARTMENT
AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING

78 SHENTON WAY #07-16

SINGAPORE 079120

TEL : 6419 3000 FAX : 6835 7416

DATE : 27/10/2018

PAGE : 1 OF 2

Not Authorised
1.9.1
Resurvey Before

ACCIDENT REPAIR ON : SKK5407P

MODEL : VOLKSWAGEN PASSAT

POLICY NO : P/1404669

CHASSIS NO : WVVZZZ3CZDE152509

YEAR OF MANUFACTURE : 2013

DATE / TIME OF ACCIDENT : 23/10/2018@06:55HRS

LOCATION : ALONG CTE TOWARDS AYE-BEFORE BRADDELL EXIT

THIRD PARTY VEHICLE NO : SKT778D

REPLACEMENT OF PARTS		QUANTITY	UNIT PRICE	AMOUNT	
1	REAR TAILLAMP LH	1	<i>Ln</i>	\$ 310.00	X
2	REAR TAILLAMP LOWER BRACKET LH	1		\$ 85.00	X
3	REAR BUMPER	1	<i>Bnd</i>	\$ 1,180.00	✓
4	REAR BUMPER SIDE RETAINER LH	1	<i>Ln</i>	\$ 75.00	X
5	REAR BUMPER SIDE RETAINER RH	1	<i>Ln</i>	\$ 75.00	X
6	REAR BUMPER REVERSE SENSOR	<i>Ln</i> 4	\$ 155.00	\$ 620.00	X
7	REAR BUMPER NUMBER PLATE WITH HOLDER	1	<i>Ln</i>	\$ 65.00	<i>455x</i>
8	REAR BUMPER NUMBER PLATE LAMP LH	1		\$ 55.00	X
9	REAR BUMPER NUMBER PLATE LAMP RH	1		\$ 55.00	X
10	REAR BUMPER OUTER CHROME MOULDING LH	1	<i>Ln</i>	\$ 165.00	✓
11	REAR BUMPER OUTER CHROME MOULDING RH	1		\$ 165.00	✓
12	REAR BUMPER TOW HOOK COVER	1	<i>Ln</i>	\$ 35.00	X
13	REAR BUMPER LOWER GARNISH	1		\$ 320.00	?
14	REAR BUMPER UNDER COVER	1	<i>Ln</i>	\$ 250.00	X
15	REAR BUMPER INNER SPONGE	1		\$ 115.00	?
16	REAR BUMPER REINFORCEMENT	1		\$ 420.00	?
17	REAR END PANEL	1	<i>Ln</i>	\$ 1,050.00	X
18	REAR END PANEL INNER TOP GARNISH	1	<i>Ln</i>	\$ 290.00	X
19	REAR EXHAUST SILENCER BOX	1	<i>Ln</i>	\$ 690.00	X
20	REAR EXHAUST TOP RUBBER MOUNTING	<i>Ln</i> 2	\$ 45.00	\$ 90.00	
SUB TOTAL				\$ 6,110.00	
LESS 10%				\$ (611.00)	
PARTS TOTAL				\$ 5,499.00	

SPECIAL NETT ITEMS		QUANTITY	UNIT PRICE	AMOUNT	
1	REAR TAILLAMP CLIPS LH	<i>Ln</i> 3	\$ 8.00	\$ 24.00	X
2	REAR BUMPER CLIPS	<i>Ln</i> 10	\$ 5.00	\$ 50.00	✓
3	REAR BUMPER RIVET	10	\$ 5.00	\$ 50.00	?
4	REAR BUMPER UNDER COVER CLIPS	<i>Ln</i> 4	\$ 5.00	\$ 20.00	X
5	REAR END PANEL INNER TOP GARNISH CLIPS	<i>Ln</i> 4	\$ 5.00	\$ 20.00	X
PARTS TOTAL				\$ 164.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ACCIDENT REPAIR ON : SKK5407P

MODEL : VOLKSWAGEN PASSAT

POLICY NO : P/1404669

CHASSIS NO : WVVZZZ3CZDE152509

YEAR OF MANUFACTURE : 2013

DATE / TIME OF ACCIDENT : 23/10/2018@06:55HRS

LOCATION : ALONG CTE TOWARDS AYE-BEFORE BRADDELL EXIT

THIRD PARTY VEHICLE NO : SKT778D

DATE : 27/10/2018

PAGE : 2 OF 2

LABOUR CHARGES FOR REAR PORTION		AMOUNT
1	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT AND WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	\$ 800.00
2	PROVIDE SKILL LABOUR AND MATERIAL TO PUTTY ALL DAMAGED PARTS AND PANEL AND TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.	\$ 500.00
3	REMOVE AND REPLACE REAR BUMPER SENSOR TO FACILITATE REPAIRS.	\$ 50.00
4	REMOVE AND REPLACE REAR EXHAUST SILENCER BOX TO FACILITATE REPAIRS.	\$ 120.00
5	TUFF KOTE AND ANTI RUST COATING ALL REPLACE AND REPAIR PARTS.	\$ 80.00
6	DISCONNECT, CHECK, RESET AND DIAGNOSTIC ELECTRICAL SYSTEM WIRING, HARNESS, WIRE SOCKETS AND ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 250.00
LABOUR TOTAL		\$ 1,800.00

2001

2501

✓

x

x

?

TOTAL PARTS & LABOUR	\$ 7,463.00
GST 7%	\$ 522.41
GRAND TOTAL	\$ 7,985.41
ESTIMATE REPAIR DURATION	5 DAYS

2 days

YOURS SINCERELY,



ESTIMATOR : KIT

TEL : 8405 4058

FAX : 6269 2404

EMAIL : karkit.ngai@bhauto.com.sg

SURVEY ATTENDED BY :

NAME	Kenneth
COMPANY	CLCC
DATE	29/10/18
TIME	1.35pm
TEL	96910663
EMAIL	