

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05871

Vehicle Insured : GBH3830K

Accident Date : 23-Oct-2018

Date : 25-Oct-2018

Our Ref : 218177 (AIG) / CHAN

PAGE : 1

DYNAMIC WORLD CONTRACTOR SERVICES P.L.

180 PAYA LEBAR ROAD #10-02

YI GUANG FACTORY BUILDING

Singapore 409032

NOT Notarized

11 Sep 87

Re survey After Repair

4 days

ESTIMATED COST OF REPAIR FOR MIT.CANTER FEB21 YN7907T

=====

1 pc Tail gate	Rp 2,200.00	—
1 pc Tail gate "MITSUBISHI" sticker	M 125.00	—
2 pcs Taillamp	@ S\$268.06 CM 536.12	—
1 pc Rear no.plate bracket	Rp 78.68	—
1 pc Rear no.plate lamp	CM 115.72	—
1 pc Rear exhaust pipe	Rp 841.45	—
	3,896.97	
	Less 25% :	974.24

1 pc Tail gate 60km/h sticker	M 15.00	sn	—
1 pc Tail gate 23pax sticker	M 15.00	sn	—
1 pc Rear step bar	Rp 150.00	sn	—
1 pc Rear no .plate	Rp 25.00	sn	—
1 pc Rear bumper (metal)	Rp 450.00	sn	—
2 pcs Rear bumper side bracket	Rp 280.00	sn	—
4 pcs Rear bumper side bracket screw	M 24.00	sn	—

To remove and renew exhaust silencer box 80.00 *601*

To putty and spray replaced parts 600.00 *3001*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts 800.00 *5501*

Total : S\$ 5,361.73

=====

Singapore Dollars Five Thousand Three Hundred and Sixty One and Cents Seventy Three Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: