



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SGF9099S

Lim Kian Boon

383E Pasir Panjang Road  
Singapore 118718

Mobile: 96901198

### Vehicle & Document Information

WIP No **27870**  
Reg No/Reg Date **SGF9099S / 08/03/2016**  
Date In/Mileage **/ 0**  
Chassis No **WDD2050402R137658**  
Engine No **27491030509055**  
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**  
Colour/Trim **027 775 Iridium sil/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	25/10/2018/ 16:17	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 2100455125-02 / 24.10.18 DRIVE IN/EXCESS : 25.10.18 // TP AR NO.: GBD5867M=AXA INS DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	✓ 380.00
A BPILAB DISASSEMBLE AND REPLACE ON FRONT BUMPER ,RHF FENDER				960 1920.00
A BPIRES RESPRAY ON FRONT BUMPER,RHF FENDER				600 800.00
M FRONT BUMPER	1.00	1506.37	00.00	de 1506.37
M RH BASIC MOUNTING FOR BUMPER	1.00	68.53	00.00	an 68.53

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Tan Jia 97495749  
wp  
20/11/18 2 1pm  
1 sur@lkkauto.com  
03 days

Confirmed & accepted by

Nett **5,674.90**  
7% GST on **5674.90** **397.24**  
**Total Payable 6,072.14**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg