



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGF9099S

Lim Kian Boon

383E Pasir Panjang Road
Singapore 118718

Vehicle & Document Information

WIP No 27870
Reg No/Reg Date SGF9099S / 08/03/2016
Date In/Mileage 20/11/2018/ 37733
Chassis No WDD2050402R137658
Engine No 27491030509055
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 775 Iridium sil/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	04/12/2018/ 15:54	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN

POLICY NO/ACC DATE : 2100455125-02 / 24.10.18
DRIVE IN/EXCESS : 25.10.18 // TP AR NO. GBD5867M-AXA INS
DATE IN/DATE SURVEY: 20.11.18 // 20.11.18 TAUFIKH-LKK 13:00PM
DIRECT SETTLEMENT: HSIAO TONG-LKK

X DISTANCE SENSOR

1.00 172.07 00.00 172.07

SUPPLEMENTARY

Confirmed & accepted by

7% GST on **Nett** 172.07 **172.07**
12.04

Authorized signatory and company stamp

Total Payable 184.11

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler Stuttgart Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Page 1 of 1



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGF9099S

Lim Kian Boon

383E Pasir Panjang Road
Singapore 118718

Vehicle & Document Information

WIP No **27870**
Reg No/Reg Date **SGF9099S / 08/03/2016**
Date In/Mileage **20/11/2018/ 37733**
Chassis No **WDD2050402R137658**
Engine No **27491030509055**
Make/Model **MB/MB C 180 SEDAN (W205) "AVANTGARDE / A**
Colour/Trim **027 775 Iridium sil/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator				
CSI00001	Cash	04/12/2018/ 15:53	VS	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 2100455125-02 / 24.10.18
DRIVE IN/EXCESS : 25.10.18 // TP AR NO.: GBD5867M=AXA INS
DATE IN/DATE SURVEY: 20.11.18 // 20.11.18 TAUFIKH-LKK 13:00PM
DIRECT SETTLEMENT: HSIAO TONG-LKK

A BPILAB

USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

0.10

380.00

A BPILAB

DISASSEMBLE AND REPLACE ON FRONT BUMPER ,RH FENDER

960.00

A BPIRES

RESPRAY ON FRONT BUMPER

600.00

X FRONT BUMPER

1.00

1506.37 00.00

1506.37

X RH BASIC MOUNTING FOR BUMPER

1.00

68.53 00.00

68.53

X DISTANCE SENSOR

1.00

172.07 00.00

172.07

Finalization

3 days

Confirmed & accepted by

Nett **3,686.97**
7% GST on **3686.97** **258.09**

Authorized signatory and company stamp

Total Payable **3,945.06**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg