Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)

Sent: Wednesday, 10 July 2019 5:51 PM

To: Rosalyn TAN (SPF); Olivia Lau (LKKAuto); SUR

Cc: Hafizul Farhan RAHMAT (SPF)

Subject: RE: URGENT Clarification on Upper Range of repair cost- SDV 7948G

Dear Rosalyn,

As mentioned that was indicated in our preliminary advice.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email:sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>

Sent: Tuesday, 9 July 2019 4:21 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; SUR

<sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: Hafizul Farhan RAHMAT (SPF) < Hafizul_Farhan_RAHMAT@spf.gov.sg> **Subject:** RE: URGENT Clarification on Upper Range of repair cost-SDV 7948G

Veron,

If this is the case, then why is there the following note:

NOTES: THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$45,000

Rosalyn Tan Sock Buay Head Coporate Services & Safe Driving Police Logistics Department/ AEMD Singapore Police Force

DID: (65) 6478 4832 | FAX: (65) 6478 4838





WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Sent: Tuesday, 9 July 2019 3:13 PM

To: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; SUR <sur@lkkauto.com>; assignments

<assignments@lkkauto.com>; Rosalyn TAN (SPF) <Rosalyn TAN@spf.gov.sg>
Cc: Hafizul Farhan RAHMAT (SPF) <Hafizul Farhan RAHMAT@spf.gov.sg>
Subject: RE: URGENT Clarification on Upper Range of repair cost- SDV 7948G

Dear Rosalyn,

The amount \$31,589.00 in our report dated 7/11/2018 was our preliminary advice.

We have reviewed Borneo Motor's repair bill attached in your email and is of the opinion that the amount \$34,508.14 (including GST) is a reasonable and fair repair cost.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Olivia Lau (LKKAuto)

Sent: Monday, 8 July 2019 5:46 PM

To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: FW: URGENT Clarification on Upper Range of repair cost

From: Rosalvn TAN (SPF)

Sent: Monday, 8 July 2019 5:45:25 PM (UTC+08:00) Kuala Lumpur, Singapore

To: Olivia Lau (LKKAuto)

Cc: Hafizul Farhan RAHMAT (SPF)

Subject: URGENT Clarification on Upper Range of repair cost

Olivia,

Above LKK report refers.

Third Party Workshop Borneo Motor's repair bill is \$34,508.14 whereas LKK's adjusted repair bill is \$31,589.00.

Noted that LKK has adjusted Borneo Motor's Workshop estimates from \$48,954.50 to \$31,589.00.

You have further indicated that the following:

Appreciate your clarifications if the upper repair range of \$50,000 is a reasonable, fair repair cost? (For this case, Borneo Motors is the authorised agent for Lexus)

NOTES: THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$45,00

Can you please advise what LKK mean by the above statement?

Please call me if you need further clarifications.

Rosalyn Tan Sock Buay Head Coporate Services & Safe Driving Police Logistics Department/ AEMD <u>Singapore Police Force</u> DID: (65) 6478 4832 | FAX: (65) 6478 4838



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."