

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5862K**AAD1810-255***Not Authorized*
1/1 Sep 8

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5862K
VF1ABL15AUC281456
RENAULT
LATITUDE
23.10.18
III

PART		LIST	
1	BUMPER COVER FRT	\$	1,259.42
1	BUMPER SPOILER FRT	\$	181.75
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT RH	\$	150.77
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER UNDERTRAY FRT	\$	472.83
1	BUMPER GRILLE LOWER FRT	\$	266.80
1	BUMPER FOG LAMP GRILLE RH	\$	207.21
1	BUMPER BEAM FRT	\$	914.08
1	HEADLAMP RH	\$	1,184.43
1	HEADLAMP PANEL FRT RH	\$	152.15
1	FENDER PANEL FRT RH	\$	783.83
1	WHEELARCH FRT RH	\$	278.84
1	FENDER BRACKET LOWER RH	\$	15.79
1	FENDER INSULATOR RH	\$	130.84
1	LOWER ARM RH L70Y	\$	685.76
1	KNUCKLE ARM RH L70Y	\$	846.98
1	ABSORBER FRT RH L70Y	\$	360.54
1	DRIVESHAFT RH	\$	1,747.45
1	STABILIZER BAR FRT	\$	604.65
1	WIPER RESERVOIR MOTOR	\$	270.06
1	WIPER RESERVOIR	\$	348.25
1	WIPER RESERVOIR NECK	\$	136.11

TOTAL	\$	11,517.11
10%	\$	1,151.71
	\$	10,365.40

Trans-cab Auto Services Pte Ltd

AAD1810-255

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5862K

Special Nett

1SET	BUMPER CLIP FRT	\$	na	66.00	}
1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
1SET	WHEELARCH CLIP FRT RH	\$	na	30.50	
1SET	Front licence plate with holder	\$	na	80.00	
1	FRONT RIGHT TYRE	\$	na	330.00	
1	FRONT RIGHT TYRE RIM	\$	na	380.00	}
1	WINDSCREEN SEALANT	\$	na	253.80	
1	FRONT WINDSCREEN MOULDING	\$	na	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	

TOTAL	\$	1,571.80
--------------	-----------	-----------------

TOTAL PARTS	\$	11,937.20
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts,	\$	3,000.00	100%
Putty and spray painting of the affected portion.	\$	3,000.00	44%
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X
To rust-proofing of the affected areas.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1810-255

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5862K

To transfer of front windscreen fittings and conduct water seepage test	\$	170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	X
TOTAL	\$	8,760.00	
Over All Total	\$	20,697.20	

LUMP SUM (REPAIR DAY)~~10 DAYS~~1^{1/2} day.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: