

ASS. REC. BY:

REF: CS/FWD18019592/T19d3ST

Special Instruction:

Surveyor:
Mejren

Taufik

ASSIGNMENT (Office)

From (Person):

Clara Li

of

FWD

Date/Time:

29/10/18 @ 11-01am

Estimated Cost:

Bill to:

TP+WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 2922A

Insured:

at Workshop m/s

Tan Chong Motor
913 Bukit Timah

Tel:

64694091

of

Policy No:

PNPV2018-00005509

Claim No:

1201800013658/CL

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A.

20/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:16am @ 29/10/18

Person Contacted:

Lawrence

Vehicle:

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLP 2922A-X
30/10@	revert via Mejren
30/10@	14:36 pm authorize repair by clara. li
30/10@	2:46pm email Lawrence authorize repair excess \$500.
09/11/18@	11:34am 7id revert to Clara Li via Mejren. (supplementary).
09/11/18@	2:47pm Belliana informed CLR at 8 20283.55 via Mejren.

Tayfikh

REF:

FWD

INSURANCE

From: _____ Date: _____
 Estimated Cost: _____
 TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop n/s: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: \$500
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

 Bal. or Market Value: \$9400
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 13 days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: Lawrence Vehicle: IN / OUT

Yeh No: SLP29224 Yr Regn: 2017 mg
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or: _____
 Make: Nissan Pasqar 2.0 C.S. 1997
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp Reading: 26040 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SJNFB AJ1141937820
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/41R19 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front			Rear		
R/Bal.	6	mm	R/Bal.	6	mm
L/Bal.	6	mm	L/Bal.	6	mm
D.O.A.			D.O.I.	29/10/18	

 Survey held at: JC Bhat Timah
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 10/4/19 @ 11.51am confirmed with Lawrence final ag 2083.55, 13 days.
 (Red to 7950.45, 28%)

RECEIVED 11 APR 2019

Lawrence
 10/4/2019

Date/Time File Pass to? : Preli. Report
 : Final Report
 Date/Time File Return to? _____
 Report Format: MRP-00
 Lump Sum / I.B.R IS: 20783.55
 Days Of Repair: 13
 Resurvey No. of Trip: 1
 Add Fee: Site Insp \$
 Interview \$
 Tech. days \$
 Weekend \$
 Survey Fee: 300
 Transport: 50
 50 x 50
 10
 460

Nivitha (LKK Auto)

From: clara.li@fwd.com
Sent: Monday, 29 October 2018 11:01 AM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com; AsherSng@lkkauto.com
Subject: FW: SLF2922A DOA:20.10.2018 OD (Our Ref: 1201800013658/CL)
Attachments: 0111_001.pdf

Hi LKK team,

Please refer to the email below and liaise with OD survey. Policy Excess \$500.00

Attached is the repair estimate & OI GIA report. Password will be sent via a separate email.

Please create the case in Merimen.

Thank you.

Kind Regards

Clara Li
Senior Executive, Claims

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722
E clara.li@fwd.com
W fwd.com.sg



From: Lawrence Teo [mailto:lawrenceteo@tanchoong.com]
Sent: Monday, 29 October, 2018 10:25 AM
To: Motor Claims SG - SG Common
Subject: SLF2922A DOA:20.10.2018 OD

Dear All,

Please arrange car survey. Car in.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472

Email: lawrenceteo@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

From: Singapore Printer

Sent: 29 October 2018 10:19

To: Lawrence Teo <lawrenceteo@tanchong.com>

Subject: Attached Image

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 10 April 2019 11:51 AM
To: Lawrence Teo; Taufikh (LKKAuto)
Subject: RE: SLP2922A DOA:20.10.2018 OD (Our Ref: 1201800013658/CL)

Dear Lawrence,

WITHOUT PREJUDICE

Confirm final fig \$20,283.55 before excess \$500.00 & GST and 13 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lawrence Teo <lawrenceteo@tanchong.com>
Sent: Friday, 29 March 2019 10:23 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: RE: SLP2922A DOA:20.10.2018 OD (Our Ref: 1201800013658/CL)

Dear Sir,

See attached.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038914 :: Fax: +65-64697472
Email: lawrenceteo@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Lawrence Teo
Sent: 16 March 2019 17:01
To: 'Shiau Chan (LKKAuto)' <siewsc@lkkauto.com>; Norsipah (norsipah@tanchong.com) <norsipah@tanchong.com>
Subject: RE: SLP2922A DOA:20.10.2018 OD (Our Ref: 1201800013658/CL)

Dear all,

See attached.

Best Regards,

Lawrence Teo

Tan Chong Motor Sales Pte Ltd

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	29 Oct 2018 12:37	Cim Dtl Modified	Insured Name: -> -.	[A] Nivitha Govindasamy
2	29 Oct 2018 12:37	Cim Dtl Modified	Claimant's Name: -> -.	[A] Nivitha Govindasamy
3	29 Oct 2018 12:37	Cim Veh Model Changed	(204716) HONDA CITY 1.5 (A).	[A] Nivitha Govindasamy
4	29 Oct 2018 12:37	Cim Created	Reg No: SLF2922A. Policy No: 120180001358/CL. Acct Date: 2018/10/20. Claim Type: OD. Insurer: FWD Singapore Pte. Ltd. (HQ). Workshop: Tan Chong Motor Sales (HQ)	[A] Nivitha Govindasamy
5	29 Oct 2018 12:37	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ);; RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : Infiniti Appraisal Service.	[A] Nivitha Govindasamy
6	29 Oct 2018 12:37	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/08	[A] Nivitha Govindasamy
7	29 Oct 2018 12:37	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
8	29 Oct 2018 12:38	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
9	29 Oct 2018 12:40	Cim Registration Modified	Reg No:SLF2922A->SLP2922A. Pol No:120180001358/CL->PNPV2018-00005509. Eccess: -> 500.00.	[I] Clara Li Zi Rong
10	30 Oct 2018 11:51	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
11	30 Oct 2018 11:51	Cim Dtl Modified	JPJ Reg. Date: -> 2017/05/31.	[A] DENISE TAY KWEE CHENG
12	30 Oct 2018 11:51	Cim Details Notified		[A] DENISE TAY KWEE CHENG
13	30 Oct 2018 14:24	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/11/08	[A] DENISE TAY KWEE CHENG
14	30 Oct 2018 14:24	Adj Mandate Request	Cur Req:25954.00:damage consistent repair cost economical	[A] DENISE TAY KWEE CHENG
15	30 Oct 2018 14:36	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/08. Mandate Remarks: Please re-see mandate on the check items after being verified	[I] Clara Li Zi Rong
16	30 Oct 2018 14:36	Adj Mandate Set	Approved:16000.00:Please re-see mandate on the check items after being verified	[I] Clara Li Zi Rong
17	09 Apr 2019 11:19	Cim Veh Model Changed	(204716) -> (204488) NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A).	[A] SHIAU CHAN
18	09 Apr 2019 11:34	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/11/08	[A] SHIAU CHAN
19	09 Apr 2019 11:34	Adj Mandate Request	Cur Req:20283.55:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.	[A] SHIAU CHAN
20	09 Apr 2019 14:57	Adj Mandate Set	Approved:20283.55.	[I] Belliana

Date From



Date To



Audit Type

None

Go

ACTIVITY

[29/11/2018 12:00] SHIAU CHAN:
PLEASE BE INFORMED THAT THE VEHICLE STILL UNDER REPAIRING.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1960143	30/10/2018 11:51	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLP2922A		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 09 Apr 2019

Preliminary Advice

Vehicle No	: SLP2922A	Accident Date	: 20/10/2018
Make	: NISSAN QASHQAI	Policy No.	: PNPV2018-00005509
Assignment Date	: 29/10/2018	Excess	: S\$500.00
Date of Inspection	: 29/10/2018	Est. Duration of Repair	: 13.00
Inspection At	: TAN CHONG MOTOR SALES (HQ) 913 BUKIT TIMAH ROAD SINGAPORE 589622		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,931.10	(ESTIMATE \$28,234.00 + SUPPLEMENTARY \$697.10)
Revised Amount	:S\$	20,283.55	(INCLUSIVE SUPPLEMENTARY & CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	20,283.55	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	60,122.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,878.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.

View Received Message

This mail is associated with :

***SLP2922A (1201800013658)**

OD

Oct 20 2018 12:00AM

[WONG TUCK FOOK]

Tan Chong Motor Sales

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 30/10/2018 14:36 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16000.00) - SLP2922A - Claim Handler: Clara Li Zi Rong

Approved:16000.00:Please re-seek mandate on the check items after being verified

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 30 October 2018 2:46 PM
To: 'Lawrence Teo'; Admin-D (LKKAuto); assignments; SUR
Subject: RE: SLP2922A DOA:20.10.2018 OD (Our Ref: 1201800013658/CL)

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLP 2922A (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: clara.li@fwd.com <clara.li@fwd.com>
Sent: Tuesday, 30 October 2018 2:03 PM
To: lawrenceteo@tanchong.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: motorclaims.sg@fwd.com
Subject: RE: SLP2922A DOA:20.10.2018 OD (Our Ref: 1201800013658/CL)

Hi Denise,

Please expedite, thank you.

Regards,
Clara

From: Lawrence Teo [<mailto:lawrenceteo@tanchong.com>]
Sent: Tuesday, 30 October, 2018 12:32 PM
To: Clara Li Zirong - SGUser; admin-d@lkkauto.com; ASSIGNMENTS@LKKAUTO.COM; sur@lkkauto.com
Cc: Motor Claims SG - SG Common
Subject: RE: SLP2922A DOA:20.10.2018 OD (Our Ref: 1201800013658/CL)

Dear All,

This car is it approve for repair?

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 30 Oct 2018

Preliminary Advice

Vehicle No	: SLP2922A	Accident Date	: 20/10/2018
Make	: HONDA CITY	Policy No.	: PNPV2018-00005509
Assignment Date	: 29/10/2018	Excess	: S\$500.00
Date of Inspection	: 29/10/2018	Est. Duration of Repair	: 13.00
Inspection At	: TAN CHONG MOTOR SALES (HQ) 913 BUKIT TIMAH ROAD SINGAPORE 589622		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,234.00
Revised Amount	:S\$	14,938.41
Check Items (Estimated)	:S\$	11,015.59
Total	:S\$	25,954.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	60,122.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,878.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 30 Oct 2018

Preliminary Advice

Vehicle No	: SLP2922A	Accident Date	: 20/10/2018
Make	: HONDA CITY	Policy No.	: PNPV2018-00005509
Assignment Date	: 29/10/2018	Excess	: S\$500.00
Date of Inspection	: 29/10/2018	Est. Duration of Repair	: 13.00
Inspection At	: TAN CHONG MOTOR SALES (HQ) 913 BUKIT TIMAH ROAD SINGAPORE 589622		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,234.00
Revised Amount	:S\$	14,695.21
Check Items (Estimated)	:S\$	11,015.59
Total	:S\$	25,710.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	60,122.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,878.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2018 18:43
Date Of Accident	20/10/2018 21:00
Exact Location Of Accident	WEST MALAYSIA PAHANG
Country/State of Loss	MALAYSIA/PAHANG DARUL MAKMUR

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP2922A
Insured/Policyholder	
Name Of Registered Owner	WONG TUCK FOOK
NRIC No	S1795004E
Email Address	HEAVEN17@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96246062
Alternative Phone No	OFFICE-96246062

Vehicle Particulars

Manufacturer	NISSAN
Model	QASHQAI 2.0
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD. - <i>ANY WORKSHOP</i>
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00005509
Cover Note Number	

Driver

Name of Driver	WONG TUCK FOOK
NRIC No	S1795004E
Date Of Birth	21/07/1967
Occupation	INDOOR
Date Of Driving Pass	02/05/1997
Driving Experience	21 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96246062
Fax Number	
Contact Number	OFFICE-96246062
Email Address	HEAVEN17@SINGNET.COM.SG

Address	BLK 689 JURONG WEST CENTRAL 1 #05-213
Postcode	640689
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : TAN SWEE LENG GENDER: : FEMALE
Passenger 2	NAME: : POH REE GI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	TRAFIK JEMPOL
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO MALAYSIA POLICE REPORT NO. TRAFFIC JEMPOL/002042/18. TRANSLATED FROM BAHASA TO ENGLISH. ON 20/10/2018 AT ABOUT 0855HRS, I WAS DRIVING MY CAR SLP2992A A NISSAN WITH MY SPOUSE NAMED: TAN SWEE LENG, PASSPORT NO. E6178953E (PASSENGER ON MY LEFT) AND MY COUSIN NAMED POH REE GI KPT NO 901029-06-525 (PASSENGER AT THE BACK) FROM SINGAPOEE TOWARDS BERA. ARRIVED AT KM 38, JALAN BAHAU - KEMAYAN, SUDDENLY AT A BEND, A LORRY NO THAT I AM UNSURE OF CAME FROM THE FRONT WENT INTO MY LANE AND GRAZE THE RIGHT SIDE OF THE VEHICLE I WAS DRIVING. I SUFFERED INJURIES TO MY HANDS, WHILE MY WIFE SUFFERER MINOR INJURIES TO HER HANDS AND MY COUSIN DIDNT SUFFER ANY INJURIES. DAMAGES TO MY VEHICLE ARE BROKEN RIGHT SIDE MIRROR, DENTED FRONT BONNET, DENTED FRONT AND REAR RIGHT DOOR, DENTED FRONT AND REAR RIGHT MUDGUARD. OTHER DAMAGES THAT I AM UNAWARE OF. THATS ALL FOR MY REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	UNKNOWN
Details Of Properties	

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	UNKNOWN DRIVER
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	WONG TUCK FOOK
Approximate Age	
Injuries Sustain	SUFFERED INJURIES ON HANDS
Injured person in which vehicle?	SLP2922A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	TAN SWEE LENG
Approximate Age	
Injuries Sustain	SUFFERER MINOR INJURIES ON HANDS
Injured person in which vehicle?	SLP2922A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5004E
Vehicle Details	
Vehicle No.:	SLP2922A
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	MR20455964W
Chassis No.:	SJNFBAJ11U1937820
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$19,507.00
Original Registration Date:	31 May 2017
First Registration Date:	31 May 2017
Transfer Count:	0
Actual ARF Paid:	\$19,507.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2027
PARF Rebate Amount:	\$14,630.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$45,492.00
Total Rebate Amount:	\$60,122.00

The information contained herein is correct as at 30 Oct 2018

OK



POLIS DIRAJA MALAYSIA
REPOUT POLIS

Bela: TRAFIK JEMPOL
Dzarah: JEMPOL
Kontinjen: NEGERI SEMBILAN
No Repot: TRAFIK JEMPOL/002042/18
Tarikh: 20/10/2018
Waktu: 1355 PM
Bahasa Diterima: B. Malaysia

Pegawai Penyiasat: R107580

Butir-butir Penerima Repot

Nama: NOR FARALIZA BT NAQAM
Butir-butir Jurubahasa (Jika Ada):
Nama: ---
No Paspor: ---
Alamat: ---
No Personal: R155115
Pangkat: KPL
No K/P (Baru): ---
Bahasa Asal: ---
No Polis/Tentera: ---

Butir-butir Pengadu

Nama: WONG TUCK FOOK
No K/P (Baru): ---
No Sijil Beranak: ---
Jantina: Lelaki
Keturunan: Cina
Pekerjaan: MANAGER
Alamat Tempat Tinggal: BLOCK 835, JURONG WEST CTR 1, 05-215, SINGAPORE, 640889
Alamat Butirpa: ---
Alamat Pejabat: ---
No Tel (Rumah): ---
Emel: ---
No Polis/Tentera: ---
Warganegara: Singapore
Tarikh Lahir: 21/07/1967
Umur: 51 tahun 2 bulan
No Paspor: E3056632F
No Tel (Pejabat): ---
No Tel (HP): 6596246062

Pengadu Menyatakan:

PADA 20/10/2018 JAM L/KURANG 0355 HRS. SEMASA MEMANDU MIKAR NO SLP 2922 A JENIS NISSAN BERSAMA ISTERI SAYA NAMA TAN SWEE LENG. PASSPORT NO: E6178953E (PENUMPANG SEBELAH PEMANDU) DAN SEPUPU SAYA NAMA FOH REE GI. K/P NO: 901026-06-5202 (PENUMPANG BAHAGIAN BELAKANG) DARI SINGAPORE HENDAK KE BERA. AFABILA SAMPAI DI KM 38, JALAN BAHAU - KEMAYAN, SEMASA MELALUI SELEKOH TIBA-TIBA SEBUAH M/LORI NO TIDAK TAHJ YANG DATANG DARI ARAH DEPAN TELAH MASUK KELALUAN SAYA DAN TERUS MENGESEL BAHAGIAN SISI KANAN KENDERAAN YANG SAYA PANDU. SAYA MENGALAMI LUKA-LUKA DI BAHAGIAN TANGAN MANAKALA ISTERI SAYA HANYA MENGALAMI CEDERA RINGAN DI BAHAGIAN TANGAN DAN SEPLUPU SAYA TIADA SEBARANG KECEDEeraan. KEROSAKAN KENDERAAN SAYA ADALAH CERMIN SISI KANAN PATAH, BONET DEPAN KANAN KEMEK, PINTU DEPAN DAN BELAKANG KANAN KEMEK. MURGUARD DEPAN DAN BELAKANG KANAN KEMEK. LAIN-LAIN KEROSAKAN TIDAK PASTI. SEKIAN REPOUT SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

R155115 | 20/10/2018 02:18:23 PM

SALINAN DIAMUKI SAH

Malaysia Police Report

POL 316



Cawangan Trafik
Ibu Pejabat Polis Daerah Jempol, Polis Diraja Malaysia, 72120 Bandar Seri
Jempol, Negeri Sembilan.
06-4582222

Baik Akan Penerimaan Repot Polis :

Nama Pengadu : WONG TUCK FOOK
No Kad Pengenalan / Pasport : E396652F
No Repot Polis : TRAFIK JENPOL/002042/18
Tarikh @ Masa Repot Polis : 20/11/2018 @ 13:55
Pengesahan Penerimaan Repot :

.....
Tandatangan Ketua Pejabat Pertanyaan

Pegawai Penyiasat :

Nama Pegawai Penyiasat : (R107680) SJH ABD KARIM BIN BUANG
Tempat Tugas : NEGERI SEMBILAN, JENPOL
No Telefon Pejabat : No Telefon Simbit : 013-9227680
Tarikh @ masa Perjumpaan :
Pengesahan Penerimaan Repot :

.....
Tandatangan Pegawai Penyiasat

Juru Gambar :

Nama	No Badan	Pangkat
.....

Tarikh @ Masa Gambar Diambil :
Pengesahan Gambar Diambil :

.....
Tandatangan Juru Gambar

Unit Pembekalan Dokumen Siasatan :

No Telefon Unit Pembekalan Dokumen :

Waktu Pejabat :
Isnin - Khamis :
08:00 Pagi - 01:00 Tengah Hari
02:00 Petang - 04:30 Petang
Jumaat :
08:00 Pagi - 12:30 Tengah Hari
02:45 Petang - 04:30 Petang
Cuti Umum / Khas : Tutup

Jenis Dokumen Dibekal Kepada Pengadu :

- 1. Salinan Repot Polis
- 2. Gambar Kenderaan
- 3. Rajah Kasar Kemalangan
- 4. Keputusan Siasatan
- 5. Lain-lain Dokumen

Tarikh @ Masa Dokumen Diserah :

Pengesahan Kaunter Pembekalan Dokumen :

.....
Tandatangan Pegawai Kaunter
Pembekalan Dokumen

Identification Card

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of Wong Tuck Fook

License Number: **S1795004E**
Name: **WONG TUCK FOOK**
Birth Date: **21 Jul 1967**
Issue Date: **25 Apr 2003**

Barcode: 000427643J

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S1795004E**

Portrait of Wong Tuck Fook

Name: **WONG TUCK FOOK**

Race: **CHINESE**
Date of Birth: **21-07-1967**
Country of Birth: **SINGAPORE**

Sex: **M**

Stamp: **S1795004E**



Identification Card

LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
02 May 1997

Licence No: S1795004E

NP 428A

1812997

NRIC No: S1795004E

Blood Group Date of issue
AB+ 21-03-1994

APT BLK 689 JURONG WEST CENTRAL 1 #05-213
SINGAPORE 640689

NRIC No: S1795004E Date: 14-08-2004 No: 5005721

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

LICK

10234

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0477/2018
DATE : 26-OCT-2018

RSC

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER
S(038986)
TEL : 6820 8888
FAX :
ATTN : CLAIM MANAGER

00

OWNER'S NAME : WONG TUCK FOOK
ADDRESS : APT BLK 689 JURONG WEST CENTRAL 1
#05-213
S(640689)
TELEPHONE NO : 96246062

Clar I.H.

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : PNPV2018-00005509
VEHICLE NO : SLP2922A
MODEL CODE : FDRARBZJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0 MY2014
ENGINE NO : MR20455964W-J11WV
CHASSIS NO : SJNFBZJ11U1937820
MILEAGE : 26046 KM
DATE IN : 26/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 20/10/2018

94568832

Tanjah 97495749

Ex \$500

Revert

Not Authorise
29/10/18 4:15pm
sure lkk out with
Resurvey before paint.
12-13 days

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 PHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	20.00	✓
2 LC	LEATHER CONDITIONING	80.00	?
3 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$25/PANEL X 10	250.00	200
4 SDG	INSTALL ULTRAMAX SOLAR FILM - DOOR GLASS RH FRONT	80.00	✓
5 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 06	600.00	500
6 SFW	INSTALL ULTRAMAX SOLAR FILM - FRT W/SCREEN WUTH ANTI GLARE	150.00	✓
7 SQG	INSTALL ULTRAMAX SOLAR FILM - QUARTER GLASS RH REAR	50.00	✓
8 UG10	RENEW FRONT WINDSHIELD GLASS ASSY. INCL SEALNT	170.00	✓
9 ZZ/001	RENEW WIRE HARDNESS RH FRONT/RH REAR DOOR AND MAIN HARDNESS \$200/PC X 03	600.00	?
10 ZZ/002	R/I DASHBOARD TO RENEW	200.00	?
11 ZZ/003	RENEW RH FRONT DOOR GLASS AND TRANSFER RH REAR DOOR GLASS \$80/PC X 02	160.00	✓
12 ZZ/004	RENEW RH REAR 1/4 GLASS	120.00	✓
13 ZZ/005	R/I RH FRONT/REAR SEAT TO ASSIST REPAIR	200.00	120
14 ZZ/006	R/I PETROL TANK TO ASSIST REPAIR	80.00	✓
15 ZZ/007	RENEW RH FRONT HOODLEDGE	600.00	?
16 ZZ/008	RENEW RH REAR FENDER INCLUDING REPAIR END PANEL	1000.00	140 950
17 ZZ/009	REPAIR LH FRONT FENDER, BOTH FRONT PILLAR, RH CENTER PILLAR, FRONT/REAR BUMPER AND RENEW BONNET,		
18 ZZ/011	S/PAINT FRONT PORTION, BOTH FRONT PILLAR, RH FRONT HOODLEDGE, RH FRONT/REAR DOOR, REAR BUMPER(2 TONE),		200 1600
19 ZZ/012	RH CENTER PILLAR, END PANEL, RH REAR FENDER, RH FRONT PILLAR AND RH WING MIRROR	3600.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
20	ZZ/013	R/I REVERSE SENSOR TO ASSIST REPAIR	110.00	✓
21	ZZ/014	SUPPLY AND RENEW RH FRONT DOOR LEATHER	300.00	?
22	ZZ/015	VACUMM GLASS CHIP	240.00	?
23	ZZ/016	TRANSFER OR REWIRE RH WING MIRROR LED	120.00	✓
24	ZZ/10	RH FRONT/REAR DOOR	2280.00	?
TOTAL LABOUR CHARGES			11010.00	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 RH FRONT DOOR TRIMBOARD	80900-4EA3A	1869.50		dl ✓
2 COVER ASSY INSTRUMENT RH LOWER	68920-4EA1A	76.90		?
3 MASK INSTRUMENT RH SIDE	68498-4EA0A	12.30		?
4 HARDNESS REAR RH DOOR	24126-4EA1A	475.70		?
5 WIRING HARNESS-BODY	24014-4EB1D	1499.10		?
6 RH FRONT DOOR WIRE HARDNESS	24124-4EA3C	432.70		cut ✓
7 COVER-MIRR BODY RH	96373-4EA8E	105.70		mis ✓
8 MIRROR ASSY-OUT RH	96301-4EA5E	497.10		bro ✓
9 CANOE RIVET RH FRONT FENDER/BUMPER \$6.50 EA X 07	76882-0M000	45.50		re ✓
10 CLIP BUMPER REAR \$7.40 EA X 04	85284-JD00A	29.60		re ✓
11 RETAINER-BUMPER RH REAR	79184-4EA0A	23.80		?
12 GROMMET BUMPER REAR \$2.50 EA X 04	63846-5V000	10.00		?
13 BRACKET-BUMPER RH REAR	85220-4EA0A	35.90		?
14 GLASS RH REAR 1/4	83312-4EA0A			380.00 ?
15 GRIP-OUTSIDE RH REAR DOOR	806B0-4EH0B	96.20		at ✓
16 ESCUT-OUTSIDE HANDLER COVER RH REAR DOOR	80644-4EH0A	32.30		?
17 LOCK & REMOTE C RH REAR DOOR	82500-4EA2A	166.70		?
18 REGULATOR-DOOR RH REAR	82700-4EA0A	434.20		?
19 GLASS RUN RUBBER RH REAR	82330-4EA1A	147.50		aq ✓
20 COVER-SASH INNER RH REAR DOOR	822D4-4EA0A	15.00		?
21 CORNER PIECE-RH REAR DOOR	82234-4EA1A	54.00		
22 SEAL RUBBER RH REAR DOOR	82834-4EA0A	63.50		re ✓
23 W/STRIP-RR DOOR RH	82830-4EA0E	132.20		re ✓
24 CHECK ASSY-RR DOOR RH	82430-4EA0A	39.50		?
25 HINGE-DOOR RH REAR POOR TOP	82400-4EA0A	56.10		bt ✓

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 MLDG RR DOOR RH	82820-4EA0A	188.90	mis?	
27 MOULDING RH REAR DOOR	82282-4EA1C	100.70	mis	
28 TAPE-RR DOOR,RH	82812-4EA0A	29.90	ne	
29 TAPE-RR DOOR,RH	82818-4EA0A	29.90	ne	
30 DOOR-REAR RH	H2100-HV0MA	1104.80	H	
31 HANDLE-PULL RH FRONT DOOR INNER	80950-4EA0A	63.00	?	
32 CAP-DOOR GRIP,RH FRONT	80944-4EA2A	84.00	mis	
33 FINISR-P/WDW SW RH FRONT DOOR	80960-4EA0A	126.00	?	
34 ESCUTCHEON RH FRONT DOOR COIN HOLDER	80682-4EA1A	63.00	dis	
35 SEAL A FR DOOR RH	80834-4EA0A	59.40	ne	
36 GROMMET HANDLER \$2.90 EA X 02	01281-00801			5.80 ne
37 CLIP HANDLER \$2.50 EA X 02	80897-AM800	5.00	ne	
38 HANDLE DOOR INSIDE RH FRONT	80670-4EA1A	41.00	?	
39 STRIKER ASSY RH FRONT/REAR DOOR \$57.80 EA X 02	80570-AA20A	115.60	?	
40 LOCK & REMOTE C RH FRONT DOOR	80500-4ER2A	166.70	?	
41 BRKT DOOR RH FRONT/REAR HANDLE \$51.60 EA X 02	80610-5FD0B	103.20		
42 GSKT-DOOR OUTSIDE RH FRONT DOOR HANDLE \$3.20EAX 04	80652-4EA0A			12.80 ne
43 GASKET-OUTSIDE HANDLER \$3.20 EA X 04	80654-4EA0A			12.80 ne
44 HANDLE SET-FRONT RH	80640-4EA2A	165.20	dis	
45 ESCUT-OUTSIDE HANDLE RH FRONT COVER	80644-4EA2A	32.30	mis	
46 REGULATOR-DOOR RH FRONT	80700-4EA3C	487.90	?	
47 GLASS-FR DOOR,RH	80300-4EA0A			760.00 bus
48 GLASS RUN RUB RH FRONT DOOR	80330-4EA2A	161.60	ne	
49 CONN ASSY-HOODLEDGE RH	F4190-4EAMA	129.90	?	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
50 PLATE-CLOSING RH FRONT DOOR	G5130-4EAMA			159.30 ?
51 LINK-DOOR STOP RH FRONT DOOR	80430-4EA0A	39.50	?	
52 HINGE ASSY RH FRONT DOOR BOTTOM	82420-4EA0A	56.10	?	
53 HINGE RH FRONT/RH REAR DOOR TOP/BOTTOM \$56.10EAX 2	82421-4EA0A	112.20	?	
54 SEAL LOWER RH FRONT DOOR RUBBER	80838-4EA0A	70.40	na	
55 WSTRIP ASSY-FRONT RH DOOR FRAME	80830-4EA1E	132.20	na	
56 MOULDING RH FRONT DOOR SASH	80282-4EA1B	100.70	del	
57 COVER-SASH INNER RH FRONT DOOR	802D4-4EA0A	15.00	ms	
58 MLDG ASSY-FR DOOR RH	80820-4EA0A	188.90	del	
59 TAPE-FR DOOR,RH	80812-4EA0A	29.90	del	
60 DOOR-FRONT RH	H0100-4EAAA	1104.80	del	
61 GROMMET FENDER	01281-00831	1.50	del	
62 CLIP FENDER \$1.20 EA X 05	01553-05131	6.00	del	
63 PROTECTOR-REAR RH FENDER	76748-4EA2A	186.40	?	
64 LID GAS FILLER COVER PANEL	G8830-4EAME	93.40	mis	
65 BASE-FILLER LID PETROL	G8120-4EAMA	66.00	?	
66 RETAINER-TAPPING FENDER RH REAR	G6690-4EAMA	19.30	del	
67 FENDER-REAR RH	G8100-4EAMA	1169.40	del	
68 WELT BODY RH FRONT DOOR	76922-4EA0A	205.10	?	
69 FENDER ARC RH REAR	93828-4EA0A	483.00	?	
70 FENDER-OVER,FR RH ARC	63810-4EA0A	483.00	?	
71 MOUL-ROOF DRIP RH	73852-4EA1A	213.90	?	
72 MOULDING RH REAR DOOR PAD	82870-4EA0A	264.80	?	
73 MOULDING RH FRONT DOOR PAD	80870-4EA0A	323.60	?	
74 SEALANT 1/4 GLASS	SEALANT - 3			48.00 del

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
75 SEALANT - FRONT W/SCREEN GLASS	SEALANT - 2			80.00 <i>ng</i>
76 MLDG WS UPPER	72752-4EA1A	134.60	<i>ue</i>	
77 RUBBER-DUM	G2716-89900	60.20	<i>ue</i>	
78 GLASS-FR WIND	72700-4EA4A	1244.60	<i>one</i>	
79 VENTILATOR RH DASHBOARD	68760-4EA0A	100.50	?	
80 PANEL & PAD	68200-4EA1A	1374.50	?	
81 HOOK ASSY-HOOD	65603-4EA0A	82.80	?	
82 MALE ASSY-HOOD	65601-4EA0A	67.60	?	
83 HINGE HOOD RH	65400-4EA0A	56.10	<i>bt</i>	
84 HOOD HINGE LH	65401-4EA0A	56.10	<i>bt</i>	
85 CLIP-HOOD INSUL \$1.60 EA X 13	65846-30F00	20.80	<i>uo</i>	
86 INSULATOR-HOOD	65840-4EA0A	185.50	<i>de</i>	
87 HOOD	F5100-4EAAA	961.40	<i>bt</i>	
88 COVER-HOLE FENDER SIDE RH	66898-4EA0B	57.70	?	
89 CLIP FENDER PROTECTOR \$1.30 EA X 13	01553-09321	16.90	?	
90 PROTECTOR-FR,RH FENDER	63842-HV00A	87.50	?	
91 FENDER-FRONT RH	F3100-4EAMB	622.70	<i>bt</i>	
92 CLIP BUMPER \$1.20 EA X 08	01553-05933	9.60	?	
93 GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40 ?
94 BRKT-BPR SIDE,RH FRONT	62222-4EA0A	20.90	?	
95 RH REAR C/COMB SEALING	76848-83P00	25.70	?	
96 LAMP COMB RR,RH REAR	26550-4EA0A	323.70	<i>cut</i>	
97 LAMP ASSY-RH	26010-4EA0B	1617.00	<i>one</i>	
98 BRKT MAIN RAIN	28537-3JA0A			47.60 ?

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
99 IU BRACKET	IU			26.00 <i>ok</i>
100 SENSOR A-RAIN WINDSCREEN	28535-00Q0B			210.70 <i>ok</i>
101 SW-AUTO POWER WINDOW RH FRONT	25401-4EA0A			189.90 ?
102 GROMMET FILLER	17240-5M300			11.20 ?
SUB TOTAL		22100.50	0.00	1948.50
LESS DISCOUNT (NETT-30.00%, LIST-45.00%, S/NETT-10.00%)		6630.15	0.00	194.85
GRAND TOTAL		15470.35	0.00	1753.65
OVERALL TOTAL		17224.00		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLP2922A

TOTAL LABOUR CHARGES 11010.00
TOTAL SPARE PARTS CHARGES 17224.00

GRAND TOTAL 28234.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

-LICK

10234

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0477/2018
DATE : 26-OCT-2018

RSC

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER
S(038986)
TEL : 6820 8888
FAX :
ATTN : CLAIM MANAGER

00

OWNER'S NAME : WONG TUCK FOOK
ADDRESS : APT BLK 689 JURONG WEST CENTRAL 1
#05-213
S(640689)
TELEPHONE NO : 96246062

car IH.

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : PNPV2018-00005509
VEHICLE NO : SLP2922A
MODEL CODE : FDRARBZJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0 MY2014
ENGINE NO : MR20455964W-J11W
CHASSIS NO : SJNFBAJ11U1937820
MILEAGE : 26046 KM
DATE IN : 26/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 20/10/2018

- 94568832

Tanjin 97495749.

Ex \$500

Revert

Not Authorise
29/10/18 4:15 pm
sure the car was
resurvey before paint.
12-13 days

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	20.00	✓
2	LC	LEATHER CONDITIONING	80.00	? <i>rec</i> ✓
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$25/PANEL X 10	250.00	200 ✓
4	SDG	INSTALL ULTRAMAX SOLAR FILM - DOOR GLASS RH FRONT	80.00	✓
5	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 06	600.00	500 ✓
6	SFW	INSTALL ULTRAMAX SOLAR FILM - FRT W/SCREEN WUTH ANTI GLARE	150.00	✓
7	SQG	INSTALL ULTRAMAX SOLAR FILM - QUARTER GLASS RH REAR	50.00	✓
8	UG10	RENEW FRONT WINDSHIELD GLASS ASSY. INCL SEALNT	170.00	✓
9	ZZ/001	RENEW WIRE HARDNESS RH FRONT/RH REAR DOOR AND MAIN HARDNESS \$200/PC X 03	600.00	? X <i>hr</i>
10	ZZ/002	R/I DASHBOARD TO RENEW	200.00	? <i>rec</i> ✓
11	ZZ/003	RENEW RH FRONT DOOR GLASS AND TRANSFER RH REAR DOOR GLASS \$80/PC X 02	160.00	✓
12	ZZ/004	RENEW RH REAR 1/4 GLASS	120.00	✓
13	ZZ/005	R/I RH FRONT/REAR SEAT TO ASSIST REPAIR	200.00	120 ✓
14	ZZ/006	R/I PETROL TANK TO ASSIST REPAIR	80.00	✓
15	ZZ/007	RENEW RH FRONT HOODLEDGE	600.00	? ✓
16	ZZ/008	RENEW RH REAR FENDER INCLUDING REPAIR END PANEL ¹⁹⁰	1000.00	950 ⁶⁹⁵ ✓
* 17	ZZ/009	REPAIR LH FRONT FENDER, BOTH FRONT PILLAR, RH CENTER PILLAR, FRONT/REAR BUMPER AND RENEW BONNET,		
18	ZZ/011	S/PAINT FRONT PORTION, BOTH FRONT PILLAR, RH FRONT HOODLEDGE, RH FRONT/REAR DOOR, REAR BUMPER (2 TONE),		200 ✓
19	ZZ/012	RH CENTER PILLAR, END PANEL, RH REAR FENDER, RH FRONT PILLAR AND RH WING MIRROR	3600.00	2000 ✓

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
20	ZZ/013	R/I REVERSE SENSOR TO ASSIST REPAIR	110.00	✓
21	ZZ/014	SUPPLY AND RENEW RH FRONT DOOR LEATHER	300.00	? 250/
22	ZZ/015	VACUMM GLASS CHIP	240.00	? 100/
23	ZZ/016	TRANSFER OR REWIRE RH WING MIRROR LED	120.00	✓
24	ZZ/10	RH FRONT/REAR DOOR	2280.00	? 1170/
<i>continue from no 17</i> TOTAL LABOUR CHARGES			11010.00	