

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1 RH FRONT DOOR TRIMBOARD	80900-4EA3A	1869.50	ll		
2 COVER ASSY INSTRUMENT RH LOWER	68920-4EA1A	76.90	? X	} un	
3 MASK INSTRUMENT RH SIDE	68498-4EA0A	12.30	? X		
4 HARDNESS REAR RH DOOR	24126-4EA1A	475.70	? X		
5 WIRING HARNESS-BODY	24014-4EB1D	1499.10	? X		
6 RH FRONT DOOR WIRE HARDNESS	24124-4EA3C	432.70	cut		
7 COVER-MIRR BODY RH	96373-4EA8E	105.70	mis		
8 MIRROR ASSY-OUT RH	96301-4EA5E	497.10	bro	X un	
9 CANOE RIVET RH FRONT FENDER/BUMPER \$6.50 EA X 07	76882-0H000	45.50	re		
10 CLIP BUMPER REAR \$7.40 EA X 04	85284-JD00A	29.60	re		
11 RETAINER-BUMPER RH REAR	79184-4EA0A	23.80	? X	} part	
12 GROMMET BUMPER REAR \$2.50 EA X 04	63846-5V000	10.00	? X		
13 BRACKET-BUMPER RH REAR	85220-4EA0A	35.90	? X		
14 GLASS RH REAR 1/4	83312-4EA0A				380.00 ? dis
15 GRIP-OUTSIDE RH REAR DOOR	80680-4EH0B	96.20	ca		
16 ESCUT-OUTSIDE HANDLER COVER RH REAR DOOR	80644-4EH0A	32.30	? X	} un	
17 LOCK & REMOTE C RH REAR DOOR	82500-4EA2A	166.70	? X		
18 REGULATOR-DOOR RH REAR	82700-4EA0A	434.20	? X		
19 GLASS RUN RUBBER RH REAR	82330-4EA1A	147.50	re		
20 COVER-SASH INNER RH REAR DOOR	822D4-4EA0A	15.00	? X	} un	
21 CORNER PIECE-RH REAR DOOR	82234-4EA1A	54.00	X		
22 SEAL RUBBER RH REAR DOOR	82834-4EA0A	63.50	re		
23 W/STRIP-RR DOOR RH	82830-4EA0E	132.20	re		
24 CHECK ASSY-RR DOOR RH	82430-4EA0A	39.50	? X un		
25 HINGE-DOOR RH REAR FOOT TOP	82400-4EA0A	56.10	bt		

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 MLDG RR DOOR RH	82820-4EA0A	188.90	mis. ? x nn	
27 MOULDING RH REAR DOOR	82282-4EA1C	100.70	mis /	
28 TAPE-RR DOOR, RH	82812-4EA0A	29.90	ne /	
29 TAPE-RR DOOR, RH	82818-4EA0A	29.90	ne /	
30 DOOR-REAR RH	H2100-HV0MA	1104.80	bt /	
31 HANDLE-PULL RH FRONT DOOR INNER	80950-4EA0A	63.00	? x nn	
32 CAP-DOOR GRIP, RH FRONT	80944-4EA2A	84.00	mis /	
33 FINISR-P/WDW SW RH FRONT DOOR	80960-4EA0A	126.00	? x nn	
34 ESCUTCHEON RH FRONT DOOR COIN HOLDER	80682-4EA1A	63.00	dis /	
35 SEAL A FR DOOR RH	80834-4EA0A	59.40	ne /	
36 GROMMET HANDLER \$2.90 EA X 02	01281-00801			5.80 ne /
37 CLIP HANDLER \$2.50 EA X 02	80897-AM800	5.00	ne /	
38 HANDLE DOOR INSIDE RH FRONT	80670-4EA1A	41.00	? x } ? x }	
39 STRIKER ASSY RH FRONT/REAR DOOR \$57.80 EA X 02	80570-AA20A	115.60	? x }	
40 LOCK & REMOTE C RH FRONT DOOR	80500-4ER2A	166.70	? ✓ dis /	
41 BRKT DOOR RH FRONT/REAR HANDLE \$51.60 EA X 02	80610-5FD0B	103.20	✓ dis /	
42 GSKT-DOOR OUTSIDE RH FRONT DOOR HANDLE \$3.20EAX 04	80652-4EA0A			12.80 ne /
43 GASKET-OUTSIDE HANDLER \$3.20 EA X 04	80654-4EA0A			12.80 ne /
44 HANDLE SET-FRONT RH	80640-4EA2A	165.20	dis /	
45 ESCUT-OUTSIDE HANDLE RH FRONT COVER	80644-4EA2A	32.30	mis /	
46 REGULATOR-DOOR RH FRONT	80700-4ER3C	487.90	? ✓ bt	
47 GLASS-FR DOOR, RH	80300-4EA0A			760.00 buw /
48 GLASS RUN RUB RH FRONT DOOR	80330-4EA2A	161.60	na /	
49 CONN ASSY-HOODLEDGE RH	F4190-4EAMA	129.90	? x nn	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
50 PLATE-CLOSING RH FRONT DOOR	G5130-4EAMA			159.30 ? X 1/2
51 LINK-DOOR STOP RH FRONT DOOR	80430-4EA0A	39.50	? ✓ bt	
52 HINGE ASSY RH FRONT DOOR BOTTOM	82420-4EA0A	56.10	? X un	
53 HINGE RH FRONT/RH REAR DOOR TOP/BOTTOM \$56.10EAX 2	82421-4EA0A	112.20	? X un	
54 SEAL LOWER RH FRONT DOOR RUBBER	80838-4EA0A	70.40	na ✓	
55 WSTRIP ASSY-FRONT RH DOOR FRAME	80830-4EA1E	132.20	na ✓	
56 MOULDING RH FRONT DOOR SASH	80282-4EA1B	100.70	dl ✓	
57 COVER-SASH INNER RH FRONT DOOR	802D4-4EA0A	15.00	mis ✓	
58 MLDG ASSY-FR DOOR RH	80820-4EA0A	188.90	dl ✓	
59 TAPE-FR DOOR, RH	80812-4EA0A	29.90	all ✓	
60 DOOR-FRONT RH	H0100-4EAAA	1104.80	6/ ✓	
61 GROMMET FENDER	01281-00831	1.50	all ✓	
62 CLIP FENDER \$1.20 EA X 05	01553-05131	6.00	all ✓	
63 PROTECTOR-REAR RH FENDER	76748-4EA2A	186.40	? X un	
64 LID GAS FILLER COVER PANEL	G8830-4EAME	93.40	mis ✓	
65 BASE-FILLER LID PETROL	G8120-4EAMA	66.00	? na ✓	
66 RETAINER-TAPPING FENDER RH REAR	G6690-4EAMA	19.30	all ✓	
67 FENDER-REAR RH	G8100-4EAMA	1169.40	bul ✓	
68 WELT BODY RH FRONT DOOR	76922-4EA0A	205.10	? X	} na X
69 FENDER ARC RH REAR	93828-4EA0A	483.00	? X	
70 FENDER-OVER, FR RH ARC	63810-4EA0A	483.00	? X	
71 MOUL-ROOF DRIP RH	73852-4EA1A	213.90	? X	
72 MOULDING RH REAR DOOR PAD	82870-4EA0A	264.80	? ✓ dis ✓	
73 MOULDING RH FRONT DOOR PAD	80870-4EA0A	323.60	? ✓ dis ✓	
74 SEALANT 1/4 GLASS	SEALANT - 3			48.00 all ✓

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
75 SEALANT - FRONT W/SCREEN GLASS	SEALANT - 2			80.00 <i>ng</i>
76 MLDG WS UPPER	72752-4EA1A	134.60	<i>ue</i>	
77 RUBBER-DUM	G2716-89900	60.20	<i>ue</i>	
78 GLASS-FR WIND	72700-4EA4A	1244.60	<i>ue</i>	
79 VENTILATOR RH DASHBOARD	68760-4EA0A	100.50	? <i>de</i>	
80 PANEL & PAD	68200-4EA1A	1374.50	? <i>de</i>	
81 HOOK ASSY-HOOD	65603-4EA0A	82.80	? <i>x nn</i>	
82 MALE ASSY-HOOD	65601-4EA0A	67.60	? <i>x nn</i>	
83 HINGE HOOD RH	65400-4EA0A	56.10	<i>bt</i>	
84 HOOD HINGE LH	65401-4EA0A	56.10	<i>bt</i>	
85 CLIP-HOOD INSUL \$1.60 EA X 13	65846-30P00	20.80	<i>wo</i>	
86 INSULATOR-HOOD	65840-4EA0A	185.50	<i>de</i>	
87 HOOD	F5100-4EAAA	961.40	<i>bt</i>	
88 COVER-HOLE FENDER SIDE RH	66898-4EA0B	57.70	? <i>de</i>	
89 CLIP FENDER PROTECTOR \$1.30 EA X 13	01553-09321	16.90	? <i>x nn</i>	
90 PROTECTOR-FR,RH FENDER	63842-HV00A	87.50	? <i>x nn</i>	
91 FENDER-FRONT RH	F3100-4EAMB	622.70	<i>bt</i>	
92 CLIP BUMPER \$1.20 EA X 08	01553-05933	9.60	? <i>x nn</i>	
93 GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40 ? <i>x</i>
94 BRKT-BPR SIDE,RH FRONT	62222-4EA0A	20.90	? <i>x nn</i>	
95 RH REAR C/COMB SEALING	76848-83P00	25.70	? <i>x nn</i>	
96 LAMP COMB RR,RH REAR	26550-4EA0A	323.70	<i>cut</i>	
97 LAMP ASSY-RH	26010-4EA0B	1617.00	<i>ue</i>	
98 BRKT MAIN RAIN	28537-3JA0A			47.60 ? <i>x</i>

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
99 IU BRACKET	IU			26.00	OK ✓
100 SENSOR A-RAIN WINDSCREEN	28535-00Q0B			210.70	OK ✓
101 SW-AUTO POWER WINDOW RH FRONT	25401-4EA0A			189.90	? X OK
102 GROMMET FILLER	17240-5M300			11.20	? X OK
SUB TOTAL		22100.50	0.00	1948.50	
LESS DISCOUNT (NETT-30.00%, LIST-45.00%, S/NETT-10.00%)		6630.15	0.00	194.85	
GRAND TOTAL		15470.35	0.00	1753.65	
OVERALL TOTAL		17224.00			

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLP2922A

TOTAL LABOUR CHARGES 11010.00
TOTAL SPARE PARTS CHARGES 17224.00

GRAND TOTAL 28234.00 *

28234.03

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

LICK

10234

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0477/2018
DATE : 26-OCT-2018

RSC

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER
S(038986)
TEL : 6820 8888
FAX :
ATTN : CLAIM MANAGER

OD

OWNER'S NAME : WONG TUCK FOOK
ADDRESS : APT BLK 689 JURONG WEST CENTRAL 1
#05-213
S(640689)
TELEPHONE NO : 96246062

car IH.

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : PNPV2018-00005509
VEHICLE NO : SLP2922A
MODEL CODE : FDRARBEJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0 MY2014
ENGINE NO : MR20455964W-J11WW
CHASSIS NO : SJNFBAJ11U1937820
MILEAGE : 26046 KM
DATE IN : 26/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 20/10/2018

- 94568832

Tanpin 97495799.

Ex \$500

Revert
Not Authorise
29/10/18 4:15 pm
sure like out with
Resony before print.
12-13 days

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	PHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	20.00	✓
2	LC	LEATHER CONDITIONING	80.00	✓
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$25/PANEL X 10	250.00	200
4	SDG	INSTALL ULTRAMAX SOLAR FILM - DOOR GLASS RH FRONT	80.00	✓
5	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 06	600.00	500
6	SFW	INSTALL ULTRAMAX SOLAR FILM - FRT W/SCREEN WUTH ANTI GLARE	150.00	✓
7	SQG	INSTALL ULTRAMAX SOLAR FILM - QUARTER GLASS RH REAR	50.00	✓
8	UG10	RENEW FRONT WINDSHIELD GLASS ASSY. INCL SEALNT	170.00	✓
9	ZZ/001	RENEW WIRE HARDNESS RH FRONT/RH REAR DOOR AND MAIN HARDNESS \$200/PC X 03	600.00	?
10	ZZ/002	R/I DASHBOARD TO RENEW	200.00	✓
11	ZZ/003	RENEW RH FRONT DOOR GLASS AND TRANSFER RH REAR DOOR GLASS \$80/PC X 02	160.00	✓
12	ZZ/004	RENEW RH REAR 1/4 GLASS	120.00	✓
13	ZZ/005	R/I RH FRONT/REAR SEAT TO ASSIST REPAIR	200.00	120
14	ZZ/006	R/I PETROL TANK TO ASSIST REPAIR	80.00	✓
15	ZZ/007	RENEW RH FRONT HOODLEDGE	600.00	✓
16	ZZ/008	RENEW RH REAR FENDER INCLUDING REPAIR END PANEL	1000.00	190
17	ZZ/009	REPAIR LH FRONT FENDER, BOTH FRONT PILLAR, RH CENTER PILLAR, FRONT/REAR BUMPER AND RENEW BONNET,	695	
18	ZZ/011	S/PAINT FRONT PORTION, BOTH FRONT PILLAR, RH FRONT HOODLEDGE, RH FRONT/REAR DOOR, REAR BUMPER(2 TONE),	200	
19	ZZ/012	RH CENTER PILLAR, END PANEL, RH REAR FENDER, RH FRONT PILLAR AND RH WING MIRROR	3600.00	2000 10 portion

COUNT
 22/10
 1820

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
20	ZZ/013	R/I REVERSE SENSOR TO ASSIST REPAIR	110.00 ✓	
21	ZZ/014	SUPPLY AND RENEW RH FRONT DOOR LEATHER	300.00	250.
22	ZZ/015	VACUMM GLASS CHIP	240.00	100
23	ZZ/016	TRANSFER OR REWIRE RH WING MIRROR LED	120.00 ✓	
24	ZZ/10	RH FRONT/REAR DOOR	2280.00	
TOTAL LABOUR CHARGES			1170	
			11010.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS-DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 RH FRONT DOOR TRIMBOARD	80900-4EA3A	1869.50	ll ✓	
2 COVER ASSY INSTRUMENT RH LOWER	68920-4EA1A	76.90	?	
3 MASK INSTRUMENT RH SIDE	68498-4EA0A	12.30	?	
4 HARDNESS REAR RH DOOR	24126-4EA1A	475.70	?	
5 WIRING HARNESS-BODY	24014-4EB1D	1499.10	?	
6 RH FRONT DOOR WIRE HARDNESS	24124-4EA3C	432.70	cut ✓	
7 COVER-MIRR BODY RH	96373-4EA8E	105.70	mis ✓	
8 MIRROR ASSY-OUT RH	96301-4EA5E	497.10	bro ✓	
9 CANOE RIVET RH FRONT FENDER/BUMPER \$6.50 EA X 07	76882-0M000	45.50	re ✓	
10 CLIP BUMPER REAR \$7.40 EA X 04	85284-JD00A	29.60	re ✓	
11 RETAINER-BUMPER RH REAR	79184-4EA0A	23.80	?	
12 GROMMET BUMPER REAR \$2.50 EA X 04	63846-5V000	10.00	?	
13 BRACKET-BUMPER RH REAR	85220-4EA0A	35.90	?	
14 GLASS RH REAR 1/4	83312-4EA0A			re ✓ 380.00
15 GRIP-OUTSIDE RH REAR DOOR	806B0-4EH0B	96.20	af ✓	
16 ESCUT-OUTSIDE HANDLER COVER RH REAR DOOR	80644-4EH0A	32.30	?	
17 LOCK & REMOTE C RH REAR DOOR	82500-4EA2A	166.70	?	
18 REGULATOR-DOOR RH REAR	82700-4EA0A	434.20	?	
19 GLASS RUN RUBBER RH REAR	82330-4EA1A	147.50	re ✓	
20 COVER-SASH INNER RH REAR DOOR	822D4-4EA0A	15.00	?	
21 CORNER PIECE-RH REAR DOOR	82234-4EA1A	54.00	?	
22 SEAL RUBBER RH REAR DOOR	82834-4EA0A	63.50	re ✓	
23 W/STRIP-RR DOOR RH	82830-4EA0E	132.20	re ✓	
24 CHECK ASSY-RR DOOR RH	82430-4EA0A	39.50	?	
25 HINGE-DOOR RH REAR FOUR TOP	82400-4EA0A	56.10	bt ✓	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
26	MLDG RR DOOR RH	82820-4EA0A	188.90	<i>mis?</i>	
27	MOULDING RH REAR DOOR	82282-4EA1C	100.70	<i>Mis</i>	
28	TAPE-RR DOOR,RH	82812-4EA0A	29.90	<i>na</i>	
29	TAPE-RR DOOR,RH	82818-4EA0A	29.90	<i>na</i>	
30	DOOR-REAR RH	H2100-HV0MA	1104.80	<i>bl</i>	
31	HANDLE-PULL RH FRONT DOOR INNER	80950-4EA0A	63.00	<i>?</i>	
32	CAP-DOOR GRIP,RH FRONT	80944-4EA2A	84.00	<i>mis</i>	
33	FINISR-P/WDW SW RH FRONT DOOR	80960-4EA0A	126.00	<i>?</i>	
34	ESCUTCHEON RH FRONT DOOR COIN HOLDER	80682-4EA1A	63.00	<i>dis</i>	
35	SEAL A FR DOOR RH	80834-4EA0A	59.40	<i>na</i>	
36	GROMMET HANDLER \$2.90 EA X 02	01281-00801			5.80 <i>na</i>
37	CLIP HANDLER \$2.50 EA X 02	80897-AM800	5.00	<i>na</i>	
38	HANDLE DOOR INSIDE RH FRONT	80670-4EA1A	41.00	<i>?</i>	
39	STRIKER ASSY RH FRONT/REAR DOOR \$57.80 EA X 02	80570-AA20A	115.60	<i>?</i>	
40	LOCK & REMOTE C RH FRONT DOOR	80500-4ER2A	166.70	<i>?</i>	
41	BRKT DOOR RH FRONT/REAR HANDLE \$51.60 EA X 02	80610-5PD0B	103.20	<i>?</i>	
42	GSKT-DOOR OUTSIDE RH FRONT DOOR HANDLE \$3.20EAX 04	80652-4EA0A			12.80 <i>na</i>
43	GASKET-OUTSIDE HANDLER \$3.20 EA X 04	80654-4EA0A			12.80 <i>na</i>
44	HANDLE SET-FRONT RH	80640-4EA2A	165.20	<i>dis</i>	
45	ESCUOT-OUTSIDE HANDLE RH FRONT COVER	80644-4EA2A	32.30	<i>mis</i>	
46	REGULATOR-DOOR RH FRONT	80700-4EA3C	487.90	<i>?</i>	
47	GLASS-FR DOOR,RH	80300-4EA0A			760.00 <i>bu</i>
48	GLASS RUN RUB RH FRONT DOOR	80330-4EA2A	161.60	<i>na</i>	
49	CONN ASSY-HOODLEDGE RH	F4190-4EAMA	129.90	<i>?</i>	

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

		DAMAGED PARTS & PRICES		
S/NO-PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
50 PLATE-CLOSING RH FRONT DOOR	G5130-4EAMA			159.30 ?
51 LINK-DOOR STOP RH FRONT DOOR	80430-4EA0A	39.50	?	
52 HINGE ASSY RH FRONT DOOR BOTTOM	82420-4EA0A	56.10	?	
53 HINGE RH FRONT/RH REAR DOOR TOP/BOTTOM \$56.10EAX 2	82421-4EA0A	112.20	?	
54 SEAL LOWER RH FRONT DOOR RUBBER	80838-4EA0A	70.40	NA ✓	
55 WSTRIP ASSY-FRONT RH DOOR FRAME	80830-4EA1E	132.20	NA ✓	
56 MOULDING RH FRONT DOOR SASH	80282-4EA1B	100.70	de ✓	
57 COVER-SASH INNER RH FRONT DOOR	802D4-4EA0A	15.00	ms ✓	
58 MLDG ASSY-FR DOOR RH	80820-4EA0A	188.90	de ✓	
59 TAPE-FR DOOR,RH	80812-4EA0A	29.90	de ✓	
60 DOOR-FRONT RH	H0100-4EAAA	1104.80	de ✓	
61 GROMMET FENDER	01281-00831	1.50	de ✓	
62 CLIP FENDER \$1.20 EA X 05	01553-05131	6.00	de ✓	
63 PROTECTOR-REAR RH FENDER	76748-4EA2A	186.40	?	
64 LID GAS FILLER COVER PANEL	G8830-4EAME	93.40	ms ✓	
65 BASE-FILLER LID PETROL	G8120-4EAMA	66.00	?	
66 RETAINER-TAPPING FENDER RH REAR	G6690-4EAMA	19.30	de ✓	
67 FENDER-REAR RH	G8100-4EAMA	1169.40	bul ✓	
68 WELT BODY RH FRONT DOOR	76922-4EA0A	205.10	?	
69 FENDER ARC RH REAR	93828-4EA0A	483.00	?	
70 FENDER-OVER,FR RH ARC	63810-4EA0A	483.00	?	
71 MOUL-ROOF DRIP RH	73852-4EA1A	213.90	?	
72 MOULDING RH REAR DOOR PAD	82870-4EA0A	264.80	?	
73 MOULDING RH FRONT DOOR PAD	80870-4EA0A	323.60	?	
74 SEALANT 1/4 GLASS	SEALANT - 3			48.00 de ✓

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
75 SEALANT - FRONT W/SCREEN GLASS	SEALANT - 2			80.00 <i>net</i>
76 MLDG WS UPPER	72752-4EA1A	134.60	<i>net</i>	
77 RUBBER-DUM	G2716-89900	60.20	<i>net</i>	
78 GLASS-FR WIND	72700-4EA4A	1244.60	<i>net</i>	
79 VENTILATOR RH DASHBOARD <i>Accept</i>	68760-4EA0A	100.50		<i>dis</i>
80 PANEL & PAD	68200-4EA1A	1374.50		<i>de</i>
81 HOOK ASSY-HOOD	65603-4EA0A	82.80	?	
82 MALE ASSY-HOOD	65601-4EA0A	67.60	?	
83 HINGE HOOD RH	65400-4EA0A	56.10	<i>bt</i>	
84 HOOD HINGE LH	65401-4EA0A	56.10	<i>bt</i>	
85 CLIP-HOOD INSUL \$1.60 EA X 13	65846-30F00	20.80	<i>net</i>	
86 INSULATOR-HOOD	65840-4EA0A	185.50	<i>de</i>	
87 HOOD	F5100-4EAAA	961.40	<i>bt</i>	
88 COVER-HOLE FENDER SIDE RH	66898-4EA0B	57.70	?	
89 CLIP FENDER PROTECTOR \$1.30 EA X 13	01553-09321	16.90	?	
90 PROTECTOR-FR,RH FENDER	63842-HV00A	87.50	?	
91 FENDER-FRONT RH	F3100-4EAMB	622.70	<i>bt</i>	
92 CLIP BUMPER \$1.20 EA X 08	01553-05933	9.60	?	
93 GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40 ?
94 BRKT-BPR SIDE,RH FRONT	62222-4EA0A	20.90	?	
95 RH REAR C/COMB SEALING	76848-83P00	25.70	?	
96 LAMP COMB RR,RH REAR	26550-4EA0A	323.70	<i>cut</i>	
97 LAMP ASSY-RH	26010-4EA0B	1617.00	<i>cut</i>	
98 BRKT MAIN RAIN	28537-3JA0A			47.60 ?

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
99 IU BRACKET	IU			26.00 <i>OK</i>
100 SENSOR A-RAIN WINDSCREEN	28535-00Q0B			210.70 <i>OK</i>
101 SW-AUTO POWER WINDOW RH FRONT	25401-4EA0A			189.90 ?
102 GROMMET FILLER	17240-5M300			11.20 ?
SUB TOTAL		22100.50	0.00	1948.50
LESS DISCOUNT (NETT-30.00%, LIST-45.00%, S/NETT-10.00%)		6630.15	0.00	194.85
GRAND TOTAL		15470.35	0.00	1753.65
OVERALL TOTAL		17224.00		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

103 *PH Outer Reinforcement* *bt*
F4180-4EAM7 - ORD

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLP2922A

TOTAL LABOUR CHARGES	11010.00
TOTAL SPARE PARTS CHARGES	17224.00
GRAND TOTAL	28234.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

15-Mar-2018

INS/IC/LAW/0477/2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER
Singapore 038986

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SLP2922A
POLICY NO. : PNPV2018-000005509

Further to our claim we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

<u>Replacement of Damaged Items</u>			
1	COVER-COWL TOP	dev	\$144.90 N
2	LOCK&ROD ASSY	bt	\$45.30 N
3	SPRING DOOR	dis	\$6.00 N
4	ADJUSTER-S/BELT	aut	\$139.80 S/N
5	REINF-HOODLEDGE RH OUTER	dev	\$355.00 N
6	SUNDRIES	re	\$5.50 S/N
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
		TOTAL	\$696.50 697.10

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully

TAN CHONG MOTOR SALES PTE LTD

LAWRENCE TEO
Insurance Claim Dept

Cc: Surveyor

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0477/2018
DATE : 26-OCT-2018

16/23/19

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER
S(038986)
TEL : 6820 8888
FAX :
ATTN : CLAIM MANAGER

T. S. S. S. S.

OWNER'S NAME : NGONG TUCK FOCK
ADDRESS : APT BLK 689 JURONG WEST CENTRAL 1
#05-213
S(640689)
TELEPHONE NO : 96246062



TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : PNPV2018-00005509
VEHICLE NO : SLP2922A
MODEL CODE : FDRARB2J11EWAPAJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0
ENGINE NO : MR20455964W-J11WW
CHASSIS NO : SJNFBAJ11U1937820
MILEAGE : 26046 KM
DATE IN : 26/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 500.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 20/10/2018

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	20.00	20.00
2	LC	LEATHER CONDITIONING	80.00	80.00
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$25/PANEL X 10	250.00	200.00
4	SDG	INSTALL ULTRAMAX SOLAR FILM - DOOR GLASS RH FRONT	80.00	80.00
5	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 06	600.00	500.00
6	SEW	INSTALL ULTRAMAX SOLAR FILM - FRT W/SCREEN WUTH ANTI GLARE	150.00	150.00
7	SQG	INSTALL ULTRAMAX SOLAR FILM - QUARTER GLASS RH REAR	50.00	50.00
8	UG10	RENEW FRONT WINDSHIELD GLASS ASSY. INCL SEALHT	170.00	170.00
9	EZ/001	RENEW WIRE HARDNESS RH FRONT/RH REAR DOOR AND MAIN HARDNESS \$200/PC X 03	600.00	.00
10	EZ/002	R/I DASHBOARD TO RENEW	200.00	200.00
11	EZ/003	RENEW RH FRONT DOOR GLASS AND TRANSFER RH REAR DOOR GLASS \$80/PC X 02	160.00	160.00
12	EZ/004	RENEW RH REAR 1/4 GLASS	120.00	120.00
13	EZ/005	R/I RH FRONT/REAR SEAT TO ASSIST REPAIR	200.00	120.00
14	EZ/006	R/I PETROL TANK TO ASSIST REPAIR	80.00	80.00
15	EZ/007	RENEW RH FRONT HOODLEDGE	600.00	600.00
16	EZ/008	RENEW RH REAR FENDER INCLUDING REPAIR END PANEL	1000.00	695.00
17	EZ/009	REPAIR LH FRONT FENDER, BOTH FRONT PILLAR, RH CENTER PILLAR, FRONT/REAR BUMPER AND RENEW BONNET,		
18	EZ/011	S/PAINT FRONT PORTION, BOTH FRONT PILLAR, RH FRONT HOODLEDGE, RH FRONT/REAR DOOR, REAR BUMPER(2 TONE),		
19	EZ/012	RH CENTER PILLAR, END PANEL, RH REAR FENDER, RH FRONT PILLAR AND RH WING MIRROR	3600.00	2200.00

*at RH front
 fenders - Ref Panel
 200 of 2004 - 4.2.2004*

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
20	ZZ/013	R/I REVERSE SENSOR TO ASSIST REPAIR	110.00	110.00
21	ZZ/014	SUPPLY AND RENEW RH FRONT DOOR LEATHER	300.00	250.00
22	ZZ/015	VACUUM GLASS CHIP	240.00	100.00
23	ZZ/016	TRANSFER OR REWIRE RH WING MIRROR LED	120.00	120.00
24	ZZ/10	RH FRONT/REAR DOOR	2280.00	1170.00
TOTAL LABOUR CHARGES			11010.00	7175.00

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	SUNDRIES - SUPPLEMENTARY <i>plus parts</i>	NPN <i>Comp</i>			5.50	OK
2	REINF-HOODLEDGE RH OUTER - SUPPLEMENTARY <i>plus</i>	F4180-4EA0A	355.00			OK
3	PROTECTOR-REAR RH FENDER	76748-4EA2A	166.40			X
4	MIRROR ASSY-OUT RH	96301-4EA5E	497.10			X
5	ADJUSTER-S/BELT - SUPPLEMENTARY <i>plus</i>	87824-4EA0A			139.80	OK
6	SPRING DOOR - SUPPLEMENTARY <i>plus</i>	78836-AG000	6.60			OK
7	LOCK&ROD ASSY - SUPPLEMNETARY <i>plus</i>	78827-4EA1A	45.30			OK
8	COVER-COWL TOP - SUPPLEMNETARY <i>plus</i>	66862-4EA1A	144.90			OK
9	COVER-MIRR BODY RH	96373-4EA8E	105.70			OK
10	CANOE RIVET RH FRONT FENDER/BUMPER \$6.50 EA X 07	76882-0M000	45.50			OK
11	CLIP BUMPER REAR \$7.40 EA X 04	85284-JD00A	29.60			OK
12	RETAINER-BUMPER RH REAR	79184-4EA0A	23.80			X
13	GROMMET BUMPER REAR \$2.50 EA X 04	63846-5V000	10.00			X
14	BRACKET-BUMPER RH REAR	85220-4EA0A	35.90			X
15	GLASS RH REAR 1/4 <i>plus</i>	83312-4EA0A			380.00	OK
16	GRIP-OUTSIDE RH REAR DOOR	80680-4EH0B	96.20			OK
17	ESCUT-OUTSIDE HANDLER COVER RH REAR DOOR	80644-4EH0A	32.30			X
18	GROMMET HANDLER \$2.90 EA X 02	01281-00801			5.80	OK
19	CLIP HANDLER \$2.50 EA X 02	80897-AM800	5.00			OK
20	HANDLE DOOR INSIDE RH FRONT	80670-4EA1A	41.00			X
21	STRIKER ASSY RH FRONT/REAR DOOR \$57.80 EA X 02	80570-AA20A	115.60			X
22	LOCK & REMOTE C RH FRONT DOOR <i>plus</i>	80500-4ER2A	166.70			OK
23	BRKT DOOR RH FRONT/REAR HANDLE \$51.60 EA X 02 <i>plus</i>	80610-5FD0B	103.20			OK
24	GSKT-DOOR OUTSIDE RH FRONT DOOR HANDLE \$3.20EA X 04	80652-4EA0A			12.80	OK
25	GASKET-OUTSIDE HANDLER \$3.20 EA X 04	80654-4EA0A			12.80	OK

TAN CHONG MOTOR SALES PTE. LTD.
 DUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 HANDLE SET-FRONT RH	80640-4EA2A	165.20		OK
27 ESCUT-OUTSIDE HANDLE RH FRONT COVER	80644-4EA2A	32.30		OK
28 REGULATOR-DOOR RH FRONT <i>plano</i>	80700-4EA3C	487.90		OK
29 GLASS-FR DOOR, RH	80300-4EA0A		760.00	OK
30 GLASS RUN RUB RH FRONT DOOR	80330-4EA2A	161.60		OK
31 CONN ASSY-HOODLEDGE RH	F4190-4EAMA	129.90		X
32 PLATE-CLOSING RH FRONT DOOR	G5130-4EAMA		159.30	X
33 LINK-DOOR STOP RH FRONT DOOR	80430-4EA0A	39.50		OK
34 HINGE ASSY RH FRONT DOOR BOTTOM	82420-4EA0A	56.10		X
35 HINGE RH FRONT/RH REAR DOOR TOP/BOTTOM \$56.10EAX 2	82421-4EA0A	112.20		X
36 SEAL LOWER RH FRONT DOOR RUBBER	80838-4EA0A	70.40		OK
37 WSTRIP ASSY-FRONT RH DOOR FRAME	80830-4EA1E	132.20		OK
38 HOULDING RH FRONT DOOR SASH	80282-4EA1B	100.70		OK
39 COVER-SASH INNER RH FRONT DOOR	802D4-4EA0A	15.00		OK
40 MLDG ASSY-FR DOOR RH	80820-4EA0A	188.90		OK
41 TAPE-FR DOOR, RH	80812-4EA0A	29.90		OK
42 DOOR-FRONT RH	H0100-4EAAA	1104.80		OK
43 GROHMET FENDER	01281-00831	1.50		OK
44 CLIP FENDER \$1.20 EA X 05	01553-05131	6.00		OK
45 LID GAS FILLER COVER PANEL	G8830-4EAME	93.40		OK
46 BASE-FILLER LID PETROL <i>not constant fender</i>	G8120-4EAMA	66.00		OK
47 RETAINER-TAPPING FENDER RH REAR	G6690-4EAMA	19.30		OK
48 FENDER-REAR RH	G8100-4EAMA	1169.40		OK
49 WELT BODY RH FRONT DOOR	76922-4EA0A	205.10		X

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SKOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
50 FENDER ARC RH REAR	93828-4EA0A	483.00			X
51 FENDER-OVER,FR RH ARC	63810-4EA0A	483.00			X
52 MOUL-ROOF DRIP RH	73852-4EA1A	213.90			X
53 MOULDING RH REAR DOOR PAD <i>photo</i>	82870-4EA0A	264.80			OK
54 MOULDING RH FRONT DOOR PAD <i>photo</i>	80870-4EA0A	323.60			OK
55 SEALANT 1/4 GLASS	SEALANT - 3			48.00	OK
56 SEALANT - FRONT W/SCREEN GLASS	SEALANT - 2			80.00	OK
57 MLDG WS UPPER	72752-4EA1A	134.60			OK
58 RUBBER-DUM	G2716-89900	60.20			OK
59 GLASS-FR WIND	72700-4EA4A	1244.60			OK
60 VENTILATOR RH DASHBOARD <i>photo</i>	68760-4EA0A	100.50			OK
61 PANEL & PAD <i>photo</i>	68200-4EA1A	1374.50			OK
62 HOOK ASSY-HOOD	65603-4EA0A	82.80			X
63 MALE ASSY-HOOD	65601-4EA0A	67.60			X
64 HOOD HINGE LH	65401-4EA0A	56.10			OK
65 CLIP-HOOD INSUL \$1.60 EA X 13	65846-30F00	20.80			OK
66 INSULATOR-HOOD	65840-4EA0A	185.50			OK
67 HOOD	F5100-4EAAA	961.40			OK
68 COVER-HOLE FENDER SIDE RH <i>photo</i>	66898-4EA0B	57.70			OK
69 CLIP FENDER PROTECTOR \$1.30 EA X 13	01553-09321	16.90			X
70 PROTECTOR-FR,RH FENDER	63842-HV00A	87.50			X
71 FENDER-FRONT RH	F3100-4EAMB	622.70			OK
72 CLIP BUMPER \$1.20 EA X 08	01553-05933	9.60			X
73 GROMMET BUMPER \$2.20 EA X 02	01281-00111			4.40	X
74 BRKT-BFR SIDE,RH FRONT	62222-4EA0A	20.90			X

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
75 RH REAR C/COMB SEALING	76848-83P00	25.70			X
76 LAMP COMB RR,RH REAR	26550-4EA0A	323.70			OK
77 LAMP ASSY-RH	26010-4EA0B	1617.00			OK
78 BRKT MAIN RAIN	28537-3JA0A			47.60	X
79 IU BRACKET	IU			26.00	OK
80 SENSOR A-RAIN WINDSCREEN	28535-00Q0B			210.70	OK
81 SW-AUTO POWER WINDOW RH FRONT	25401-4EA0A			189.90	X
82 RH FRONT DOOR TRINBOARD	80900-4EA3A	1869.50			OK
83 COVER ASSY INSTRUMENT RH LOWER	68920-4EA1A	76.90			X
84 MASK INSTRUMENT RH SIDE	68498-4EA0A	12.30			X
85 HARDNESS REAR RH DOOR	24126-4EA1A	475.70			X
86 WIRING HARNESS-BODY	24014-4EB1D	1499.10			X
87 RH FRONT DOOR WIRE HARDNESS	24124-4EA3C	432.70			OK
88 LOCK & REMOTE C RH REAR DOOR	82500-4EA2A	166.70			X
89 REGULATOR-DOOR RH REAR	82700-4EA0A	434.20			X
90 GLASS RUN RUBBER RH REAR	82330-4EA1A	147.50			OK
91 COVER-SASH INNER RH REAR DOOR	822D4-4EA0A	15.00			X
92 CORNER PIECE-RH REAR DOOR	82234-4EA1A	54.00			X
93 SEAL RUBBER RH REAR DOOR	82834-4EA0A	63.50			OK
94 W/STRIP-RR DOOR RH	82830-4EADE	132.20			OK
95 CHECK ASSY-RR DOOR RH	82430-4EA0A	39.50			X
96 HINGE-DOOR RH REAR POOR TOP	82400-4EA0A	56.10			OK
97 MLDG RR DOOR RH	82820-4EA0A	188.90			X
98 MOULDING RH REAR DOOR	82282-4EA1C	100.70			OK

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAR W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP2922A

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
99 TAPE-RR DOOR, RH	82812-4EA0A	29.90		OK
100 TAPE-RR DOOR, RH	82818-4EA0A	29.90		OK
101 DOOR-REAR RH	H2100-HV0MA	1104.80		OK
102 HANDLE-PULL RH FRONT DOOR INNER	80950-4EA0A	63.00		X
103 CAP-DOOR GRIP, RH FRONT	80944-4EA2A	84.00		OK
104 FINISR-P/NDW SW RH FRONT DOOR	80960-4EA0A	126.00		X
105 ESCUTCHEON RH FRONT DOOR COIN HOLDER	80682-4EA1A	63.00		OK
106 SEAL A FR DOOR RH	<i>photo</i> 80834-4EA0A	59.40		OK
107 HINGE HOOD RH	65400-4EA0A	56.10		OK
108 GROMMET FILLER	17240-5M300		11.20	X
SUB TOTAL		16564.70	0.00	1681.40
LESS DISCOUNT (NETT-30.00%, LIST-45.00%, S/NETT-10.00%)		4969.41	0.00	168.14
GRAND TOTAL		11595.29	0.00	1513.26
OVERALL TOTAL		13108.55		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLP2922A

NETT ITEM	16564.70
LESS 30.00%	-4969.41
NETT AMOUNT	11595.29
LIST ITEM	0.00
LESS 45.00%	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	1681.40
LESS 10.00%	-168.14
SPECIAL NETT AMOUNT	1513.26
TOTAL LABOUR CHARGES	7175.00
TOTAL SPARE PARTS CHARGES	13108.55
TOTAL CHARGES	20283.55
LESS EXCESS	500.00
TOTAL	19783.55
ADD 7 % GST	1384.85
GRAND TOTAL	21168.40

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Oct 2018 Edit Reg		29 Oct 2018 00:00 Edit Adj Rpt	S\$20,283.55 Edit Estimates	S\$20,283.55 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	WONG TUCK FOOK , ID: S1795004E		
Vehicle Reg. No.:	SLP2922A	Date of Loss:	20/10/2018 00:00 - :59 [16 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800013658	Policy/Cover Note No.:	PNPV2018-00005509 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Tan Chong Motor Sales (HQ) 913 Bukit Timah Road, 589622 Bukit Timah - Tel: 64601694		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/11/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (09/04/2019): Alert - Adj Mandate Approved (S\$20283.55) - SLP2922A - Claim Handler: Clara Li Z...
- FWD_SG (30/10/2018): Alert - Adj Mandate Approved (S\$16000.00) - SLP2922A - Claim Handler: Clara Li Z...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP2922A (1201800013658)
 OD
 Oct 20 2018 12:00AM
 [WONG TUCK FOOK]
 Tan Chong Motor Sales

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▾

Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 14:24	Adjuster Immediate Advice	Load HTM	
2	09/04/19 11:34	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
2	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
3	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
9	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
10	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
11	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
12	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
13	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
14	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
15	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
16	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
17	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
18	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
19	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
20	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
21	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
22	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
23	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
24	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
25	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
26	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
27	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
28	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
29	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
30	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
31	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>
32	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
34	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
35	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
38	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
40	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
41	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
44	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
46	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
47	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
48	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
49	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
50	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
51	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
52	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
53	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
54	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
55	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
56	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
57	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
58	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
59	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
60	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
61	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
62	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
63	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
64	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
65	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
66	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
67	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
68	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
69	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
70	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
71	09/04/19 11:20	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
72	09/04/19 11:20	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
73	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
74	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
75	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
76	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
77	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
78	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
79	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
80	09/04/19 11:20	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
82	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
83	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
84	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
85	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
86	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
87	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
88	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
89	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
90	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
91	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
92	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
93	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
94	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
95	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
96	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
97	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
98	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
99	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
100	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
101	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
102	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
103	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
104	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
105	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
106	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
107	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
108	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
109	09/04/19 11:20	General View	 Load JPG	<input checked="" type="checkbox"/>
110	09/04/19 11:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	09/04/19 11:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	09/04/19 11:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	09/04/19 11:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	09/04/19 11:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	09/04/19 11:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	09/04/19 11:24	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	09/04/19 11:24	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
129	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
130	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
131	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
132	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
133	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
134	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
135	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
136	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
137	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
138	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
139	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
140	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
141	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
142	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
143	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
144	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
145	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
146	09/04/19 11:24	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
147	09/04/19 11:25	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
148	09/04/19 11:25	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
149	09/04/19 11:25	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
150	09/04/19 11:25	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
151	09/04/19 11:25	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
152	09/04/19 11:25	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
153	09/04/19 11:25	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
154	09/04/19 11:25	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
155	09/04/19 11:25	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
156	09/04/19 11:25	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	30/10/18 11:48	ESTIMATE		Load PDF <input type="checkbox"/>
2	09/04/19 11:28	SUPPLEMENTARY LIST		Load PDF <input type="checkbox"/>

No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	30/10/18 14:43	Status of Driving Licence		Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18019592/T1QD3S2

Date: 23/04/2019

REFERENCE

Insured/Claimant: WONG TUCK FOOK Policy No: PNPV2018-00005509
Date of Loss: 20/10/2018 Nature of Claim: OD Claim No: 1201800013658

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP2922A**
Make & Model: NISSAN QASHQAI, 2.0 CVT ABS D/AIRBAG 2WD 5DR Engine No: MR20455964W
S/R (A)
Reg. Date: 31/05/2017 (Man. Year: 2017) Chassis No: SJNFBAJ11U1937820
Colour: Grey Odometer: 26046 km
Engine Capacity: 1997 cc
Market Value/New Car Price: S\$94,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R19 Rear Tyre Size: 225/45R19
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,741.03	13,108.55	4,632.48	26.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,010.00	7,175.00	3,835.00	34.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,751.03	20,283.55	8,467.48	29.45
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	28,251.03	19,783.55	8,467.48	29.97
+ GST 7.00/7.00% (S\$)	1,977.57	1,384.85	592.72	29.97
Nett Amount (S\$)	30,228.60	21,168.40	9,060.20	29.97

INSPECTION

Date of Assignment: 29/10/2018
Date Inspected: 29/10/2018 Inspected At: Tan Chong Motor Sales (HQ)
913 Bukit Timah Road
Singapore 589622
Estimated Period of Repair: 13.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Apr 2019)

Parts: M1-SUV NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLP2922A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR TRIMBOARD	Deformed	1,869.50 FN	*1,869.50 FN
2	1		*COVER ASSY INSTRUMENT RH LOWER	Not Necessary	76.90 FN	*- FN
3	1		*MASK INSTRUMENT RH SIDE	Not Necessary	12.30 FN	*- FN
4	1		*HARDNESS REAR RH DOOR	Not Necessary	475.70 FN	*- FN
5	1		*WIRING HARNESS - BODY	Not Necessary	1,499.10 FN	*- FN
6	1		*RH FRONT DOOR WIRE HARDNESS	Cut	432.70 FN	*432.70 FN
7	1		*COVER - MIRR BODY RH	Missing	105.70 FN	*105.70 FN
8	1		*MIRROR ASSY - OUT RH	Not Necessary	497.10 FN	*- FN
9	7		*CANOE RIVET RH FRONT FENDER / BUMPER	Necessary	45.50 FN	*45.50 FN
10	4		*CLIP BUMPER REAR	Necessary	29.60 FN	*29.60 FN
11	1		*RETAINER - BUMPER RH REAR	Not Necessary	23.80 FN	*- FN
12	4		*GROMMET BUMPER REAR	Not Necessary	10.00 FN	*- FN
13	1		*BRACKET - BUMPER RH REAR	Not Necessary	35.90 FN	*- FN
14	1		*GRIP - OUTSIDE RH REAR DOOR	Cut	96.20 FN	*96.20 FN
15	1		*ESCUT - OUTSIDE HANDLER COVER RH REAR DOOR	Not Necessary	32.30 FN	*- FN
16	1		*LOCK & REMOTE C RH REAR DOOR	Not Necessary	166.70 FN	*- FN
17	1		*REGULATOR - DOOR RH REAR	Not Necessary	434.20 FN	*- FN
18	1		*GLASS RUN RUBBER RH REAR	Necessary	147.50 FN	*147.50 FN
19	1		*COVER - SASH INNER RH REAR DOOR	Not Necessary	15.00 FN	*- FN
20	1		*CORNER PIECE - RH REAR DOOR	Not Necessary	54.00 FN	*- FN
21	1		*SEAL RUBBER RH REAR DOOR	Necessary	63.50 FN	*63.50 FN
22	1		*W/STRIP - RR DOOR RH	Necessary	132.20 FN	*132.20 FN
23	1		*CHECK ASSY - RR DOOR RH	Not Necessary	39.50 FN	*- FN
24	1		*HINGE - DOOR RH REAR FOOR TOP	Bent	56.10 FN	*56.10 FN
25	1		*MLDG RR DOOR RH	Not Necessary	188.90 FN	*- FN
26	1		*MOULDING RH REAR DOOR	Missing	100.70 FN	*100.70 FN
27	1		*TAPE - RR DOOR, RH	Necessary	29.90 FN	*29.90 FN
28	1		*TAPE - RR DOOR, RH	Necessary	29.90 FN	*29.90 FN
29	1		*DOOR - REAR RH	Bent	1,104.80 FN	*1,104.80 FN
30	1		*HANDLE - PULL RH FRONT DOOR INNER	Not Necessary	63.00 FN	*- FN
31	1		*CAP - DOOR GRIP, RH FRONT	Missing	84.00 FN	*84.00 FN
32	1		*FINISR-P/WDW SW RH FRONT DOOR	Not Necessary	126.00 FN	*- FN
33	1		*ESCUTCHEON RH FRONT DOOR COIN HOLDER	Distorted	63.00 FN	*63.00 FN
34	1		*SEAL A FR DOOR RH	Necessary	59.40 FN	*59.40 FN
35	2		*CLIP HANDLER	Necessary	5.00 FN	*5.00 FN
36	1		*HANDLE DOOR INSIDE RH FRONT	Not Necessary	41.00 FN	*- FN
37	2		*STRIKER ASSY RH FRONT / REAR DOOR	Not Necessary	115.60 FN	*- FN
38	1		*LOCK & REMOTE C RH FRONT DOOR	Distorted	166.70 FN	*166.70 FN
39	2		*BRKT DOOR RH FRONT / REAR HANDLE	Distorted	103.20 FN	*103.20 FN
40	1		*HANDLE SET - FRONT RH	Distorted	165.20 FN	*165.20 FN
41	1		*ESCUT - OUTSIDE HANDLE RH FRONT COVER	Missing	32.30 FN	*32.30 FN
42	1		*REGULATOR - DOOR RH FRONT	Bent	487.90 FN	*487.90 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*GLASS RUN RUB RH FRONT DOOR	Necessary	161.60 FN	*161.60 FN
44	1		*CORN ASSY - HOODLEDGE RH	Not Necessary	129.90 FN	*- FN
45	1		*LINK - DOOR STOP RH FRONT DOOR	Bent	39.50 FN	*39.50 FN
46	1		*HINGE ASSY RH FRONT DOOR BOTTOM	Not Necessary	56.10 FN	*- FN
47	2		*HINGE RH FRONT / RH REAR DOOR TOP / BOTTOM	Not Necessary	112.20 FN	*- FN
48	1		*SEAL LOWER RH FRONT DOOR RUBBER	Necessary	70.40 FN	*70.40 FN
49	1		*WSTRIP ASSY - FRONT RH DOOR FRAME	Necessary	132.20 FN	*132.20 FN
50	1		*MOULDING RH FRONT DOOR SASH	Deformed	100.70 FN	*100.70 FN
51	1		*COVER - SASH INNER RH FRONT DOOR	Missing	15.00 FN	*15.00 FN
52	1		*MLDG ASSY - FR DOOR RH	Deformed	188.90 FN	*188.90 FN
53	1		*TAPE - FR DOOR, RH	Necessary	29.90 FN	*29.90 FN
54	1		*DOOR - FRONT RH	Bent	1,104.80 FN	*1,104.80 FN
55	1		*GROMMET FENDER	Necessary	1.50 FN	*1.50 FN
56	5		*CLIP FENDER	Necessary	6.00 FN	*6.00 FN
57	1		*PROTECTOR - REAR RH FENDER	Not Necessary	186.40 FN	*- FN
58	1		*LID GAS FILLER COVER PANEL	Missing	93.40 FN	*93.40 FN
59	1		*BASE - FILLER LID PETROL	Bent	66.00 FN	*66.00 FN
60	1		*RETAINER - TAPPING FENDER RH REAR	Necessary	19.30 FN	*19.30 FN
61	1		*FENDER - REAR RH	Buckled	1,169.40 FN	*1,169.40 FN
62	1		*WELT BODY RH FRONT DOOR	Not Necessary	205.10 FN	*- FN
63	1		*FENDER ARC RH REAR	Not Necessary	483.00 FN	*- FN
64	1		*FENDER - OVER, FR RH ARC	Not Necessary	483.00 FN	*- FN
65	1		*MOUL - ROOF DRIP RH	Not Necessary	213.90 FN	*- FN
66	1		*MOULDING RH REAR DOOR PAD	Distorted	264.80 FN	*264.80 FN
67	1		*MOULDING RH FRONT DOOR PAD	Distorted	323.60 FN	*323.60 FN
68	1		*MLDG WS UPPER	Necessary	134.60 FN	*134.60 FN
69	1		*RUBBER - DUM	Necessary	60.20 FN	*60.20 FN
70	1		*GLASS - FR WIND	Cracked	1,244.60 FN	*1,244.60 FN
71	1		*VENTILATOR RH DASHBOARD	Deformed	100.50 FN	*100.50 FN
72	1		*PANEL & PAD	Deformed	1,374.50 FN	*1,374.50 FN
73	1		*HOOK ASSY - HOOD	Not Necessary	82.80 FN	*- FN
74	1		*MALE ASSY - HOOD	Not Necessary	67.60 FN	*- FN
75	1		*HINGE HOOD RH	Bent	56.10 FN	*56.10 FN
76	1		*HOOD HINGE LH	Bent	56.10 FN	*56.10 FN
77	13		*CLIP - HOOD INSUL	Necessary	20.80 FN	*20.80 FN
78	1		*INSULATOR - HOOD	Deformed	185.50 FN	*185.50 FN
79	1		*HOOD	Bent	961.40 FN	*961.40 FN
80	1		*COVER - HOLE FENDER SIDE RH	Deformed	57.70 FN	*57.70 FN
81	13		*CLIP FENDER PROTECTOR	Not Necessary	16.90 FN	*- FN
82	1		*PROTECTOR - FR, RH FENDER	Not Necessary	87.50 FN	*- FN
83	1		*FENDER - FRONT RH	Bent	622.70 FN	*622.70 FN
84	8		*CLIP BUMPER	Not Necessary	9.60 FN	*- FN
85	1		*BRKT - BPR SIDE, RH FRONT	Not Necessary	20.90 FN	*- FN
86	1		*RH REAR C/COMB SEALING	Not Necessary	25.70 FN	*- FN
87	1		*LAMP COMB RR, RH REAR	Cut	323.70 FN	*323.70 FN
88	1		*LAMP ASSY - RH	Cracked	1,617.00 FN	*1,617.00 FN
89	1		*GLASS RH REAR 1/4 (10%)	Distorted	342.00 FS	*342.00 FS
90	2		*GROMMET HANDLER (10%)	Necessary	5.22 FS	*5.22 FS
91	1		*GSKT - DOOR OUTSIDE RH FRONT DOOR HANDLE (10%)	Necessary	11.52 FS	*11.52 FS
92	4		*GASKET - OUTSIDE HANDLER (10%)	Necessary	11.52 FS	*11.52 FS
93	1		*GLASS - FR DOOR, RH (10%)	Buckled	684.00 FS	*684.00 FS
94	1		*PLATE - CLOSING RH FRONT DOOR (10%)	Not Necessary	143.37 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
95	1		*SEALANT 1/4 GLASS (10%)	Necessary	43.20 FS	*43.20 FS
96	1		*SEALANT - FRONT W/SCREEN GLASS (10%)	Necessary	72.00 FS	*72.00 FS
97	2		*GROMMET BUMPER (10%)	Not Necessary	3.96 FS	*- FS
98	1		*BRKT MAIN RAIN (10%)	Not Necessary	42.84 FS	*- FS
99	1		*IU BRACKET (10%)	Necessary	23.40 FS	*23.40 FS
100	1		*SENSOR A-RAIN WINDSCREEN (10%)	Necessary	189.63 FS	*189.63 FS
101	1		*SW-AUTO POWER WINDOW RH FRONT (10%)	Not Necessary	170.91 FS	*- FS
102	1		*GROMMET FILLER (10%)	Not Necessary	10.08 FS	*- FS
103	1		*COVER-COWL TOP	Deformed	144.90 FN	*144.90 FN
104	1		*LOCK & ROD ASSY	Bent	45.30 FN	*45.30 FN
105	1		*SPRING DOOR	Distorted	6.60 FN	*6.60 FN
106	1		*REINF-HOODLEDGE RH OUTER	Deformed	355.00 FN	*355.00 FN
107	1		*ADJSTER-S/BELT (10%)	Activated	125.82 FS	*125.82 FS
108	1		*SUNDRIES (10%)	Necessary	4.95 FS	*4.95 FS

F=Franchise part. S=SpcNett, N=NettItemDisc.

Sub Total (S\$)	24,536.72	18,077.96
- Nett Item Discount on N Items 30.00/30.00% (S\$)	6,795.69	4,969.41
Total Parts (S\$)	17,741.03	13,108.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION.	New	20.00	20.00
2	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	New	250.00	200.00
3	INSTALL ULTRAMAX SOLAR FILM - DOOR GLASS RH FRONT.	New	80.00	80.00
4	APPLY SEALANT TO ALL NECESSARY PANEL JOINTS & RESEAL NECESSARY AREA.	New	600.00	500.00
5	INSTALL ULTRAMAX SOLAR FILM - FRT W/SCREEN WITH ANTI GLARE.	New	150.00	150.00
6	INSTALL ULTRAMAX SOLAR FILM - QUARTER GLASS RH REAR.	New	50.00	50.00
7	RENEW FRONT WINDSHIELD GLASS ASSY INCL SEALANT.	New	170.00	170.00
8	RENEW WIRE HARDNESS RH FRONT / RH REAR DOOR AND MAIN HARDNESS.	New	600.00	0.00
9	R/I DASHBOARD TO RENEW.	New	200.00	200.00
10	RENEW RH FRONT DOOR GLASS AND TRANSFER RH REAR DOOR GLASS.	New	160.00	160.00
11	RENEW RH REAR 1/4 GLASS.	New	120.00	120.00
12	R/I RH FRONT / REAR SEAT TO ASSIST REPAIR.	New	200.00	120.00
13	R/I PETROL TANK TO ASSIST REPAIR.	New	80.00	80.00
14	RENEW RH FRONT HOODLEDGE.	New	600.00	600.00
15	RENEW RH REAR FENDER INCLUDING REPAIR AND PANEL.	New	1,000.00	695.00
16	REPAIR LH FRONT FENDER, BOTH FRONT PILLAR, RH CENTER PILLAR, FRONT / REAR BUMPER AND RENEW BONNET, (NPA)	New	0.00	0.00
17	S/PAINT FRONT PORTION, BOTH FRONT PILLAR, RH FRONT HOODLEGDE, RH FRONT / REAR DOOR, REAR BUMPER (2 TONE). (NPA)	New	0.00	0.00
18	RH CENTER PILLAR, END PANEL, RH REAR FENDER, RH FRONT PILLAR AND RH WING MIRROR.	New	3,600.00	2,200.00
19	R/I REVERSE SENSOR TO ASSIST REPAIR.	New	110.00	110.00
20	SUPPLY AND RENEW RH FRONT DOOR LEATHER.	New	300.00	250.00
21	VACUUM GLASS CHIP.	New	240.00	100.00
22	TRANSFER OR REWIRE RH WING MIRROR LED.	New	120.00	120.00
23	RH FRONT / REAR DOOR.	New	2,280.00	1,170.00
24	LEATHER CONDITIONING.	New	80.00	80.00
Gross Labour Cost (\$\$)			11,010.00	7,175.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >