

ASS. REC. BY:

REF: CS/SPF 18019601/T11b02

Special Instruction:

Surveyor:

Tawfik

ASSIGNMENT (Office)

From (Person):

Frankie Thay

of

SPF

Date/Time:

24.10.2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 7777L

Insured:

BX 4008

at Workshop m/s

Ding Auto

Tel:

9239 4128 / 9733 5832

of

249 Jin Boon Lay

Policy No:

Claim No:

AEMD / 105 / 009 / 2018 / 152

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26.10.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

24.10.2018 11:03am

Person Contacted:

Jing feng

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

Do Not Finalize

SLG 7777L x

BX 4008 x

Submit L/s \$6K @ 11 days (Red: \$10,578.50, 6K)

MV: \$50K, LTA: \$43,216.00, NV: \$6784.00

Surveyor: *Tanpin*

REF:


SPF

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: *950k*
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SLG 7727L* Yr Regn: *20/6 Oct.*
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: *Mitsubishi Pajero* C.C. *1/93-*
Colour: *Red* A/C Insured / Std / NI / NA
Sp. Reading: *92334* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *MM B5TA15AH002923*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *185/60R14*
R: *185/60R14*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. <i>6</i>	mm	R/Bal. <i>6</i>	mm
L/Bal. <i>6</i>	mm	L/Bal. <i>6</i>	mm
D.O.A.		D.O.I. <i>29/10/18</i>	

Survey held at *Ding Antu*
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>Revised \$3,508</i>
	<i>Repair limit \$6k. Inform Jing Fay</i>
	<i>Repair Range \$6000 - \$8000.</i>
	<i>249 Jln Boon Lay.</i>

RECEIVED 20 NOV 2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1) *tanpin*

Date/Time, File Return to?

2) */*

Days Of Repair: *11*

Resurvey No. of Trip: *7*

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format: *TP*

Lump Sum H.B.I: (\$) *6000*

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

280

280



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SLG7727L

Our Ref : AEMD/105/009/2018/152

Date : 29 October 2018

Tel: 64784841

Fax: 64784848

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 # 01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir,

ACCIDENT INVOLVING GOVERNMENT VEHICLE QX400B AND OTHER VEHICLE SLG7727L ON 26 October 2018

We refer to the above matter.

- 2 Kindly arrange for a Pre-Repair Inspection for Vehicle SLG7727L at 249 Jalan Boon Lay Singapore 619523.
- 3 Please contact Mr Duan Hong Bo @ 92394128 for appointment.
- 4 Thank you.

Yours faithfully,

Frankie Thay
Safe Driving Manager
For ASSISTANT DIRECTOR

A FORCE FOR THE NATION

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLG7727L
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Nov 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	3A92UDL4428
Chassis No.:	MMBSTA13AHH002923
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$14,909.00
Original Registration Date:	13 Oct 2016
First Registration Date:	13 Oct 2016
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Oct 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$39,466.00
Total Rebate Amount:	\$43,216.00

The information contained herein is correct as at 20 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/10/2018 14:24
Date Of Accident	26/10/2018 10:15
Exact Location Of Accident	ALONG ROAD 1 AYER RAJAH EXPRESSWAY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLG7727L
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	ATTRAGE-1.2 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995145
Cover Note Number	
Driver	
Name of Driver	IMRAN BIN MOHAMED BASIR
NRIC No	S8814449Z
Date Of Birth	06/05/1988
Occupation	OUTDOOR
Date Of Driving Pass	23/03/2007
Driving Experience	11 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92394128
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address 249 JALAN BOON LAY

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - RELIEF

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : UNKNOWN

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TRAFFIC POLICE DIVISION HQ

Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: UNKNOWN

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number QX400B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category GOVERNMENT

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/ID No.:

SKETCH PLAN

AYER RATAH
EXPRESSWAY
Along Road 1.



VEH A: SL67127L

VEH B: QX400B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Name & Address
Name:
NCR/CPN No.:





**SINGAPORE
POLICE FORCE**



T/20181026/2089

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20181026/2089

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/10/2018 15:14		Vide Report No.: D/20181026/0039		Station Diary No.:	
Informant's Particulars					
Name of Informant: IMRAN BIN MOHAMED BASIR			Address: APT BLK 148 SIMEI STREET 1 #06-133 SINGAPORE 520148		
ID Type / ID No.: NRIC NO / S8814449Z			Contact No.: Home/Office: Mobile: 96310302		
Nationality:			Email:		
Sex: Male	Age: 30	Date of Birth: 06/05/1988	Type of Informant: Driver		
Race:			Language:	Institution / School Name:	
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 26/10/2018 10:15	Type of Location: Straight Road
Location: Along Road 1 AYER RAJAH EXPRESSWAY AYE(MCE) 6 KM				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX400B	POLICE VEHICLE					5
SLG7727L	Car					1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181026/2089

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20181026/2089

CONTINUATION OF REPORT

Driver:			
Name	PARIKSHIT THEBE		ID No. G6250992P
Related Vehicle	QX400B (POLICE VEHICLE)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver:			
Name	IMRAN BIN MOHAMED BASIR		ID No. S8814449Z
Related Vehicle	SLG7727L (Car)		Contact No. 96310302
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED TIME, DATE AND LOCATION.

I WAS DRIVING ON THE RIGHT LANE OF 3 LANES. AS I WAS DRIVING, I NOTICED THE VEHICLES AHEAD WERE SLOWING DOWN, SO I APPLIED THE BRAKES, THE POLICE VEHICLE BEHIND ME PROBABLY ALSO HIT THE BRAKE, BUT STILL COLLIDED INTO THE REAR OF MY VEHICLE. NO ONE WAS INJURED AS A RESULT OF THIS ACCIDENT. I EXCHANGED PARTICULARS WITH THE DRIVER AND POLICE ATTENDED TO THE ACCIDENT. NO ONE WAS INJURED.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20181026/2089

3 of 3

Report No. T/20181026/2089

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
KHALED AMR HASSAN MOHSSEN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
26/10/2018 15:14

Officer In Charge Of Case:
TP / GIT /
Staff Sgt LEE GUANG HUI
Contact No.: 65476138

Classification Of Case:



**SINGAPORE
POLICE FORCE**

Authentication Stamp
NP168

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

26/10/2018 14:01

JOB-NO: 85008732

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE LTD

CONTACT:

Page 1 of 3

ADDRESS: 60 ANSON ROAD
MAPLE TREE ANSON
LEVEL 11 SINGAPORE
079914

NOEMAIL@GMAIL.COM

VEHICLE DETAILS

LICENSE NO: SLG7727L

TRANS: AUTO

CHASSIS: MMBSTA13AHH002923

MAKE / MODEL: MITSUBISHI Others

ENGINE: 3A92UDL4428

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	2,200.00	0.00	2,200.00	Y		1500.
2 TO SPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		200
3 TO SPRAY REAR END PANEL	1.00	250.00	0.00	250.00	Y		200
4 TO SPRAY REAR SPARE TYRE PANEL	1.00	250.00	0.00	250.00	Y		200
5 TO SPRAY BOOTLID	1.00	250.00	0.00	250.00	Y		200
6 TO SPRAY REAR FENDER LHS	1.00	250.00	0.00	250.00	Y		200
7 TO SPRAY REAR FENDER RHS	1.00	250.00	0.00	250.00	Y		200
8 TO SPRAY REAR FENDER WHEEL HOUSE PANEL LHS	1.00	250.00	0.00	250.00	Y		X n1
9 TO SPRAY REAR FENDER WHEEL HOUSE PANEL RHS	1.00	250.00	0.00	250.00	Y		X n1
10 TO SPRAY REAR CHASSIS LHS	1.00	250.00	0.00	250.00	Y		150
11 TO SPRAY REAR CHASSIS RHS	1.00	250.00	0.00	250.00	Y		X n1
12 RUST PROOFING	1.00	120.00	0.00	120.00	Y		60
13 TO ADJUST TAIL LAMP & CHECK WIRING	1.00	130.00	0.00	130.00	Y		40.
14 REMOVE & REFIT REAR SPARE TYRE PANEL,REAR FENDER TRIM LHS & RHS,REAR SPARE TYRE BOARD,CUSHION,AND ETC	1.00	130.00	0.00	130.00	Y		60.
15 REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	1.00	140.00	0.00	140.00	Y		30.
16 REMOVE & REFIT FUEL TANK	1.00	200.00	0.00	200.00	Y		X n1
17 REMOVE REAR WINDSCREEN	1.00	150.00	0.00	150.00	Y		120.
18 MOUNT WORKBENCH	1.00	350.00	0.00	350.00	Y		200 X plus n1
19 ALIGNMENT REAR CHASSIS	1.00	280.00	0.00	280.00	Y		100.
20 R & R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00	Y		60.
21 REMOVE & REFIT EXHAUST PIPE & MUFFLER	1.00	180.00	0.00	180.00	Y		X n1
22 REMOVE REAR SEAT & REMOVE REAR SPEAKER PANEL TRIM	1.00	180.00	0.00	180.00	Y		80.
23 R & R ROOF LINING	1.00	150.00	0.00	150.00	Y		X n1
24 TO SPRAY REAR TAIL LAMP PANEL LHS	1.00	250.00	0.00	250.00	Y		n1 X
25 TO SPRAY REAR TAIL LAMP PANEL RHS	1.00	250.00	0.00	250.00	Y		n1 X
TOTAL:		7,360.00	0.00	7,360.00			3400

MATERIALS

1 REAR BUMPER	1.00	708.00	70.80	637.20	L	Y	de
---------------	------	--------	-------	--------	---	---	----

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
2 REAR BUMPER SIDE RETAINER LHS	1.00	26.00	2.60	23.40	L	Y	ne
3 REAR BUMPER SIDE RETAINER RHS	1.00	26.00	2.60	23.40	L	Y	ne
4 REAR BUMPER REFLECTOR LHS	1.00	20.00	2.00	18.00	L	Y	X un
5 REAR BUMPER REFLECTOR RHS	1.00	20.00	2.00	18.00	L	Y	? X un
6 BOOTLID	1.00	828.00	82.80	745.20	L	Y	bt
7 BOOTLID "MIT" LOGO EMBLEM	1.00	41.00	4.10	36.90	L	Y	ne
8 BOOTLID "ATTRAGE" EMBLEM	1.00	38.00	3.80	34.20	L	Y	ne
9 BOOTLID OPEN SWITCH	1.00	79.00	7.90	71.10	L	Y	? X un
10 BOOTLID HINGE LHS	1.00	192.00	19.20	172.80	L	Y	bt
11 BOOTLID HINGE RHS	1.00	192.00	19.20	172.80	L	Y	bt
12 BOOTLID LOCK	1.00	206.00	20.60	185.40	L	Y	bt
13 BOOTLID OUTER CHROME GARNISH	1.00	318.00	31.80	286.20	L	Y	at
14 BOOTLID LICENSE PLATE LAMP LHS	1.00	48.00	4.80	43.20	L	Y	X un
15 BOOTLID LICENSE PLATE LAMP RHS	1.00	48.00	4.80	43.20	L	Y	X un
16 TAIL LAMP LHS	1.00	276.00	27.60	248.40	L	Y	ae
17 TAIL LAMP RHS	1.00	276.00	27.60	248.40	L	Y	ae
18 REAR END PANEL	1.00	402.00	40.20	361.80	L	Y	bt
19 REAR END PANEL TOP GARNISH	1.00	65.00	6.50	58.50	L	Y	? X un
20 REAR SPARE TYRE PANEL	1.00	906.00	90.60	815.40	L	Y	Rp
21 REAR SPARE TYRE PANEL FLOOR BOARD	1.00	185.00	18.50	166.50	L	Y	? X un
22 REAR END PANEL WEATHERSTRIP	1.00	148.00	14.80	133.20	L	Y	ae
23 REAR FENDER LHS	1.00	723.00	72.30	650.70	L	Y	bt
24 REAR FENDER RHS	1.00	723.00	72.30	650.70	L	Y	Rp
25 REAR FENDER INNER SHIELD LHS	1.00	38.00	3.80	34.20	L	Y	X un
26 REAR FENDER INNER SHIELD RHS	1.00	38.00	3.80	34.20	L	Y	X
27 REAR FENDER INNER PANEL TRIM LHS	1.00	158.00	15.80	142.20	L	Y	de
28 REAR FENDER INNER PANEL TRIM RHS	1.00	158.00	15.80	142.20	L	Y	? X un
29 REAR EXHAUST PIPE	1.00	340.00	34.00	306.00	L	Y	X
30 REAR FENDER MUDFLAP LHS	1.00	39.00	3.90	35.10	L	Y	X
31 REAR FENDER MUDFLAP RHS	1.00	39.00	3.90	35.10	L	Y	X
32 REAR END PANEL AIR DUCT	1.00	27.00	2.70	24.30	L	Y	? X un
33 BOOTLID LOCK CATCH	1.00	19.00	1.90	17.10	L	Y	bt
34 REAR SPARE TYRE PANEL INSULATOR PIT	1.00	185.00	18.50	166.50	L	Y	? X un
35 TAIL LAMP PANEL LHS	1.00	115.00	11.50	103.50	L	Y	bt
36 TAIL LAMP PANEL RHS	1.00	115.00	11.50	103.50	L	Y	bt
37 REAR WHEEL HOUSE PANEL LHS	1.00	550.00	55.00	495.00	L	Y	X
38 REAR WHEEL HOUSE PANEL RHS	1.00	550.00	55.00	495.00	L	Y	X
39 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	ae
40 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	ae
41 REAR NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	bt
42 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	X
43 REAR FENDER INNER SHIELD CLIP LHS	1.00	35.00	0.00	35.00	S	Y	X
44 REAR FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	S	Y	X
45 REAR FENDER INNER PANEL TRIM LHS CLIP	1.00	35.00	0.00	35.00	S	Y	ne
46 REAR FENDER INNER PANEL TRIM CLIP RHS	1.00	35.00	0.00	35.00	S	Y	? X un
47 REAR WINDSCREEN SEALANT	1.00	30.00	0.00	30.00	S	Y	ne
48 REAR END PANEL SEALANT	1.00	40.00	0.00	40.00	S	Y	ne
49 REAR SPARE TYRE PANEL SEALANT	1.00	40.00	0.00	40.00	S	Y	X
50 REAR SPARE TYRE	1.00	600.00	0.00	600.00	S	Y	X
TOTAL:		10,105.00	886.50	9,218.50			

TOTAL PARTS & LABOUR :

17,465.00

886.50

16,578.50

EXCESS/LOADING:\$S 0.00

No. Of Day:

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$S

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

DATE OF SURVEY: 21/10/18SURVEYED BY: TanghrCONTACT NO: 9244574FAX NO: sur@lkkauto.com

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:



WP
* to check repair limit

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Janice Lee (LKKAUTO)

From: Duan Hongbo <duan.hongbo@dingauto.sg>
Sent: Tuesday, November 13, 2018 5:15 PM
To: Taufikh (LKKAUTO); SUR
Cc: CS A Team; Kenneth Ding; You jingfeng; Dd hashim; Ding Auto Admin; Accounts Ding Auto; Carlor Chan
Subject: 85008732/SLG7727L- FINALIZE AMOUNT AND AFTER PAINT PHOTO
Attachments: SLG7727L ESTIMATE.pdf; IMG_1341.jpg; IMG_1340.jpg; IMG_1338.jpg; IMG_1342.jpg; IMG_1339.jpg; IMG_1344.jpg

HI ALL

Please see attach file for the finalize according to our conversion to finalize for SLG7727L

Total Repair - 11 Days

L/S REPAIR

Labour - \$3700.00
Special Netts - \$385.00
Parts - \$4326.30
Parts discount 10%- \$4326.30
Total (Labour + S.N + Part) :\$8411.30

L/S Repair after 20%- \$6729.04

Limit amount \$6000.00

Thanks You And Please Help To Close The File
BEST REGARDS

DING AUTO PTE LTD

DUAN HONG BO
TEL Office : 64521208
FAX :64520614

ALL MAILL LETTER AND CHEQUE PAYMENT IS TO BE MAILED TO OUR MAIN OFFICE AS BELOW
- BLOCK 10 #01-20 SIN MING INDUSTRIAL EST.SEC C SINGAPORE 5756

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

26/10/2018 14:01

JOB-NO: 85008732

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE LTD CONTACT:

Page 1 of 3

ADDRESS: 60 ANSON ROAD
MAPLETREE ANSON
LEVEL 11 SINGAPORE
079914

NOEMAIL@GMAIL.COM

VEHICLE DETAILS

LICENSE NO: SLG7727L

TRANS: AUTO

CHASSIS: MMBSTA13AHH002923

MAKE / MODEL: MITSUBISHI Others

ENGINE: 3A92UDL4428

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	2,200.00	0.00	2,200.00	Y		1500
2 TO SPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		200
3 TO SPRAY REAR END PANEL	1.00	250.00	0.00	250.00	Y		200
4 TO SPRAY REAR SPARE TYRE PANEL	1.00	250.00	0.00	250.00	Y		200
5 TO SPRAY BOOTLID	1.00	250.00	0.00	250.00	Y		200
6 TO SPRAY REAR FENDER LHS	1.00	250.00	0.00	250.00	Y		200
7 TO SPRAY REAR FENDER RHS	1.00	250.00	0.00	250.00	Y		X
8 TO SPRAY REAR FENDER WHEEL HOUSE PANEL LHS	1.00	250.00	0.00	250.00	Y		X
9 TO SPRAY REAR FENDER WHEEL HOUSE PANEL RHS	1.00	250.00	0.00	250.00	Y		150
10 TO SPRAY REAR CHASSIS LHS	1.00	250.00	0.00	250.00	Y		X
11 TO SPRAY REAR CHASSIS RHS	1.00	120.00	0.00	120.00	Y		60
12 RUST PROOFING	1.00	130.00	0.00	130.00	Y		60
13 TO ADJUST TAIL LAMP & CHECK WIRING	1.00	130.00	0.00	130.00	Y		60
14 REMOVE & REFIT REAR SPARE TYRE PANEL,REAR FENDER TRIM LHS & RHS,REAR SPARE TYRE BOARD,CUSHION,AND ETC	1.00	140.00	0.00	140.00	Y		30
15 REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	1.00	200.00	0.00	200.00	Y		X
16 REMOVE & REFIT FUEL TANK	1.00	150.00	0.00	150.00	Y		120
17 REMOVE REAR WINDSCREEN	1.00	350.00	0.00	350.00	Y		200? photo
18 MOUNT WORKBENCH	1.00	280.00	0.00	280.00	Y		100
19 ALIGNMENT REAR CHASSIS	1.00	150.00	0.00	150.00	Y		60
20 R & R BOOTLID COMPONENTS	1.00	180.00	0.00	180.00	Y		X
21 REMOVE & REFIT EXHAUST PIPE & MUFFLER	1.00	180.00	0.00	180.00	Y		80
22 REMOVE REAR SEAT & REMOVE REAR SPEAKER PANEL TRIM	1.00	150.00	0.00	150.00	Y		X
23 R & R ROOF LINING	1.00	250.00	0.00	250.00	Y		
24 TO SPRAY REAR TAIL LAMP PANEL LHS	1.00	250.00	0.00	250.00	Y		
25 TO SPRAY REAR TAIL LAMP PANEL RHS	1.00	250.00	0.00	250.00	Y		
TOTAL:		7,360.00	0.00	7,360.00			
<u>MATERIALS</u>							
1 REAR BUMPER	1.00	708.00	70.80	637.20	L	Y	de

G-STAR-WI-ET-001-02 Rev00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
2 REAR BUMPER SIDE RETAINER LHS	1.00	26.00	2.60	23.40	L	Y	net
3 REAR BUMPER SIDE RETAINER RHS	1.00	26.00	2.60	23.40	L	Y	net
4 REAR BUMPER REFLECTOR LHS	1.00	20.00	2.00	18.00	L	Y	?
5 REAR BUMPER REFLECTOR RHS	1.00	20.00	2.00	18.00	L	Y	?
6 BOOTLID	1.00	828.00	82.80	745.20	L	Y	bt
7 BOOTLID "MIT" LOGO EMBLEM	1.00	41.00	4.10	36.90	L	Y	net
8 BOOTLID "ATTRAGE" EMBLEM	1.00	38.00	3.80	34.20	L	Y	net
9 BOOTLID OPEN SWITCH	1.00	79.00	7.90	71.10	L	Y	?
10 BOOTLID HINGE LHS	1.00	192.00	19.20	172.80	L	Y	bt
11 BOOTLID HINGE RHS	1.00	192.00	19.20	172.80	L	Y	bt
12 BOOTLID LOCK	1.00	206.00	20.60	185.40	L	Y	bt
13 BOOTLID OUTER CHROME GARNISH	1.00	318.00	31.80	286.20	L	Y	as
14 BOOTLID LICENSE PLATE LAMP LHS	1.00	48.00	4.80	43.20	L	Y	x
15 BOOTLID LICENSE PLATE LAMP RHS	1.00	48.00	4.80	43.20	L	Y	x
16 TAIL LAMP LHS	1.00	276.00	27.60	248.40	L	Y	as
17 TAIL LAMP RHS	1.00	276.00	27.60	248.40	L	Y	as
18 REAR END PANEL	1.00	402.00	40.20	361.80	L	Y	bt
19 REAR END PANEL TOP GARNISH	1.00	65.00	6.50	58.50	L	Y	?
20 REAR SPARE TYRE PANEL	1.00	906.00	90.60	815.40	L	Y	RP
21 REAR SPARE TYRE PANEL FLOOR BOARD	1.00	185.00	18.50	166.50	L	Y	?
22 REAR END PANEL WEATHERSTRIP	1.00	148.00	14.80	133.20	L	Y	net
23 REAR FENDER LHS	1.00	723.00	72.30	650.70	L	Y	bt
24 REAR FENDER RHS	1.00	723.00	72.30	650.70	L	Y	RP
25 REAR FENDER INNER SHIELD LHS	1.00	38.00	3.80	34.20	L	Y	x
26 REAR FENDER INNER SHIELD RHS	1.00	38.00	3.80	34.20	L	Y	x
27 REAR FENDER INNER PANEL TRIM LHS	1.00	158.00	15.80	142.20	L	Y	de
28 REAR FENDER INNER PANEL TRIM RHS	1.00	158.00	15.80	142.20	L	Y	?
29 REAR EXHAUST PIPE	1.00	340.00	34.00	306.00	L	Y	x
30 REAR FENDER MUDFLAP LHS	1.00	39.00	3.90	35.10	L	Y	x
31 REAR FENDER MUDFLAP RHS	1.00	39.00	3.90	35.10	L	Y	x
32 REAR END PANEL AIR DUCT	1.00	27.00	2.70	24.30	L	Y	?
33 BOOTLID LOCK CATCH	1.00	19.00	1.90	17.10	L	Y	bt
34 REAR SPARE TYRE PANEL INSULATOR PIT	1.00	185.00	18.50	166.50	L	Y	?
35 TAIL LAMP PANEL LHS	1.00	115.00	11.50	103.50	L	Y	bt
36 TAIL LAMP PANEL RHS	1.00	115.00	11.50	103.50	L	Y	bt
37 REAR WHEEL HOUSE PANEL LHS	1.00	550.00	55.00	495.00	L	Y	x
38 REAR WHEEL HOUSE PANEL RHS	1.00	550.00	55.00	495.00	L	Y	x
39 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	net
40 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	room
41 REAR NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	bt - 45
42 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	x
43 REAR FENDER INNER SHIELD CLIP LHS	1.00	35.00	0.00	35.00	S	Y	x
44 REAR FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	S	Y	net
45 REAR FENDER INNER PANEL TRIM LHS CLIP	1.00	35.00	0.00	35.00	S	Y	?
46 REAR FENDER INNER PANEL TRIM CLIP RHS	1.00	35.00	0.00	35.00	S	Y	?
47 REAR WINDSCREEN SEALANT	1.00	30.00	0.00	30.00	S	Y	net
48 REAR END PANEL SEALANT	1.00	40.00	0.00	40.00	S	Y	net
49 REAR SPARE TYRE PANEL SEALANT	1.00	40.00	0.00	40.00	S	Y	x
50 REAR SPARE TYRE	1.00	600.00	0.00	600.00	S	Y	x
TOTAL:		10,105.00	886.50	9,218.50			
TOTAL PARTS & LABOUR :		17,465.00	886.50	16,578.50			
EXCESS/LOADING:\$	0.00						
No. Of Day:	11						
RE-SURVEY: BEFORE/AFTER PAINTING							
PART-BY-PART OR LUMP SUM: \$							

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
DATE OF SURVEY:	29/10/18						
SURVEYED BY:	Tanpin						
CONTACT NO:	9249574						
						940@lukaauto.com	

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

WP
\$ to check repair limit

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile**AUTOMOTIVE ENGINEERING & MGT DIVISION** Ref : CS/SPF18019602/T1rbe2ACCIDENT CLAIM SECTION(SINGAPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMYSINGAPORE 298333

Date : 05-12-2018



ATTN : FRANKIE THAY

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 400B	Veh. Inspected	SLG 7727L
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/152	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	29/10/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI ATTRAGE	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MMBSTA13AHH002923	Colour	RED
Odometer	92334	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R14	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R14	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R14	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R14	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	26/10/2018	Inspection Date	29/10/2018
Survey held at	249 JLN BOON LAY		
Repairer	DING AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 7727L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	708.00	708.00
1	REAR BUMPER SIDE RETAINER LHS	NECESSARY	26.00	26.00
1	REAR BUMPER SIDE RETAINER RHS	NECESSARY	26.00	26.00
1	REAR BUMPER REFLECTOR LHS	NOT NECESSARY	20.00	-
1	REAR BUMPER REFLECTOR RHS	NOT NECESSARY	20.00	-
1	BOOTLID	BENT	828.00	828.00
1	BOOTLID "MIT" LOGO EMBLEM	NECESSARY	41.00	41.00
1	BOOTLID "ATTRAGE" EMBLEM	NECESSARY	38.00	38.00
1	BOOTLID OPEN SWITCH	NOT NECESSARY	79.00	-
1	BOOTLID HINGE LHS	BENT	192.00	192.00
1	BOOTLID HINGE RHS	BENT	192.00	192.00
1	BOOTLID LOCK	BENT	206.00	206.00
1	BOOTLID OUTER CHROME GARNISH	CRACKED	318.00	318.00
1	BOOTLID LICENSE PLATE LAMP LHS	NOT NECESSARY	48.00	-
1	BOOTLID LICENSE PLATE LAMP RHS	NOT NECESSARY	48.00	-
1	TAIL LAMP LHS	CRACKED	276.00	276.00
1	TAIL LAMP RHS	CRACKED	276.00	276.00
1	REAR END PANEL	BENT	402.00	402.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	65.00	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	906.00	-
1	REAR SPARE TYRE PANEL FLOOR BOARD	NOT NECESSARY	185.00	-
1	REAR END PANEL WEATHERSTRIP	TWISTED	148.00	148.00
1	REAR FENDER LHS	BUCKLED	723.00	723.00
1	REAR FENDER RHS	TO REPAIR SEE LABOUR	723.00	-
1	REAR FENDER INNER SHIELD LHS	NOT NECESSARY	38.00	-
1	REAR FENDER INNER SHIELD RHS	NOT NECESSARY	38.00	-
1	REAR FENDER INNER PANEL TRIM LHS	DEFORMED	158.00	158.00
1	REAR FENDER INNER PANEL TRIM RHS	NOT NECESSARY	158.00	-
1	REAR EXHAUST PIPE	NOT NECESSARY	340.00	-
1	REAR FENDER MUDFLAP LHS	NOT NECESSARY	39.00	-
1	REAR FENDER MUDFLAP RHS	NOT NECESSARY	39.00	-
1	REAR END PANEL AIR DUCT	NOT NECESSARY	27.00	-

Report Ref No. CS/SPF18019602/T1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID LOCK CATCH	BENT	19.00	19.00
1	REAR SPARE TYRE PANEL INSULATOR PIT	NOT NECESSARY	185.00	-
1	TAIL LAMP PANEL LHS	BENT	115.00	115.00
1	TAIL LAMP PANEL RHS	BENT	115.00	115.00
1	REAR WHEEL HOUSE PANEL LHS	NOT NECESSARY	550.00	-
1	REAR WHEEL HOUSE PANEL RHS	NOT NECESSARY	550.00	-
	LESS 10% DISCOUNT		-886.50	-480.70
			7,978.50	4,326.30
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	REAR REVERSE SENSOR (SN)	NOT WORKING	260.00	200.00
1	REAR NUMBER PLATE & CASING (SN)	BENT	60.00	45.00
1	REAR END PANEL TOP & GARNISH CLIP (SN)	NOT NECESSARY	35.00	-
1	REAR FENDER INNER SHIELD CLIP LHS (SN)	NOT NECESSARY	35.00	-
1	REAR FENDER INNER SHIELD CLIP RHS (SN)	NOT NECESSARY	35.00	-
1	REAR FENDER INNER PANEL TRIM LHS CLIP (SN)	NECESSARY	35.00	35.00
1	REAR FENDER INNER PANEL TRIM CLIP RHS (SN)	NOT NECESSARY	35.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	30.00	30.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	40.00	40.00
1	REAR SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	40.00	-
1	REAR SPARE TYRE (SN)	NOT NECESSARY	600.00	-
			1,240.00	385.00
	<u>LABOUR</u>			
	TO REMOVE & REPLACED DAMAGED BODY PARTS, REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL AND REAR FENDER RHS.		2,200.00	1,500.00
	TO SPRAY REAR BUMPER.		250.00	200.00
	TO SPRAY REAR END PANEL.		250.00	200.00
	TO SPRAY REAR SPARE TYRE PANEL.		250.00	200.00
	TO SPRAY BOOTLID.		250.00	200.00
	TO SPRAY REAR FENDER LHS.		250.00	200.00
	TO SPRAY REAR FENDER RHS.		250.00	200.00
	TO SPRAY REAR FENDER WHEEL HOUSE PANEL LHS.	NOT NECESSARY	250.00	-
	TO SPRAY REAR FENDER WHEEL HOUSE PANEL RHS.	NOT NECESSARY	250.00	-
	TO SPRAY REAR CHASSIS LHS.		250.00	150.00

Report Ref No. CS/SPF18019602/T1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY REAR CHASSIS RHS.	NOT NECESSARY	250.00	-
	RUST PROOFING.		120.00	60.00
	TO ADJUST TAIL LAMP & CHECK WIRING.		130.00	40.00
	REMOVE & REFIT REAR SPARE TYRE PANEL, REAR FENDER TRIM LHS & RHS, REAR SPARE TYRE BOARD, CUSHION, AND ETC.		130.00	60.00
	REMOVE & REFIT REAR REVERSE SENSOR & SPRAY.		140.00	30.00
	REMOVE & REFIT FUEL TANK.	NOT NECESSARY	200.00	-
	REMOVE REAR WINDSCREEN.		150.00	120.00
	MOUNT WORKBENCH.	NOT NECESSARY	350.00	-
	ALIGNMENT REAR CHASSIS.		280.00	100.00
	R & R BOOTLID COMPONENTS.		150.00	60.00
	REMOVE & REFIT EXHAUST PIPE & MUFFLER.	NOT NECESSARY	180.00	-
	REMOVE REAR SEAT & REMOVE REAR SPEAKER PANEL TRIM.		180.00	80.00
	R & R ROOF LINING.	NOT NECESSARY	150.00	-
	TO SPRAY REAR TAIL LAMP PANEL LHS.	NOT NECESSARY	250.00	-
	TO SPRAY REAR TAIL LAMP PANEL RHS.	NOT NECESSARY	250.00	-
			7,360.00	3,400.00
GRAND TOTAL			16,578.50	8,111.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,000.00

Report Ref No. CS/SPF18019602/T1rbe2

MARKET VALUE: \$50,000.00(EST)-LTA REIMBURSEMENT VALUE: \$43,216.00=NETT VALUE: \$6,784.00

NOTES : THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.