

ASS. REC. BY:

REF:

CS/CTI18019604/Atd3

n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

26/10/18 @ 4:39pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMC6040A

Insured:

SGC 5347T

at Workshop n/s

SK Automobile

Tel:

6789 5155

of

23 kaki Bkt Ave 4 #03-01

Policy No:

DMPK SN 3000761807

Claim No:

8NM18D05087C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/10/18

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:20am @ 29/10/18

Person Contacted:

Jheron

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SMC6040A - NBA/CTI18019430/Y

DOA: 25/10/2018

SGG 5347T - NBA/CTI18019430/Y

DOA: 25/10/2018

Lump Sum \$15000 - (Red: 11,100.96; 68%)

REF: CT1

## ASSIGNMENT

From:

Date: 29/10/18

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMC 6040A

at Workshop m/s

SK Automobile

of

23 Kaki Bukit Ave 4 # 03-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS<sup>(up)</sup>

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC6040A - Yr Regn: 2018 July.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elentra . c.c 1591

Colour:

Silver.

A/C: Insured / Std / NI / NA

Sp. Reading

4317.

T/Radio: Insured / Std / NI / NA

Eng. No:

C/No:

KMHD841CM JU 715217

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

195/65R15

R:

195/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

29/10/18.

Survey held at

S.K.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Tp China.

RECEIVED 01 MAR 2019

Date/Time, File Pass to?

1) B Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$

Tp  
5000/-

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others:

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                                               |
|------|-------------|---------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 26 Oct 2018 |               | 26 Oct 2018<br>16:39<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|      |           |               |           |                          |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | <a href="#">Show All</a> |
|------|-----------|---------------|-----------|--------------------------|

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

|                             |                                                                                                                      |                        |                                  |  |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------------|--|
| Insured:                    | TAY HAI HWEE (ZHENG HAIHUI), ID: S7709132G                                                                           |                        |                                  |  |
| Main Claimant:              | CHUA YEOW YEW                                                                                                        |                        |                                  |  |
| Vehicle Reg. No.:           | SMC6040A                                                                                                             | Date of Loss:          | 25/10/2018 08:00 - :59           |  |
| Claim Type:                 | TP / SNM18D05087C02                                                                                                  | Policy/Cover Note No.: | DMPCSN3000761807 (Comprehensive) |  |
| Vehicle Reg. No. (Insured): | SGC5347T                                                                                                             | Policy No. (Claimant): |                                  |  |
|                             |                                                                                                                      | Excess:                | S\$0.00                          |  |
| Repairer:                   | SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155 |                        |                                  |  |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]  |                        |                                  |  |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/11/2018]                                    |                        |                                  |  |
| Adj Asg. Remarks:           | NO EST, ASSIGN ADRIAN LING AS SJE.                                                                                   |                        |                                  |  |

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

IS YOUR CAR DUE FOR  
SCRAP OR EXPORT?

Use Our **FREE** Service To Get  
The Best Selling Price!



Hyundai Elantra Min Price ▼ to No Max ▼ Depreciation ▼ Vehicle Type ▼ Category ▼

Advanced Search

Home » New Cars » Hyundai Elantra Search Results

## Hyundai Elantra Search Results (1 vehicles)

Sort by Model (Ascending) ▼

15 ▼ results/page

| Car Model                                                                                     | Price                            | Dealer                            | Built in     | User Rating                  |
|-----------------------------------------------------------------------------------------------|----------------------------------|-----------------------------------|--------------|------------------------------|
| <b>Hyundai Elantra</b>                                                                        |                                  | Komoco Motors                     | <b>Korea</b> |                              |
|  1.6 GLS (A) | <b>\$70,999</b><br>\$6,500 /yr ? | • 15.6km/l   126bhp   6-speed (A) |              | 28 User Reviews              |
| 1.6 GLS "S" (A)                                                                               | <b>\$76,999</b> ▲                | • 15.6km/l   126bhp   6-speed (A) |              | Promotion<br>Editor's Review |
| 1.6 GLS Elite (A)                                                                             | <b>\$83,999</b> ▲                | • 15.6km/l   126bhp   6-speed (A) |              |                              |

| Car Model | Price | Dealer | Built in | User Rating       |
|-----------|-------|--------|----------|-------------------|
|           |       |        |          | 15 ▼ results/page |

2 result(s) for **Hyundai Elantra** models no longer being sold by local distributors  
View all [past Hyundai cars](#)



Hyundai Elantra  
(2014-2016)



Hyundai Elantra  
(2011-2014)

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car site for buying Singapore cars, including new cars, parallel import cars & used cars. View all new cars, such as Toyota, Honda, Nissan, Volkswagen, Mitsubishi & BMW. We have new car dealers comprising parallel importers, authorised car distributors, and used car dealers. Find new car pricelists, new car launches, new car promotions, new car reviews, latest car news & car advice. Also join our car discussion and forum discussion for car reviews, motoring news & motoring guides. Visit our partner sites who have job openings for Singapore jobs, Singapore classifieds, mover and real estate properties for sale.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow **sgCarMart.com**

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                                      |
|-------------------------------------|--------------------------------------|
| <b>Vehicle Owner Particulars</b>    |                                      |
| Owner ID Type:                      | Singapore NRIC                       |
| Owner ID:                           | 9602F                                |
| <b>Vehicle Details</b>              |                                      |
| Vehicle No.:                        | SMC6040A                             |
| Vehicle to be Exported:             | Yes                                  |
| Intended Deregistration Date:       | 26 Oct 2018                          |
| Vehicle Make:                       | HYUNDAI                              |
| Vehicle Model:                      | ELANTRA AD 1.6 GLS AT (AMS)          |
| Primary Colour:                     | Silver                               |
| Manufacturing Year:                 | 2018                                 |
| Engine No.:                         | G4FGJU219317                         |
| Chassis No.:                        | KMHD841CMJU715217                    |
| Maximum Power Output:               | 93.8 kW (125 bhp)                    |
| Open Market Value:                  | \$10,751.00                          |
| Original Registration Date:         | 12 Jul 2018                          |
| First Registration Date:            | 12 Jul 2018                          |
| Transfer Count:                     | 0                                    |
| Actual ARF Paid:                    | \$10,751.00                          |
| <b>Intended PARF Rebate Details</b> |                                      |
| PARF Eligibility:                   | Yes                                  |
| PARF Eligibility Expiry Date:       | 11 Jul 2028                          |
| PARF Rebate Amount:                 | \$8,063.00                           |
| <b>Intended COE Rebate Details</b>  |                                      |
| COE Expiry Date:                    | 11 Jul 2028                          |
| COE Category:                       | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):                  | 10                                   |
| QP Paid:                            | \$25,000.00                          |
| COE Rebate Amount:                  | \$20,000.00                          |
| <b>Total Rebate Amount:</b>         | <b>\$28,063.00</b>                   |

The information contained herein is correct as at 26 Oct 2018

OK

70 999  
28,063  
-----  
\$ 42,000

Ching

MALP18139074-01 / Alpine Motors Pte Ltd - HQ  
 ENTRY DATE & TIME: 26/10/2018 11:13  
 SUBMITTED BY: RONNIE TAN GUAN HIN

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 26/10/2018 11:13  
 Date Of Accident 25/10/2018 08:30  
 Exact Location Of Accident COMMONWEALTH AVE WEST TWDS CITY  
 Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC8040A  
**Insured/Policyholder**  
 Name Of Registered Owner CHUA YEOW YEW  
 NRIC No S6909602F  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-87821648  
 Alternative Phone No OFFICE-60000000  
**Vehicle Particulars**  
 Manufacturer HYUNDAI  
 Model ELANTRA-1.6 AD (A)  
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
 Are you claiming under your own Insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category PRIVATE CAR  
**Insurance Company**  
 Name of Insurance Company AXA INSURANCE PTE LTD  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number VPA/P2157604  
 Cover Note Number  
**Driver**  
 Name of Driver CHUA YEOW YEW  
 NRIC No S6909602F  
 Date Of Birth 25/03/1969  
 Occupation INDOOR  
 Date Of Driving Pass 11/04/2000  
 Driving Experience 18 YEARS AND 6 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-87821648  
 Fax Number  
 Contact Number OFFICE-60000000  
 Email Address NOEMAIL

Address BLK 447 CHOA CHU KANG AVE 4 #07-379  
Postcode 680447  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles Involved In the accident  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

Report Please refer to Sketch Plan

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SGC5347T  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## Sketch Plan


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name: 1802046  
NRIC/FIN No.: 511318048

## Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

25 OCT 2018 AT 0830HRS I WAS DRIVING ALONG COMMONWEALTH  
 AVE WEST. WHEN THE FRONT VEHICLE STOPPED, I FOLLOW SUIT.  
 SUPPOSEDLY VEHICLE B COLLIDED INTO ME.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.




Policyholder's Signature  
 Date & Time:



Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

L

Reporting Centre Personnel's Signature  
 Name:   
 NRIC/TIN No.: 571518090

SK Automobile Pte Ltd  
(Co Reg. No. 201500047H)  
23 Kaki Bukit Ave 4, #03-01  
Vicom Inspection Centre (S415933)  
Tel: 6789 5155 Fax : 6783 5155

|                                                 |                     |                        |                    |
|-------------------------------------------------|---------------------|------------------------|--------------------|
| TO                                              | : CHINA             | DATE                   | : 26-Oct-18        |
| ATTENTION                                       | : MOTOR CLAIMS DEPT | JOB TYPE               | : T/P CLAIM        |
| ESTIMATE REPORT                                 | :                   |                        |                    |
| <u>OWNER'S PARTICULAR</u>                       |                     | <u>VEHICLE DETAILS</u> |                    |
| NAME                                            | :                   | VEHICLE NO             | : SMC6040A         |
| ADDRESS                                         | :                   | MODEL                  | : HYUNDAI 'ELANTRA |
| TEL. NO.                                        | :                   | CHASSIS NO             | :                  |
| OWNER'S INSURANCE                               | :                   |                        |                    |
| POLICY NO.                                      | :                   |                        |                    |
| <u>ACCIDENT DETAILS</u>                         |                     | DATE                   | :                  |
|                                                 |                     | TIME                   | :                  |
| THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482 |                     |                        |                    |

#### QUOTATION SUMMARY

#### CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                             | QTY | UNIT LIST PRICE | TOTAL LIST PRICE       |
|-----|-----------------------------------------|-----|-----------------|------------------------|
| 1   | REAR BUMPER <i>Deh d</i>                | 1   | \$ 698.00       | \$ <del>698.00</del>   |
| 2   | REAR BUMPER LOWER <i>Deh d</i>          | 1   | \$ 389.00       | \$ 389.00              |
| 3   | REAR BUMPER RETAINER <i>Neu</i>         | 2   | \$ 54.50        | \$ 109.00              |
| 4   | REAR BUMPER BRACKET <i>2nd 3 pieces</i> | 5   | \$ 19.80        | \$ <del>99.00</del>    |
| 5   | REAR BUMPER REFLECTOR <i>Rlt could</i>  | 2   | \$ 198.00       | \$ <del>396.00</del>   |
| 6   | REAR BUMPER REINFORCEMENT <i>Best</i>   | 1   | \$ 345.00       | \$ 345.00              |
| 7   | BOOTLID <i>Deh d</i>                    | 1   | \$ 1,602.00     | \$ 1,602.00            |
| 8   | BOOTLID REFLECTOR <i>Neu</i>            | 2   | \$ 298.00       | \$ 596.00              |
| 9   | BOOT LID LOCK DETECTOR <i>Neu</i>       | 2   | \$ 315.50       | \$ 631.00              |
| 10  | BOOT LID EMBLEM 'ELANTRA' <i>?</i>      | 1   | \$ 68.60        | \$ 68.60               |
| 11  | BOOT LID EMBLEM 'ELITE' <i>Neu</i>      | 1   | \$ 38.00        | \$ 38.00               |
| 12  | BOOTLID LOGO <i>Neu</i>                 | 1   | \$ 48.20        | \$ 48.20               |
| 13  | BOOTLID TOP LOCK <i>Neu 2nd</i>         | 1   | \$ 298.00       | \$ <del>298.00</del>   |
| 14  | BOOTLID LOWER LOCK <i>Neu</i>           | 1   | \$ 42.70        | \$ 42.70               |
| 15  | BOOTLID WEATHER STRIP <i>lot</i>        | 1   | \$ 198.00       | \$ 198.00              |
| 16  | BOOTLID INNER TRIM <i>Neu</i>           | 1   | \$ 398.00       | \$ 398.00              |
| 17  | TAILLAMP <i>crashed</i>                 | 2   | \$ 896.00       | \$ <del>1,792.00</del> |

559.40  
59.40  
198 58.  
120.80  
768.

|    |                                           |   |           |           |     |
|----|-------------------------------------------|---|-----------|-----------|-----|
| 18 | TAILLAMP PANEL <i>Repair</i>              | 2 | \$ 253.00 | \$ 506.00 | x   |
| 19 | REAR FENDER INNER COWLING <i>3 new</i>    | 2 | \$ 98.70  | \$ 197.40 | x   |
| 20 | REAR FENDER INNER TRIM <i>3 new</i>       | 2 | \$ 354.00 | \$ 708.00 | x   |
| 21 | REAR END PANEL <i>Revised</i>             | 1 | \$ 580.90 | \$ 580.90 | /   |
| 22 | REAR END PANEL TOP GARNISH <i>Revised</i> | 1 | \$ 224.00 | \$ 224.00 | 105 |
| 23 | REAR FLOOR PANEL <i>Not new</i>           | 1 | \$ 986.90 | \$ 986.90 | x   |
| 24 | REAR FLOOR PANEL TOP BOARD <i>3 new</i>   | 1 | \$ 338.00 | \$ 338.00 | x   |
| 25 | REAR FLOOR TOOLS BOX SPONGE               | 1 | \$ 210.00 | \$ 210.00 | x   |
| 26 | REAR UNDER COVER RH                       | 1 | \$ 98.00  | \$ 98.00  | x   |
| 27 | REAR UNDER COVER LH                       | 1 | \$ 189.00 | \$ 189.00 | x   |
| 28 | REAR EXHAUST PIPE                         | 1 | \$ 962.00 | \$ 962.00 | x   |
| 29 | REAR EXHAUST INSULATOR                    | 1 | \$ 210.00 | \$ 210.00 | x   |
| 30 | REAR EXHAUST PIPE MOULTING                | 2 | \$ 45.00  | \$ 90.00  | x   |

5049.30

4039.44

TOTAL PRICE \$ 13,048.70  
 LESS 20% \$ 2,609.74  
 SUB TOTAL PRICE \$ 10,438.96

| S/N | DESCRIPTION                                     | QTY | UNIT S/NETT | TOTAL S/NETT |     |
|-----|-------------------------------------------------|-----|-------------|--------------|-----|
| 1   | REAR NUMBER PLATE <i>Not new</i>                | 1   | \$ 50.00    | \$ 50.00     | x   |
| 2   | REAR BUMPER CLIP <i>New</i>                     | 10  | \$ 6.50     | \$ 65.00     | 30  |
| 3   | BOOT LID SEALANT <i>Not new</i>                 | 1   | \$ 80.00    | \$ 80.00     | x   |
| 4   | BOOT LID INSULATOR CLIP <i>Not new</i>          | 10  | \$ 6.50     | \$ 65.00     | x   |
| 5   | TAIL LAMP CLIP <i>new</i>                       | 4   | \$ 8.00     | \$ 32.00     | /   |
| 6   | TAIL LAMP PANEL SEALANT <i>Not new</i>          | 2   | \$ 80.00    | \$ 160.00    | x   |
| 7   | REAR FENDER INNER COWLING CLIP <i>3 new</i>     | 18  | \$ 6.50     | \$ 117.00    | x   |
| 8   | REAR FENDER INNER TRIM CLIPS <i>3 new</i>       | 18  | \$ 6.50     | \$ 117.00    | x   |
| 9   | REAR END PANEL TOP GARNISH CLIPS <i>new</i>     | 4   | \$ 6.50     | \$ 26.00     | 10  |
| 10  | REAR END PANEL SEALANT <i>new</i>               | 1   | \$ 120.00   | \$ 120.00    | 60  |
| 11  | REAR FLOOR PANEL INSULATION SEAL <i>Not new</i> | 1   | \$ 250.00   | \$ 250.00    | x   |
| 12  | REVERSE SENSOR <i>Damaged</i>                   | 1   | \$ 220.00   | \$ 220.00    | 200 |

332

TOTAL \$ 1,302.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

|   |                                            |             |     |  |
|---|--------------------------------------------|-------------|-----|--|
| 1 | PANEL BEATING, REMOVAL AND REPLACING PARTS | \$ 1,600.00 | 800 |  |
| 2 | TO SPRAY PAINT AFFECTED AREA               | \$ 1,500.00 | 800 |  |
| 3 | TUFF COAT                                  | \$ 250.00   | 60  |  |
| 4 | WIRING CHECK                               | \$ 60.00    | 30  |  |

|    |                                                                  |           |    |  |
|----|------------------------------------------------------------------|-----------|----|--|
| 5  | REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR | \$ 180.00 | 60 |  |
| 6  | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING             | \$ 80.00  | 50 |  |
| 7  | TRANSFER BOOTLID MECHANISM                                       | \$ 80.00  | X  |  |
| 8  | CONDUCT WATER LEAKAGE TEST                                       | \$ 80.00  | X  |  |
| 9  | MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.   | \$350.00  | X  |  |
| 10 | REMOVE AND REFIX REAR EXHAUST PIPE                               | \$ 180.00 | X  |  |

TOTAL

\$4,360.00

1800

#### ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,740.96  
 TOTAL LABOUR COST : \$ 4,360.00  
 TOTAL REPAIR COST : \$ 16,100.96

#### APPROVED DETAILS

EXCESS :  
 NO. OF WORKING DAYS :  
 RE-SURVEY :  
 PART BY PART OR LUMP SUM :  
 DATE & TIME OF SURVEY :  
 SURVEYED BY :  
 CONTACT NUMBER :  
 FAX NUMBER :

Adrian Lij total 6271.44  
 4/s 29/10/18 4/s: 5K  
 06hys. (5K)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

to check Dragnostics of vehicle

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019604/ATD3N2

Date: 04/03/2019

## REFERENCE

|                       |                                               |                      |                  |
|-----------------------|-----------------------------------------------|----------------------|------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMPCSN3000761807 |
| Claimant Vehicle No : | SMC6040A                                      | Insured Vehicle No : | SGC5347T         |
| Date of Loss:         | 25/10/2018                                    | Nature of Claim:     | TP               |
|                       |                                               | Claim No:            | SNM18D05087C02   |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SMC6040A                     | Engine No:  | G4FGJU219317      |
| Make & Model:               | HYUNDAI ELANTRA, 1.6 AD (A)  | Chassis No: | KMHD841CMJU715217 |
| Reg. Date:                  | 12/07/2018 (Man. Year: 2018) | Odometer:   | 4317 km           |
| Colour:                     | Silver                       |             |                   |
| Engine Capacity:            | 1591 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (\$\$):         | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 195/65R15  | Rear Tyre Size:  | 195/65R15  |
| Front Left Side:  | Nexen 6 mm | Rear Left Side:  | Nexen 6 mm |
| Front Right Side: | Nexen 6 mm | Rear Right Side: | Nexen 6 mm |

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

|                                           | Repairer's       | Adjuster's      | Difference       | Diff %       |
|-------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                     | 11,740.96        | 4,371.44        | 7,369.52         | 62.77        |
| Miscellaneous Items                       | 0.00             | 0.00            | 0.00             |              |
| Labour                                    | 4,360.00         | 1,900.00        | 2,460.00         | 56.42        |
| Paintwork Labour                          | 0.00             | 0.00            | 0.00             |              |
| Towing                                    | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (\$\$)</b>      | <b>16,100.96</b> | <b>6,271.44</b> | <b>9,829.52</b>  | <b>61.05</b> |
| <b>Approved Total (Overridden) (\$\$)</b> |                  | <b>5,000.00</b> |                  |              |
| <b>(\$\$)</b>                             | 16,100.96        | 5,000.00        | 11,100.96        | 68.95        |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 1,127.07         | 350.00          | 777.07           | 68.95        |
| <b>Nett Amount (\$\$)</b>                 | <b>17,228.03</b> | <b>5,350.00</b> | <b>11,878.03</b> | <b>68.95</b> |

## INSPECTION

|                     |                          |                                                                                                             |
|---------------------|--------------------------|-------------------------------------------------------------------------------------------------------------|
| Date of Assignment: | 26/10/2018               |                                                                                                             |
| Date Inspected:     | 29/10/2018 Inspected At: | SK Automobile Pte Ltd (HQ)<br>23 Kaki Bukit Avenue 4, #03-01 Vicom<br>Inspection Centre<br>Singapore 415933 |

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

|               |                                                                                                                                                                              |                                                              |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 04 Mar 2019)                |
| Parts:        | 143                                                                                                                                                                          | HYUNDAI ELANTRA 1.6 AD (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                            |
| Print Code:   | (Unsubmitted, no print-code for SMC6040A)                                                                                                                                    |                                                              |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                              |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                              |

## Recommended Parts

| No. | Qty | Part No. Particulars              | Condition            | Repairer's  | Amount       |
|-----|-----|-----------------------------------|----------------------|-------------|--------------|
| 1   | 1   | *REAR BUMPER                      | Deformed             | 698.00 FL   | *559.40 FL   |
| 2   | 1   | *REAR BUMPER LOWER                | Deformed             | 389.00 FL   | *389.00 FL   |
| 3   | 2   | *REAR BUMPER RETAINER             | Necessary            | 109.00 FL   | *109.00 FL   |
| 4   | 1   | *REAR BUMPER BRACKET<br>(5 Pcs)   | Damaged (3 Pcs only) | 99.00 FL    | *59.40 FL    |
| 5   | 1   | *REAR BUMPER REFLECTOR            | O/s Cracked          | 396.00 FL   | *58.00 FL    |
| 6   | 1   | *REAR BUMPER REINFORCEMENT        | Bent                 | 345.00 FL   | *345.00 FL   |
| 7   | 1   | *BOOTLID                          | Dented               | 1,602.00 FL | *1,602.00 FL |
| 8   | 2   | *BOOTLID REFLECTOR                | Not Necessary        | 596.00 FL   | *- FL        |
| 9   | 2   | *BOOT LID LOCK DETECTOR           | Not Necessary        | 631.00 FL   | *- FL        |
| 10  | 1   | *BOOT LID EMBLEM ELANTRA          | Necessary            | 68.60 FL    | *68.60 FL    |
| 11  | 1   | *BOOT LID EMBLEM ELITE            | Necessary            | 38.00 FL    | *38.00 FL    |
| 12  | 1   | *BOOTLID LOGO                     | Necessary            | 48.20 FL    | *48.20 FL    |
| 13  | 1   | *BOOTLID TOP LOCK                 | Damaged              | 298.00 FL   | *120.80 FL   |
| 14  | 1   | *BOOTLID LOWER LOCK               | Not Necessary        | 42.70 FL    | *- FL        |
| 15  | 1   | *BOOTLID WEATHER STRIP            | Cut                  | 198.00 FL   | *198.00 FL   |
| 16  | 1   | *BOOTLID INNER TRIM               | Not Necessary        | 398.00 FL   | *- FL        |
| 17  | 2   | *TAILLAMP                         | Cracked              | 1,792.00 FL | *768.00 FL   |
| 18  | 2   | *TAILLAMP PANEL                   | Repair               | 506.00 FL   | *- FL        |
| 19  | 2   | *REAR FENDER INNER COWLING        | Not Necessary        | 197.40 FL   | *- FL        |
| 20  | 2   | *REAR FENDER INNER TRIM           | Not Necessary        | 708.00 FL   | *- FL        |
| 21  | 1   | *REAR END PANEL                   | Dented               | 580.90 FL   | *580.90 FL   |
| 22  | 1   | *REAR END PANEL TOP GARNISH       | Deformed             | 224.00 FL   | *105.00 FL   |
| 23  | 1   | *REAR FLOOR PANEL                 | Not Necessary        | 986.90 FL   | *- FL        |
| 24  | 1   | *REAR FLOOR PANEL TOP BOARD       | Not Necessary        | 338.00 FL   | *- FL        |
| 25  | 1   | *REAR FLOOR TOOLS BOX SPONGE      | Not Necessary        | 210.00 FL   | *- FL        |
| 26  | 1   | *REAR UNDER COVER RH              | Not Necessary        | 98.00 FL    | *- FL        |
| 27  | 1   | *REAR UNDER COVER LH              | Not Necessary        | 189.00 FL   | *- FL        |
| 28  | 1   | *REAR EXHAUST PIPE                | Not Necessary        | 962.00 FL   | *- FL        |
| 29  | 1   | *REAR EXHAUST INSULATOR           | Not Necessary        | 210.00 FL   | *- FL        |
| 30  | 2   | *REAR EXHAUST PIPE MOULTING       | Not Necessary        | 90.00 FL    | *- FL        |
| 31  | 1   | *REAR NUMBER PLATE                | Not Necessary        | 50.00 FS    | *- FS        |
| 32  | 10  | *REAR BUMPER CLIP                 | Necessary            | 65.00 FS    | *30.00 FS    |
| 33  | 1   | *BOOT LID SEALANT                 | Not Necessary        | 80.00 FS    | *- FS        |
| 34  | 10  | *BOOT LID INSULATOR CLIP          | Not Necessary        | 65.00 FS    | *- FS        |
| 35  | 4   | *TAIL LAMP CLIP                   | Necessary            | 32.00 FS    | *32.00 FS    |
| 36  | 2   | *TAIL LAMP PANEL SEALANT          | Not Necessary        | 160.00 FS   | *- FS        |
| 37  | 18  | *REAR FENDER INNER COWLING CLIP   | Not Necessary        | 117.00 FS   | *- FS        |
| 38  | 18  | *REAR FENDER INNER TRIM CLIPS     | Not Necessary        | 117.00 FS   | *- FS        |
| 39  | 4   | *REAR END PANEL TOP GARNISH CLIPS | Necessary            | 26.00 FS    | *10.00 FS    |
| 40  | 1   | *REAR END PANEL SEALANT           | Necessary            | 120.00 FS   | *60.00 FS    |
| 41  | 1   | *REAR FLOOR PANEL INSULATION SEAL | Not Necessary        | 250.00 FS   | *- FS        |
| 42  | 1   | *REVERSE SENSOR                   | Damaged              | 220.00 FS   | *200.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

| No.                                                 | Qty | Part No. | Particulars | Condition | Repairer's | Amount   |
|-----------------------------------------------------|-----|----------|-------------|-----------|------------|----------|
| Sub Total (\$\$)                                    |     |          |             |           | 14,350.70  | 5,381.30 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) |     |          |             |           | 2,609.74   | 1,009.86 |
| Total Parts (\$\$)                                  |     |          |             |           | 11,740.96  | 4,371.44 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                          | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                      |          |                 |                 |
| 1                               | PANEL BEATING, REMOVAL AND REPLACING PARTS                                                           | New      | 1,600.00        | 900.00          |
| 2                               | TO SPRAY PAINT AFFECTED AREA                                                                         | New      | 1,500.00        | 800.00          |
| 3                               | TUFF COAT                                                                                            | New      | 250.00          | 60.00           |
| 4                               | WIRING CHECK                                                                                         | New      | 60.00           | 30.00           |
| 5                               | REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING<br>TO FACILITATE REPAIR                                  | New      | 180.00          | 60.00           |
| 6                               | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE<br>SETTING                                              | New      | 80.00           | 50.00           |
| 7                               | TRANFER BOOTLID MECHANISM                                                                            | New      | 80.00           | 0.00            |
| 8                               | CONDUCT WATER LEAKAGE TEST                                                                           | New      | 80.00           | 0.00            |
| 9                               | TO CHECK DIAGNOSTICS OF VEHICLE<br>MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO<br>SPECIFICATION ETC | New      | 350.00          | 0.00            |
| 10                              | REMOVE AND REFIX REAR EXHAUST PIPE                                                                   | New      | 180.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                      |          | <b>4,360.00</b> | <b>1,900.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >