

15/00/04

4. UPC 19615, Gfa3n2

LKK:

LKK:

P00001

X62

L00

ASSIGNMENT

16-10-18

pdkn

Date / Time:

26-10-18

Registered in Merimen:

Pre-assign / CCU / FTE

GBC 8337



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

Excess Set II :SS

Is driver the owner? (/ NO)

If NO, Driver Name / Age :

Driver Tel No. :

HP: 28/10/18
D.O.A:

Nature of Accident :

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHA 1690 B



INSRS:

WSP:

Tel:

Liability:

RMKS:

CDW
loyars.

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

2/11
CDWSHA 1690 B - CDW AXA 12011451 / Hateda : 007 6/6/12
GBC 8337 - X

BOLA 27, 100%

posting thence estimate

KIV LOP

file pass for mandate report

After repair photo

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

ATA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

30/10/2018

HMK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 4,550.00 (5 days) Reduction: 28.88 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: (w/LOI)

S\$ 4,868.50

Loss of Rental (LOR):

S\$ 469.12 (4 days) x \$117.28

Loss of Use (LOU):

S\$ - (\$ x days)

Loss of Income (LOI):

S\$ 200.00 (\$50.00 x 4 days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search

S\$ 7.49

Medical:

S\$ -

Disbursement:

S\$ -

Legal Cost

S\$ -

Total:

S\$ 5,545.11

Global Sum S\$: 5,540.00

1) Claim status: Normal/Reject/Private Settle

2) Report Format: 7P

3) Survey fee: \$450.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

S\$ 5,540.00

Name 1:

ContortDelgro Engineering Pte Ltd

Payee 2 (GIA/LTA):

S\$

Name 2:

Payee 3 (GIA/LTA):

S\$

Name 3:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/LPC18019615/Gfa3

Date: 30/10/2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA 1690B


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26.10.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

| | | |
|-------------------------------|-------|----------|
| Workshop Estimate Amount | : S\$ | 6,397.70 |
| Revised Estimate Amount | : S\$ | 5,684.32 |
| "Check" Items Amount | : S\$ | 318.02 |
| Total (Including Check Items) | : S\$ | 6,002.34 |
| Market Value | : S\$ | - (est.) |
| LTA Reimbursement Value | : S\$ | - (est.) |
| Nett Value | : S\$ | - (est.) |

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

XING GUO QIANG
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|---|---------------------------------|
| Owner ID Type: | Company |
| Owner ID: | 3821R |
| Vehicle Details | |
| Vehicle No.: | SHA1690B |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 29 Oct 2018 |
| Vehicle Make: | HYUNDAI |
| Vehicle Model: | I40 1.7L CRDI AT ABS AIRBAG 4DR |
| Primary Colour: | Blue |
| Manufacturing Year: | 2013 |
| Engine No.: | D4FDFU595653 |
| Chassis No.: | KMHLB41UMDU043674 |
| Maximum Power Output: | 100.0 kW (134 bhp) |
| Open Market Value: | \$18,807.00 |
| Original Registration Date: | 11 Feb 2014 |
| First Registration Date: | 11 Feb 2014 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$11,307.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 10 Feb 2022 |
| PARF Rebate Amount: | \$8,480.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 10 Feb 2022 |
| COE Category: | A - Car (1600cc & below) |
| COE Period(Years): | 8 |
| PQP Paid: | \$58,590.00 |
| COE Rebate Amount: | \$24,059.00 |
| Total Rebate Amount: | \$32,539.00 |
| Message | |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 29 Oct 2018

OK

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHA 1690B

MAKE :

MODEL : HYUNDAI i40

DATE 26/10/2018 9:22

DOA 25.10.18 LS

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|--|---|------|------------|--------------------------|
| | Boot Lid / <i>buc</i> | | | \$ 2,174.90 |
| | Boot Lid Lock Upper / <i>BT</i> | | | \$ 102.60 |
| | Boot Lid Lock Lower / <i>NN</i> | | | \$ 31.70 |
| | Boot Lid 'H' Emblem / <i>buc</i> | | | \$ 28.70 |
| | Boot Lid CRDI Plate / <i>buc</i> | | | \$ 27.90 |
| | Bootlid Moulding / <i>buc</i> | | | \$ 227.90 |
| | Bootlid i40 Emblem / <i>NN</i> | | | \$ 27.90 |
| | Bootlid Lower Garnish / <i>NN</i> | | | \$ 227.90 |
| | Rear Bumper / <i>re</i> | | | \$ 553.00 |
| | Rear Bumper Reinforcement / <i>BT</i> | | | \$ 428.40 |
| | Rear Bumper Reinforcement Bracket (LH/RH) / <i>BT</i> | | \$ 80.30 | \$ 160.60 |
| | Rear Bumper Clip 10 pcs / <i>MGL</i> | | | \$ 22.00 |
| | Rear Bumper Bracket / <i>re</i> | | \$ 35.60 | \$ 71.20 |
| | Rear Bumper Sponge / <i>CPA</i> | | | \$ 103.50 |
| | Rear Bumper Under Cover / <i>cut</i> | | | \$ 228.00 |
| | Rear Panel / <i>buc</i> | | | \$ 526.70 |
| | Rear Panel Garnish / <i>re</i> | | | \$ 57.70 |
| | Rear Panel Lower Panel / <i>BT</i> | | | \$ 89.40 |
| | SUB TOTAL | | | \$ 5,090.00 |
| | LESS 20% | | | \$ 1,018.00 |
| | DISCOUNTED TOTAL | | | \$ 4,072.00 |
| | Boot Lid Comfort Logo & Tel No. Sticker / <i>MGL</i> | | | \$ 30.00 Nett |
| | Rear Bumper Reverse Sensor / <i>NN</i> | | | \$ 135.70 Nett |
| | Rear Bumper Rubber Mat / <i>MGL</i> | | | \$ 50.00 Nett |
| | Rear Bumper Advertisement Logo / <i>MGL</i> | | | \$ 50.00 Nett |
| | Rear Fender Advertisement Logo (LH/RH) / <i>MGL</i> | | \$ 100.00 | \$ 200.00 Nett |
| | | | | \$ 465.70 |
| | Labour Charge | | | |
| | Panel Beating / <i>Empson Repair.</i> | | | \$ 800.00 <i>600</i> |
| | Spray Painting Charge / <i>After repair photos.</i> | | | \$ 900.00 <i>600 800</i> |
| | Wiring Charge / <i>One Amp.</i> | | | \$ 30.00 <i>20</i> |
| | Tuff Kote / <i>26/10/18</i> | | | \$ 50.00 <i>30</i> |
| | Remove/Refix Reverse Sensor / <i>16/10.</i> | | | \$ 80.00 <i>40.</i> |
| | TOTAL LABOUR | | | \$ 1,860.00 |
| | ESTIMATE TOTAL | | | \$ 6,397.70 |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. | | | | |

Larry Ng

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 8280 Facsimile + 65 6260 9755

Workshops

59 Loyang Drive Singapore 508968
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609296
24 Senoko Loop Singapore 756136
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768730

Date/Time: 25.10.2018 18:29 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305230584

CUSTOMER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

VARC

VMS

CUSTOMER NO.

DRESS

(R)

(P)

(O)

COUNT CARD NO.

REGN NO.:

SHA1690B

MILEAGE

MAKE:

HYUNDAI

FUEL

E..... 1/2..... F

MODEL

I-40

DATE/TIME IN

25.10.2018 15:05

YR OF MANU

11.02.2014

TARGET DATE

CHASSIS CODE

KMHLB41UMDU043674

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 25.10.2018

NATURE: 3P 25.10.2018

S/NO

LABOR CODE

DESCRIPTION


FRONT

LONPAC - Rear damage



LEFT SIDE

REAR



RIGHT SIDE

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Signature

Date

Signature

SHA1690B

LARRY

Vehicle No.:

SHA1690B

Larry Ng

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

Poh K'm

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305230584
Date : 29. Oct. 2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SHA1690B

Date of Accident: 25. Oct. 2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: LONPAC GBC833Z

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$4,550.00

3. Estimated normal period for repairs: 5 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : Gue Ape

Name : Gue Ape

Date : 01/11/18

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|---|--------|--------------------------------|---------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | | | | |
| 3. Survey Fees | | | | |
| 4. LTA Search Fee | | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 26 October 2018 12:14 PM
To: assignments@lkkauto.com; Catherine Chong (LKK Auto)
Cc: MT_Claim_SG
Subject: Our Ref: TBA Acc inv GBC833Z & SHA1690B on 25/10/2018
Attachments: 26102018121119.pdf

12.17pm @ 26/10/2018
Vehicle In

Dear Catherine/Nivitha

Please refer to the attached and arrange TP survey.

SURE GWO Qianq

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



COMFORTDELGRO ENGINEERING

Our Ref : 305230584

Date : 26.10.2018

Time of Fax : 1035h

LONPAC

Via Fax : 62962706

Your Insured : GBC 833 Z

Date of Acc : 25.10.2018

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506489V

Workshop

Attn : Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHA 1690 B

→ Loyang
59 Loyang Drive
Singapore 508969

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find :
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng Tel no. 62148355 or Hp no. 98240811
 Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305
 Lim Tien Siong Tel no. 62148398 or Hp no. 96358546
 Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006
 Fauzy Bin Mokhtar Tel no: 62148319 or Hp no : 81259176
 Larry Ng Tel: 6214 8316
- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

7 Thank you.

Yours faithfully

L. N Larry Ng

for Vice President
Crash Repairs & Claims Recovery

Mei Kwan (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 31 October, 2018 5:49 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG; CS A Team; Admin A
Subject: RE: Our Ref: 18/18/18/VC00/021062 Acc inv GBC833Z & SHA1690B on 25/10/2018
Attachments: GBC833Z 251018.PDF

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan

Please see attached for our Insured's GIA report.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 31 October, 2018 11:53 AM
To: ONG LI LI
Cc: MT_Claim_SG; CS A Team; Admin A
Subject: RE: Our Ref: TBA Acc inv GBC833Z & SHA1690B on 25/10/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: TBA
LKK REF: CC4/LPC18019615/Gfa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SHA 1690B

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Poh Kin and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Poh Kin (LKKAUTO)

From: Kazali Haji Selahudin <kazali@cdge.com.sg>
Sent: Thursday, 28 February 2019 3:56 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A
Subject: Re: RTA involving vehicle nos. GBC 833Z and SHA 1690B on 25/10/2018

Categories: clear

Dear Poh Kin,

Your proposed offer below is **accepted**. Kindly let us have your DV for our execution and early return.
Thank you.

Best Regards

Kazali Hj Selahudin

Claims Department / ComfortDelGro Engineering Pte Ltd

Off: 6214 8736 / Fax: 6214 1843

From: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>
Sent: Tuesday, 26 February 2019 10:44 AM
To: Kazali Haji Selahudin
Cc: Admin A
Subject: RTA involving vehicle nos. GBC 833Z and SHA 1690B on 25/10/2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Our Ref: CC4/LPC18019615/Gfa3
Your Ref: T1018/ SHA 1690B/KS(st)

Dear Kazali,

We refer to above matter and your letter of demand.

towards an amicable settlement, we offer settlement at global sum of **\$5,540.00(all in)** on this matter.

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Tuesday, 26 February 2019 10:45 AM
To: 'Kazali Haji Selahudin'
Cc: Admin A
Subject: RTA involving vehicle nos. GBC 833Z and SHA 1690B on 25/10/2018

Importance: High

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Our Ref: CC4/LPC18019615/Gfa3
Your Ref: T1018/ SHA 1690B/KS(st)

Dear Kazali,

We refer to above matter and your letter of demand.

towards an amicable settlement, we offer settlement at global sum of **\$5,540.00(all in)** on this matter.

Kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Poh Kin (LKKAUTO)


From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 25 February 2019 5:56 PM
To: Poh Kin (LKKAUTO)
Cc: MT_Claim_SG; Admin A
Subject: RE: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBC 833Z (OI) AND SHA 1690B (TP) ON 25-10-2018; LKK ref : CC4/LPC18019615/Gfa3; Lonpac ref: 18/18/18/VC00/021062 [External Confidential]

Lonpac External - Confidential

Dear Poh Kin

Pls proceed.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: Saturday, 23 February, 2019 10:08 AM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A
Subject: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBC 833Z (OI) AND SHA 1690B (TP) ON 25-10-2018; LKK ref : CC4/LPC18019615/Gfa3; Lonpac ref: 18/18/18/VC00/021062
Importance: High

Without Prejudice

Our Ref: CC4/LPC18019615/Gfa3
Your Ref: 18/18/18/VC00/021062

Dear Ms Li Li,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBC 833Z (OI) AND SHA 1690B (TP) ALONG GEYLANG ROAD ON 25/10/2018

We refer to the above matter.

Liability: The accident occurred when our Insured Driver collided into rear of third party vehicle. Liability is down against our Insured.

Summary to offer to third party repairer, ComfortDelgro Engineering Pte Ltd is as follows: -

| | Claimed Amount | Revised Amount |
|--|----------------|----------------|
|--|----------------|----------------|

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Saturday, 23 February 2019 10:08 AM
To: 'ONG LI LI'
Cc: MT_Claim_SG; Admin A
Subject: SEEK MANDATE; ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBC 833Z (OI) AND SHA 1690B (TP) ON 25-10-2018; LKK ref : CC4/LPC18019615/Gfa3; Lonpac ref: 18/18/18/VC00/021062
Attachments: LKK Adjustment report.pdf; LKK Inspection report.pdf; LKK RESURVEY PHOTO.pdf; LKK RESURVEY PHOTO-AFTER REPAIR.pdf; LKK SURVEY PHOTO.pdf; TP LOD_SHA 1690B.pdf
Importance: High

Without Prejudice

Our Ref: CC4/LPC18019615/Gfa3
Your Ref: 18/18/18/VC00/021062

Dear Ms Li Li,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. GBC 833Z (OI) AND SHA 1690B (TP) ALONG GEYLANG ROAD ON 25/10/2018

We refer to the above matter.

Liability: The accident occurred when our Insured Driver collided into rear of third party vehicle. Liability is down against our Insured.

Summary to offer to third party repairer, ComfortDelgro Engineering Pte Ltd is as follows: -

| | Claimed Amount | Revised Amount |
|---------------------------|----------------------------------|-----------------------------------|
| 1. Cost of Repair (w/GST) | \$ 6,845.54 (\$6,397.70 + 7%gst) | \$ 4,868.50 (\$4,550.00 + 7% gst) |
| 2. Loss of Rental | \$ 586.40 (\$117.28 x 5 days) | \$ 527.76 (\$117.28 x 4.5 days) |
| 3. Loss of Income | \$ 400.00 (\$80.00 x 5 days) | \$ 225.00 (\$50.00 x 4.5 days) |
| 4. LTA search fee | \$ 7.49 | \$ 7.49 |
| Total | \$ 7,839.43 | \$ 5,628.75 |

****05 days recommendation for repair**

Relevant supporting claim documents are attached herewith for your perusal and reference.

The above is for your approval.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18019615/Gfa3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 03-04-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------------|----------------|------------|
| Insured Veh. | GBC 833Z | Veh. Inspected | SHA 1690B |
| Policy No. | Z/18/VC00/101550 | Coverage (\$) | 0.00 |
| Claim No. | 18/18/18/VC00/021062 | Excess (\$) | 0.00 |
| Assign From | ONG LI LI | Assign Date | 26/10/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|----------|
| Make & Model | HYUNDAI I40 | c.c | 1685 |
| Engine No. | HIDDEN | Year of Reg. | 2014 |
| Chassis No. | KMHLB41UMDU043674 | Colour | BLUE |
| Odometer | 640971 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|---------|---------|
| R/H Front Tyre | 205/60 R16 | HANKOOK | 6 mm |
| L/H Front Tyre | 205/60 R16 | HANKOOK | 6 mm |
| R/H Rear Tyre | 205/60 R16 | HANKOOK | 6 mm |
| L/H Rear Tyre | 205/60 R16 | HANKOOK | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 25/10/2018 | Inspection Date | 26/10/2018 |
| Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1690B

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---|---------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | BOOT LID | BUCKLED | 2,174.90 | 2,174.90 |
| 1 | BOOT LID LOCK UPPER | BENT | 102.60 | 102.60 |
| 1 | BOOT LID LOCK LOWER | NOT NECESSARY | 31.70 | - |
| 1 | BOOT LID 'H' EMBLEM | NECESSARY | 28.70 | 28.70 |
| 1 | BOOT LID CRDI PLATE | NECESSARY | 27.90 | 27.90 |
| 1 | BOOTLID MOULDING | NECESSARY | 227.90 | 227.90 |
| 1 | BOOTLID I40 EMBLEM | NECESSARY | 27.90 | 27.90 |
| 1 | BOOTLID LOWER GARNISH | NOT NECESSARY | 227.90 | - |
| 1 | REAR BUMPER | DEFORMED | 553.00 | 553.00 |
| 1 | REAR BUMPER REINFORCEMENT | BENT | 428.40 | 428.40 |
| 2 | REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30 | BENT | 160.60 | 160.60 |
| 10 | REAR BUMPER CLIP | NECESSARY | 22.00 | 22.00 |
| 2 | REAR BUMPER BRACKET @\$35.60 | DEFORMED | 71.20 | 71.20 |
| 1 | REAR BUMPER SPONGE | CRACKED | 103.50 | 103.50 |
| 1 | REAR BUMPER UNDER COVER | CUT | 228.00 | 228.00 |
| 1 | REAR PANEL | BUCKLED | 526.70 | 526.70 |
| 1 | REAR PANEL GARNISH | DEFORMED | 57.70 | 57.70 |
| 1 | REAR PANEL LOWER PANEL | BENT | 89.40 | 89.40 |
| | LESS 20% DISCOUNT | | -1,018.00 | -966.08 |
| | | | 4,072.00 | 3,864.32 |
| SPECIAL NETT ITEMS | | | | |
| 1 | BOOT LID COMFORT LOGO & TEL NO. STICKER (SN) | NECESSARY | 30.00 | 30.00 |
| 1 | REAR BUMPER REVERSE SENSOR (SN) | NOT NECESSARY | 135.70 | - |
| 1 | REAR BUMPER RUBBER MAT (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | REAR BUMPER ADVERTISEMENT LOGO (SN) | NECESSARY | 50.00 | 50.00 |
| 2 | REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN) | NECESSARY | 200.00 | 200.00 |
| | | | 465.70 | 330.00 |
| LABOUR | | | | |
| | PANEL BEATING. | | 800.00 | 600.00 |

Report Ref No. CC4/LPC18019615/Gfa3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|-------------------------------|-----------|---------------------------|-------------------|
| | SPRAY PAINTING CHARGE. | | 900.00 | 800.00 |
| | WIRING CHARGE. | | 30.00 | 20.00 |
| | TUFF KOTE. | | 50.00 | 30.00 |
| | REMOVE/REFIX REVERSE SENSOR . | | 80.00 | 40.00 |
| | | | 1,860.00 | 1,490.00 |
| GRAND TOTAL | | | 6,397.70 | 5,684.32 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 4,550.00 |

Report Ref No. CC4/LPC18019615/Gfa3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.