

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 688A**AAD1810-257***Not Notarised**Resony Bepain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 688A

WDD2120012B221893

MERCEDES BENZ

E220 CDI

24.10.18

AIG**PART****LIST**

1	1	Front Bumper	\$	<i>Bumper</i> 1,897.50	✓
2	1	Front Bumper Reinforcement	\$	<i>n</i> 984.00	} X
3	1	Front Bumper Centre Inner Frame LH	\$	<i>sn</i> 97.50	
4	1	Front Bumper Side Retainer LH	\$	<i>sn</i> 132.00	
5	1	Front Bumper Side Retainer RH	\$	<i>sn</i> 132.00	
6	1	Front Bumper Centre Inner Frame RH	\$	<i>sn</i> 97.50	
7	1	Front Bumper Side Inner Frame LH	\$	<i>sn</i> 69.00	
8	1	Front Bumper Side Inner Frame RH	\$	<i>sn</i> 69.00	
9	1	Front Bumper Inner Sponge Centre	\$	<i>sn</i> 87.00	}
10	1	Front Bumper Inner Sponge Side LH	\$	<i>sn</i> 82.50	
11	1	Front Bumper Inner Sponge Side RH	\$	<i>sn</i> 82.50	
12	1	Front Headlamp RH	\$	1,416.00	?
13	1	Headlamp Bracket RH	\$	<i>n</i> 144.60	X
14	1	Frame for Headlamp Panel RH	\$	<i>n</i> 260.00	X
15	1	Radiator grille	\$	<i>sn</i> 1,580.00	X
16	1	Radiator assemble	\$	<i>sn</i> 2,520.00	X
20	1	Bonnet	\$	<i>n</i> 4,368.00	X

TOTAL	\$	14,019.10
10%	\$	1,401.91
	\$	12,617.19

Special Nett

1	1SET	Rocker panel Fastener Clip	\$	<i>na</i> 80.00	X
2	1SET	Door LEDGE Clip FTR LH	\$	<i>na</i> 120.00	X
3	1 SET	Front Bumper Inner Frame Clip	\$	<i>na</i> 90.00	X
4	1 SET	Front Bumper Inner Frame Metal Clip	\$	<i>na</i> 60.00	X
5	1 SET	Front Bumper clip	\$	<i>na</i> 61.83	✓
TOTAL	\$	411.83			

Trans-cab Auto Services Pte Ltd

AAD1810-257

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 688A

TOTAL PARTS	\$	13,029.02
--------------------	-----------	------------------

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,500.00	2501
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	200.00	151
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, to Enable Repair.	\$	nn 380.00	X
To Transfer Of Fender Fittings, Attachment And Perform Water Seepage Test.	\$	nn 170.00	X
To Check Steering Geometry And Computer Wheel Alignment.	\$	nn 220.00	X
Putty And Spray Painting Of The Affected Portion.	\$	3,500.00	2501
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 200.00	X

TOTAL	\$	8,340.00
--------------	-----------	-----------------

Over All Total	\$	21,369.02
-----------------------	-----------	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DAYS (PART-BY-PART)**10 DAYS**

2 days